

23/03/2002

ASS. REC. BY:

REF:

1C71 19016148 / FC f3

Special Instruction:

Surveyor: Ram

ASSIGNMENT (Office)

minimum

From (Person): Elaine Chong of CTI Date/Time: 11.9.19 1633PM

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBB 5100C Insured: SFH 1717Xat Workshop m/s M.S Panel Beating workshop Tel: 9739 1788of 2 KOKI Bukit Ave 6 #02. 17 AutohubPolicy No: DMPCSN3044518044 Claim No: SNM1902047C02

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 6.9.2019

(Client's Record)

awp'

12.9.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 12.9.19 5.07p.m Person Contacted: Pauline Vehicle IN OUT

Date/Time	Action/Instruction ( X ) Estimate
	GBB 5100C - X
	SFH 1717X - X
	Dismantle: 13/9/2019
	After repair: 18/9/2019

ASS. REC. BY:

REF: C71

PRS

## ASSIGNMENT

From:

Date:

12.9.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBB 5100 C

at Workshop m/s

M-S. Panel Beating workshop  
of 2 Karis Bukit Ave 6 # 03-17 Autohub

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

wp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBB 5100C

Yr Regn: MAY / 2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna

C.C 2982

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

25"1680

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFAT35Y90-K20644

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 185 R 15C

Westlake

R: 155 R 12C

Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

1/f

mm

L/Bal.

5

mm

L/Bal.

4/4

mm

D.O.A. 06/09/2019

D.O.I.

12/09/19

Survey held at

M3 Panel Beating Wksp

Des. of Damages: Frt

Rear

O/S / N/S / U/C / Rooftop or

rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair days: 4 days  
Range: \$2000-\$3000

MV: \$48000

PV: \$25749

NV: \$22000\*

Date/Time, File Pass to?



Preli. Report



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Week end (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Rep. Form:

PRS

Lump Sum / F.B. / C

**...CLAIM SUBFOLDER...(New Assignment)**

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Sep 2019		11 Sep 2019 16:33 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All																				
<b>CLAIM SUBFOLDER DETAILS</b>			<b>[Created by insurer]</b>																					
Insured:																								
Main Claimant:		CHIP GUAN ENGINEERING PTE LTD, Co. Reg. No.: 197400209N																						
Vehicle Reg. No.:		GBB5100C	Date of Loss:	06/09/2019 19:00 - :59																				
Claim Type:		TP / SNM19D204247C02	Policy/Cover Note No.:	DMPCSN30144518044																				
Vehicle Reg. No. (Insured):		SFH1717X	Policy No. (Claimant):	D19MTPCVE001215																				
		Excess:	S\$750.00																					
Repairer:		M.s Panel Beating Workshop (HQ) 2 KAKI BUKIT AVE 6, # 02 . 17 AUTOHUB @ KAKI BUKIT, 417921 Kaki Bukit - Tel:																						
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]																						
Claimant's Insurer:		Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555																						
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/09/2019]																						
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>																				
There are no mail for this case.																								
<div>  <b>ALL ASSOCIATED TASKS</b> </div> <div> <div> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </div> <table> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

# Centro-Legal Law Corporation

ADVOCATES AND SOLICITORS

151 Chin Swee Road  
#02-21 Manhattan House  
Singapore 169876  
Tel: 6235 0633  
Fax: 6235 6939

Your ref : To be advised (SFH1717X)

Our ref : CLLC.PD.139.2019 LI

10.09.2019

**CHINA TAIPING INSURANCE (S'PORE) PTE LTD**

3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

Attn: **Officer-In-Charge**

Dear Sirs,

**NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2  
WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION  
PROTOCOL FOR NIMA CASE**

We act for **CHIP GUAN ENGINEERING PTE LTD**, the owner of motor vehicle **GBB5100C**, who has appointed us to act on his behalf to claim against your insured's vehicle no SFH1717X in regard to the road traffic accident on 06.09.2019.

Please be informed that the said motor vehicle can be inspected at:-

**M.S.PANEL BEATING WORKSHOP**

No. 2 Kaki Bukit Ave 2  
#02-17 AUTOHUB, Singapore 417921  
Tel: 9739 1788 / 9143 6036 Fax: 6747 8306

Kindly contact **PAULINE HP:9739 1788**

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or public Holiday, the said workshop will commence repairs thereafter without further reference to you.



**CENTRO-LEGAL LAW CORPORATION**  
Cc: **PAULINE** FAX NO: 6747 8306

UEN NO.201302032G

CENTRO-LEGAL LAW CORPORATION is incorporated as a company in Singapore

## Nivitha (LKK Auto)

---

**From:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Sent:** Wednesday, 11 September 2019 3:51 PM  
**To:** 'ling@centrollc.com.sg'; assignments  
**Subject:** RE: OUR REF: SNM19D204247-SFH1717X-CML - FW: PRE-REPAIR INSPECTION - OUR REF: CLLC.PD.139.2019 YOUR REF: SFH1717X

### WITHOUT PREJUDICE

Dear Mr Ling,

We refer to your email of 11.09.19.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below with attachment and liaise with third party workshop accordingly.

Thank you.

Regards,

**Elaine Cheong**  
Executive (Motor Claims)  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6530  
Fax: 6224 7478 / 6224 7175  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

---

**From:** ling@centrollc.com.sg [mailto:ling@centrollc.com.sg]  
**Sent:** Wednesday, 11 September, 2019 10:16 AM  
**To:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Subject:** RE: OUR REF: SNM19D204247-SFH1717X-CML - FW: PRE-REPAIR INSPECTION - OUR REF: CLLC.PD.139.2019 YOUR REF: SFH1717X

### WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

Our client is not agreeable with your surveyors. However, our client would like to propose the surveyors as below:

1. CHANG FUH KEONG, DAVE - SINCERE APPRAISAL SERVICES

2. HOW ANDREW - PROMINENT APPRAISER SERVICES PTE LTD  
3. TAN TIONG HAI - PRO PLUS AUTOMOBILE ENGINEERS  
4. NG SON AIK, FRANCIS - PRESTIGE APPRAISER SERVICES  
5. NG SOON CHUAN, LOUIS - PRESTIGE APPRAISER SERVICES  
6. WONG AH KOW - RW AUTOMOBILE APPRAISERS SERVICES  
7. YAP TECK CHYE, MICHAEL - MC-COY APPRAISER PTE LTD  
8. FONG KOK HENG, STANLEY - AUTOMAX SURVEY  
Kindly revert which surveyor is your preference. Thanks  
Best Regards,

MR LING  
Centro-Legal Law Corporation  
151 Chin Swee Road  
#02-21 Manhattan House  
Singapore 169876  
Tel: 6235 0633  
Fax: 6235 6939  
H/P: 96628304

---

**From:** Elaine Cheong <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>  
**Sent:** Wednesday, 11 September 2019 10:10 AM  
**To:** [ling@centrollc.com.sg](mailto:ling@centrollc.com.sg)  
**Subject:** RE: OUR REF: SNM19D204247-SFH1717X-CML - FW: PRE-REPAIR INSPECTION - OUR REF: CLLC.PD.139.2019 YOUR REF: SFH1717X

**WITHOUT PREJUDICE**

Dear Mr Ling,

We refer to your email of 10.09.19.

We would like to conduct pre-repair survey of the vehicle at the appointed workshop.

We propose the following list of surveyors to be nominated as the Single Joint Expert to conduct survey of the claimant's vehicle:-

1. ADRIAN LING	6. KENNETH KONG
2. Kelvin Ang	7. SIMON HO
3. SEE CHEW SENG	8. CHUA WEIJIE
4. MOHD FADHILAH BIN OSMAN	9. MARCUS CHUA
5. XING QUO QIANG	10. HENRY NG

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

As per the NIMA Protocol, the survey by our appointed surveyor would include survey of your vehicle pre-repair, after it is dismantled, and post repairs. Hence, you need to provide us / our surveyors with the list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.

As stated above, please inform us and our surveyor after the claimant's vehicle had been repaired so that our surveyor can carry out post repair inspection before the vehicle is returned to your client. Please co-ordinate with our surveyor immediately after the repair is completed.

Regards,

**Elaine Cheong**  
Executive (Motor Claims)  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6530  
Fax: 6224 7478 / 6224 7175  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

---

**From:** Claims Dept of CTI  
**Sent:** Tuesday, 10 September, 2019 2:30 PM  
**To:** Elaine Cheong <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>; Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; [ling@centrollc.com.sg](mailto:ling@centrollc.com.sg)  
**Subject:** OUR REF: SNM19D204247-SFH1717X-CML - FW: PRE-REPAIR INSPECTION - OUR REF: CLLC.PD.139.2019 YOUR REF: SFH1717X

Dear Elaine,

Please conduct PRS for GBB5100C.

Note : officer in charge – Elaine Cheong 63896530.

Regards,

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
T: (65) 63896116 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

---

**From:** [ling@centrollc.com.sg](mailto:ling@centrollc.com.sg) [mailto:[ling@centrollc.com.sg](mailto:ling@centrollc.com.sg)]  
**Sent:** Tuesday, 10 September, 2019 10:13 AM  
**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>; Irene Tay <[irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)>; Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; Angie Foo <[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)>  
**Cc:** [sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)  
**Subject:** PRE-REPAIR INSPECTION - OUR REF: CLLC.PD.139.2019 YOUR REF: SFH1717X

**WITHOUT PREJUDICE**

Dear Sir/Madam,

Kindly refer to the attachment. ( PRE-REPAIR INSPECTION )

Thank you and have a nice day.

Best Regards,

MR LING

Centro-Legal Law Corporation  
151 Chin Swee Road  
#02-21 Manhattan House  
Singapore 169876  
Tel: 6235 0633  
Fax: 6235 6939  
H/P: 96628304

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	209N
Vehicle Details	
Vehicle No.:	GBB5100C
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 MANUAL 3SEATER
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	1KD1923936
Chassis No.:	JTFAT35Y90K200544
Maximum Power Output:	-
Open Market Value:	\$24,970.00
Original Registration Date:	12 May 2009
First Registration Date:	12 May 2009
Transfer Count:	0
Actual ARF Paid:	\$1,249.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$26,760.00
COE Rebate Amount:	\$25,749.00
Total Rebate Amount:	\$25,749.00

The information contained herein is correct as at 16 Sep 2019

Remaining : 9 years 7 months 24 days (115.8) OK

Depri: \$5000/yearly \$416/monthly

$115.8 \times \$416 = \$48172.80$

## Mercedes Owners Thread

## 2019 facelift Honda Shuttle

[Advanced Search](#)

[Home](#) » [Used Cars](#) » [SA Motor Trading](#) » [Toyota Dyna 150 3.0M \(COE till 05/2029\)](#)

### Toyota Dyna 150 3.0M (COE till 05/2029)

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

<b>Price</b>	\$47,800	<b>Lifespan</b>	31-May-2029
<b>Depreciation</b> ⓘ	\$4,920 /yr	<b>Reg Date</b>	01-Jun-2009 (9yrs 8mths 15days COE left)
<b>Mileage</b>	N.A.	<b>Manufactured</b> ⓘ	2009
<b>Road Tax</b> ⓘ	N.A.	<b>Transmission</b>	Manual
<b>Dereg Value</b> ⓘ	\$27,019 as of today (change)	<b>OMV</b> ⓘ	\$24,970
<b>COE</b> ⓘ	\$27,819	<b>ARF</b> ⓘ	\$1,249
<b>Engine Cap</b>	2,982 cc	<b>No. of Owners</b> ⓘ	3
<b>Curb Weight</b> ⓘ	1,760 kg		
<b>Type of Vehicle</b>	Truck		

#### Features

View specs of the Toyota Dyna 150 (2014)

#### Description

Well Kept By One Careful Owner. Loan/Trade In Available. Call Now. Don't Miss.

#### Category

COE Car

#### Status

Available

#### Resources



#### Car Valuation - Free

Find out the market value of your existing car for free. Get started



#### Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Location Map

[Shortlist](#)

[Compare](#)

[Add note](#)

[Report Error](#)

[More Actions](#)

#### Seller Information

<b>Company</b>	<b>SA Motor Trading</b> » dealer's pricelist » 4 vehs sold   7 vehs available	
<b>Address</b>	21 Toh Guan Road East #09-05 Search cars nearby this location	
<b>Location</b>	Toh Guan Centre	
<b>Office No</b>	65151328	
<b>Contact Person(s)</b>	Tang Chai	98893854 96868552

Posted on: 26-Aug-2019 | Last Updated on: 07-Sep-2019

#### Upfront Payment


<b>Transfer Fee</b> ⓘ	\$25	
<b>Down Payment</b> ⓘ	\$4,780 (change)	Maximum 90% Loan
<b>1st Instalment</b> ⓘ	\$1,058	Based on 4.5% interest rate

#### Insurance

You'll also need a valid car insurance to drive this vehicle. **18% off with code CAR18**  
Get a quote now!

[» more Financial info](#)

Powered by



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Data Of Report 09/09/2019 14:18  
 Date Of Accident 06/09/2019 19:25  
 Exact Location Of Accident JUNCTION OF CTE PIE CITY & AMK AVE 3  
 Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number GBB5100C  
**Insured/Policyholder**  
 Name Of Registered Owner CHIP GUAN ENGINEERING PTE LTD  
 Co Reg No 197400209N  
 Email Address TSSIM\_CGE@PACIFIC.NET.SG  
 Mobile Phone No  
 Alternative Phone No OFFICE-97569728  
**Vehicle Particulars**  
 Manufacturer TOYOTA  
 Model DYNA  
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USAGE  
 Are you claiming under your own insurance policy for repair to your vehicle? YES  
 If No, Please state action to be taken  
 Vehicle Category GOODS VEHICLE  
**Insurance Company**  
 Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.  
 Type Of Coverage COMPREHENSIVE  
 Fleet Policy NO  
 Policy Number D19MTPCVE001215  
 Cover Note Number  
**Driver**  
 Name of Driver SIM TIONG SWEE  
 NRIC No S1145373B  
 Date Of Birth 31/10/1955  
 Occupation OUTDOOR  
 Date Of Driving Pass 31/12/1975  
 Driving Experience 43 YEARS AND 8 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-97569728  
 Fax Number  
 Contact Number  
 Email Address NOEMAIL

Address	29 LIMBOK TERRACE
Postcode	545187
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	T/20190908/2055
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFH1717X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name

SIM TIONG SWEE

Approximate Age

Injuries Sustain

Injured person in which vehicle?

GBB5100C


Were seat belts worn?

Was this injured conveyed to hospital by  
ambulance?

Address

Postcode

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 06/09/2019, around 7:25pm, I was driving towards CTE (PIE/CITY), Come to the Junction of Ang Mo Kio Ave 3, I stop my lorry at the Junction. Vehicle SFH1717X suddenly knock on my back of my Vehicle. and caused the damage.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

COMFORTDELGRO ENGINEERING PTE LTD  
EXTERNAL BUSINESS DIV, UBI BRANCH  
NAME & SIGNATURE: \_\_\_\_\_  
DESIGNATION: \_\_\_\_\_ DATE: \_\_\_\_\_

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

Adjuster Letter/DV not verified.  
This claim is to be authorized on the insurer's behalf.  
Submissions will not be allowed until the Letter of Offer/DV is VERIFIED.  
Click on 'View Letter/DV' to verify the offer.

You cannot authorize this offer because  
Adjuster Letter/DV not verified.  
File to be authorized by your superior.

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19016148/FCF3Q  
Date: 27/09/2019

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No: DMPCSN30144518044

Claimant Vehicle No: GBB5100C

Insured Vehicle No: SFH1717X

Date of Loss: 06/09/2019

Nature of Claim: TP

Claim No: SNM19D204247C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBB5100C**  
Make & Model: TOYOTA DYNA, 3.0 D (M)  
Reg. Date: 12/05/2009 (Man. Year: 2009)  
Colour: White  
Engine Capacity: 2982 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1KD1923936  
Chassis No: JTFAT35Y90K200544  
Odometer: 251680 km

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	185 R15C	Rear Tyre Size:	155 R12C (D)
Front Left Side:	West Lake 5 mm	Rear Left Side:	Falken 4/4 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	Falken 4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment: 11/09/2019

Date Inspected: 12/09/2019 Inspected At:

M.s Panel Beating Workshop (HQ)  
2 KAKI BUKIT AVE 6, # 02 . 17 AUTOHUB @ KAKI BUKIT  
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

9/27/2019

Merimen e-Claims

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00



**REPAIR DETAILS**

Reference		
Part Source:	(Last Synchronised: 27 Sep 2019)	
Parts:	N/A	TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB5100C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts****There are no new parts selected.**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items  
**There are no new miscellaneous items selected.**

Recommended Labour  
**There are no labour items selected.**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >