

#### Accident Photo




# Accident Photo



Accident Photo



**Accident Photo** 




Accident Photo



Accident Photo



# Accident Photo



Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenu: 3 SINGAPORE 408865 Tel No: 6547(000





T/20150714/2121

1 of 3

03/07/2015

04/07/2014

Report No. T/20150714/2121

Data/Time P	ne Report Made:			Vide Penort No :				Station Diary No.:	
Pate/Time Report Made: 4/07/2015 15:27		1	Vide Report No.:				Station Diary 110		
alumanile.	THE PERSON NAMED IN	NUMBER			10 C				<b>是此一种企业</b>
lame of Info		THE PERSON NAMED IN		Address	:				
	ned Aljoffri Bin Syed Alwi		Alwi	APT BLK 138 EDGEDALE PLAINS #04-120 HDB-SENGKANG SINGAPORE 820138					
D Type / ID	No.:			Contact No.:					
VRIC NO / S				110100 0 11111			98733580		
Nationality:				Email:					
Sex: Male	Age:	Date of Bir	rth:	Type of Informant:					
Race: Arab							on / School Name:		
Occupation: Police officer				Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		•			
Type of Acc	In Ir	of the Arcide ijury ttended by P			Drink Drive: No	Date/Tin 02/07/20	ne of Accid	lent:	Type of Location
Type of Acc Location: Along Road PASIR RIS PASIR RIS infront of SF	l Travelin	ijury	olice oad 2	sir Ris Dr	No 4	1776-7803-790-7877			T-Junction ~
Type of Acc Location: Along Road PASIR RIS PASIR RIS infront of SI Weather:	l Travelin	ijury ttended by P ng Toward R	olice oad 2	sir Ris Dr Road S Dry	No	1776-7803-790-7877			T-Junction
Type of Acc Location: Along Road PASIR RIS PASIR RIS infront of SF	Travelin RIVE 4 RIVE 3 C Petrol	ijury ttended by P ng Toward R	olice oad 2	Road S Dry	No 4	1776-7803-790-7877		Road 50 Ki	Speed Limit: m/h ic Volume:
Type of Acc Location: Along Road PASIR RIS PASIR RIS infront of SI Weather: Clear	I Traveling RIVE 4 PRIVE 3	ijury ttended by P ng Toward R	olice oad 2	Road S Dry	No  4  Surface:	1776-7803-790-7877		Road 50 Kr Traff Light	T-Junction  Speed Limit: m/h ic Volume:
Type of Acc Location: Along Road PASIR RIS PASIR RIS infront of SI Weather: Clear Traffic Flow Dual Carria	Traveling RIVE 4 PRIVE 3 C Petrol Way	ijury ttended by P ng Toward R	olice oad 2 225 Pas	Dry Traffic	No  4  Surface:	1776-7803-790-7877		Road 50 Kr Traff Light	Speed Limit: m/h ic Volume:
Type of Acc Location: Along Road PASIR RIS PASIR RIS infront of SF Weather: Clear Traffic Flow Dual Carria Type of Col Between Mo	dent: Ir A  I Traveling RIVE 4  RIVE 3  C Petrol  Way  ition:  ving Veh	ijury ttended by P ng Toward R Stn near Blk nicles - Head	olice oad 2 225 Pas To Side	Road S Dry Traffic	No  4 Surface:	1776-7803-790-7877	15 20:50	Road 50 Kr Traff Light Anyo ambu Yes	Speed Limit: m/h ic Volume: in conveyed by ilance:
Type of Acc Location: Along Road PASIR RIS PASIR RIS infront of SF Weather: Clear Traffic Flow Dual Carria Type of Col Between Mo	I Travelin RIVE 4 PRIVE 3 C Petrol	ijury ttended by P ng Toward R Stn near Blk nicles - Head	olice oad 2 225 Pas	Road S Dry Traffic	No  4  Surface:	1776-7803-790-7877	15 20:50	Road 50 Kr Trafff Light Anyo ambu Yes	Speed Limit: m/h ic Volume: tone conveyed by alance:
Type of Acc Location: Along Road PASIR RIS PASIR RIS infront of SF Weather: Clear Traffic Flow Dual Carria Type of Col Between Mo	I Travelin RIVE 4 PRIVE 3 C Petrol	ijury ttended by P ng Toward R Stn near Blk nicles - Head	olice oad 2 225 Pas To Side	Road S Dry Traffic	No  4 Surface:	1776-7803-790-7877	15 20:50 T	Road 50 Kr Traffi Light Anyo ambu Yes	Speed Limit: m/h ic Volume: ione conveyed by ilance:
Type of Acc Location: Along Road PASIR RIS PASIR RIS infront of SF Weather: Clear Traffic Flow Dual Carria Type of Col Between Mo	I Traveling RIVE 4 PRIVE 3 C Petrol  Way lition: Owing Vehicle for the formula in the control of	ijury ttended by Peng Toward R Stm near Blk nicles - Head	olice oad 2 225 Pas To Side	Road S Dry Traffic	No  4 Surface:	1776-7803-790-7877	15 20:50 T D S	Road 50 Kr Trafff Light Anyo ambu Yes	Speed Limit: m/h ic Volume: in conveyed by ilance:
Type of Acc Location: Along Road PASIR RIS PASIR RIS infront of SI Weather: Clear Traffic Flow Dual Carria Type of Col Between Mo	I Travelin RIVE 4 RIVE 3 C Petrol  Way lition: oving Vehicle for the formula in the control of t	ijury ttended by P ng Toward R Stn near Blk nicles - Head	olice oad 2 225 Pas To Side	Road S Dry Traffic	No  4 Surface: Control:	02/07/20	15 20:50 T D S	Road 50 Kr Trafff Light Anyo ambu Yes	Speed Limit: m/h ic Volume: in conveyed by ilance:

AXA INSURANCE SINGAPORE PTE

FU455P

LTD

Report No. T/20150714/2121



# CONTINUATION OF REPORT

Details of Person Any Pedestrian In		PERSONAL SERVICES	TOETHE.			
No. of Redestrians	Use of Pedestrian Crossing: NA					
Rider				20,000		
Name	Syed Muhammed Aljoffri Bin Syed Alwi		ID No.		\$78054401	
Related Vehicle	FU455P (Motorcycle)		Contact No.		98733580 Class: 2B,2A,2,3 Date of Expiry: NIL	
Hospital/Clinic	Clinic CHANGI GENERAL HOSPITAL		Class Drivit Licen Expir	ıg		
Date Treatment	02/07/2015	Date Disc	-	07/07	/2015	
No. of Days grant	Degree of	Injury	Serio	15		

#### Brief Details.

On 02/07/2015 at about 8.50pm, I was travelling on the right lane of 2 lanes dual carriageway Pasir Ris Drive 4 towards Pasir Ris Drive 3. While I was travelling straight near to the entrance of SPC Petrol Station, an oncoming taxi SHD3087P came from opposite direction and turn in into SPC Petrol Station without giving way to me. I could not stop in time to avoid the collision thus crashed onto the taxi left side front portion. I was flung onto the taxi windscreen and onto the road ahead a few metres. I was then warded at CGH for head injuries and swelling on arms and legs.

Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

> NEO CHIN LOONG Contact No : 65476435

> > Signature:\_\_\_\_\_\_

Authentication Stamp





T/20150714/2121

3 of 3

Report No. T/20150714/2121

con	NTINUATION OF REPORT
Sketch Plan	
Informant is not able to provide sketch plan	
1	
1	
.	
IÌ.	
11	
11	
II.	
1	
11	
11	
IMPORTANT Please attach a copy of your vehicle	e's Insurance Certificate to this report. If you don't have the
certificate with you now, please fax a copy to 6547	74885 stating the report number as references.
	Signature Of Informati:
Signature Of Officer Recording The Report:	Signature of morning.
TP / FOO SHI YUH JACKSON	
Signature Of Interpreter:	Date/Time:
Not applicable	14/07/2015 16:27
\$10.00 P. T.	
Officer In Charge Of Case:	. Classification Of Case:
TP/GIT/	

attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.	

# PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189 Tel: 6315 1239, Fax: 6315 3298, Mobile: 9061 0543

### ACCIDENT VEHICLE INSPECTION REPORT

Report no

: 408M0715.DW

Vehicle no

: FU455P

#### 1 REFERENCE

Date of inspection

: 29 July 2015

Requested by

: Syed Faisal Aljoffri Bin Syed Alwi

c/o Blk 138 Edgedale Plains

#04-120

Singapore 820138

Type of survey

: Independent

Repairer

: Dirt Wheel Motor Trading

Blk 9004 Tampines St 93, #01-100, Singapore 528838

Date of accident

: 2 July 2015

#### 2 VEHICLE DATA

Make/model

: K.T.M 390 Duke

Chassis no

: VBKJGJ408DC215161

Engine no

: 0390203829

Date of registration

: 3 July 2014

Engine capacity

: 373 cc

Colour

: Black

Odometer reading

: NA

#### 3 STATIC CONDITION CHECK

Steering

: Serviceable

Foot brakes

: Serviceable

Hand brakes

: Serviceable

Paintwork

: Good

General

: Good

# 4 TIRE CONDITION CHECK mm/MAKE

SIZE

Front tread

: 3 mm/Metzeler

110/70ZR17

Rear tread

: 5 mm/MRF

150/70ZR17

# 5 BRIEF DESCRIPTION OF DAMAGE

Please see photographs attached for details.

#### 6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs. The inspection accounts only for those parts that are visibly damaged but does not include parts that are hidden from view and needed dismantling to ascertain their condition.

Report no

: 408M0715.DW

Vehicle no

: FU455P

#### 7 RECOMMENDATION

Apart from damages to the body panels, lightings and mechanical components, the main chassis frame of the vehicle was seriously damaged in the course of the collision.

The chassis frame was bent, twisted and distorted. This chassis damage cannot be structurally repaired to a roadworthy condition as it is unsafe to cold work the frame back to it original strength and integrity.

Replacing the damaged chassis cannot be done as it is prohibited by LTA.

Therefore, it is necessary to treat the vehicle as a as a "Total Loss" instead of repair.

In establishing the pre-accident market value of the vehicle, calls were made to a few second hand motorcycle retailers but no quotes were obtained as these retailers were not trading in KTM motorcycles.

A check with SGBikeMart revealed that a similar make/model of vehcile registered on 17 June 2014 was selling for \$15,888.00.

However, the sole distibutor M/s Dirt Wheel Motor Trading had quoted a pre-accident market value of about \$13,500.00 which we believed is a fair and reasonable value.

Hence, it is recommended that the vehicle be treated as a "Total Loss" at the pre-accident market value of \$13,500.00

Yours faithfully

Liaw Leong San

Licensed Automotive Appraiser