

ASSIGNMENT

From:

Date:

Estimated Cost:

Veh No:

SMB 3529H

Yr Regn:

1/9/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

Truck / Trailer or

at Workshop m/s

Make:

Alexon dir Dennis Larriv 500

c.c

8849

Colour:

Silver Metal

A/C:

Insured / Std / NI / NA

Sp. Reading

347865

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SFO 76L RSEMTL 3458

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

305/70R22.5

R:

11 101

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Firm 29

Front

Rear

R/Bal.

5

mm

R/Bal.

5/5

mm

L/Bal.

5

mm

L/Bal.

5/5

mm

D.O.A.

3/9/19

D.O.I.

9/9/19

Survey held at

SMRT

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SMB 3529H - NSI INC 19011279/5, b2

SMB 27034 - NSI INC 19015631 24

Finalize confm \$1850, 3 days (9/10/19)

ROA - 11/12/2017

ROA - 03/09/2019

(Red 929.40, 3390)

RECEIVED 13 SEP 2019

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 13/9 - typist

Report Format:

TP

Lump Sum / L.B. 1: L/S 1850/-

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Wheel end (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Veron Chen (LKKAUTO)

From: MTCL@income.com.sg
Sent: Friday, 13 September 2019 11:28 AM
To: Veron Chen (LKKAUTO)
Subject: FW: REQUEST FOR CLAIM NUMBER

Hi,

Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
MT/1060972-002	SMRT BUSES LTD	SMB 3529H	SMC 2703Y

D.O.A	Time of Accident	Estimate	Tentative repair cost
3/9/2019	16:15	\$2,779.40	\$1,850.00

Claim number provided for your reference, thanks.

Ignatius Koh
Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Friday, 13 September 2019 9:04 AM
To: MTCL@income.com.sg
Subject: REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Kindly provides us claim number

Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
	SMRT BUSES LTD	SMB 3529H	SMC 2703Y

D.O.A	Time of Accident	Estimate	Tentative repair cost
3/9/2019	16:15	\$2,779.40	\$1,850.00

Best Regards,

• **Veron Chen** | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

Change Language

Change Password

Log Out

My Desktop

Notice of Loss

Policy Query

Policy No.

Vehicle No.(For Motor)

Date of Accident

Certificate Number

Search

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5106937496		RELIABLE RIDES PTE LTD	201611527N	GFT	drive CLASSIC	SMC2703Y	SMC2703Y	28/06/2019	

Continue

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/09/2019 13:41
Date Of Accident	03/09/2019 16:15
Exact Location Of Accident	BENCOOLEN STREET BEFORE BS: 04019 (OPP BENCOOLEN S
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB3529H
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	ALEXANDER DENNIS
Model	ENVIRO 500

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-19093203MFBP
Cover Note Number	

Driver

Name of Driver	CHOO LIANG SAN
NRIC No	S1362426G
Date Of Birth	07/06/1959
Occupation	OUTDOOR
Date Of Driving Pass	07/01/1983
Driving Experience	36 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	NO ADDRESS
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WHILE TRAVELLING STRAIGHT ON THE LEFT LANE ALONG BENCOOLEN STREET, A PTE CAR (SMC2703Y) THAT WAS ON THE RIGHT LANE TRIED TO OVERTAKE AND CUT INTO MY PATH TO ENTER LORONG PAYAH THEN SIDE- SWIPED THE RIGHT FRONT PORTION OF MY BUS. MY BUS SUSTAINED SCRATCHES ON THE RIGHT FRONT PORTION. THE PTE CAR SUSTAINED DENTS ON THE LEFT REAR PORTION. THERE WERE ABOUT 4 PASSENGERS IN MY BUS AND NO INJURIES WERE REPORTED.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING DOWNLOAD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMC2703Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ANG
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	

No. Of Passenger (Including Driver)

ENCLOSURE
SKETCH PLAN

CM 635294

IMPORTANT NOTICE

1. Please report **promptly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **rescind policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers to the General Insurance Association of Singapore (GIAS) for archiving and the copies of this report will be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if needed.
8. **Consent under the Personal Data Protection Act (PDPA)**

I, undersigned, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore (GIAS) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or generated by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all parties who have insured vehicles involved in this accident (all "insureds") who have insured vehicles involved in this accident shall be collectively referred to as the "Insurers". The Insurers, my insurer, my workshop, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claim and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claim (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/final package); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "purpose(s)").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my personal information, or one or more of the above purpose(s), and
- (c) my personal information may/can be disclosed by any of the Insurers and/or GIAS to their third party service providers or agents/including their lawyer/law firms, which may be used outside of Singapore, for one or more of the above purpose(s).
- (d) my personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulation, law enforcement and Government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



[Signature]




Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: AALQISH
NIDCRN No.: SB3403252

SKETCH PLAN

(A) 5MB35294
(B) 5MC2703Y



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO REPORT

PAPER TO REPORT

DECLARATION

We declare the foregoing particulars are true in every respect.

Polycythaemia Signa-
Data & Time

Driver's Signature
If driver is not the policyholder,
Date & Title

Reporting Center Personnel's Signature
Name: BALQISH
NID/CFR No.: 563403252

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 292D

Vehicle Details

Vehicle No.: SMB3529H

Vehicle to be Exported: No

Intended Deregistration Date: 12 Sep 2019

Vehicle Make: ALEXANDER DENNIS

Vehicle Model: ENVIRO500

Primary Colour: Silver

Secondary Colour: Black

Manufacturing Year: 2014

Engine No.: 22120165

Chassis No.: SFD76CLR5EMTL3458

Maximum Power Output: -

Open Market Value: \$470,004.00

Original Registration Date: 01 Sep 2014

First Registration Date: 01 Sep 2014

Transfer Count: 0

Actual ARF Paid: \$0.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Rebate Amount: \$0.00

Total Rebate Amount: \$0.00

The information contained herein is correct as at 12 Sep 2019

OK



SMRT Accident Vehicle Repair Estimates

NTUC

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 09/09/2019

User ID : BoonChewTay

Section A - Accident Details



Registration Number	SMB3529H
Case Reference Number	BUS/09/19/1020
Registration Date	1/9/2014
Company Type	SMRT Buses Ltd
Make	AL EXANDER DENNIS
Model	ENVIRO 500
Name of Driver	Choo Liang San
Type of Accident	Side Swipe
Accident Date and Time	3/9/2019 4:15 PM
Accident Reported Date and Time	3/9/2019 6:45 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB3529H - RIGHT FRONT PORTION SMC2703Y (TP) - INSURED WITH NTUC
Prepared Date and Time	9/9/2019 11:47 AM
Chassis Number	SFD76CLR5EMTL3458
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$538.00	\$0.00
Total Spare Part Cost	\$850.61	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,448.61	\$0.00
Lump Sum Total	\$2,450.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	09/09/2019 11:52 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



Steve (LKH)


WL P70L

9/9/19, 2-774

L/S

Ry AL SP

3 djs


12/9/19



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 11/09/2019

User ID : CatherineLee

Section A - Accident Details


Registration Number	SMB3529H
Case Reference Number	BUS/09/19/1020
Registration Date	1/9/2014
Company Type	SMRT Buses Ltd
Make	ALEXANDER DENNIS
Model	ENVIRO 500
Name of Driver	Choo Liang San
Type of Accident	Side Swipe
Accident Date and Time	3/9/2019 4:15 PM
Accident Reported Date and Time	3/9/2019 6:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24103278
Special Instruction to ARC, if any	SMB3529H - RIGHT FRONT PORTION SMC2703Y (TP) - INSURED WITH NTUC
Prepared Date and Time	9/9/2019 11:47 AM
Chassis Number	SFD78CLR5EMTL3458
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$795.00
Total Spray Cost	\$538.00	\$446.00
Total Spare Part Cost	\$850.61	\$850.61
Total Other Cost	\$0.00	(\$248.20)
TOTAL COST	\$2,448.61	\$1,843.41
Lump Sum Total	\$2,450.00	\$1,850.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Boon Chew Tay	STEVE CHEN
ARC / Surveyor Sign Off Date	09/09/2019 11:52 AM	09/09/2019 2:25 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685692
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 11/09/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,060.00	\$795.00
Total Labour	\$1,060.00	\$795.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$538.00	\$446.00
Total Spray Painting & Panel Beating	\$538.00	\$446.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$248.20)
Total Other Costs	\$0.00	(\$248.20)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011052	BODY RH	20590172/2	BUMPER,CORNER R/H, FOR ADL E500 DD BUS	1.00	\$1,181.40	10.00	\$1,063.26	Replace	Replace
Total					\$1,181.40		\$1,063.26		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Veron Chen (LKKAuto)

From: Steve Chen (LKK Auto)
Sent: Thursday, 12 September 2019 5:00 PM
To: Catherine Lee Sau Chan (Auto Svcs/ARC/ARC/Buses)
Cc: Koo Yew Chung (Auto Svcs/ARC/ARC); AutoSvs-ARC (Bus); SUR
Subject: Finalisation - SMB3529H (BUS/09/19/1020) - NTUC

Dear Catherine,

We confirm the finalize \$1850 (L/S, before GST). 3 repair days.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Lee Sau Chan (Auto Svcs/ARC/ARC/Buses) [mailto:catherineleesc@smrt.com.sg]
Sent: Wednesday, September 11, 2019 5:28 PM
To: Steve Chen (LKK Auto); SUR; Admin A
Cc: Koo Yew Chung (Auto Svcs/ARC/ARC); AutoSvs-ARC (Bus)
Subject: Finalisation - SMB3529H (BUS/09/19/1020) - NTUC

Hi Steve,

Attached herewith our copy and your marked copy of the bus repair estimate for the case.
Our finalised amount is \$1,850/- @ 3 working days under lump sum repair. Attached after repair photos for your perusal.

Please confirm the COR by return email ASAP.

Thank you

Best Regards
Catherine Lee
SMRT Automotive Services Pte Ltd
(Accident Repair Centre)
DID: 6866 2669 Fax: 6368 5592
catherineleesc@smrt.com.sg



Moving People, Enhancing Lives



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19016156/Evf3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 17-09-2019



189556

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMC 2703Y	Veh. Inspected	SMB 3529H
Policy No.	5106937496	Coverage (\$)	0.00
Claim No.	MT/1060972-002	Excess (\$)	0.00
Assign From		Assign Date	09/09/2019

2. Vehicle Particulars & Condition

Make & Model	ALEXANDER DENNIS ENVIRO500	c.c	8849
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	SFD76CLR5EMTL3458	Colour	MULTI COLOUR
Odometer	347865	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	305/70 R22.5	FIRENZA	5 mm
L/H Front Tyre	305/70 R22.5	FIRENZA	5 mm
R/H Rear Tyre	305/70 R22.5 (D)	FIRENZA	5/5 mm
L/H Rear Tyre	305/70 R22.5 (D)	FIRENZA	5/5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/09/2019	Inspection Date	09/09/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 3529H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BUMPER, CORNER: R/H FOR ADL E500 DD BUS LESS 10% DISCOUNT	BROKEN	1,181.40	1,181.40
			-	-118.14
			1,181.40	1,063.26
<u>LABOUR</u>				
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		1,060.00	793.00
	PROVIDE LABOUR AND MATERIAL. TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		538.00	446.00
			1,598.00	1,239.00
GRAND TOTAL			2,779.40	2,302.26
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,850.00

Report Ref No. NS/INC19016156/Evf3s2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.