

22/03/2012

ASS. REC. RV.

REF:

CS/GAI19016167/Dsd362

Instruction

ok

Manager: BryonASSIGNMENT (Office)From (Person): Sherry Wong

of

GAIDate/Time: 13/9/19 @ 8.57am

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: _____

FU 9075T

Insured: _____

at Workshop m/s _____

SG 98 Motor

Tel: _____

6452 4898.

of _____

81K 4001 #01-21 AMK Ind. park 1

Policy No: _____

Claim No: _____

CLMOMVC 000003702

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 19.7.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 10:17am @ 13/9/19

Person Contacted: _____

RoseVehicle (IN) OUT

Date/Time

Action/Instruction

Follow up02/12/19@ 14:48 pm revised PA to Kelvyns v/a email

ASSIGNMENT

COE May 2022

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FU 90751

Vr Regn: 2002 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda CB 400 C.C. 399

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: N.A T/Radio: Insured / Std / NI / NA

Eng/No: NC23E2031176

C/No: NC391031164

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/60 R17

R: 160/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Metzeler

Front

Rear

R/Bal. 2 mm R/Bal. 2 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 19/07/2019 D.O.I. 16/09/2019

Survey held at SG 98 AMK

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Front y O/S Body y O/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Correct American

MV 7500.00

VIA 487.00

NL 7K

RECEIVED 31 JAN 2020

31/01/2020 Invoice L/S 2700/- with 4 days of rev
(\$ 2,453.00 Red - 51%)

Date/Time, File Pass to/

31/01/20

1) Typist

Date/Time, File Return to/

2)

Date/Time, File Return to/

3)

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee: 290

Transportation: _____

S + RS. _____

Finlos _____

Other _____

290

\$ 2,700/- 45

Nivitha (LKK Auto)

From: Wong, Shery <Shery.Wong@sg.gaig.com> on behalf of Motor Claims <MotorClaims@sg.gaig.com>
Sent: Friday, 13 September 2019 8:57 AM
To: sg_motor_enterprise@yahoo.com.sg; assignments@lkkauto.com; Admin-D (LKKAuto)
Cc: Ngian, Kelvyna
Subject: FW: Our Ref:CLMOMVC000003702, Plse arrange PRI on bike FU 9075T as per attached.

Without Prejudice

Dear Rose,

Noted on your request.

Dear LKK,

Please accept assignment for TP survey. Thank you.

Regards

Shery Wong, Executive, Claims | P. +65 68046077 | F. +65 62353354 | shery.wong@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 17, 2018

Moody's
A1 (Good)
Published December 2018

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Sg motor enterprise Giam <sg_motor_enterprise@yahoo.com.sg>
Sent: 12 September 2019 5:21 PM
To: sgmotor2000@yahoo.com.sg; Motor Claims <MotorClaims@sg.gaig.com>
Cc: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: [External] Re: Our Ref:CLMOMVC000003702, Plse arrange PRI on bike FU 9075T as per attached.

Hi all,

pls arrange L:KK to survey the bike no : FU9075T

Best Rgds
rose

On Thursday, 12 September 2019, 03:47:15 pm GMT+8, Motor Claims <MotorClaims@sg.gaig.com> wrote:

Without Prejudice

Dear Leena,

We append the following list of our panel surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. A-PAC Adjusters & Surveyors Pte. Ltd.
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants

Kindly let us know which SJE is selected and furnish the estimates for the survey to be carried out.

Moving forward please email us at MotorClaims@sg.gaig.com for motor related matters

Regards

Shery Wong, Executive, Claims | P. +65 68046077 | F. +65 62353354 | shery.wong@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 17, 2018

Moody's
A1 (Good)
Published December 2018

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Sg Motor <sgmotor2000@yahoo.com.sg>
Sent: 12 September 2019 3:34 PM
To: General Claims <GeneralClaims@sg.gaig.com>
Cc: Sg Motor <sg_motor_enterprise@yahoo.com.sg>
Subject: [External] Plse arrange PRI on bike FU 9075T as per attached.

Attn: Motor Claims Dept

Plse arrange PRI on bike FU 9075T as per attached.

Thank You

Regards

Leena

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 2 December 2019 2:48 pm
To: 'Ngian, Kelvyna'
Cc: SUR; assignments
Subject: RE: Our Ref:CLMOMVC000003702, Plse arrange PRI on bike FU 9075T as per attached.
Attachments: PRELI ADVISE - FU 9075T.pdf

Dear Kelvyna,

Enclosed preliminary revised of vehicle FU 9075T.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 29 November 2019 12:01 pm
To: 'Ngian, Kelvyna' <kelvyna.ngian@sg.gaig.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Our Ref:CLMOMVC000003702, Plse arrange PRI on bike FU 9075T as per attached.

Dear Kelvyna,

Noted with thanks.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ngian, Kelvyna [<mailto:kelvyna.ngian@sg.gaig.com>]
Sent: Friday, 29 November 2019 12:00 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CLMOMVC000003702

Date: 02 December 2019

Our Ref: CS/GAI19016167/Dsd3

The Motor Claims Department
GREAT AMERICAN INSURANCE COMPANY

Dear Sir/Madam,


PRELIMINARY ADVISE REPORT OF VEHICLE NO. FU 9075T .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/09/2019 at the premises of M/s SG 98 Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,453.00</u> .
Revised Estimate Amount	: S\$ <u>3,182.00</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the o/s front, o/s body & o/s rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 4 days

Yours faithfully

Bryan Ang
Automotive Assessor

**POLICE FORCE**

 1/20190721/2139

Police Station Of Origin
 Bukit Batok N.P.C.
 21 Bukit Batok East Avenue 4 SINGAPORE
 659840
 Tel No 1800-6659999

1 of 4
 Report No: 1/20190721/2139

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/07/2019 21:10	Vide Report No.:	Station Diary No. 196
--	------------------	--------------------------

Informant's Particulars

Name of Informant: YUSMAN SHAH BIN MD SALLEH			Address: APT BLK 296A BUKIT BATOK STREET 22 #04-54 SINGAPORE 651296		
ID Type / ID No. NRIC NO / S7836949C			Contact No. Home/Office: Mobile: 97900661		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 40	Date of Birth: 14/12/1978	Type of Informant: Rider		
Race: Malay			Language:		Institution / School Name
Occupation: Supply and distribution/Logistics/Warehousing manager			Driving Licence Information: Class: 2B,2A Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 19/07/2019 19:25	Type of Location: Bend
Location: Along Road 1 TUAS ROAD TUAS WEST ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Avoidance skid.				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passengers
U9075T F9075T	Motorcycle	HONDA	CB400SF2J	Maroon		1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Exp
U9075T	FWD Singapore Pte. Ltd	PNMC2019- 00002373	10/05/2019	09/



Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
Rider			
Name	YUSMAN SHAH BIN MD SALLEH	ID No.	S7836949C
Related Vehicle	FU9075T (Motorcycle)	Contact No.	97900661
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A Date of Expiry: NIL
Date Treatment	19/07/2019	Date Discharge	23/07/2019
No. of Days granted Medical Leave	33	Degree of Injury	Slight
Pillion			
Name	Hairul Azhar Bin Mulia	ID No.	S8818645A
Related Vehicle	FU9075T (Motorcycle)	Contact No.	87842971
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.

On 19/07/2019 at about 1925hrs, I was riding my motorcycle, A maroon color Honda CB400 along Tuas Road towards Tuas West Road. The traffic volume was moderate. I was on a two lane road, on the second lane. On the first lane beside me, was a large trailer truck of unknown registration number. At point of the road, a large trailer truck had suddenly in a fast manner, started to enter my lane. I honked several times to warn him. However, there was no reaction. I did emergency brake to avoid being squashed. As a result, my motorcycle skidded and I fell, together with my pillion, Mr Hairul.

Immediately after the accident, I noticed that my motorcycle had skidded far in front of me. Someone assisted to pull me over to the grass patch nearby for safety. I asked my friend if the Ambulance has called and he said yes. When the Ambulance arrived, I was brought into the vehicle. We waited for Police to arrive as the trailer driver only wanted to give particulars to the Police. I was then conveyed to Ng Teng Fong Hospital. My Pillion, Mr Hairul followed me in the Ambulance and sought his own medical attention afterwards.

I sustained a deep cut on my left foot which needed about 24 stitches. There's a suspected crack on my right shoulder's bone. There were multiple abrasions on my left and right arms and palms. I was subsequently given 33 days of MC from 19/07/2019 to 20/07/2019.

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /

Sgt 3 MUHAMMAD AMIRUL HASIF BIN
MOHAMED YUNOS

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt MOHAMED SUFIAN BIN MOHAMED
JUNID

Contact No: 65476247

SN 114

Authentication Stamp

NP 158

Signature Of Informant:

Sheh

Date/Time:

27/07/2019 21:10

Classification Of Case:

Police Force

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 18 September 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel: 97237799


VEHICLE NO : FU 9075T

Honda S4 Spec 2

ACCIDENT DATE: 19 July 2019

Description	Qty	Quotation \$
1 Handle Bar <i>new</i>	1	265.00 X
2 Brake Lever <i>cut</i>	1	125.00 ✓
3 Mirror RH <i>new</i>	1	95.00 X
4 Visor <i>cut</i>	1	215.00 ✓
5 Fog Light <i>cut</i>	1 set	500.00 ✓ 200/-
6 Front Mudguard <i>new</i>	1	280.00 X
7 Fuel Tank <i>new</i>	1	450.00 X
8 Crash Bar <i>cut</i>	1	460.00 ✓
9 RH Front Fork <i>distorted</i>	1	480.00 ✓
10 Throttle Cable <i>cut</i>	1	180.00 ✓
11 Exhaust <i>cut</i>	1	680.00 ✓
12 Balancer <i>Dem o/s new</i>	1 set	240.00 ✓ 120.00
Sub-Total		3,970.00
Less 10%		397.00
Sub-Total		3,573.00

Supplementary front rim - \$ 420.00 ✓
front brake disc - \$ 280.00 distorted ✓



3160.00
 10% 2844.00

VEHICLE NO : FU 9075T

Honda S4 Spec 2

Nett Items

1	Rear box Cwt	280.00	180/-
2	Towing Fee	40.00	NH
3	Remove & re-fit necessary parts, align & etc	280.00	180/-
4	Remove & replace front fork & top up oil	180.00	80/-
5	Putty & respray paint touch up	350.00	120/-
6	Repress front rim	120.00	30/-

590.00

Sub-Total 1,250.00
Nett Total 4,823.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

5453

3434.00

Kindly revert upon completion. Thank you

2/5 2700/-

SG 98 MOTOR PTE LTD

16/09/2019 @ 1800m

N/A Actual

2/Sum 4 days

2/Sum
you

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY			Ref : CS/GAI19016167/Dsd3e2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Date : 03-02-2020	
			Code : GAI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.		Veh. Inspected		FU 9075T
Policy No.		Coverage (\$)		0.00
Claim No.	CLMOMVC000003702	Excess (\$)		0.00
Assign From	SHERY WONG	Assign Date		13/09/2019
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB400	c.c	399	
Engine No.	HIDDEN	Year of Reg.	2002	
Chassis No.	NC391031164	Colour	RED	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/60 R17	METZELER	2 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60 R17	METZELER	2 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT, O/S BODY AND O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/07/2019	Inspection Date	16/09/2019	
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FU 9075T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HANDLE BAR	NOT NECESSARY	265.00	-
1	BRAKE LEVER	CUT	125.00	125.00
1	MIRROR RH	NOT NECESSARY	95.00	-
1	VISOR	CUT	215.00	215.00
1	SET FOG LIGHT	CUT	500.00	200.00
1	FRONT MUDGUARD	TO REPAIR SEE LABOUR	280.00	-
1	FUEL TANK	TO REPAIR SEE LABOUR	450.00	-
1	CRASH BAR	CUT	460.00	460.00
1	RH FRONT FORK	DISTORTED	480.00	480.00
1	THROTTLE CABLE	CUT	180.00	180.00
1	EXHAUST	CUT	680.00	680.00
1	SET BALANCER	O/S DAMAGED / N/S NOT NECESSARY	240.00	120.00
1	FRONT RIM	BENT	420.00	420.00
1	FRONT BRAKE DISC	DISTORTED / BENT	280.00	280.00
	LESS 10% DISCOUNT		-467.00	-316.00
			4,203.00	2,844.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR BOX (SN)	CUT	280.00	180.00
			280.00	180.00
<u>LABOUR</u>				
	TOWING FEE.	NOT NECESSARY	40.00	-
	REMOVE & RE-FIT NECESSARY PARTS,ALIGN & ETC.INCLUSIVE OF THE REPAIR OF FRONT MUDGUARD AND FUEL TANK.		280.00	180.00
	REMOVE & REPLACE FRONT FORK & TOP UP OIL.		180.00	80.00
	PUTTY & RESPRAY PAINT TOUCH UP.		350.00	120.00
	REPRESS FRONT RIM.		120.00	30.00
			970.00	410.00

Report Ref No. CS/GAI19016167/Dsd3e2



GRAND TOTAL		5,453.00	3,434.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,700.00

Report Ref No. CS/GAI19016167/Dsd3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.