



Case Details

Case Reference Number : BUS/08/19/5062
 Type of Repair : Accident Repair
 Vehicle Registration Number : SMB256P

Company Type : SMRT Buses Ltd
 Estimation ID : EST-8451-ID
 Assigned By : Claiming Case Owner Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 30/08/2019 09:00 AM
 Vehicle Age(In Months) : 88

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation												Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main	VE	6010303	LAMP,INDICATOR,SIDE:LED (MAN BUS)	1	186.10	186.10	20.00	148.88	Replace		1	148.8	Replace	
Total Spare Part Cost									148.88			Surveyor Total		148.88	
Lump Sum Discount (%)									20.00			Lump Sum Dis (%)		20.00	
Final Spare Part Cost									119.10			Final Sur Total		119.10	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,060.00	530.00	
Total:			1,060.00	530.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	432.00	262.00	(TBA)
Total:			432.00	262.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Summary

Estimator Assesment(\$)	Surveyor Assesment(\$)
-------------------------	------------------------

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	119.10	119.10
Total Labour Cost	1,060.00	530.00
Total Spray Painting	432.00	262.00
Other	0.00	0.00
Overall Total	1,611.10	911.10
Lump Sum Repair Option	☐	☒
Lump Sum Total	0.00	900.00
Surveyor Approved Amount		900.00
No of Repair Days*	3	119.10
Remarks	-	L/S repair, take after spray
Surveyor Name		STEVE CHEN
Signature		
Survey Date	11/09/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve CLKK) WKL App'd - 11/9/19, 11.39am
2 days
L/S
Ry AL SM