

22/03/2002

ASS. REC. BY:

REF: CS3/SPF19016178/ETP321

Special Instruction: *ole*SURVIVOR: *Steve*ASSIGNMENT (Office)

From (Person):

*Frankie Than*

of

*SPF*

Date/Time:

*12.9.19 1.57p.m*

Estimated Cost:

Bill to:

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No:

*FQ 1761U*

Insured:

at Workshop m/s

*ONG motor*

Tel:

*838 02233 68420051*

of

*414 MacPurson Road*

Policy No:

Claim No:

*AZ MD / 105 / 009 / 2019 / 092*

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

*1/8/2019*

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

*12.9.19**2.50p.m*

Person Contacted:

*Jacky*Vehicle IN / OUT

Date/Time

Action/Instruction ( *X* ) Estimate*FQ 1761U - KA / INC 19014326 / R3 DOA - 01/12/2019***Do Not Finalise**

ASS. REC. BY: Steve

REF

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lump Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: FG 17614Yr Regn: May, 1998

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Primo Mover /

Truck / Trallor or

Make: Yamaha RX2C.C. 133Colour Blue

N/C: Insured / Std / NI / NA

Sp. Reading 40339

T/Radio: Insured / Std / NI / NA

Eng/No: -

C/No: ZMC 235642

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 80 / 90 - 18R: 80 / 90 - 18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Master.

Front


Rear

R/Dnl. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mm

D.O.A.

D.O.I. 12/09/2019 0400pmSurvey held at Ang MotorDos. of Damages: Frnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.



Date / Time

Action / Instruction

NO GIA

NO Estimate

Prepare DAR with parts price

Submit DAR Report, Lump sum \$4091.60

Repair day - 5  
Weekend - 1

Range - 4000 - 5000

RECEIVED 03 OCT 2019

Date/Time, File Pass to?



Prel. Report



Final Report

1) 2/10 Typet

Date/Time, File Return to?

Days Of Repair: 5

Resurvey No. of Trip:

Add Foo:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$1

) Photos

) Others

TOTAL

220
220

Report Format :

TP - DAR

Lump Sum / I.B.I. (\$)

## Nivitha (LKK Auto)

---

**From:** Frankie THAY (SPF) <Frankie\_THAY@spf.gov.sg>  
**Sent:** Thursday, 12 September 2019 1:57 PM  
**To:** assignments; Veron Chen (LKKAuto)  
**Cc:** Hafizul Farhan RAHMAT (SPF)  
**Subject:** RE : Pre-Repair Inspection for vehicle FQ1761U

Your reference: FQ1761U

Our reference: AEMD/105/009/2019/092

Veron,

Please conduct a Pre-Repair Inspection for vehicle FQ1761U at the address listed below:

**464 MACPHERSON ROAD.**

**SINGAPORE 368182**

**CONTACT PERSON : MR JACKY SIAH AT 83802233**

KINDLY CONTACT MR JACKY SIAH TO ARRANGE FOR PRI.

Thanks.

Frankie Thay (Mr)  
Safe Driving Manager  
Automotive Engineering & Management Division  
Police Logistics Department  
Singapore Police Force  
DID: (65) 6478 4841 | FAX: (65) 6478 4848



**HOME TEAM**  
TRANSFORMATION 2025  
One Home, One Team  
Building Our Future Together

**WARNING** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

## Enquire Vehicle Transfer Fee

### Vehicle Details

Vehicle No.  
**FQ1761U**

Make / Model  
**YAMAHA / RXZ**

Vehicle Type :  
**P00 - Passenger Motorcycle/Autocycle/Moped**

Vehicle Attachment 1 :  
**No Attachment**

Vehicle Scheme :  
**Normal**

Chassis No. :  
**ZMC235692**

Propellant :  
**Petrol**

Engine No. :  
**3BS235692**

Motor No. :  
**-**

Engine Capacity :  
**133 cc**

Power Rating :  
**-**

Maximum Power Output :  
**-**

Maximum Laden Weight :  
**-**

Unladen Weight :  
**-**

Year Of Manufacture :

**1998**

Original Registration Date :

**19 May 1998**

Lifespan Expiry Date :

**30 Jun 2028**

COE Category :

**D - Motorcycle**

PQP Paid :

**\$7,906.00**

COE Expiry Date :

**30 Apr 2028**

Road Tax Expiry Date :

**31 Oct 2019**

PARF Eligibility Expiry Date :

-

Inspection Due Date :

**31 Oct 2019**

Intended Transfer Date :

**03 Oct 2019**

CO2 Emission :

-

CEV/VES Rebate Utilised Amount :

-

CO Emission :

-

HC Emission :

-

NOx Emission :

-

PM Emission :

-

## Fees To Be Paid For Transfer

Transfer Fees	\$25.00
Road Tax Renewal - 6 months (01 Nov 2019 to 30 Apr 2020)	\$48.00
Road Tax Renewal - 12 months (01 Nov 2019 to 31 Oct 2020)	\$96.00

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	469B
<b>Vehicle Details</b>	
Vehicle No.:	FQ1761U
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Oct 2019
Vehicle Make:	YAMAHA
Vehicle Model:	RXZ
Primary Colour:	Blue
Manufacturing Year:	1998
Engine No.:	3BS235692
Chassis No.:	ZMC235692
Maximum Power Output:	-
Open Market Value:	\$3,331.00
Original Registration Date:	19 May 1998
First Registration Date:	19 May 1998
Transfer Count:	9
Actual ARF Paid:	\$500.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	30 Apr 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$7,906.00
COE Rebate Amount:	\$6,779.00
<b>Total Rebate Amount:</b>	<b>\$6,779.00</b>
<b>Message</b>	
Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.	
This motorcycle is currently eligible for an incentive of \$2,000 from NEA if it is deregistered on or before 5 April 2023. The last registered owner of this motorcycle will receive the incentive from NEA.	
This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.	
For more information, please visit <a href="http://www.nea.gov.sg/mtcincentive">http://www.nea.gov.sg/mtcincentive</a> or contact NEA at 1800-2255-632.	

The information contained herein is correct as at 03 Oct 2019

OK

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	16/08/2019 17:21
Date Of Accident	01/08/2019 00:20
Exact Location Of Accident	WOODLANDS CENTRE RD CARPARK ENTRANCE OF BLK 162
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FQ1761U
Insured/Policyholder	
Name Of Registered Owner	KHAIRUL HAFEEZ BIN NOOR HISHAM
NRIC No	S9435469B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90298462
Alternative Phone No	OTHERS-90298462
<b>Vehicle Particulars</b>	
Manufacturer	YAMAHA
Model	RXZ
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5084419068-02
Cover Note Number	

#### Driver

Name of Driver	KHAIRUL HAFEEZ BIN NOOR HISHAM
NRIC No	S9435469B
Date Of Birth	01/10/1994
Occupation	OUTDOOR
Date Of Driving Pass	17/06/2016
Driving Experience	3 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90298462
Fax Number	
Contact Number	OTHERS-90298462
Email Address	NOEMAIL

Address	BLK 856 WOODLANDS ST 83 #02-12
Postcode	730856
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE POLICE REPORT: T/20190807/2026

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX1216K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	KHAIRUL HAFEEZ BIN NOOR HISHAM
------	--------------------------------



Approximate Age	
Injuries Sustain	SERIOUS
Injured person in which vehicle?	FQ1761U
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

## Accident Sketch Plan

### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

 16/08/19  
Report Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

COPEX  
Entrance of 346 162


As per Police report no: T/20190807/2021


A- FQ 1761 U


B- QX 1216 K

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

 16/08/19  
Reporting Centre Personnel's Signature  
Name:  
NAIC/FIN No

## Individual Statement



**SINGAPORE  
POLICE FORCE**



T/20190807/2026

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20190807/2026

## CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Rider</b>			
Name	KHAIRUL HAFEEZ BIN NOOR HISHAM	ID No.	S9435469B
Related Vehicle	FQ1761U (Motorcycle)	Contact No.	90298462
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

ON THE ABOVE MENTIONED DATE, TIME AND LOCATION,

I WAS TRAVELLING ON WOODLANDS CENTRE ROAD TOWARDS WOODLANDS AVE 1. I WAS TRAVELLING ABOUT 50KM/HR. I WAS ON THE LEFT LANE OUT OF 2 LANES. I WAS APPROACHING AN UNCONTROLLED JUNCTION WHERE I SAW A POLICE CAR ON THE OPPOSITE TRAFFIC MAKING A RIGHT TURN. UPON SEEING THE POLICE CAR MAKING THE RIGHT TURN, I JAMMED BRAKED MY MOTORCYCLE BUT I COULD NOT STOP IN TIME AND I COLLIDED INTO THE FRONT LEFT DOOR OF THE POLICE CAR. AFTER THAT THE POLICE OFFICER CALLED FOR TP, AND AMBULANCE. THEN I WAS CONVEYED TO KTPH AND WAS ISSUED 14DAYS MC.

VIDE REPORT NO. L/20190801/0004

*Spoke to 2 SA SUBSTANT on Aug 2015 at 1247PM  
regarding the Medical record.*

## Motorcycle

Vehicle No: EQ 1761U

NAC	INC	Item	CON	AC	Qty
3001	991886	Front Number Plate	MIS	✓	10
3001	995065	Front Tyre	CRU	✓	50
3002	995095	Front Rim	BT	✓	300
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard			
3005	991283	Front Brake Disc	BT	✓	120
3006	991281	Front Brake Caliper	CRU	✓	80
3007	991785	Front Fork Assy	BT	✓	2 500
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork Bracket	BT	✓	125
3011	991182	Front Fork Oil Seal	NRC	✓	30
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp	CRU	✓	120
3015	992337	Front Headlamp Bracket	CRU	✓	50
3016	992345	Front Headlamp Fairing	CRU	✓	85
3017	992130	Front Windshield	MIS	✓	60
3018	992134	Front Wing Mirror	MIS	✓	2 50
3019	995245	Front LH Signal Lamp	CRU	✓	45
3020	995246	Front RH Signal Lamp	CRU	✓	45
3021	992556	Meter Casing			
3022	992553	Meter Assy	SCH	✓	390
3023	991019	ERP Bracket			
3024	991020	ERP Unit	BR	✓	150
3025	992446	Ignition Switch			
3026	992442	Ignition Key Assy			
3027	990706	Cowling Stay			
3028	994470	Steering Stem			
3029	994427	Steering Cone	CRU	✓	35
3030	992299	Handle Bar	BT	✓	110
3031	992312	Handle Bar Switch <i>Barrel</i>	BR	✓	2
3032	992310	Handle Bar Grip			
3033	995184	Handle Bar Balancer LH	SCH	✓	30
3034	992300	Handle Bar Balancer RH	SCH	✓	30
3035	992179	Fuel Tank	BT	✓	350
3036	990438	Brake Reservoir			
3037	990621	Clutch Lever	SCH	✓	20
3038	992293	Hand Brake Lever	SCH	✓	20
3039	991119	Side Fairing	BR	✓	155
3040	994220	Side Fairing Top Garnish			
3041	994219	Side Fairing Inner Garnish			
3042	991118	Fairing Shield <i>front lower</i>	BR	✓	80
3043	992047	Front Top Fairing Inner Garnish			
3044	991123	Fairing Top Garnish			
3045	990538	Center Fairing			
	993378	Rear Fairing			
	991121	Fairing Stopper			
	991117	Fairing Lower			
		Rim Shaft	BT	✓	38

NAC	INC	Item	CON	AC	Qty
3046	995074	Radiator			
3047	992738	Radiator Cowling			
3048	994146	Seat Assy	BR	✓	120
3049	990915	Engine Crash Bar			
3050	990928	Engine Guard			
3051	990219	Battery			
3052	990224	Battery Cover			
3053	990223	Battery Bracket			
3054	991144	Foot Brake			
3055	991154	Front Foot Rest	CRU	✓	38
3056	991779	Front Foot Rest Bracket			
3057	994269	Side Stand			
3058	992549	Main Stand			
3059	990615	Clutch Engine Cover			
3060	992478	Kick Starter Rubber			
3061	992477	Kick Starter Lever			
3062	991145	Foot Gear Shifter			
3063	993500	Rear Foot Rest	BR	✓	38
3064	993501	Rear Foot Rest Bracket			
3065	992581	Exhaust Muffler Heat Shield			
3066	991058	Exhaust Muffler Assy	BR	✓	45
3067	993719	Rear LH Shock Absorber			
3068	993720	Rear RH Shock Absorber			
3069	995065	Rear Tyre			
3070	991200	Rear Rim			
3071	994872	Rear Tyre Rim Spoke			
3072	993474	Rear Fender Wheel Guard			
3073	993443	Rear Fender Mudflap			
3074	992940	Rear Brake Disc			
3075	992936	Rear Brake Caliper			
3076	995236	Rear Spocket			
3077	990585	Chain			
3078	990580	Chain Guard			
3079	994530	Swing Arm			
3080	993819	Rear Sub frame			
3081	995245	Rear LH Signal Lamp			
3082	995246	Rear RH Signal Lamp			
3083	995251	Rear Taillamp			
3084	993626	Rear Number Plate			
3085	994192	Side Box			
3086	992927	Rear Box			
3087	992928	Rear Box Bracket			
3088	991328	Emblem			
3089	990247	Sticker			

No of Items:

Assessor:

Labour - 400

Paint - 250

P - 3824

- 10%  
3441.60

L - 400

P - 250

= \$4091.60

repa chgs - 5 chgs



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION  
ACCIDENT CLAIM SECTION (SPORE POLICE  
FORCE) 1 MOUNT PLEASANT ROAD  
BLK 8 OLD POLICE ACADEMY SINGAPORE 298333  
ATTN : FRANKIE THAY

Ref: CS3/SPF19016178/Etf3e2

Date: 10-10-2019



Code: SPF

#### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	Veh. Inspected	FQ 1761U
Policy No.	Coverage (\$)	0.00
Claim No. AEMD/105/009/2019/092	Excess (\$)	0.00
Assign From FRANKIE THAY	Assign Date	12/09/2019

#### 2. Vehicle Particulars & Condition

Make & Model	YAMAHA RXZ	c.c	133
Engine No.	HIDDEN	Year of Reg.	1998
Chassis No.	ZMC235692	Colour	BLUE
Odometer	40339 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	80/90-18	MASTER	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-18	MASTER	5 mm
L/H Rear Tyre			mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	01/08/2019	Inspect Date / Time	12/09/2019 ( 04:00 PM )
Survey held at	ONG MOTOR TRADING NO. 464 MACPHERSON ROAD SINGAPORE 368182		

#### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### OPINION ON REPAIR COST FOR VEHICLE NO. FQ 1761U

Qty	Description of Parts	Condition	Recommended (\$)
	<b>REPLACEMENT OF PARTS</b>		
1	FRONT NUMBER PLATE	MISSING	10.00
1	FRONT TYRE	CRUSHED	50.00
1	FRONT RIM	BENT	300.00
1	FRONT BRAKE DISC	BENT	120.00
1	FRONT BRAKE CALIPER	CUT	180.00
2	FRONT FORK ASSY	BENT	500.00
1	FRONT FORK BRACKET	BENT	125.00
1	FRONT FORK OIL SEAL	NECESSARY	30.00
1	FRONT HEADLAMP	CRUSHED	120.00
1	FRONT HEADLAMP BRACKET	CRUSHED	50.00
1	FRONT HEADLAMP FAIRING	CRUSHED	85.00
1	FRONT WINDSHIELD	MISSING	60.00
2	FRONT WING MIRROR	MISSING	50.00
1	FRONT LH SIGNAL LAMP	CRUSHED	45.00
1	FRONT RH SIGNAL LAMP	CRUSHED	45.00
1	METER ASSY	SCRATCHED	390.00
1	ERP UNIT	BROKEN	150.00
1	STEERING CONE	CRUSHED	35.00
2	HANDLE BAR	BENT	110.00
1	HANDLE BAR BRACKET (NPA)	BROKEN	-
1	HANDLE BAR BALANCER LH	SCRATCHED	30.00
1	HANDLE BAR BALANCER RH	SCRATCHED	30.00
1	FUEL TANK	BENT	350.00
1	CLUTCH LEVER	SCRATCHED	20.00
1	HAND BRAKE LEVER	SCRATCHED	20.00
1	SIDE FAIRING	BROKEN	155.00
1	FAIRING FRONT LOWER	BROKEN	80.00
1	RIM SHAFT	BENT	38.00
1	SEAT ASSY	BROKEN	120.00
1	FRONT FOOT REST	CUT	38.00
1	REAR FOOT REST	BROKEN	38.00
1	EXHAUST MUFFLER ASSY	DENTED	450.00

Report Ref No. CS3/SPF19016178/Etf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Recommended (\$)
	LESS 10% DISCOUNT		-382.40
			3,441.60
	<u>LABOUR</u>		
	LABOUR.		400.00
	PAINT.		250.00
			650.00
	GRAND TOTAL		4,091.60

RECOMMENDED COST OF REPAIRS	4,091.60
-----------------------------	----------

Report Ref No. CS3/SPF19016178/Etf3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

RECOMMENDED REPAIR DAYS : 5

WEEKEND : 1

TOTAL DAYS : 6

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.