

(5/9/2019)

INS. CASE OWNER:

PROTECH

CC 6/AIG1901 6182, UH639, LKK:

IDAC:

Surveyor:

MARLUS

DOI:

ASSIGNMENT

IV/A/19

Date / Time:

12/1/19

Registered in Merimen:

12/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SME 2917L

Claim No.:

202205841256

Name of Insured:

TAN FMJ SOON

Policy No.:

180114612

Insured Tel No.:

HP:

Make / Model:

Audi

Excess Sec II : \$5

D.O.A.:

11/1/19

Place of Accident:

PIE TMS LAMU

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TAN XINYU GIBSON

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L- YES / NO)

Insured Liability:

%

Final ? Yes / No

SME 7817

INSRS:
WSP:
Tel:
Liability:
RMKS:

Fasten

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE/ PIC
		Non-Reporting Itr (1st):	
		Non-Reporting Itr (2nd):	
		Non-Reporting Itr (Final):	
		Notification Itr (if non-pickup):	
17/09/19	- MR. KENNEDY. OLD INVOLVED IN A 4 VEH. C.C.; OLD 2ND CATE. SEND LETTER & EMAIL TO OI TO NOTIFY TP CLAIM & NCD ISSUES.	Call OI:	
	- PLANNED	After call Itr to OI:	17/09/19 - VC
	- ORIGINAL TP LOD IN	Documentation Check List:	Handler Typist
		Notification Itr (if non-pickup)	
		After call Itr to OI:	
15/10/19	- UPLOAD U IN WIKIMEDIA	Authorisation To Act:	
		Release Voucher:	
31/10/19	- MG APPROVED WAIVER	Final Repair Bill:	
01/11/19	- SEND SET OFFER TO TP	Car Rental Invoice:	
	- TP ACCEPTED OFFER.	Towing Invoice:	
	- ALL LODS IN ORDER.	LTA / GIA:	
	- TO CLOS.	Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

46

\$5

4,000.00

(5 days)

Reduction:

75

%

Email

Call

FINAL SETTLEMENT

Date/Time:

01/11/19

Confirm with:

STACON

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

0%

Repair Cost: (w/loss)

\$5

4,280.00

CA VEH-C.C.; OLD 2ND)

Loss of Rental (LOR):

\$5

(days)

Loss of Use (LOU):

\$5

600.00

(500 x 6 days)

Loss of Income (LOI):

\$5

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/TA Search

\$5

2.00

Medical:

\$5

-

Disbursement:

\$5

-

(e.g. Tow/ Independent)

Legal Cost:

\$5

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

6320.00

Total:

\$5

4,882.00

Global Sum \$5:

4,880.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

4,880.00

Name 1:

PROTECH AUTO PRO LTD

Payee 2: (Strike if N.A.)

\$5

-

Name 2:

-

Payee 3: (Strike if N.A.)

\$5

-

Name 3:

-

ASS. REC. BY: MCRWJ

REF:

Ala/

VIC

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SML 7821J

at Workshop m/s 24.

of

Insured: SME 2917L

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 28

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

273F

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SML 7821J Yr Regn: 1 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make: Toyota Camry c.c. 2362

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 163510 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053BK 4007044173

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Dayton

Front: 6 mm Rear: 6 mm

R/Bal: 6 mm L/Bal: 6 mm

D.O.A. 11/9/19 D.O.I. 12/9/19

Survey held at: —

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 207126
LTA 20472 1yrs 3m n4 7828

16/9/19 2/5 of 4000 conf. with Ala.
(2000 & 12,150.31/75%)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair:

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip:

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$

Transportation:

Report Format:

Lump Sum / I.B.I. (\$

☐ : Interview (\$

Photos

☐ : Tech. Invs (\$

Other

☐ : Weekend (\$

TOTAL

000/11/13 waf
ASS. REC. BY: *Morins*

REF:

Ala/

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: *SMC 7821J*
at Workshop m/s: *21*
of _____
Insured: *SME 2917L*
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *28*
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

273F

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction *207126*
L7A 20472 1yrs 3m net 7528

Veh No: *SMC 7821J* Yr Regn: *1 11*
Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *CA/*
Make: *Toyota Camry* c.c. *2362*
Colour: *Grey* A/C: Insured / Std / NI / NA
Sp. Reading: *163510* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *MR053BK 4007044173*
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: *225/45 R18*
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *Dayton*
Front: *6* mm Rear: *6* mm
R/Bal: *6* mm L/Bal: *6* mm
D.O.A. *11/9/19* D.O.L. *12/9/19*
Survey held at: _____
Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Date/Time, File Return to?

Add Fee:

☐ : Site Insp (\$ _____) ☐ : S + RS \$ _____
☐ : Interview (\$ _____) ☐ : Photos
☐ : Tech. Invs (\$ _____) ☐ : Others
☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I. (\$ _____)

TO SPRAY ROOF PROOFING
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$1,200.00 *600*
\$1,500.00 *900*
TOTAL \$16,150.31

P-403440
600
3025.80
5045.80

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 273F

Vehicle Details

Vehicle No.: SML7821J

Vehicle to be Exported: No

Intended Deregistration Date: 12 Sep 2019

Vehicle Make: TOYOTA

Vehicle Model: CAMRY 2.4 AUTO ABS AIRBAG

Primary Colour: Grey

Manufacturing Year: 2010

Engine No.: 2AZE200704

Chassis No.: MR053BK4007044173

Maximum Power Output: 123.0 kW (164 bhp)

Open Market Value: \$26,586.00

Original Registration Date: 05 Jan 2011

First Registration Date: 05 Jan 2011

Transfer Count: 3

Actual ARF Paid: \$26,586.00 13293

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 04 Jan 2021

PARF Rebate Amount: \$14,622.00

Intended COE Rebate Details

COE Expiry Date: 04 Jan 2021

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$44,900.00

COE Rebate Amount: \$5,850.00

Total Rebate Amount: \$20,472.00

The information contained herein is correct as at 12 Sep 2019

OK

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Low Mileage, Excellent Condition At Reasonable Price



One Of The Best Condition You
Can Find, Definitely Won't
Regret Buying This Unit
Carz World Pte Ltd StarAd







Browse by Category

Sort by Date Posted 20 results/page

5 vehicles

camry

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	camry		Any	Any	2011	Any	Any	Any	Available
	Toyota	Camry 2.0A	\$34,800	\$11,630 /yr	22-Sep-2011	1,998 cc	-	Luxury	Available
1 Owner Well Maintained Call Now For Viewing.									
Posted: 11-Sep-2019 Tags: 2011 Toyota Camry, 2011 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota									
	Toyota	Camry 2.0A	\$36,555	\$12,580 /yr	22-Jul-2011	1,998 cc	85,200 km	Luxury	Available
1 Careful Owner, Low Mileage, Regularly Serviced And Maintained With Proper Serviced History Record, Servicing Just Done Recently, TL...									
Posted: 10-Sep-2019 Tags: 2011 Toyota Camry, 2011 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota									
	Toyota	Camry 2.0A	\$32,500	\$12,920 /yr	21-Apr-2011	1,998 cc	118,112 km	Luxury	Available
Rare! Elegant, Facelifted Pearl White Camry 2.0A! Super Low Mileage Clocked Of 13800km Annually Only. Very Well Maintained, No Furt...									
Lake View Credit Pte Ltd									
Posted: 08-Sep-2019 Tags: 2011 Toyota Camry, 2011 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota									
	Toyota	Camry 2.0A	\$38,822	\$12,710 /yr	14-Nov-2011	1,998 cc	92,886 km	Luxury	Available
1 Owner Only! No Structural/Chassis Damage Before. Low Mileage Done, \$12k Per Annum. Very Well Maintained Interior And Leather U...									
Posted: 07-Sep-2019 Tags: 2011 Toyota Camry, 2011 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota									
Is your COE expiring? Let us help you renew it!									
Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.									
	Toyota	Camry 2.0A	\$28,500	\$12,260 /yr	06-Jan-2011	1,998 cc	150,000 km	Luxury	Available
New Aircon Change 2 Years Ago! Well Maintained Unit By Owner! Good Car To Renew COE! Don't Miss A Chance To Own This Beautiful...									
Prem Roy Motoring									
Posted: 08-Aug-2019 Tags: 2011 Toyota Camry, 2011 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Print Received Message

This mail is associated with :

***SML7821J (2022058412SG)
[SME2917L]**

TP
PHNG THENG PHNG
Sep 11 2019 3:00PM
[TAN ENG SOON]
Fastech Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 31/10/2019 15:46 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4882.00) - SML7821J - Claim Handler: Ler, Bernard-JQ

Approved:4882.00:Cost of Repair : \$4,280.00 As per surveyor finalization Loss of Use : \$600.00 6 days @ S\$ 100/day LTA/ GIA Search Fee : \$2.00 Total : \$4,882.00



SINGAPORE POLICE FORCE



F/20190917/7038

1 of 1

POLICE REPORT (NP299)

Report No. F/20190917/7038

Police Station Of Origin
Ang Mo Kio Division HQ
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No:1800-2180000

Date/Time Report Made 17/09/2019 15:57	Vide Report No.	Station Diary No.	
Name Of Informant PHNG THENG PHNG	Address APT BLK 642 HOUGANG AVENUE 8 #04-187 SINGAPORE 530642		
ID Type / ID No. NRIC NO / S7342273F	Contact No. Home/Office:	Mobile: 94878550	
Nationality SINGAPORE CITIZEN	Email Address eccentri@hotmail.com		
Occupation SALES	Sex Male	Age 45	Date of Birth 02/11/1973
			Race Chinese
Institution/School Name	Language English		
Date/Time Of Incident 11/09/2019 15:00	Location Of Incident APT BLK 642 HOUGANG AVENUE 8 #04-187 SINGAPORE 530642		

Brief details.

When driving along PIE toward Changi, the traffic flow is heavy, the front car stop, I also stop. Suddenly i foelt an impact from behind, then I come down and saw chain collision.

Total: 4 car collision.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 17/09/2019 15:57
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5110057401

Cover : drivo CLASSIC

- | | |
|---|---------------------|
| 1. Index mark and Registration Number of Vehicle | : SML7621J |
| Chassis Number | : MR053BK4007044173 |
| 2. Name of Policyholder | : PHNG THENG PHNG |
| 3. Effective Date of Insurance | : 16 Jun 2019 |
| 4. Expiry Date of Insurance | : 15 Jun 2020 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |

6. Limitations as to Use#

- (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
(b) Use for racing, pace-making, reliability trial or speed-testing.
(c) Use for the carriage of goods (other than samples) in connection with any trade or business.
(d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: PHNG THENG PHNG
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: HONG LEONG FINANCE LIMITED
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : THOMSON CREDIT (S) PTE LTD (00000614577)
Date of Issue : 15 Jun 2019 13:40 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 273F

Vehicle Details

Vehicle No.: SML7821J
Vehicle to be Exported: Yes
Intended Deregistration Date: 12 Sep 2019
Vehicle Make: TOYOTA
Vehicle Model: CAMRY 2.4 AUTO ABS AIRBAG
Primary Colour: Grey
Manufacturing Year: 2010
Engine No.: 2AZE200704
Chassis No.: MR053BK4007044173
Maximum Power Output: 123.0 kW (164 bhp)
Open Market Value: \$26,586.00
Original Registration Date: 05 Jan 2011
First Registration Date: 05 Jan 2011
Transfer Count: 3
Actual ARF Paid: \$26,586.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 04 Jan 2021
PARF Rebate Amount: \$14,622.00

Intended COE Rebate Details

COE Expiry Date: 04 Jan 2021
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$44,900.00
COE Rebate Amount: \$5,850.00
Total Rebate Amount: \$20,472.00

The information contained herein is correct as at 12 Sep 2019

OK

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67465405 / 67465376 Fax No: 67458520

Tax Reg No: 200006262D

Date : 23.09.2019

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

ACCIDENT INVOLVING VEHICLE: SML 7821J AND SME 2917L ON 11.09.2019

We are the authorized repair workshop for the owner of motor vehicle no: **SML7821J**, which was involved in the captioned accident with your insured vehicle no: **SME 2917L**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$	4,280.00
2) Loss Of Use (5 days + 1 sun X \$120)	\$	720.00
3) GIA Search Fee	\$	2.00
	\$	5,002.00

We enclosed herewith the following documents to support the claims:

- | | |
|---------------------------------|------------------------------------|
| a) Final Repair Invoice | b) Vehicle Registration Log Card |
| c) GIA Report/GIA Search Result | d) I/C & Driving Licence |
| e) Insurance Certificate | f) Letter of Authorisation, etc... |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.

Yours faithfully,

Jason Tang
For Fastech Auto Pte Ltd



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG19016182/Uhb3

17 SEPTEMBER 2019

**TAN ENG SOON
BLOCK 109 JALAN BUKIT MERAH
#02-1746
SINGAPORE 160109**

By Post & By Email

Dear Sir/Madam,

ACCIDENT INVOLVING SME 2917L / SML 7821J / OTHERS ON 11/09/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a Property Damage Claim from Body Repairer/Workshop acting on behalf of the owner of SML 7821J against your motor insurance policy.


Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,


Vic Alpeh
Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)
tanengsoon@lubritrade.com.sg / gibz_1990@hotmail.com
(Email)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Tuesday, 17 September, 2019 4:19 PM
To: tanengsoon@lubritrade.com.sg
Cc: gibz_1990@hotmail.com; Admin A; Vic (LKKAUTO)
Subject: Your Ref: SME 2917L - ACCIDENT INVOLVING SME 2917L / SML 7821J / OTHERS ON 11/09/2019



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG19016182/Uhb3

17 SEPTEMBER 2019

**TAN ENG SOON
BLOCK 109 JALAN BUKIT MERAH
#02-1746
SINGAPORE 160109**

By Post & By Email

Dear Sir/Madam,

ACCIDENT INVOLVING SME 2917L / SML 7821J / OTHERS ON 11/09/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a Property Damage Claim from Body Repairer/Workshop acting on behalf of the owner of SML 7821J against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Phng Theng Phay ("the third party claimant")
of 642 Hongkong Ave 8 #04-187 (S) 530642 (address),
owner of SML 7821J (vehicle no.) hereby authorize
FasTech Auto Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SML 7821J that was
damaged pursuant to the accident which occurred on 11/9/19 (date) along
PIE towards Changi (location)
involving vehicle no/s SME 2917L ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 12 day of sep (month) 20 19 (year)

See.

Signed by "the third party claimant"

f



Signed by "the workshop"



RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I, Fusatech Auto Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd, LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 4,880.00 (GLOBAL BUM - ALL IN) (repair costs), S\$ - (loss of use/rental) S\$ - (~~search fees~~) for vehicle no. SML 7821J that was damaged pursuant to the accident which occurred on 11/9/19 (date) along PIE towards Changi (location) involving vehicle no/s SME 2917L

This is pursuant to the inspection conducted on 12/09/19 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Phng Thany Phng ("third party claimant") of vehicle no. SML 7821J to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SML 7821J (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 01 day of 11 (month) 20 19 (year)



CKS

Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

TAX INVOICE

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax.Reg No: 200006262D

AIG Asia Pacific Insurance Pte Ltd
Chartis Building
78 Shenton Way #07-16
Singapore 079120

Attn: Motor Claim Department

Tax Invoice : 21371

Date: 23.09.2019
Vehicle No: SML 7821J
Make/Model: TOYOTA CAMRY

Accident Date: 11.09.2019
Claim No : 0919-21371
Reference :
Policy No :

	Amount
To proceed on lump sum repair	S\$ 4,000.00

E. & O. E.	Total : S\$	4,000.00
	GST @ 7% : S\$	280.00
	Amount Due : S\$	4,280.00


for FASTECH AUTO PTE LTD

All Invoices are subjected to GST

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

RECORDS MANAGEMENT CENTRE

Third Party Insurer Enquiry

Our Ref No: GR-19-150084

Date of Request: 12/09/2019

Your Ref No:

Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 12/09/2019

Enquiry By Tang Kok Wee, Allan

Vehicle No. SME2917L

Accident Date 11/09/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SME2917L	AIG Asia Pacific Insurance Pte. Ltd.	24/09/2018-23/09/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-150084
Date of Request: 12/09/2019

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 12/09/2019
Enquiry By Tang Kok Wee, Allan
Vehicle No. SME2917L
Accident Date 11/09/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Sep 2019 Edit Reg		12 Sep 2019 00:00 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAN ENG SOON , ID: S1392191A								
Main Claimant:	PHNG THENG PHNG , ID: S7342273F								
Vehicle Reg. No.:	SML7821J	Date of Loss:	11/09/2019 15:00 - :59 104 Months and 6 Days From LTA Reg Date (Man Yr)						
Claim Type:	TP / 2022058412SG	Policy/Cover Note No.:	1800114612 (Comprehensive)						
Vehicle Reg. No. (Insured):	SME2917L	Policy No. (Claimant):	511057401						
		Excess:							
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 23/09/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (31/10/2019): Alert - Adj Mandate Approved (S\$4882.00) - SML7821J - Claim Handler: Ler, Bernar... AIG_SG (13/09/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SML7821J (2022058412SG)

[SME2917L]

TP

PHNG THENG PHNG

Sep 11 2019 3:00PM

[TAN ENG SOON]

Fastech Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View in Browser"/>	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown							Edit		
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	15/10/19 15:09	Adjuster Immediate Advice							Load HTM		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	12/09/19 18:04	Chassis Number							Load JPG <input checked="" type="checkbox"/>		
2	12/09/19 18:04	Odometer Reading							Load JPG <input checked="" type="checkbox"/>		
3	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
4	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
5	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
6	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
7	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
8	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
9	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
10	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
11	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
12	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
13	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
14	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
15	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
16	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
17	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
18	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
19	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
20	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
21	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
22	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
23	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
24	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
25	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
26	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
27	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
28	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
29	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
30	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
31	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
32	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
33	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
34	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
35	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		
36	12/09/19 18:05	General View							Load JPG <input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
38	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
39	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
40	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
41	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
42	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
43	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
44	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
45	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
46	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
47	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
48	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
49	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
50	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
51	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
52	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
53	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
54	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
55	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
56	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
57	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
58	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
59	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
60	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
61	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
62	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
63	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
64	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
65	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
66	12/09/19 18:05	General View		<input checked="" type="checkbox"/>
67	17/09/19 18:25	After Repair Photo		<input checked="" type="checkbox"/>
68	17/09/19 18:25	After Repair Photo		<input checked="" type="checkbox"/>
69	17/09/19 18:25	After Repair Photo		<input checked="" type="checkbox"/>
70	17/09/19 18:25	After Repair Photo		<input checked="" type="checkbox"/>
71	17/09/19 18:25	After Repair Photo		<input checked="" type="checkbox"/>
72	17/09/19 18:25	After Repair Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/09/19 09:03	TP GIA REPORT		<input type="checkbox"/>
2	17/09/19 16:20	EMAIL TO OI		<input type="checkbox"/>
3	17/09/19 16:20	LETTER TO OI		<input type="checkbox"/>
4	15/10/19 14:44	TP ESTIMATE - FINALIZED		<input type="checkbox"/>
5	15/10/19 14:52	TP LOD		<input type="checkbox"/>
6	05/11/19 09:01	WORKSHOP INVOICE		<input type="checkbox"/>
7	05/11/19 09:01	AUTHORISATION TO ACT FORM		<input type="checkbox"/>
8	05/11/19 09:01	Release Voucher		<input type="checkbox"/>
9	05/11/19 09:01	GIA SEARCH		<input type="checkbox"/>
10	05/11/19 09:01	LOD		<input type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	13/09/19 10:44	OI GIA REPORT		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SME2917L (Insd veh)	Model:	TOYOTA CAMRY 2.0 (A)
	SML7821J (TP veh)		
Date of Accident:	11/09/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	17,280.83
Final Repair Cost	:	\$	4,880.00
Loss of Use	:	\$	6.00 days at \$100.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	4,880.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability 100 (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): 0 (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	:	\$ 4,880.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

05 Nov
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19016182/UHB3Q2

Date: 05/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800114612
Claimant
Vehicle No : SML7821J **Insured Vehicle No :** SME2917L
Date of Loss: 11/09/2019 **Nature of Claim:** TP **Claim No:** 2022058412SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML7821J**
 Make & Model: TOYOTA CAMRY, 2.0 (A) Engine No: 2AZE200704
 Reg. Date: 05/01/2011 (Man. Year: 2010) Chassis No: MR053BK4007044173
 Colour: Grey Odometer: 163510 km
 Engine Capacity: 2362 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
 Front Left Side: Dayton 6 mm Rear Left Side: Dayton 6 mm
 Front Right Side: Dayton 6 mm Rear Right Side: Dayton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,830.31	3,275.80	9,554.51	74.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,320.00	1,770.00	1,550.00	46.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,150.31	5,045.80	11,104.51	68.76
Approved Total (Overridden) (\$\$)		4,000.00		
(\$\$)	16,150.31	4,000.00	12,150.31	75.23
+ GST 7.00/7.00% (\$\$)	1,130.52	280.00	850.52	75.23
Nett Amount (\$\$)	17,280.83	4,280.00	13,000.83	75.23
+ Loss of Use (6.0 x S\$100.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		4,882.00		
Global Sum Settlement (\$\$)		4,880.00		

INSPECTION

Date of Assignment: 12/09/2019
 Date Inspected: 12/09/2019 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50
 Autobay
 Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,886.10 F	*- FL
2	1		*BOOTLID REAR LOGO	Necessary	66.50 F	*66.50 FL
3	1		*BOOTLID CAMRY EMBLEM	Necessary	68.50 F	*66.20 FL
4	1		*BOOTLID 2.4 EMBLEM	Necessary	62.30 F	*52.50 FL
5	1		*BOOTLID OUTER GARNISH	Not Necessary	679.10 F	*- FL
6	2		*BOOTLID REFLECTORS	Not Necessary	963.00 F	*- FL
7	1		*BOOTLID INNER LOCK	Not Necessary	399.10 F	*- FL
8	1		*BOOTLID LOCK SENSOR	Not Necessary	60.00 F	*- FL
9	1		*BOOTLID WEATHERSTRIP	Twisted	311.10 F	*311.10 FL
10	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	60.00 F	*- FL
11	1		*REAR BUMPER	Distorted	866.01 F	*699.10 FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	422.10 F	*415.50 FL
13	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	290.00 F	*- FL
14	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
15	1		*REAR BUMPER REFLECTORS	O/S Cracked	196.20 F	*98.10 FL
16	1		*REAR END PANEL	Dented / Bent	639.10 F	*639.10 FL
17	1		*REAR END PANEL TOP GARNISH	Deformed / Torn	415.10 F	*415.10 FL
18	1		*TAILLAMPS	O/S Cracked	1,360.20 F	*680.10 FL
19	1		*TAILLAMP HOUSING PANEL O/S	Not Necessary	450.10 F	*- FL
20	1		*REAR FENDER O/S	Not Necessary	1,055.10 F	*- FL
21	1		*REAR FENDER INNER TRIM O/S	Not Necessary	388.10 F	*- FL
22	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
23	1		*REAR FLOOR PANEL TOP BOARD	Torn	421.10 F	*421.10 FL
24	1		*REAR EXHAUST	Repair	1,021.50 F	*- FL
25	1		*REAR EXHAUST CHROME PIPE	Bent	120.00 F	*120.00 FL
26	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
27	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
28	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,830.31	4,284.40
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,008.60
Total Parts (\$\$)	12,830.31	3,275.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX BOOTLID MECHANISM	New	120.00	0.00
4	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	60.00
6	TO SPRAY RUST PROOFING	New	120.00	50.00
7	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,200.00	600.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	900.00
Gross Labour Cost (S\$)			3,320.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >