

ASS. REC. BY:

REF:

CS3/AGI19016184/11cd30

Special Instruction:

Surveyor: TauferhASSIGNMENT (Office)From (Person): Wj Ratilla

of

AGIDate/Time: 12/9/19 @ 9:51am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 5336Z

Insured:

SGM 5347R

at Workshop in/s

8in Foo Hing Battery

Tel:

9733 6031

of

27A Jurong Port Road # 01-30

Policy No:

Claim No:

C10003981 / KY

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10/09/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:44am @ 12/9/19

Person Contacted:

Mr-SinVehicle-IN OUT

Date/Time	Action/Instruction
	<u>Edmond (X)</u>
	<u>SGM 5347R - CC6 / DA 15017863 / kpb 3s 2</u>
	<u>D.O.A. 17/10/15</u>
	<u>GBE 5336Z - X</u>
	<u>Before paint: 18/9/2019</u>
	<u>After paint: 23/9/2019</u>

ASS. REC. BY:

REF:

AGI

PRS

ASSIGNMENT

From:

Date:

13/09/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBE 5336Z

at Workshop m/s

Sin Foo Hing Battery

of

27A Juncus post Road # 01-30

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBE 5336Z

Yr Regn:

/

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna. c.c 2982

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

143508

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KDY23 802245

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/75/15

R:

145/113 (17)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

D.O.I.

13/9/19 212pm

Survey held at

Sin Foo Hing

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

N. 6/14

\$9000 - \$10,000, 10 days

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

10

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

100

60

60

20

Report Format:

PRS

Lump Sum / LBL (\$)

Nivitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Thursday, 12 September 2019 9:51 AM
To: Admin-D (LKKAuto)
Cc: sur@lkkauto.com; Justin Wong
Subject: FW: TPPD Survey: Claim ref:C10003981/KY || OI- SGM5347R (Brown) TP- GBE5336Z || Est:0.00 || M/s Sin Foo Hing Battery Service

Hi Team,

Good morning.

We would like to arrange TP PRS for GBE5336Z.

Workshop information:

M/s Sin Foo Hing Battery Service, 27A Jurong Port Road #01-30 Singapore 619101. Contact number 97336031.

Please confirm.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: bonnie kwok <litigation@bonniekwok.com>

Sent: Wednesday, 11 September 2019 5:40 PM

To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>

Cc: Claims <claims@budgetdirect.com.sg>; Justin Wong <justin.wong@budgetdirect.com.sg>

Subject: Re: PRI - Acc Inv: GBE 5336 Z & SGM 5347 R ON 10 SEPTEMBER 2019 || C10003981

Dear Ivy,

We refer to your email dated 11 September 2019.

Our client disagrees to your list of surveyors.

Our client proposes their Single Joint Experts (SJE) as follows:-

NO NAME OF SURVEYOR

- 1 Philip Foo
- 2 Ng Kong Beng Patrick
- 3 Lim Yong Tian
- 4 Ong Hock Leng
- 5 Louis S C Ng Cae Amimi
- 6 Lawrence Ng Chun Kee
- 7 Fong Kok Heng Stanley
- 8 Sim Siak Tong
- 9 Tan Chin Suan
- 10 Matthew Ng

Regards,
June

Dear Sir,

We refer to the above matter.

I hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle GBE 5336 Z at M/s Sin Foo Hing Battery Service, 27A Jurong Port Road #01-30 Singapore 619101. Contact number 97336031.

Regards,
June

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AUTO & GENERAL INSURANCE (S) PL		Ref: CS3/AGI19016184/T1cd3e2		
(BUDGET DIRECT INSURANCE)190CLEMENCEAU		Date: 07-10-2019		
AVENUE #03-01 S S C SINGAPORE 239924		Code: AGI		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SGM 5347R	Veh. Inspected	GBE 5336Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10003981/KY	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	12/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2982	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	KDY2318022415	Colour	SILVER	
Odometer	143508 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/75 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	175/75 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	145 R13 (D)	BRIDGESTONE	6/6 mm	
L/H Rear Tyre	145 R13 (D)	BRIDGESTONE	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
5. General Information				
Accident Date	10/09/2019	Inspect Date / Time	13/09/2019 (12:00 PM)	
Survey held at	SIN FOO HING-27A JURONG PORT ROAD#01-30			
Repairer	-			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000-\$10,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		

Report Ref No. CS3/AGI19016184/T1cd3e2

Inspected By

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.