

ASS. REC. BY:

REF: CS3/A1419016200 / Fed321 Special Instruction:

Surveyor: Ram

ASSIGNMENT (Office)

From (Person): chin lee ying of A19 Date/Time: 12/9/19 2200pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFJ 172M Insured: SLZ 7236L

at Workshop m/s Khek Jhao Motor Tel: 9616 6658

of 81K 9004 Tampines street 93 # 01-94

Policy No: Claim No: SF03162011SG

Sum Insured: Excess:

Make of Veh: D.O.A. 31/08/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 232pm 12/9/19 Person Contacted: Mr. Ng Vehicle IN / OUT

Date/Time	Action/Instruction
	Johny (X)
	SFJ 172M - X
	SLZ 7236L - X
	Dismantle: 17/9/2019
	After repair: 20/9/2019

AG ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFJ172M

at Workshop m/s KHEK JOO MOTOR

of BIK 9004 TAMPAKING IND PARK / #01-94

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle. IN / OUT

Veh No:

SFJ172M

Yr Regn: DEC / 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Harrier 2.0 elegance c.c 1986

Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 55544

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ZSU600076736

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/65 R17

R: 225/65 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 6 mm

L/Bal. 5 mm

L/Bal. 6 mm

D.O.A. 31/08/2019

D.O.A. 16/9/19

Survey held at

KHEK JOO MOTOR

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range:

Repair days:

MV: \$97000

PV: \$53992

NV: \$43000

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

4

Resurvey No. of Trip:

2

1)

☐

: Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format:

DAR

Lump Sum / I.B.I: (\$

Survey Fee:

180

Transportation:

3 + RS, 31

Photos

Others

11

TOTAL

191

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Sep 2019 Edit Reg		12 Sep 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main		Reference		Claim Details		Documents		Show All	
CLAIM SUBFOLDER DETAILS								[Created by adjuster]	
Insured:	GOLDBELL CAR RENTAL PTE LTD, Co. Reg. No.: 200710651D								
Main Claimant:	-								
Vehicle Reg. No.:	SFJ172M			Date of Loss:	31/08/2019 00:00 - :59				
Claim Type:	TP / 5703162011SG			Policy/Cover Note No.:	(Comprehensive)				
Vehicle Reg. No. (Insured):	SLZ7236L			Policy No. (Claimant):					
				Excess:					
Repairer:	Khek Joo Motor Workshop (HQ) BLK 9004 TAMPINES STREET 93 #01-94, 528838 Tampines - Tel: 67854258								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 23/09/2019]								
ASSOCIATED MAIL RECEIVED								View All Compose Case Mail	
<ul style="list-style-type: none"> AIG_SG (13/09/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS								View All Search Tasks Create New Task Complete	
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Your password will expire in 3 days. [Click here to change it.](#)

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 9/12/2019 2:20:15 PM

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Rachel Ling [mailto:jin@tcmg.com.sg]

Sent: Thursday, September 12, 2019 11:21 AM

To: Hor, Yinrul

Cc: 'Ling Leong Hui'; 'Jenny'; 'Mdm Ling'

Subject: [EXTERNAL] RE: PRE REPAIR INSPECTION NOTICE FOR SFJ 172 M | YOUR REF: SLZ 7236 L

This message is from an external sender; be cautious with links and attachments.

URGENT

Hi Yinrul,

We forward herewith our pre-repair inspection notice of 9th September 2019 for your immediate attention.

Regards,
Rachel Ling

From: Rachel Ling [mailto:jin@tcmg.com.sg]

Sent: Monday, 9 September, 2019 9:28 AM

To: 'shengyang.lim@aig.com' <shengyang.lim@aig.com>

Cc: 'Ling Leong Hui' <lhling@tcmg.com.sg>; 'Jenny' <jenny@tcmg.com.sg>; 'Mdm Ling' <mdmling@tcmg.com.sg>

Subject: PRE REPAIR INSPECTION NOTICE FOR SFJ 172 M | YOUR REF: SLZ 7236 L

Our Ref: TCMG/SFJ 172 M/0919/KJM

Your Ref: SLZ 7236 L

Dear Sirs,

PRE-REPAIR INSPECTION NOTICE

We act for **Wong Yong Seng Andrew**, the owner and/or driver of motor vehicle no. **SFJ 172 M**, which was involved in an accident along Yishun Ring Road on 31st August 2019 at 19:35 hrs.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **SLZ 7236 L** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Khek Joo Motor, (9004, Tampines Street 93 #01-94, Singapore 528838 – Mr. Ng Wee Khiang @ 9616 6658).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 501H

Vehicle Details

Vehicle No.: SFJ172M
Vehicle to be Exported: No
Intended Deregistration Date: 17 Sep 2019
Vehicle Make: TOYOTA
Vehicle Model: HARRIER 2.0 ELEGANCE AT ABS D/AIRBAG 2WD
Primary Colour: White
Manufacturing Year: 2016
Engine No.: 3ZRB771424
Chassis No.: ZSU600076736
Maximum Power Output: 111.0 kW (148 bhp)
Open Market Value: \$28,830.00
Original Registration Date: 15 Dec 2016
First Registration Date: 15 Dec 2016
Transfer Count: 0
Actual ARF Paid: $\$27,362.00 \times 50\% = \$13,681$

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 14 Dec 2026
PARF Rebate Amount: \$20,521.00

Intended COE Rebate Details

COE Expiry Date: 14 Dec 2026
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$46,229.00
COE Rebate Amount: \$33,471.00
Total Rebate Amount: \$53,992.00

The information contained herein is correct as at 17 Sep 2019

Remaining : 7yrs 3months 15day (87.5) OK

\$11500/yrly \$958/monthly

$87.5 \times \$958 = \$83825 + \$13681 = \97506

Toyota Harrier

Price Range ▼

Depreciation ▼

2016 ▼

Vehicle Type ▼



Home » Used Cars » Hamilton Autohub Pte Ltd » Toyota Harrier 2.0A Elegance Panoramic

Toyota Harrier 2.0A Elegance Panoramic

Overview

Financial

Insurance


Accessories

Similar

Research

Photos

Map



Price \$95,800

Depreciation \$11,630 /yr
View models with similar depreReg Date 30-Sep-2016
(7yrs 12days COE left)

Mileage 65,000 km (21.9k /yr)

Manufactured 2016

Road Tax \$1,196 /yr

Transmission Auto

Dereg Value \$60,906 as of today (change)

OMV \$29,157

COE \$56,889

ARF \$27,820

Engine Cap 1,986 cc

Power 111.0 kW (148 bhp)

Curb Weight 1,610 kg

No. of Owners 1

Type of Vehicle SUV

Features

2.0L Inline 4 Cylinder DOHC, Producing 148Bhp, Super CVT-I, FWD, SRS Airbags, ABS, Low Fuel Consumption At 16Km/L. Keyless Entry/Push Start. View specs of the Toyota Harrier (2014)

Accessories

Electrical Retractable Side Mirrors, New Touch Screen Digital Aircon, Multi Zone Aircon, Rear Aircon, Driver Electric Seat, Tailgate, Etc.

Description

1 Owner, Pearl White Colour, Cheapest In Low Depreciation, Very Well Maintained By Previous Owner, Superb Interior Condition, Low Maintained & Reliable Engine, (High & Flexible Loan Available Up To 100%), Low Interest Rate From 2.28%, High Value For Trade In Car, Immaculate Condition, 100% Accident Free, Call For Viewing Now, Before It' Gone.

Category

PARF Car

Status

Available

Resources

Compare


Le Evaluation



Location Map

Price Chart

Summary



Click on the point to view the vehicle

Shortlist

Compare

Add no

Report Error

More Actions

Seller Information

Company

Hamilton Autohub Pte



» dealer's pricelist

» 54 vehs sold | 37 vehs a

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/09/2019 11:33
Date Of Accident	31/08/2019 19:35
Exact Location Of Accident	YISHUN RING RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFJ172M
Insured/Policyholder	
Name Of Registered Owner	WONG YONG SENG ANDREW
NRIC No	S7721501H
Email Address	ANDREWYS20@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-97587007
Alternative Phone No	OTHERS-97587007

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER 2.0 SUV
Exact Purpose for which vehicle was being used at time of accident	PVT USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ18-008149
Cover Note Number	15/12/18-14/12/19

Driver

Name of Driver	WONG YONG SENG ANDREW
NRIC No	S7721501H
Date Of Birth	03/08/1977
Occupation	INDOOR
Date Of Driving Pass	30/11/2000
Driving Experience	18 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97587007
Fax Number	
Contact Number	OTHERS-97587007
EEmail Address	ANDREWYS20@YAHOO.COM.SG

Address	BLK 237 YISHUN RING RD #07-1032
Postcode	760237
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	6
Passenger 1	NAME: : QUEK CHENG PHONG BRENDA GENDER: : FEMALE
Passenger 2	NAME: : WONG WEI JUN CLEVON GENDER: : MALE
Passenger 3	NAME: : WONG SHI YING DANIELLE GENDER: : FEMALE
Passenger 4	NAME: : MAK TONG YOKE GENDER: : FEMALE
Passenger 5	NAME: : QUEK KIM CHONG GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER SKETCH ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLZ7236L
-----------------------------	----------

Vehicle Make/Model/Colour

*Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

LIM CHEW KIAT

NRIC/Passport Number

S1811420H

Contact Number

91417887

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN


VEHICLE NO.: SFJ172N
INSURER : EGA
DATE & TIME: 31-8-19 @ 7:35pm


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Evelyn
NRIC/FIN No.: 43

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was in my vehicle at that time, stationary waiting for traffic light to turn green. I was with my family members. Out of sudden, we felt a great impact and realized m/car (B) have collided onto our vehicle.

Both drivers got down to assess and I took down the particulars of the driver of m/car (B). As no one was injured, we left the scene shortly.

~~***~~ I tried to call ED ins to seek advice and left a voice message. However there was no reply till today when I call again, my line got through. The officer advice me to file my report soonest.

Note: Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Stedh
NRIC/FIN No.: YS

☐ Claim Own Policy ☐ Claim Third Party ☐ Reporting Only
☒ Claim OD/TP at other workshop ()

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	51		
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC		
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	NEC		
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	Br		
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	30		
1159	993327	Rear End Panel	DD	R	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD		
1182	991328	Tailgate Emblem	NEC		
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEC		
1196	994607	Tailgate Glass Sealant	NEC		
1197	994629	Tailgate Lock	BT		
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SFJ172M

NAC	INC	Item	CON	A
1202	993784	Spare Tyre Board		
1203	994328	Spare Tyre Panel		
1204	995065	Spare Tyre		
1205	994326	Spare Tyre Lock Screw		
1206	993787	Spare Tyre Cover		
1207	995323	Triangle Breakdown Sign		
1208	990507	CD Changer Assy		
1209	990164	Antenna		
1210	990534	Centre Exhaust Pipe Assy		
1211	990532	Centre Exhaust Mounting		
1212	993364	Rear Exhaust Pipe		
1213	993357	Rear Exhaust Chrome Pipe		
1214	993361	Rear Exhaust Mounting		
1215	993358	Rear Exhaust Heat Shield		
1216	995223	Rear LH Chassis Member		
1217	993165	Rear RH Chassis Member		
1218	993436	Rear LH Fender		
1219	993449	Rear LH Fender Protector		
1220	993420	Rear LH Fender Inner Panel		
1221	993431	Rear LH Fender Inner Trim		
1222	993415	Rear LH Fender Inner Garnish		
1223	993425	Rear LH Fender Inner Shield		
1224	993621	Rear LH Mudflap		
1225	993933	Rear LH Wheel Rim		
1226	994025	Rear LH Rim Cover		
1227	995065	Rear LH Tyre		
1228	993456	Rear RH Fender		
1229	993450	Rear RH Fender Protector		
1230	993420	Rear RH Fender Inner Panel		
1231	993431	Rear RH Fender Inner Trim		
1232	993415	Rear RH Fender Inner Garnish		
1233	993425	Rear RH Fender Inner Shield		
1234	993622	Rear RH Mudflap		
1235	993934	Rear RH Wheel Rim		
1236	994025	Rear RH Rim Cover		
1237	995065	Rear RH Tyre		
1238	995162	Rear Fender Extension Panel LH		
1239	993401	Rear Fender Extension Panel RH		
1240	993430	Rear Fender Inner Top Garnish		
1241	993673	Rear Fender 1/4 Glass		
1242	993452	Rear Fender 1/4 Glass Rubber		
1243	993453	Rear Fender 1/4 Glass Sealant		
1244	993949	Rear Windscreen Glass		
1245	993976	Rear Windscreen Rubber		
1246	993961	Rear Windscreen Moulding		
1247	993955	Rear Windscreen Sealant		
1248	994729	Third Brake Light		
1249	993385	Rear Fender Air Grille		
1250	992167	Fuel Lid		
1251	992168	Fuel Neck		
1252	992179	Fuel Tank		
1253	992184	Fuel Tank Bracket		
1254	992191	Fuel Tank Float		
1255	990247	Sticker		

No of Items: _____

Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Sep 2019 Edit Reg		12 Sep 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by adjuster]					
Insured:	GOLDBELL CAR RENTAL PTE LTD, Co. Reg. No.: 200710651D								
Main Claimant:	-								
Vehicle Reg. No.:	SFJ172M	Date of Loss:	31/08/2019 00:00 - :59 [32 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5703162011SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SLZ7236L	Policy No. (Claimant):							
		Excess:							
Repairer:	Khek Joo Motor Workshop (HQ) BLK 9004 TAMPINES STREET 93 #01-94, 528838 Tampines - Tel: 67854258								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 23/09/2019]								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG (13/09/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									












































Claim Documents






















***SFJ172M (5703162011SG)
[SLZ7236L]**

TP

-

**Aug 31 2019 12:00AM
[GOLDBELL CAR RENTAL PTE LTD]
Khek Joo Motor Workshop**

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	25/09/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>		
2	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
3	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
4	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
5	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
6	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
7	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
8	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
9	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
10	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
11	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
12	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
13	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
14	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
15	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
16	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
17	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
18	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
19	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
20	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
21	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
22	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
23	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
24	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
25	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
26	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
27	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
28	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
29	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
30	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
31	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
32	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
33	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
34	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
35	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
36	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
37	25/09/19 10:12	General View		Load JPG	<input checked="" type="checkbox"/>		
38	25/09/19 10:12	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
39	25/09/19 10:12	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
40	25/09/19 10:12	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
41	25/09/19 10:12	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
42	25/09/19 10:12	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
43	25/09/19 10:12	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	25/09/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	25/09/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	25/09/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	25/09/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	25/09/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	25/09/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	25/09/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	25/09/19 10:12	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
52	25/09/19 10:12	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
53	25/09/19 10:12	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
54	25/09/19 10:12	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
55	25/09/19 10:12	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
56	25/09/19 10:12	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
57	25/09/19 10:12	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
58	25/09/19 10:12	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
59	25/09/19 10:12	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
60	25/09/19 10:12	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
61	25/09/19 10:12	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
62	25/09/19 10:12	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
63	25/09/19 10:12	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	13/09/19 15:25	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19016200/FCD3E2

Date: 07/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SFJ172M

Insured Vehicle No : SLZ7236L

Date of Loss: 31/08/2019

Nature of Claim: TP

Claim No: 5703162011SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFJ172M**

Make & Model: TOYOTA HARRIER, 2.0 Elegance (A)

Engine No: 3ZRB771424

Reg. Date: 15/12/2016 (Man. Year: 2016)

Chassis No: ZSU600076736

Colour: White

Odometer: 55544 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65 R17

Rear Tyre Size:

225/65 R17

Front Left Side: Yokohama 5 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 5 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 12/09/2019

Date Inspected: 16/09/2019 Inspected At:

Khek Joo Motor Workshop (HQ)
 BLK 9004 TAMPINES STREET 93
 #01-94
 Singapore 528838

Estimated Period of Repair: 4.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	* Check	0.00 F	*- F
5	1		*REAR BUMPER SPONGE	Broken	0.00 F	*- F
6	1		*REVERSE SENSOR	Short Circuit	0.00 F	*- F
7	1		*REAR END PANEL	Repair	0.00 F	*- F
8	1		*TAILGATE	Dented	0.00 F	*- F
9	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
10	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
11	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
12	1		*TAILGATE LOCK	Bent	0.00 F	*- F
				Total Parts (\$\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >