



Khanching



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/09/2019

User ID : CatherineLee

Section A - Accident Details		
Registration Number	SMB1625B	
Case Reference Number	BUS/08/19/7033	
Registration Date	13/2/2015	
Company Type	SMRT Buses Ltd	
Make	MAN	
Model	MAN NL320F(A22)	
Name of Driver	Zhang Chengshuang	
Type of Accident	Side Swipe	
Accident Date and Time	27/8/2019 6:52 AM	
Accident Reported Date and Time	27/8/2019 9:45 AM	
Is Surveyor Required?	Yes	
Survey by		
Vehicle is Towed Back?	No	
Towed Back Date and Time		
Replacement Vehicle issued?	No	
Job Card Number	24103122	
Special Instruction to ARC, if any	SMB1625B - RIGHT CENTRE TO REAR PORTION GBD7243A (TP) - INSURED WITH CHINA TAIPING	
Prepared Date and Time	28/8/2019 3:24 PM	
Chassis Number	WMAA22ZZ6F7002611	
Mileage		
Work Shop		
Repair Completion Date and Time		

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$795.00
Total Spray Cost	\$616.00	\$528.00
Total Spare Part Cost	\$133.99	\$133.99
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,074.99	\$1,456.99
Lump Sum Total	\$0.00	\$1,450.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Kok Khoon Goh	STEVE CHEN
ARC / Surveyor Sign Off Date	28/08/2019 3:34 PM	30/08/2019 2:25 PM
Signature		
Remarks	L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com. Survey on 28/08/2019, marked estimate on 30/08/2019.	

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/09/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$1,325.00	\$795.00
Total Labour	\$1,325.00	\$795.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00	\$528.00
Total Spray Painting & Panel Beating	\$616.00	\$528.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010303	VE	4001B05-LAM141	LAMP, INDICATOR, SIDE: LED (MAN BUS)	1.00	\$186.10	10.00	\$167.49	Replace	Replace
6010330	Body	5029	TRIM, WHEELARCH, FOR MB OC500 LE BUS	1.00	\$124.20	100.00	\$0.00	Repair	Repair
6009988	BODY RH	A01001-CW567	PANEL, SIDE: R7, FOR MAN A22 BUS	1.00	\$885.50	100.00	\$0.00	Repair	Repair
6009989	BODY RH	A01001-CW566	PANEL, SIDE: R8, FOR MAN A22 BUS	1.00	\$330.70	100.00	\$0.00	Repair	Repair
Total					\$1,526.50		\$167.49		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

167.49
- 20% Lurpsum
133.99
795
528
L/S- 1456.99
= 1450



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/08/2019

User ID : GohKK2

Section A - Accident Details	
Registration Number	SMB1625B
Case Reference Number	BUS/08/19/7033
Registration Date	13/2/2015
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Zhang Chengshuang
Type of Accident	Side Swipe
Accident Date and Time	27/8/2019 6:52 AM
Accident Reported Date and Time	27/8/2019 9:45 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1625B - RIGHT CENTRE TO REAR PORTION GBD7243A (TP) - INSURED WITH CHINA TAIPING
Prepared Date and Time	28/8/2019 3:24 PM
Chassis Number	WMAA22228F7002611
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$0.00
Total Spray Cost	\$616.00	\$0.00
Total Spare Part Cost	\$133.99	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$133.99	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	Kok Khoo Goh	
ARC / Surveyor Sign Off Date	28/08/2019 3:34 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number	28/08/2019 3:34 PM	Invoice Number	
Quotation Date	28/08/2019 3:34 PM	Invoice Date	
Invoice Amount	\$133.99	Prepared Date	

Summary Made/checked
30/8/19
Steve (LKK) 28/8/19, 3:09pm
3 days
L/S
Ry Al SH



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/08/2019

User ID : GohKK2

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS		\$1,325.00				795			
Total Labour		\$1,325.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$616.00				528			
Total Spray Painting & Panel Beating		\$616.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010303	VE	4001B05-LAM141	LAMP INDICATOR, SIDE, LED (MAN BUS)	1.00	\$186.10	10.00	\$167.49	Replace	OK
6010330	Body	5029	TRIM WHEELARCH FOR MB OC500 LE BUS	1.00	\$124.20	100.00	\$0.00	Repair	XX
6009988	BODY RH	A01001-CW567	PANEL SIDE R7 FOR MAN A22 BUS	1.00	\$865.50	100.00	\$0.00	Repair	XX
6009989	BODY RH	A01001-CW566	PANEL SIDE R8 FOR MAN A22 BUS	1.00	\$330.70	100.00	\$0.00	Repair	XX
Total					\$1,526.50		\$167.49		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: