



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 28/08/2019

User ID : GohKK2

### Section A - Accident Details

Registration Number	SMB1625B
Case Reference Number	BUS/08/19/7033
Registration Date	13/2/2015
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Zhang Chengshuang
Type of Accident	Side Swipe
Accident Date and Time	27/8/2019 6:52 AM
Accident Reported Date and Time	27/8/2019 9:45 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1625B - RIGHT CENTRE TO REAR PORTION GBD7243A (TP) - INSURED WITH CHINA TAIPING
Prepared Date and Time	28/8/2019 3:24 PM
Chassis Number	VMMAA22Z26F7002611
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$0.00
Total Spray Cost	\$616.00	\$0.00
Total Spare Part Cost	\$133.99	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$133.99	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	Kok Khoo Goh	
ARC / Surveyor Sign Off Date	28/08/2019 3:34 PM	
Signature		<input checked="" type="checkbox"/>
Remarks		

### Section C - Quotation and Accident Invoice Details

Quotation Number	Invoice Number
Quotation Date	Invoice Date
Invoice Amount	Prepared Date

Surveyor Marked estimate  
30/8/19  
Steve (LKK) 28/8/19, 3:09pm  
3 days  
LIS  
RJ AL SH



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/08/2019

User ID : GohKK2

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,325.00	795
Total Labour	\$1,325.00	

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00	528
Total Spray Painting & Panel Beating	\$616.00	

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010303	VE	4001B05-LAM141	LAMP,INDICATOR,SIDE: LED (MAN BUS)	1.00	\$186.10	10.00	\$167.49	Replace	OK
6010330	Body	5029	TRIM,WHEELARCH:FOR MB OC500 LE BUS	1.00	\$124.20	100.00	\$0.00	Repair	OK
6009988	BODY RH	A01001-CW567	PANEL,SIDE:R7,FOR MAN A22 BUS	1.00	\$885.50	100.00	\$0.00	Repair	OK
6009989	BODY RH	A01001-CW568	PANEL,SIDE:R8,FOR MAN A22 BUS	1.00	\$330.70	100.00	\$0.00	Repair	OK
Total					\$1,526.50		\$167.49		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- ~~Parts prices are subject to confirmation~~

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: