

REF: CS/SMO19016214/UTd3<sup>72</sup> Special Instruction:

BY: Marcus  
in (Person): Thelma Choo

ASSIGNMENT (Office)  
of SMD

Date/Time: 12/1/19 @ 5:44pm

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS  
SKS 8950A

Insured: SLD 2001 X

To Inspect Vehicle No:

Tel: 67465405

at Workshop m/s

Fastech Auto

of

1 Kalei Bukit Ave 6 # 01-46

Claim No: CMTD1904314

Policy No: D18MTPV01017166

Excess:

D.O.A. 07/09/2019

Sum Insured:

Make of Veh:

(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Vehicle ☒ IN / OUT

Date/Time: 9:11am @ 13/1/19

Person Contacted:

Alany

Date/Time	Action/Instruction
	<u>SKS 8950A - X</u>
	<u>SLD 2001 X - X</u>
<u>13/1 @ 10:21am</u>	<u>pending estimate sent via compose mail</u>

(08/1/13) web

ASS. REC. BY: *MACOUS*

REF:

*Smo./*

## ASSIGNMENT

From:  
Estimated Cost:

Date:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Rear

R/Bal.

L/Bal.

D.O.I.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Preli. Report

1) 26/9 Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Photos:

Others:

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

TP

11,500

450

11

461

RECEIVED 26 SEP 2019

25/9/19 4/5 @ 11500 continued with ALH. (Red: 59846.21; 83%)

2 TA4608x 545 Sub. net 11915

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Thelma Choo

Date: 26 Sep 2019

**Preliminary Advice**

Insured Vehicle No	: SLD2001X	Accident Date	: 07/09/2019
TP Vehicle No	: SKS8950A	Assignment Date	: 12/09/2019
Make	: VOLKSWAGEN JETTA	Est. Duration of Repair	: 8.00
Date of Inspection	: 12/09/2019		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear and front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	71,346.21
Revised Amount	:S\$	14,430.97
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,430.97
Lump Sum Repair	:S\$	11,500.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Survey on "WP"

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Sep 2019		12 Sep 2019 17:44 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	BORISSIK SVETLANA, ID: S7175649A		
Main Claimant:	RAYMOND KWANG MING CHUAN, ID: S1685378Z		
Vehicle Reg. No.:	SKS8950A	Date of Loss:	07/09/2019 16:00 - :59
Claim Type:	TP / CMTD1904314	Policy/Cover Note No.:	D18MTPV01017186 (Third Party Only)
Vehicle Reg. No. (Insured):	SLD2001X	Policy No. (Claimant):	
		Excess:	
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by <b>Thelma Choo</b> - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/09/2019]		
Driver/Custodian (Insured):	JULIAN LOW (), NRIC: S9639694E, Tel: +6596432428 Email: -		

### ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## View Sent Message

This mail is associated with :

**\*SKS8950A (CMTD1904314)**  
**[SLD2001X]**  
TP  
RAYMOND KWANG MING CHUAN  
Sep 7 2019 4:00PM  
[BORISSIK SVETLANA]  
Fastech Auto Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **13/09/2019 10:21 AM**.  
**To** thelma.choo@sompo.com.sg  
**Subject** **SKS8950A (CMTD1904314) [SLD2001X]**

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SKS 8950A on 12/9/2019  
We are pending estimate from repairer.

Best Regards,  
**Denise Tay** | Case Handler  
**LKK Auto Consultants Pte Ltd**

### DOCUMENTS SUMMARY

There are no documents.

## Get More Cash for Your Car, Post an Ad Today

Receive a higher selling price by selling your car yourself.  
Advertise it for sale at just \$58, list till sold.

[Advanced Search](#)

Home » Used Cars » Precise Auto Trading Pte Ltd » Volkswagen Jetta 1.4A TSI Sportline

### Volkswagen Jetta 1.4A TSI Sportline

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

<b>Price</b>	\$56,800		
<b>Depreciation</b>	\$9,170 /yr <small>View models with similar depre:</small>	<b>Reg Date</b>	13-May-2015 (5yrs 8mths COE left)
<b>Mileage</b>	67,000 km (15.4k /yr)	<b>Manufactured</b>	2014
<b>Road Tax</b>	\$620 /yr	<b>Transmission</b>	Auto
<b>Dereg Value</b>	\$45,666 as of today (change)	<b>OMV</b>	\$19,684
<b>COE</b>	\$67,749	<b>ARF</b>	\$9,684
<b>Engine Cap</b>	1,390 cc	<b>Power</b>	90.0 kW (120 bhp)
<b>Curb Weight</b>	1,417 kg	<b>No. of Owners</b>	1
<b>Type of Vehicle</b>	Mid-Sized Sedan		

#### Features

17" Sports Rims, Original RNS 510 With GPS, Jetta Sports Line, LTA Approved Chrome Matt Rose Gold Wrap, Paddle Shifters. View specs of the Volkswagen Jetta (2011-2017)

#### Accessories

Scuff Plate For 4 Doors, Retro Fitted Head Light, Custom Fit Sun Shade, Interior Blue Cabin Lighting.

#### Description

1 Owner, Never Track Before. Immaculate Condition. Delicate Care By Owner. Regular Maintenance By Owner. Always Parked In Shade. Just Did Major Servicing. Battery Replaced With 1 Year Warranty. Free 1 Servicing Upon Purchase! High Trade In/Bank And In House Loan Available. Viewing Strictly By Appointment

#### Category

PARF Car

#### Status

Available

#### Resources



#### Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



#### Car Valuation - Free

Find out the market value of your existing car for free. Get started



Location Map

[Shortlist](#)

[Compare](#)

[Add note](#)

[Report Error](#)

[More Actions](#)

#### Seller Information

<b>Company</b>	Precise Auto Trading Pte Ltd » dealer's pricelist » 18 vehs sold   34 vehs available
<b>Address</b>	1 Kaki Bukit Avenue 6 #02-34/36 <a href="#">Search cars nearby this location</a>
<b>Location</b>	Autobay @ Kaki Bukit
<b>Contact Person(s)</b>	Feng 91153492

Posted on: 07-Sep-2019 | Last Updated on: 07-Sep-2019

[Upfront Payment Compare](#)

[» more Financial info](#)



## CONNECTING CAR BUYERS &amp; SELLERS.

We'll handle your loans, insurance &amp; other paperwork for FREE.

Find out more



Jetta

Price Range

Depreciation

2015

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Direct Owners » Volkswagen Jetta GP 1.4A TSI

## Volkswagen Jetta GP 1.4A TSI

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

DIRECT OWNER

**Price** \$65,000**Depreciation** \$10,600 /yr  
View models with similar depre**Reg Date** 15-Jun-2015  
(5yrs 9mths 2days COE left)**Mileage** 22,900 km (5.4k /yr)**Manufactured** 2014**Road Tax** \$620 /yr**Transmission** Auto**Dereg Value** \$44,247 as of today (change)**OMV** \$17,864**COE** \$66,590**ARF** \$7,864**Engine Cap** 1,390 cc**Power** 90.0 kW (120 bhp)**Curb Weight** 1,417 kg**No. of Owners** 1**Type of Vehicle** Mid-Sized Sedan

## Features

Powerful And Responsive 1.4L TSI Engine Produce 120Bhp, Fog Lamps. View specs of the Volkswagen Jetta (2011-2017)

## Accessories

Parking Camera/sensors, GPS Navigation, Bluetooth, DVD Player, Radio.

## Description

Only 1 Lady Driver. Non Smoker Pristine/New And Well Maintained Blue Jetta 1.4l. Only Lightly Used, With Mileage 23,000 Kms, Well Maintained And Impeccable Condition. No Eating/Drinking In Car. Regularly Serviced At Vw, Excellent Fuel Efficiency And Superb Pick Up. Note: Direct Seller And Road Tax Paid Until June 2019.

## Category

PARF Car, Direct Owner Sale, Low Mileage Car

## Status

Available

## Resources



## Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



## Car Valuation - Free

Find out the market value of your existing car for free. Get started

Posted on: 05-Sep-2019 | Last Updated on: 12-Sep-2019


Upfront Payment  
Compare

\* more Financial info.

## Seller Information

Contact Person(s)

Anju



Preferred Viewing Area

## Price Chart



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

## &gt; Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 378Z

## Vehicle Details

Vehicle No.: SKS8950A

Vehicle to be Exported: No

Intended Deregistration Date: 12 Sep 2019

Vehicle Make: VOLKSWAGEN

Vehicle Model: JETTA GP 1.4 TSI 90 A/T HL 1634G5

Primary Colour: White

Manufacturing Year: 2014

Engine No.: CAXF19238

Chassis No.: WVVZZZ16ZFM001618

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$19,625.00

Original Registration Date: 13 May 2015

First Registration Date: 13 May 2015

Transfer Count: 0

Actual ARF Paid: \$9,625.00 4812

## Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 12 May 2025

PARF Rebate Amount: \$7,218.00

## Intended COE Rebate Details

COE Expiry Date: 12 May 2025

COE Category: A - Car up to 1600cc &amp; 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$68,589.00

COE Rebate Amount: \$38,867.00

Total Rebate Amount: \$46,085.00

The information contained herein is correct as at 12 Sep 2019

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	09/09/2019 12:41
Date Of Accident	07/09/2019 16:00
Exact Location Of Accident	CTE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS8950A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	RAYMOND KWANG MING CHUAN
NRIC No	S1685378Z
Email Address	RAYMONDKWANGMC@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97455618
Alternative Phone No	OTHERS-97455618

### Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1622255
Cover Note Number	

### Driver

Name of Driver	RAYMOND KWANG MING CHUAN
NRIC No	S1685378Z
Date Of Birth	27/06/1965
Occupation	INDOOR
Date Of Driving Pass	14/09/1988
Driving Experience	30 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97455618
Fax Number	
Contact Number	OTHERS-97455618
Email Address	RAYMONDKWANGMC@GMAIL.COM

Address	BLK 666 YISHUN AVENUE 4 #02-159
Postcode	760666
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : IRENE GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 32 YISHUN ST 81 , POSTCODE: 768456 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8522999 - FAX NO: 68522239
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD2001X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JULIAN LOW
NRIC/Passport Number	S9639694E
Contact Number	96432428
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLR8926P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

CHIANG CHUI CHIOK

NRIC/Passport Number

S1432919F

Contact Number

97980417

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name

IRENE

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

#### DETAILS OF INJURED PERSON 2

Name

RAYMOND KWNAG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available sforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:




9/9/19  
11.00 am

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2

### SKETCH PLAN

<p style="text-align: center;">CAR</p> <div style="text-align: center;">  </div>	<p><u>Vehicle</u></p> <p>A-SKS 8950 A</p> <p>B-SLD 2001X</p> <p>C-SLR 8926F</p> <p><u>Legend</u></p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;">               Vehicle         </div> <div style="text-align: center;">               Motorcycle         </div> </div>
---	---

### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Car C stop, then car A slow down.	
Car B hit car B which	
move forward and hit car C	
Incident happen on 7/9/19	
about 4pm along CTE, just after	
exiting Kampong Jawa tunnel.	
3 cars (A, B & C) were driving at	
lane 1. Traffic was heavy and	
sky was clear.	
Police & ambulance did not attend	
as no one was injured.	
Me & my passenger went to see	
a doctor on 8/9/19 for shoulder &	
neck pain	

### DECLARATION

I/We declare the foregoing particulars are true in every respect.  
 Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against your policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time:

9/9/19  
11.00am

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Not Authorized  
Date  
1/5/11 11500  
807

Qty Particular SKS 8950A

Amount S\$

## List Item:

1 PCS	BOOTLID	
2 PCS	BOOTLID HINGES @\$102.33	
1 PCS	BOOTLID WEATHERSTRIP	
1 PCS	BOOTLID INNER LOCK	
1 PCS	BOOTLID LOCK CATCH	
1 PCS	BOOTLID INNER TRIM	
1 PCS	BOOTLID REAR LOGO	
1 PCS	BOOTLID 'JETTA' EMBLEM	
1 PCS	BOOTLID 'TSI' EMBLEM	
2 PCS	BOOTLID REFLECTORS @\$245.50	
2 PCS	TAILLAMPS @\$385.50	
1 PCS	REAR BUMPER	
1 PCS	REAR BUMPER LOWER SPOILER	
2 PCS	REAR BUMPER REFLECTORS @\$55.35	
1 PCS	REAR BUMPER CENTRE HOLDER	
1 PCS	REAR BUMPER REINFORCEMENT	
1 PCS	REAR BUMPER retain	
2 PCS	REAR BUMPER SIDE RETAINERS @\$61.02	
1 PCS	REAR EXHAUST BOX	
3 PCS	REAR EXHAUST MOUNTINGS @\$58.05	
1 PCS	REAR END PANEL ASSY	
1 PCS	REAR END PANEL TOP GARNISH	
1 PCS	REAR FLOOR PANEL TOP BOARD	
1 PCS	REAR FLOOR PANEL	
1 PCS	REAR FLOOR PANEL TOOL FOAM	
2 PCS	REAR FENDER INNER TRIMS @\$343.81	
8PCS	REAR FENDER INNER TRIM CLIPS @\$5	
2 PCS	REAR FENDERS @\$1105	
1 PCS	BONNET	
2 PCS	BONNET HINGES @\$101.79	
1 PCS	BONNET RUBBER @\$24.00	
1 PCS	BONNET INSULATOR	
1 SET	BONNET INSULATOR CLIPS	
1 PCS	BONNET LOCK	
1 PCS	BONNET LOCK CATCH	
2 PCS	HEADLAMPS @\$5098.50 1100.50 x 2 = 2201.00	
2 PCS	HEADLAMP TOP PANELS @\$89.39	
1 PCS	FRONT GRILLE 485.50	
1 PCS	FRONT GRILLE LOGO	
1 PCS	FRONT GRILLE FRAME	
1 PCS	FRONT BUMPER 1215.32	
1 PCS	FRONT BUMPER NUMBER PLATE GARNISH 60.80	
1 PCS	FRONT BUMPER TOW COVER	
1 PCS	FRONT BUMPER LOWER CENTRE GRILLE	

2	\$	1,668.80	X
17	\$	204.66	X
2w	\$	226.25	
8u	\$	194.45	X
17	\$	37.53	X
17	\$	181.17	X
2u	\$	89.37	
2u	\$	76.11	
2u	\$	57.33	
u1	\$	491.00	X
2u	\$	771.00	
2/20	\$	1,459.25	
2u	\$	531.90	
17	\$	110.70	X
2u	\$	129.05	
2u	\$	514.20	
2u	\$	151.20	
17	\$	122.04	X
17	\$	926.10	X
17	\$	174.15	X
2u/20	\$	938.25	
2u	\$	118.80	
17	\$	378.10	X
17	\$	1,445.00	X
17	\$	163.88	X
17	\$	687.62	X
17	\$	40.00	X
2	\$	2,210.00	X
2	\$	1,245.30	X
17	\$	203.58	X
17	\$	48.00	X
17	\$	219.24	X
17	\$	50.00	X
17	\$	201.42	X
17	\$	46.68	X
2u	\$	10,197.00	
2	\$	178.78	X
2u	\$	708.75	
2u	\$	116.37	
2u	\$	228.42	
20/20	\$	1,445.32	
2u	\$	112.32	
17	\$	30.78	X
2u	\$	227.07	

29356.74

1 PCS	FRONT BUMPER LOWER LID	
2 PCS	FRONT BUMPER FOG LAMPS	@\$113
1 PCS	FRONT BUMPER INNER FRAME	
1 PCS	FRONT BUMPER SPONGE	
1 PCS	FRONT BUMPER REINFORCEMENT	
2 PCS	FRONT BUMPER SIDE RETAINERS	@\$35.91
1 SET	FRONT BUMPER CLIPS	
1 PCS	FRONT SUPPORT PANEL	
2 PCS	FRONT SUPPORT PANEL SIDE GARNISH	@\$51.33
1 PCS	AIRCON CONDENSER	
1 PCS	AIRCON LIQUID PIPE	
1 PCS	AIRCON DISCHARGE PIPE	
1 PCS	AIRCON SUCTION PIPE	
1 PCS	TURBO AIR COOLER	
1 PCS	RADIATOR	
1 PCS	RADIATOR FAN ASSY	
2 PCS	FRONT FENDERS	@\$641.20
2 PCS	FRONT FENDER INNER SHIELDS	@\$166.50
1 PCS	ALTERNATOR	
1 PCS	TURBO CHARGER	
1 PCS	FRONT FENDER INNER PANEL N/S	
1 PCS	AIR CLEANER BOX	
1 PCS	AIR DUCT	
1 PCS	AIRCON COMPRESSOR	
1 PCS	EXHAUST CATERLIC	
1 PCS	TURBO HEAT SHIELD	
2 PCS	FRONT DOORS	@\$1005

List Item Total:

11	\$	531.90	X
one	\$	226.00	—
NS	\$	160.11	X
for	\$	120.52	—
but	\$	579.20	—
11	\$	71.82	X
re	\$	50.00	—
one	\$	901.80	—
11	\$	102.60	X
11	\$	884.25	X
11	\$	696.60	X
11	\$	529.20	X
11	\$	588.30	X
11	\$	857.45	X
11	\$	909.47	X
11	\$	865.92	X
11	\$	1,282.40	X
11	\$	333.00	X
11	\$	1,880.00	X
11	\$	4,800.00	X
11	\$	965.20	X
11	\$	485.30	X
11	\$	115.20	X
11	\$	1,387.83	X
11	\$	2,445.00	X
11	\$	195.20	X
11	\$	2,010.00	X
	\$	62,131.21	

11474.71  
10900.97

Special Nett Item:

1 SET	REAR BUMPER REVERSE SENSOR
1 PCS	REAR END PANEL SEALANT
1 PCS	REAR LICENCE PLATE W/HOLDER
1 PCS	REAR FLOOR PANEL INSULATOR
1 PCS	FRONT LICENCE PLATE W/HOLDER
1 BOL	RADIATOR COOLANT
1 PCS	BATTERY

Special Nett Total:

shold	\$	280.00	200
rec	\$	50.00	—
11	\$	50.00	X
11	\$	300.00	X
sent	\$	50.00	40
re	\$	50.00	30
11	\$	200.00	X
	\$	980.00	

320

Labour Charge:

TOWING CHARGE	
TO CHECK WIRING	
TO DISMANTLE & REPLACE REVERSE SENSOR	
TO TRANSFER BOOTLID MECHANISM	
TO DISMANTLE & REPLACE REAR EXHAUST	
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	
TO SPRAY RUST PROOFING	
TO REFILL AIRCON GAS	
TO DISMANTLE & REPLACE TURBO CHARGE	
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACE PARTS	
TO PUTTY & SPRAY PAINTING	

Labour Charge Total:

11	\$	65.00	X
	\$	100.00	30
	\$	100.00	50
11	\$	100.00	X
11	\$	100.00	X
	\$	120.00	80
	\$	150.00	50
	\$	150.00	100
11	\$	150.00	X
	\$	4,000.00	1400
	\$	3,200.00	500
	\$	8,235.00	

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No (any) modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

320  
14430.87  
11544  
62546.21



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19016214/UTD3N2

Date: 02/10/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01017186
Claimant Vehicle No :	SKS8950A	Insured Vehicle No :	SLD2001X
Date of Loss:	07/09/2019	Nature of Claim:	TP
		Claim No:	CMTD1904314

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SKS8950A	Engine No:	CAXF19238
Make & Model:	VOLKSWAGEN JETTA, 1.4 (A)	Chassis No:	WVWZZZ16ZFM001618
Reg. Date:	13/05/2015 (Man. Year: 2014)	Odometer:	100335 km
Colour:	White		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	54,311.21	11,220.97	43,090.24	79.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,235.00	3,210.00	5,025.00	61.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>62,546.21</b>	<b>14,430.97</b>	<b>48,115.24</b>	<b>76.93</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>11,500.00</b>		
<b>(S\$)</b>	62,546.21	11,500.00	51,046.21	81.61
<b>+ GST 7.00/7.00% (S\$)</b>	4,378.23	805.00	3,573.23	81.61
<b>Nett Amount (S\$)</b>	<b>66,924.44</b>	<b>12,305.00</b>	<b>54,619.44</b>	<b>81.61</b>

## INSPECTION

Date of Assignment:	12/09/2019	
Date Inspected:	12/09/2019	Inspected At:
		Fastech Auto Pte Ltd (HQ)
		1 Kaki Bukit Ave 6, #01-46/48/50
		Autobay
		Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Oct 2019)
<b>Parts:</b>	143	VOLKSWAGEN JETTA 1.4 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKS8950A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,668.80 F	*- FL
2	2		*BOOTLID HINGES	Not Necessary	204.66 F	*- FL
3	1		*BOOTLID WEATHERSTRIP	Twisted	226.25 F	*226.25 FL
4	1		*BOOTLID INNER LOCK	Serviceable	194.45 F	*- FL
5	1		*BOOTLID LOCK CATCH	Not Necessary	37.53 F	*- FL
6	1		*BOOTLID INNER TRIM	Not Necessary	181.17 F	*- FL
7	1		*BOOTLID REAR LOGO	Necessary	89.37 F	*89.37 FL
8	1		*BOOTLID JETTA EMBLEM	Necessary	76.11 F	*76.11 FL
9	1		*BOOTLID TSI EMBLEM	Necessary	57.33 F	*57.33 FL
10	2		*BOOTLID REFLECTORS	Not Necessary	491.00 F	*- FL
11	2		*TAILLAMPS	Cracked	771.00 F	*771.00 FL
12	1		*REAR BUMPER	Dented/Deformed	1,459.25 F	*1,459.25 FL
13	1		*REAR BUMPER LOWER SPOILER	Deformed	531.90 F	*531.90 FL
14	2		*REAR BUMPER REFLECTORS	Not Necessary	110.70 F	*- FL
15	1		*REAR BUMPER CENTRE HOLDER	Cracked	129.05 F	*129.05 FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	514.20 F	*514.20 FL
17	1		*REAR BUMPER RETAINER	Cracked	151.20 F	*151.20 FL
18	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	122.04 F	*- FL
19	1		*REAR EXHAUST BOX	Not Necessary	926.10 F	*- FL
20	3		*REAR EXHAUST MOUNTINGS	Not Necessary	174.15 F	*- FL
21	1		*REAR END PANEL ASSY	Dented/Bent	938.25 F	*938.25 FL
22	1		*REAR END PANRL TOP GARNISH	Twisted	118.80 F	*118.80 FL
23	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	378.10 F	*- FL
24	1		*REAR FLOOR PANEL	Not Necessary	1,445.00 F	*- FL
25	1		*REAR FLOOR PANEL TOOL FOAM	Not Necessary	163.88 F	*- FL
26	2		*REAR FENDER INNER TRIMS	Not Necessary	687.62 F	*- FL
27	8		*REAR FENDER INNER TRIM CLIPS	Not Necessary	40.00 F	*- FL
28	2		*REAR FENDERS	Repair	2,210.00 F	*- FL
29	1		*BONNET	Repair	1,245.30 F	*- FL
30	2		*BONNET HINGES	Not Necessary	203.58 F	*- FL
31	2		*BONNET RUBBER	Not Necessary	48.00 F	*- FL
32	1		*BONNET INSULATOR	Not Necessary	219.24 F	*- FL
33	1		*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
34	1		*BONNET LOCK	Not Necessary	201.42 F	*- FL
35	1		*BONNET LOCK CATCH	Not Necessary	46.68 F	*- FL
36	2		*HEADLAMPS	Cracked	10,197.00 F	*2,201.00 FL
37	2		*HEADLAMP TOP PANELS	Repair	178.78 F	*- FL
38	1		*FRONT GRILLE	Cracked	708.75 F	*485.50 FL
39	1		*FRONT GRILLE LOGO	Cracked	116.37 F	*116.37 FL
40	1		*FRONT GRILLE FRAME	Cracked	228.42 F	*228.42 FL
41	1		*FRONT BUMPER	Dented/Deformed	1,445.32 F	*1,215.32 FL
42	1		*FRONT BUMPER NUMBER PLATE GARNISH	Torn	112.32 F	*60.80 FL
43	1		*FRONT BUMPER TOW COVER	Not Necessary	30.78 F	*- FL
44	1		*FRONT BUMPER LOWER CENTRE GRILLE	Twisted	227.07 F	*227.07 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*FRONT BUMPER LOWER LID	Not Necessary	531.90 F	*- FL
46	2	*FRONT BUMPER FOG LAMPS	Cracked	226.00 F	*226.00 FL
47	1	*FRONT BUMPER INNER FRAME	No such part	160.11 F	*- FL
48	1	*FRONT BUMPER SPONGE	Torn	120.52 F	*120.52 FL
49	1	*FRONT BUMPER REINFORCEMENT	Bent	579.20 F	*579.20 FL
50	2	*FRONT BUMPER SIDE RETAINERS	Not Necessary	71.82 F	*- FL
51	1	*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
52	1	*FRONT SUPPORT PANEL	Cracked	901.80 F	*901.80 FL
53	2	*FRONT SUPPORT PANEL SIDE GARNISH	Not Necessary	102.60 F	*- FL
54	1	*AIRCON CONDENSER	Not Necessary	884.25 F	*- FL
55	1	*AIRCON LIQUID PIPE	Not Necessary	696.60 F	*- FL
56	1	*AIRCON DISCHARGE PIPE	Not Necessary	529.20 F	*- FL
57	1	*AIRCON SUCTION PIPE	Not Necessary	588.30 F	*- FL
58	1	*TURBO AIR COOLER	Not Necessary	857.45 F	*- FL
59	1	*RADIATOR	Not Necessary	909.47 F	*- FL
60	1	*RADIATOR FAN ASSY	Not Necessary	865.92 F	*- FL
61	2	*FRONT FENDERS	Repair	1,282.40 F	*- FL
62	2	*FRONT FENDER INNER SHIELDS	Not Necessary	333.00 F	*- FL
63	1	*ALTERNATOR	Not Necessary	1,880.00 F	*- FL
64	1	*TURBO CHARGER	Not Necessary	4,800.00 F	*- FL
65	1	*FRONT FENDER INNER PANEL N/S	Not Necessary	965.20 F	*- FL
66	1	*AIR CLEANER BOX	Not Necessary	485.30 F	*- FL
67	1	*AIR DUCT	Not Necessary	115.20 F	*- FL
68	1	*AIRCON COMPRESSOR	Not Necessary	1,387.83 F	*- FL
69	1	*EXHAUST CATERLIC	Not Necessary	2,445.00 F	*- FL
70	1	*TURBO HEAT SHIELD	Not Necessary	195.20 F	*- FL
71	2	*FRONT DOORS	Not Necessary	2,010.00 F	*- FL
72	1	*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
73	1	*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
74	1	*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
75	1	*REAR FLOOR PANEL INSULATOR	Not Necessary	300.00 FS	*- FS
76	1	*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
77	1	*BOL RADIATOR COOLANT	Necessary	50.00 FS	*30.00 FS
78	1	*BATTERY	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>54,311.21</b>	<b>11,794.71</b>
<b>- List Item Discount on L Items 0.00/5.00% (\$\$)</b>	<b>0.00</b>	<b>573.74</b>
<b>Total Parts (\$\$)</b>	<b>54,311.21</b>	<b>11,220.97</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING CHARGE	New	65.00	0.00
2	TO CHECK WIRING	New	100.00	30.00
3	TO DISMANTLE & REPLACE REVERSE SENSOR	New	100.00	50.00
4	TO TRANSFER BOOTLID MECHANISM	New	100.00	0.00
5	TO DISMANTLE & REPLACE REAR EXHAUST	New	100.00	0.00
6	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	120.00	80.00
7	TO SPRAY RUST PROOFING	New	150.00	50.00
8	TO REFILL AIRCON GAS	New	150.00	100.00
9	TO DISMANTLE & REPLACE TURBO CHARGE	New	150.00	0.00
10	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACE PARTS	New	4,000.00	1,400.00
11	TO PUTTY & SPRAY PAINTING	New	3,200.00	1,500.00
<b>Gross Labour Cost (S\$)</b>			<b>8,235.00</b>	<b>3,210.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;