Transfer and the second				376.	A Real Property and the second	
11.de la 16/9/19 11:58	Jeb descripti	on	Date &Time Con	plated	Done b	Ņ
Kellin My 1MS 619016291/h4	SAS c-Illin	g	1	1		
Vehille GRE 187 U	E-mall (win	in flux, AIC 2hrs)				
11114 1419/19 13:05	I-Motor Cl	alm Form	4.			
(21) (D' Reporting Only	I-Motor W	O (Within: OD 2hrs	Tr (bis)			
	i-Photo Up	loaded	1			
TP Insurer	Assessment/	Survey Report				
	Ass't Report	by Fax/Hand to	Owner/Wksp		****	ertical.
Proformd Wksp / INC Assign Wksp / GW; (To provide the contract of the		Tel:	Fax	:	
TP Particulars: Veh No:	YP 9985T	INC(.)/Non-INC().		
Owner / Driver: (Tel:)	
	riod: ()	Cover Type: (_
Confirmed by : (Date:	Time:)	
			%; P: 21-79%. I	': 80-100	Va]	
	Varranty: YES ()/NO())			_
THE STATE OF THE PROPERTY OF THE SHARE SHA	THE PARTY OF THE PROPERTY OF	Pierra property and the property		-		****
Sence at Reinbulgues 在美国组织设计,是是国际	A SHEET SHEE	at may in an and a	EXPERIMENTAL SE	1. Zamer	m A Comment	
() Walk-In Customer : Customer's infor	mation strictly Co	ontidential & Strie	ctly NO refer of rep	olier.		
() Total Loss Case : to e-mail Insurer		The second secon	N 1			7/17/
Drive-In ()/Towed-In (); Invoice:	YES()/	NO();To	wing Co: (· ,	,)
Commenses (in Companies 6708/16616) \$2		MUSEUM STREET,	THE PROPERTY OF THE PROPERTY O	VIPWEY3	STREET STREET	(FILLES)
	Property of the Park Property of the Park	NAMES OF STREET	Paire de sen uses ann a		Stratistics of	
11 Co		1	200 (0.85) (28)			
The state of the s	ourtesy Car ()			Made and Wallet	
2) QC Check / Post Repair Inspection	()	***			
QC Check / Post Repair Inspection Upload Resurvey Photo [Repair Cost > \$30]	()	***			
2) QC Check / Post Repuir Inspection	()				
P) QC Check / Post Repair Inspection D) Upload Resurvey Photo [Repair Cost > \$30 Injury:	()			eg at.	
2) QC Check / Post (Repair Inspection 1) Upload Resurvey Photo [Repair Cost > \$30 Injury:	()			en de la companya de	NG.
(2) QC Check / Post Repair Inspection (1) Upload Resurvey Photo [Repair Cost > \$30 (Injury :	(onder in the second	NA. T.
(2) QC Check / Post Repair Inspection (1) Upload Resurvey Photo [Repair Cost > \$30 (Injury :	()			er e	N(-)
QC Check / Post Repair Inspection Upload Resurvey Photo [Repair Cost > \$30 Injury:	()			Maria Principal Control of the Contr	No.
QC Check / Post Repair Inspection Upload Resurvey Photo [Repair Cost > \$30 Injury:	(Olechian.	70-1
OC Check / Post Repair Inspection Upload Resurvey Photo [Repair Cost > \$30 Injury : att/Times (Wetton) separate (2) (2) (2) (2) (2) (2) (2) (2) (2) (2)	())			And (S) P. A.	
QC Check / Post Repuir Inspection Dipload Resurvey Photo [Repair Cost > \$30 Injury: Actions (Actions)	(involge firm			Ani((S))	
OC Check / Post Repair Inspection Deployed Resurvey Photo [Repair Cost > \$30 Injury : MAI Thronic Particulars and Actions	()	invojeciji, in		NC (380)	STATE IN	
OC Check / Post Repair Inspection Deployed Resurvey Photo [Repair Cost > \$30 Injury : MAI Thurst Particular Size Particular Size Ver/Owner:	()	1) AR ; Acadent Re 2) DA ; Damego As 3) TP ; Towing Pee 4) PT ; Follow-Thro	aussment (5100); 1	\$40/\$43 \$120	STATE IN	
OC Check / Post Repair Inspection Dupload Resurvey Photo [Repair Cost > \$30 Injury : MAI Chamber Particular Size Si	()	1) AR : Academ Re 2) DA : Damego As 3) TP : Towing Pee 4) PT : Pollow-Thro For claiming again	estiment (5100); 1 agh Survey agh Survey (Resurvey) astING Only (wef10 Is	\$40/\$43 \$120 \$30 01.2993)	STATE IN	
Open Repair Inspection Deploy Resurvey Photo [Repair Cost > \$30 Injury : MAI Thronic Particulars and Advantage A	()	1) AR: Academike 2) DA: Damego As 3) TF: Towing Fee 4) FT: Follow-Thro Forolaiming agai 6) TR: Re-inspection	estiment (5100); 1 agh Survey agh Survey (Resurvey) astING Only (wef10 I: a	\$40/\$43 \$120 \$30 01.2992) \$73	STATE IN	
Open Repair Inspection Deploy Resurvey Photo [Repair Cost > \$30 Injury : MAI Thronic Particulars and Advantage A	()	1) AR : Academ Re 2) DA : Damego As 3) TP : Towing Pee 4) PT : Pollow-Thro For claiming again	estement (5100); 1 ugh Survey ugh Survey (Resurvey) ust1NG Only (wef10 I: n MRT Survey	\$40/\$43 \$120 \$30 01.2993)	3	
OC Check / Post Repair Inspection Dupload Resurvey Photo [Repair Cost > \$30 Duploy : MAL Humanthe Particular Street Ver/Covner: Diagral Portion:	()	1) AR: Academike 2) DA: Damego As 3) TF: Follow-Thro 5) FT: Follow-Thro Farolaiming agai 6) TR: Re-impectio 7) NI: Idao DA + S 5) NTUC Additions OD:	agh Survey agh Survey (Resurvey) sating Only (wefit) n MRT Survey	\$40/\$43 \$120 \$30 01/20(2)) \$73 	3	
OC Check / Post Repair Inspection Diploid Resurvey Photo [Repair Cost > \$30 Diploy : MAL Thring Particulars (1) Forest No: Diged Portion:	()	1) AR : Academ Re 2) DA : Damego As 3) TP : Follow-Thro 5) PT : Follow-Thro Forolaiming stal 6) TR : Re-inspectio 7) NI : Idao DA + S 5) NTUC Additions OD2 *NS: Courtasy Co- *NS: Repair Co-o	agh Survey agh Survey (Resurvey) agh Survey (Resurvey) astING Only (wef10 Is a MRT Survey Services:-	\$40543 \$120 \$30 \$2093) \$75 \$160 \$510	3	
2) QC Check / Post Repair Inspection 1) Upload Resurvey Photo [Repair Cost > \$30 Injury: Oute/Times Cartier Section (Cartier Cost > \$30)	()	1) AR : Academ Re 2) DA : Damego As 3) TF : Follow-Thro 5) FT : Follow-Thro For claiming stal 6) TR : Re-impactio 7) NI : Idae DA + S 8) NTUC Additiona OD. *NS: Courtesy Ca *NS: Repair Co-o *NS: Post Repair	agh Survey agh Survey (Resurvey) biting Only (weffo is m MRT Survey Services: //Tpt Allowance chination	\$40543 \$120 \$30 0(2093) \$75 \$160 \$51 \$51 \$510 \$75	3	
2) QC Check / Post Repair Inspection 1) Upload Resurvey Photo [Repair Cost > \$30 Injury : Oute/Times CWetton Section	()	1) AR: Academike 2) DA: Damego As 3) TF: Follow-Thro 5) FT: Follow-Thro Forolaiming agai 6) TR: Re-impectio 7) NI: Idae DA + S 8) NTUC Additions OD: *N5: Courtesy Co- *N6: Repair Co-o *N7: Post Repair *N8: DV / Collect TP (N11): TP (N	agh Survey agh Survey (Resurvey) agh Survey (Resurvey) astING Only (wef10 Is a MRT Survey Services: //Tpt Allowence relination inspection t Excess Coordination on INC) against INC	\$40543 \$120 \$30 0(2093) \$75 \$160 \$35 \$10 \$73 \$33 \$33	3	
2) QC Check / Post Repair Inspection 1) Upload Resurvey Photo [Repair Cost > \$30 Injury : Date/Fine Professional Profes	()	1) AR : Anddent Re 2) DA : Danier The 3) TF : Follow-Thro For olaiming arai 6) TR : Re-inspectio 7) NI : Idae DA + S 5) NTUC Additions OD: *NS: Courtosy Ca *NS: Repair Co-o *NS: Post Repair *NS: DV / Collect	agh Survey agh Survey (Resurvey) agh Survey (Resurvey) astING Only (wef10 Is a MRT Survey Services: //Tpt Allowence relination inspection t Excess Coordination on INC) against INC	\$40543 \$120 \$30 0(2093) \$75 \$ \$160 \$75 \$19 \$75 \$33 \$20 30	3	delib

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
Consideration and a second second second	ACCIDENT STATEMENT
Date Of Report	16/09/2019 11:58
Date Of Accident	14/09/2019 13:05
Exact Location Of Accident	CHOA CHU KANG AVE 3 TWDS BRICKLAND RD
Country/State of Loss	SINGAPORE
D	DETAILS OF OWN VEHICLE
Vehicle Registration Number	GBE187U
Insured/Policyholder	
Name Of Registered Owner	YSE GLOBAL PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66610680
Vehicle Particulars	
Manufacturer	ТОУОТА
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 29003945 MKC
Cover Note Number	
Driver	
Name of Driver	NG HOCK SENG
NRIC No	S1782357D
Date Of Birth	05/08/1966
Occupation	OUTDOOR
Date Of Driving Pass	19/09/1986
Driving Experience	32 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91112351
Fax Number	
Contact Number	

NOEMAIL

BLK 404 JURONG WEST ST 42 #07-563 Address

Postcode 640404

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED Type Of Accident

CLEAR Weather Conditions Road Surface DRY

Other Information

NO Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

involved in the accident

2 NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

YES

NO

1 Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

YES

If Yes Please state which Police Station

Police Station Name

JURONG WEST NEIGHBOURHOOD POLICE CENTRE

ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: Police Station Address

SINGAPORE

TEL NO: 1800-2689999 - FAX NO: 62672438 Police Station Contact

Was notice of intended Prosecution given?

If Yes, against whom?

NO

Circumstances of Accident

REFER TO POLICE REPORT T/20190914/2102

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO NO Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

YP9985T Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

COMMERCIAL VEHICLE Vehicle Category HOSSEN MD KAOSER Name of Driver

G8312750W NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) Involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

* OF ORA

Policyholder's Signature Date & Time: 1

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature

NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

		,		
Refer	10	Police	Report	T/2019 0914 /210
				3

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signata Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:





1 of 3

Report No. T/20190914/2102

Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No: 1800-2689999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/09/2019 15:12		Vide Report No.:	Station Diary No. 169		
Informa	nt's Partic	ulars	THE PERSON NAMED IN COLUMN 2 ASSESSMENT		
Name of Informant: NG HOCK SENG		Address: APT BLK 404 JURONG WEST STREET 42 #07-563 SINGAPORE 640404			
ID Type / ID No.: NRIC NO / S1782357D		Contact No.: Home/Office: Mobile: 91112351			
National SINGAP	ity: ORE CITIZ	EN	Email:		
Sex: Male	Age: 53	Date of Birth: 05/08/1966	Type of Informant: Driver		
Race: Chinese		Language:	Institution / School Name:		
Occupation: Maintainence Officer		Driving Licence Information: Class: 3,4,5 Date of Expiry:			

General Infor	mation of the Accide	ent		
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 14/09/2019 13:05	Type of Location: T-Junction
Location: Along Road 1 CHOA CHU F Towards Bric Weather:	KANG AVENUE 3	Road Surface:		Road Speed Limit:
Clear		Dry		
Traffic Flow: Traffic Control: One Way Not Controlled			Traffic Volume: Moderate	
Type of Collis	sion: ring Vehicles - Head ⁻	Γο Rear		Anyone conveyed by ambulance:

Details of Vehicle Involved							
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger	
GBE187U	Lorry	ТОУОТА	TOYOTA DYNA 150 MANUAL	White	Slightly Damaged	0	
YP9985T	Lorry	ISUZU	NNR85UH4 A AMT	Blue	Slightly Damaged	2	

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





T/20190914/2102

2 of 3

Report No. T/20190914/2102

Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818

Tel No: 1800-2689999

CONTINUATION OF REPORT

Driver						
Name	NG HOCK SENG			ID No		S1782357D
Related Vehicle	GBE187U (Lorry)			Conta	ct No.	91112351
Hospital/Clinic	NIL					Class: 3,4,5 Date of Expiry: NIL
Date Treatment	NIL	000	Date Disc	harge	NIL	
No. of Days granted Medical Leave NIL		NIL	Degree of	Injury	NIL	
PRICATE STATE	HOSSEN MD KAOS	CED.	HINESONE BUREAU	ID No		G8312750W
Name	HOSSEN MID KAOS	DEK		ID NO		3001270011
Related Vehicle	YP9985T (Lorry)			Contact No.		NIL
Hospital/Clinic	NIL			Class Drivin Licent Expiry	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL Date Dis			-	NIL	
No. of Days gran	lo. of Days granted Medical Leave NIL			Degree of Injury NIL		

Brief Details.

On 14092019 at about 1305hrs I was driving my vehicle GBE187U along Choa Chu Kang Avenue 3. At the point of time my vehicle was stationery waiting for the traffic light to turn green. Suddenly, there was a vehicle YP9985T in front of me reversing and collided onto my front bumper. I alighted and made a check on my vehicle. My front bumper was dented and my left mirror was damaged. There was no traffic police and ambulance at scene. I wish to state that I got no in car camera in my vehicle. I am lodging this report for record purposes.





3 of 3

Report No. T/20190914/2102

Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No: 1800-2689999 CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / Sgt 1 LIM FANG JIE	Signature Of Informant:	
Signature Of Interpreter: Not applicable	Date/Time: 14/09/2019 15:12	
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:	



MSIG Insurance (Singapore) Pte. Ltd. 4 Sheaton Way, # 21 of SCX Centre 2, Salgapore (16680.) Let 65 6827 7250 Fax +65 6827 7800 Co Reg No 2004+2212C - CS7 Reg No 20-0442212S

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)

(REPUBLIC OF SINGAPORE)

THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE). OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M 2 300

COMMERCIAL VEHICLE

doese the William Wallette - Sah J

Comprehensive

Certificate No. A 29003945 MKC

Excess: SGD600

1. Index Mark and Registration Number of Vehicle

GBE187U

Name of Policyholder

YSE Global Pte. Ltd.

3. Effective Date of the Commencement of Insurance for the purposes of the Act

18/06/2019

4. Date of Expiry of Insurance

17 08/2020

5. Persons or Classes of Persons entitled to drive

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

• Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use"

the in connection with the Policyholder's business.
Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.

Use for social domestic and pleasure purposes.

The Policy does not cover

(1) Use for nire or reward or for racing pace making reliability total

or speed testing.

(2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd. Approved Insurers

for Chief Executive Officer