

ASS. REC. BY:

REF:

CS / SPF 19016302 / Fyd311

Special Instruction:

Surveyor: Ram

## ASSIGNMENT (Office)

From (Person):

Hafizul Farhan

of

SPF

Date/Time:

16/9/10 @ 12.19pm

Estimated Cost:

Bill to:

CD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

FBN 7374C

Insured:

QX 852E

1 Workshop m/s

Tachyon Motor

Tel:

6783 19

if

Blk 9004 Tampines St. 93 # 01-108

Policy No:

Claim No:

AEMD/105/009/2019/093

Sum Insured:

Excess:

Make of Veh:

Client's Record)

D.O.A.

07/09/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12.47pm 16/9/10

Person Contacted:

Lun

Vehicle

IN

OUT

Date/Time

Action/Instruction

Johnny

✓

FBN 7374C - X

QX 852E - X

Do Not Finalise

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBN 7374C

at Workshop m/s TACHYON MOTORS

of BIK 9004 Tampines St 93 #01-108

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBN 7374C

Yr Regn: Dec / 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda CB190X

C.C. 184

Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No: -

C/No: LWBPC118J100393

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/70 R17

R: 140/70 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CST

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

-

mm

L/Bal.

-

mm

D.O.A.

07/09/2019

D.O.I. 16/09/2019

Survey held at

tachyon motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt / O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range: \$2000-\$3000

Repair days: 4 days Oweekend

DARS: completed

MV: \$7800

PV: \$2753

NV: \$5000\*

Amount \$2200-00 (Red \$1854-10, 45%)

RECEIVED 06 NOV 2019

Do Not Finalise

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

4

Resurvey No. of Trip:

2

1)

☐

Final Report

Date/Time, File Return to?

2)

6/11/19 Typist

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$) 2200f

Survey Fee:

220

Transportation:

) \$ + RS, \$

) Photos

) Others

TOTAL

220

**Nivitha (LKK Auto)**

---

**From:** Hafizul Farhan RAHMAT (SPF) <Hafizul\_Farhan\_RAHMAT@spf.gov.sg>  
**Sent:** Monday, 16 September 2019 12:19 PM  
**To:** Admin-D (LKKAuto)  
**Cc:** Frankie THAY (SPF); SUR; assignments  
**Subject:** Pre-Repair survey of FBN 7374C (vs QX852E DOA: 7/9/2019)

*Message Classification: Unclassified*

Our ref: AEMD/105/009/2019/093

Hi,

Kindly conduct pre-repair survey of FBN 7374C at:

**Taehyon Motor**  
**Blk 9004 Tampines Street 93**  
**#01-108**  
**Singapore 528838**  
**Tel: 6783 1948**

*Best Regards,*

*Hafizul Farhan Bin Rahmat*  
*AEMD / PLD*  
*Singapore Police Force*  
*DID: (65) 6478 4840 | FAX: (65) 6478 4850*



**WARNING** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/09/2019 11:02
Date Of Accident	07/09/2019 10:10
Exact Location Of Accident	SLE BEFORE LENTOR AVE EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBN7374C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MUHAMMAD FAIZ BIN ROZALI
NRIC No	S9124832H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82929527
Alternative Phone No	OFFICE-82929527

### Vehicle Particulars

Manufacturer	HONDA
Model	CB190X
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	DMMPHQ18-001015
Cover Note Number	

### Driver

Name of Driver	MUHAMMAD FAIZ BIN ROZALI
NRIC No	S9124832H
Date Of Birth	22/07/1991
Occupation	INDOOR
Date Of Driving Pass	11/05/2015
Driving Experience	4 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82929527
Fax Number	
Contact Number	OFFICE-82929527
EEmail Address	NOEMAIL

Address	BLK 543 WOODLANDS DR 16 #02-15
Postcode	730543
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NURRAIFANA BINTE JAMIL GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	T20190907/0724
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX852E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name MUHAMMAD FAIZ BIN ROZALI

Approximate Age

Injuries Sustain

Injured person in which vehicle? FBN7374C

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

#### DETAILS OF INJURED PERSON 2

Name NURRAIFANA BINTE JAMIL

Approximate Age

Injuries Sustain

Injured person in which vehicle? FBN7374C

Were seat belts worn?


Was this injured conveyed to hospital by ambulance?

Address

Postcode

# Sketch Plan Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 07/09/2019 at about 1010 hrs, I (FBN7374C) together with my wife as my pillion was travelling on CTE/SLE, making our way to Punggol from Woodlands. The incident happened before Lentar Ave exit.

The condition of the road was congested and vehicles were moving slow as there was an accident happening on SLE.

As I was riding on the second last lane, there was a vehicle from the left most lane, changing lanes & into ours. With half of its body already into our lane. I maneuvered to the left side as it was too near to me. I was not speeding at all.

Then a police car (Q2852E) from behind me knocked onto the rear bumper of my motorcycle. I swerved, fell and skidded all the way to the road shoulder.

The officer, SSG 122at, came out of the vehicle and raised his voice at me, claiming that i was riding out on the road shoulder. But I was not. He also claim that he was on his way to attend the accident in front. There was no siren and blinkers on.

Ambulance was at scene, my wife and I were conveyed to KTPH. Both of us gotten 5 days MC from 07/09/2019 to 11/09/2019

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

10/09/19 / 1230 HRS

GIARMC SketchPlanForm V3

Driver's Signature

(If driver is not the policyholder)

Date & Time:

COMFORTDELGRO ENGINEERING PTE LTD

EXTERNAL BUSINESS DIV, UBI BRANCH

NAME & SIGNATURE: \_\_\_\_\_

DESIGNATION: \_\_\_\_\_ DATE: \_\_\_\_\_

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

10/09/19 / 12.30 hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	832H
<b>Vehicle Details</b>	
Vehicle No.:	FBN7374C
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Sep 2019
Vehicle Make:	HONDA
Vehicle Model:	CB190X MANUAL
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	WH161FMK18J00350
Chassis No.:	LWBPCL1A8J1003938
Maximum Power Output:	-
Open Market Value:	\$2,936.00
Original Registration Date:	05 Dec 2018
First Registration Date:	05 Dec 2018
Transfer Count:	1
Actual ARF Paid:	\$441.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	04 Dec 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$2,989.00
COE Rebate Amount:	\$2,753.00
<b>Total Rebate Amount:</b>	<b>\$2,753.00</b>

The information contained herein is correct as at 18 Sep 2019

OK

Advertisement

[Home](#) [Motorbikes](#) [Motorbikes for Sale](#) [Class 2B](#)

muesleebar

★★★★★ 58

Chat

Make  
Offer

Advertisement

S\$8,000

📌 Share

❤️ 56

## Honda CB190X Tourism black with side and TOP box

📍 Bukit Batok MRT Station (NS2)

🕒 Mailing - Meetup

📌 Used

Selling due to LOW usage as daily ride to work  
and back is less than 10km and family concerns.  
NOT LOOKING TO TRADE.

Full cash payment or self arrange loan. All fees  
to be handled by buyer.  
Mileage is about 3300km

1st owner. No accidents or bumps.  
Bike bought in MARCH 2018, bike is only 1yr  
4months old.  
Number plate: FBM xxxx E  
COE till 30th March 2028  
Road tax renewed.

Well maintained at every 1000km. Washed  
regularly and parked in shelter daily.

Includes:  
TOP box 48L  
SHAD 23 side boxes  
Black grey Camo wrapped crash bar  
Rim tape applied  
Carbon fibre wrapped the exhaust.

PM to deal.

1 month ago In Class 2B



**TACHYON MOTOR PTE LTD**

Blk 9004 Tampines St 93

#01-108 Singapore 528838

Tel:67831948

Fax:67834013

Email: tyt\_tak@hotmail.com

**ASSESSMENT FOR REPAIR : FBN7374C**

<u>S/N</u>	<u>Description</u> <u>Material</u>	<u>Qty</u>	<u>Quotation</u>
✓1	FUEL TANK COVER	1pc	235.00 scr ✓ \$210
✓2	HANDLE BAR	1 pc	110.00 ?Xnn
✓3	BALANCER RH	1 pc	55.00 scr ✓ \$20
✓4	BRAKE LEVER	1 pc	65.00 cut ✓ \$20 30
✓5	MIRROR RH	1 pc	55.00 scr ✓ \$30
✓6	BRAKE PEDAL	1 pc	86.00 BT ✓ \$40 5
✓7	FR FOOTREST RH	1 pc	55.00 scr ✓
✓8	HAND GUARD RH	1 pc	140.00 cut ✓ \$90
✓9	WINSCREEN	1 pc	195.00 scr ✓ 3100
✓10	FR SIGNAL RH	1 pc	98.00 scr ✓ \$55
✓11	HEAD LIGHT LOWER FAIRING	1 pc	220.00 cut ✓
✓12	HEAD LIGHT SIDE FAIRING RH	1pc	120.00 cut ✓
✓13	SIDE COVER RH	1pc	220.00 cut ✓
14	EXHAUST PIPE	1pc	960.00 BT ✓ 750
15	EXHAUST COVER FRONT	1pc	85.00 scr ✓ \$45
16	EXHAUST COVER REAR	1pc	90.00 cut ✓ \$75
17	REAR MUDGUARD	1SET	260.00 BT ✓ \$140
			3,049.00 \$2209.00 153
LESS 10%			-304.90 220.9
			2,744.10 \$1984.50
FRONT & REAR NUMBER PLATE			30.00 nec ✓
GIVI BOX			380.00 scr ✓ \$350
FORK ALIGNED			180.00 xnn ✓
REAR FRAM ALIGNED			280.00 xnn ✓
TRANSPORT CHARGES			60.00 xnn ✓
LABOUR CHARGES			380.00 \$300

TOTAL

4,054.10

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram(LKK)

88622778

4 repair days

L/S

LIST Item : \$1984.50

Labour : \$780

Total : \$2764.5

aft 20% L/S : \$2200.00

## Motorcycle

Vehicle No: FBN 7374C

NAC	INC	Item	CON	AC	Qty
3001	991886	Front Number Plate			
3001	995065	Front Tyre			
3002	995095	Front Rim			
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard			
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy			
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork Bracket			
3011	991182	Front Fork Oil Seal			
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp <i>lower</i>	<i>cut</i>		
3015	992337	Front Headlamp Bracket			
3016	992345	Front Headlamp Fairing <i>(side)</i>	<i>cut</i>		
3017	992130	Front Windshield	<i>scr</i>		
3018	992134	Front Wing Mirror	<i>scr</i>		
3019	995245	Front LH Signal Lamp			
3020	995246	Front RH Signal Lamp	<i>scr</i>		
3021	992556	Meter Casing			
3022	992553	Meter Assy			
3023	991019	ERP Bracket			
3024	991020	ERP Unit			
3025	992446	Ignition Switch			
3026	992442	Ignition Key Assy			
3027	990706	Cowling Stay			
3028	994470	Steering Stem			
3029	994427	Steering Cone			
3030	992299	Handle Bar			
3031	992312	Handle Bar Switch			
3032	992310	Handle Bar Grip			
3033	995184	Handle Bar Balancer LH			
3034	992300	Handle Bar Balancer RH	<i>cut</i>		
3035	992179	Fuel Tank <i>cover</i>	<i>scr</i>		
3036	990438	Brake Reservoir			
3037	990621	Clutch Lever			
3038	992293	Hand Brake Lever	<i>cut</i>		
3039	991119	Side Fairing	<i>cut</i>		
3040	994220	Side Fairing Top Garnish			
3041	994219	Side Fairing Inner Garnish			
3042	991118	Fairing Shield			
3043	992047	Front Top Fairing Inner Garnish			
3044	991123	Fairing Top Garnish			
3045	990538	Center Fairing			
	993378	Rear Fairing			
	991121	Fairing Stopper			
	991117	Fairing Lower			

NAC	INC	Item	CON	AC	Qty
3046	995074	Radiator			
3047	992738	Radiator Cowling			
3048	994146	Seal Assy			
3049	990915	Engine Crash Bar			
3050	990928	Engine Guard			
3051	990219	Battery			
3052	990224	Battery Cover			
3053	990223	Battery Bracket			
3054	991144	Foot Brake	<i>BT</i>		
3055	991154	Front Foot Rest	<i>cut</i>		
3056	991779	Front Foot Rest Bracket			
3057	994269	Side Stand			
3058	992549	Main Stand			
3059	990615	Clutch Engine Cover			
3060	992478	Kick Starter Rubber			
3061	992477	Kick Starter Lever			
3062	991145	Foot Gear Shifter			
3063	993500	Rear Foot Rest			
3064	993501	Rear Foot Rest Bracket			
3065	992581	Exhaust Muffler Heat Shield	<i>scr</i>		
3066	991058	Exhaust PIPE	<i>BT</i>		
3067	993719	Rear LH Shock Absorber			
3068	993720	Rear RH Shock Absorber			
3069	995065	Rear Tyre			
3070	991200	Rear Rim			
3071	994872	Rear Tyre Rim Spoke			
3072	993474	Rear Fender Wheel Guard	<i>cut</i>		
3073	993443	Rear Fender Mudflap	<i>BR</i>		
3074	992940	Rear Brake Disc			
3075	992936	Rear Brake Caliper			
3076	995236	Rear Spocket			
3077	990585	Chain			
3078	990580	Chain Guard			
3079	994530	Swing Arm			
3080	993819	Rear Sub frame			
3081	995245	Rear LH Signal Lamp			
3082	995246	Rear RH Signal Lamp			
3083	995251	Rear Taillamp			
3084	993626	Rear Number Plate	<i>DO</i>		
3085	994192	Side Box			
3086	992927	Rear Box	<i>scr</i>		
3087	992928	Rear Box Bracket			
3088	991328	Emblem			
3089	990247	Sticker			
		FRT RH LENS PROTECTOR	<i>DO</i>		
		FUEL TANK COWLING	<i>scr</i>		

No of Items: \_\_\_\_\_

Assessor: \_\_\_\_\_



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19016302/Fyd3e2	
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333 ATTN : HAFIZUL FARHAN		Date : 20-11-2019	
		Code : SPF	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
	Insured Veh.	QX 852E	Veh. Inspected
			FBN 7374C
	Policy No.		Coverage (\$)
			0.00
	Claim No.	AEMD/105/009/2019/093	Excess (\$)
			0.00
	Assign From	HAFIZUL FARHAN	Assign Date
			16/09/2019
<b>2. Vehicle Particulars &amp; Condition</b>			
	Make & Model	HONDA CB190X	c.c
			184
	Engine No.	HIDDEN	Year of Reg.
			2018
	Chassis No.	LWPCL1A8J1003938	Colour
			BLACK
	Odometer	-	Steering
			IN ORDER
	Brakes	IN ORDER	Modification
			SPORTS RIM
	General	FAIR	
<b>3. Conditions of Tyres</b>			
		Size	Make
			Balance
	R/H Front Tyre	110/70 R17	CST
			4 mm
	L/H Front Tyre		
			mm
	R/H Rear Tyre	140/70 R17	CST
			4 mm
	L/H Rear Tyre		
			mm
<b>4. Description of Damages</b>			
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION.		
	DAMAGES SEE DETAILS.		
<b>5. General Information</b>			
	Accident Date	07/09/2019	Inspection Date
			16/09/2019
	Survey held at	TACHYON MOTOR PTE LTD	
		BLK 9004 TAMPINES ST.93	
		#01-108 SINGAPORE 528838	
<b>5a. Remarks</b>			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.		
	B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
<b>5b. Estimate Days of Repair</b>			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 7374C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FUEL TANK COVER	SCRATCHED	235.00	210.00
1	HANDLE BAR	NOT NECESSARY	110.00	-
1	BALANCER RH	SCRATCHED	55.00	20.00
1	BRAKE LEVER	CUT	65.00	30.00
1	MIRROR RH	SCRATCHED	55.00	30.00
1	BRAKE PEDAL	BENT	86.00	45.00
1	FRT FOOTREST RH	SCRATCHED	55.00	55.00
1	HAND GUARD RH	CUT	140.00	90.00
1	WINDSCREEN	SCRATCHED	195.00	100.00
1	FR SIGNAL RH	SCRATCHED	98.00	55.00
1	HEAD LIGHT LOWER FAIRING	CUT	220.00	220.00
1	HEAD LIGHT SIDE FAIRING RH	CUT	120.00	120.00
1	SIDE COVER RH	CUT	220.00	220.00
1	EXHAUST PIPE	BENT	960.00	750.00
1	EXHAUST COVER FRONT	SCRATCHED	85.00	45.00
1	EXHAUST COVER REAR	CUT	90.00	75.00
1	SET REAR MUDGUARD	BROKEN	260.00	140.00
	LESS 10% DISCOUNT		-304.90	-220.50
			2,744.10	1,984.50
<b>SPECIAL NETT ITEMS</b>				
1	SET FRONT & REAR NUMBER PLATE (SN)	NECESSARY / BENT	30.00	30.00
1	GIVI BOX (SN)	SCRATCHED	380.00	350.00
			410.00	380.00
<b>LABOUR</b>				
	FORK ALIGNED.		180.00	100.00
	REAR FRAM ALIGNED.	NOT NECESSARY	280.00	-
	TRANSPORT CHARGES.	NOT NECESSARY	60.00	-
	LABOUR CHARGES.		380.00	300.00
			900.00	400.00
<b>GRAND TOTAL</b>			<b>4,054.10</b>	<b>2,764.50</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,200.00</b>
---	--	--	-----------------

Report Ref No. CS/SPF19016302/Fyd3e2



Report Ref No. CS/SPF19016302/Fyd3e2

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000**

**PARASURAM S/O SHANMUGAM**

**Asst. Automotive Assessor**

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**