



SMRT Accident Vehicle Repair Estimates

VIC

SMRT Automotive Services Pte Ltd
 66 Woodlands Industrial Park E4, Singapore 757705
 FAX Number: 63885592
 Estimator Telephone Number: 68602623
 Accident Reporting Number: 68682672

Date Generated : 20/09/2019
 User ID : PehSuan

| Section A - Accident Details | |
|------------------------------------|--------------------|
| Registration Number | SHB991J |
| Case Reference Number | TAX/09/19/2036 |
| Registration Date | 12/12/2017 |
| Company Type | SMRT Taxis Pte Ltd |
| Make | TOYOTA |
| Model | PRIUS4 |
| Name of Driver | LEE YOKE LIN |
| Type of Accident | Head to Rear |
| Accident Date and Time | 12/9/2019 8:30 AM |
| Accident Reported Date and Time | 12/9/2019 3:14 PM |
| Is Surveyor Required? | Yes |
| Survey by | |
| Vehicle is Towed Back? | No |
| Towed Back Date and Time | |
| Replacement Vehicle issued? | No |
| Job Card Number | 24103325 |
| Special Instruction to ARC, if any | TP |
| Prepared Date and Time | 12/9/2019 5:41 PM |
| Chassis Number | |
| Mileage | |
| Work Shop | |
| Repair Completion Date and Time | |

| Section B - Summary of Repair Estimates | | |
|---|---|-------------------------------------|
| Summary of Repair Estimates | | |
| | Quotation from ARC | Adjusted by Surveyor, if applicable |
| Total Labour Cost | \$507.00 | \$200.00 |
| Total Spray Cost | \$1,458.00 | \$300.00 |
| Total Spare Part Cost | \$4,742.72 | \$1,608.86 |
| Total Other Cost | \$580.00 | \$80.00 |
| TOTAL COST | \$7,287.72 | \$2,188.86 (P/P) |
| Lump Sum Total | \$0.00 | \$0.00 |
| Number of Repair Days | 5.0 | 3.0 |
| Prepared / Adjusted By | Tuck Foo Kok | STEVE CHEN (LKK) / AIG |
| ARC / Surveyor Sign Off Date | 16/09/2019 10:02 AM | 16/09/2019 10:31 AM |
| Signature | | |
| Remarks | Total number of repair days = 3 days. SUP = 0 day. | |
| | P/P Repair, Take before spray | |



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 80 Woodlands Industrial Park E4, Singapore 757706
 FAX Number: 63663592
 Estimator Telephone Number: 6862623
 Accident Reporting Number: 6862672

Date Generated : 20/09/2019
 User ID : PehSusan

| Section C - Quotation and Accident Invoice Details | | | |
|--|--------------|----------------|--|
| Quotation Number | QN-1909-0365 | Invoice Number | |
| Quotation Date | 20.09.2019 | Invoice Date | |
| Invoice Amount | | Prepared Date | |

| Section D - Details of Repair Estimates | | |
|---|-------------------|-------------------------------------|
| Part 1 - Labour Works | | |
| Job Scope | Quotation from AR | Adjusted by Surveyor, if applicable |
| TO REPAIR REAR PORTION | \$507.00 | \$200.00 |
| Total Labour | \$507.00 | \$200.00 |

| Part 2 - Spray Painting & Panel Beating Related Works | | |
|---|--------------------|-------------------------------------|
| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
| TO RESPRAY REAR BUMPER | \$378.00 | \$200.00 |
| TO RESPRAY FILLER RR BUMPER LH | \$180.00 | \$0.00 |
| TO RESPRAY FILLER RR BUMPER RH | \$180.00 | \$0.00 |
| TO RESPRAY BUMPER BEAM | \$180.00 | \$0.00 |
| TO RESPRAY BUMPER GUARD RR COVER LOWER | \$180.00 | \$0.00 |
| TO RESPRAY REAR SPOILER | \$180.00 | \$0.00 |
| TO RESPRAY TAILGATE OUTSIDE GARNISH | \$180.00 | \$100.00 |
| Total Spray Painting & Panel Beating | \$1,458.00 | \$300.00 |

| Part 3 - Other Costs - Accident and Accident Repair Related Expense | | |
|---|--------------------|-------------------------------------|
| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
| TO REPLACE SUNDRY PARTS | \$100.00 | \$20.00 |
| TO TRANSFER REAR TAILGATE MECHANISM | \$120.00 | \$0.00 |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM | \$120.00 | \$20.00 |
| TO APPLY RUST-PROOFING ON AFFECTED AREA | \$100.00 | \$20.00 |
| TO CHECK WIRING AND SYSTEM FUNCTION | \$80.00 | \$20.00 |
| TO WASH AND VACUUM | \$60.00 | \$0.00 |
| Total Other Costs | \$580.00 | \$80.00 |

| Part 4 - Spare Parts / Material Usage | | | | | | | | | |
|---------------------------------------|---------|----------------|-------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
| Part Number | Portion | Stock Number | Part Name | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
| | | 52159478 13 | COVER, RR BUMPER ASSY | 1.00 | \$423.90 | 25.00 | \$317.93 | Replace | Replace ✓ |
| | | 52023470 30 | REAR BUMPER REINFORCEME | 0.00 | \$318.80 | 0.00 | \$0.00 | Replace | Check X |
| | | 52575470 40 | RETAINER, RR BUMPER, RH | 1.00 | \$112.70 | 25.00 | \$84.53 | Replace | Replace ✓ |
| | | 52576470 40 | RETAINER, RR BUMPER, LH | 1.00 | \$111.50 | 25.00 | \$83.63 | Replace | Replace ✓ |
| | | 52591470 50 | SEAL, RR BUMPER, RH | 0.00 | \$85.20 | 0.00 | \$0.00 | Replace | Not Given X |
| | | 52592470 40 | SEAL, RR BUMPER, LH | 0.00 | \$85.20 | 0.00 | \$0.00 | Replace | Not Given X |
| | | 52161160 10 | CLIPS PIECE, FRT & RR | 10.00 | \$1.50 | 25.00 | \$11.25 | Replace | Replace ✓ |
| | | 52453470 10 | GUARD, RR BUMPER, | 1.00 | \$558.30 | 25.00 | \$418.73 | Replace | Replace ✓ |
| | | 52566479 00 | FILLER, RR BUMPER, LH | 0.00 | \$119.90 | 0.00 | \$0.00 | Replace | Not Given X |



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63865592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/09/2019
User ID : PohSuan

| | | | | | | | | | |
|-------|--------------|-----------------------------|------|------------|--------|------------|---------|-----------|---|
| | 5256547900 | FILLER, RR BUMPER, RH | 0.00 | \$119.90 | 0.00 | \$0.00 | Replace | Not Given | X |
| | 5216947020 | COVER, GUARD RR BUMPER | 1.00 | \$14.80 | 25.00 | \$11.10 | Replace | Replace | / |
| | 8159147010 | LENS & BODY ASSY, RR | 0.00 | \$486.80 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | PIXEL STICKER | 2.00 | \$60.00 | 0.00 | \$120.00 | Replace | Replace | / |
| | 7608547916 | SPOILER SUB-ASSY, REAR | 0.00 | \$1,322.10 | 0.00 | \$0.00 | Replace | Not Given | X |
| | 7680147110A1 | TAIL GATE BACK DOOR OUTSIDE | 1.00 | \$891.20 | 100.00 | \$0.00 | Replace | Repair | R |
| | | STICKER SMRT LOGO | 1.00 | \$7.80 | 0.00 | \$7.80 | Replace | Replace | / |
| | | STICKER DECAL 6555 8888 | 1.00 | \$21.60 | 0.00 | \$21.60 | Replace | Replace | / |
| | 7540348010 | EMBLEM SUB-ASSY, REAR | 1.00 | \$46.30 | 25.00 | \$34.73 | Replace | Replace | / |
| | 8156147151 | LENS & BODY, REAR | 0.00 | \$436.10 | 0.00 | \$0.00 | Replace | Not Given | X |
| | 8149847020 | COVER, REAR COMBINATION | 0.00 | \$54.00 | 0.00 | \$0.00 | Replace | Not Given | X |
| | 7544147090 | NAME PLATE (HYBRID) | 1.00 | \$52.30 | 25.00 | \$39.23 | Replace | Replace | / |
| | 7544247130 | NAME PLATE (PRIUS) | 1.00 | \$52.30 | 25.00 | \$39.23 | Replace | Replace | / |
| | | SENSOR REVERSE | 1.00 | \$180.00 | 0.00 | \$180.00 | Replace | Replace | / |
| | 8999730100 | ANTENNA, ELECTRICAL | 0.00 | \$60.30 | 0.00 | \$0.00 | Replace | Check | X |
| Total | | | | \$5,624.50 | | \$1,369.76 | | | |

| Added Spare Parts / Material Usage After Surveyor Signed off | | | | | | | | | |
|--|---------|--------------|--------------------------|----------|---------------|--------------|------------------|-----------|----------------|
| Part Number | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
| | | 5202347030 | REAR BUMPER REINFORCEMEN | 1.00 | \$318.80 | 25.00 | \$239.10 | Replace | Replace |
| Total | | | | | 318.80 | | 239.10 | | |

1608.86 /
+ 200.00 /
+ 380.00 /

2188.86 /



Case Details

Case Reference Number : TAX/09/19/2036
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB991J

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-8478-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 12/09/2019 12:30 AM
 Vehicle Age(In Months) : 21

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

| BOM Type | Costing Type | Portion | Material Number | SMRT Recommendation | | | | | | | Surveyor Approval | | | Remarks | |
|------------------------------|--------------|---------|-----------------|------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|-----------|--------|
| | | | | Part Name | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | | |
| One Time Key In | Main | | | COVER, RR BUMPER ASSY | 1 | 423.90 | 423.90 | 25.00 | 317.92 | Replace | 1 | 317.92 | Replace | ✓ / 100 | 317.93 |
| One Time Key In | Main | | | REAR BUMPER REINFORCEMENT | 1 | 318.80 | 318.80 | 25.00 | 239.10 | Replace | 0 | 0.00 | Check | ✓ X NN | |
| One Time Key In | Main | | | RETAINER, RR BUMPER, RH | 1 | 112.70 | 112.70 | 25.00 | 84.53 | Replace | 1 | 84.53 | Replace | ✓ / ✓ Nec | 84.53 |
| One Time Key In | Main | | | RETAINER, RR BUMPER, LH | 1 | 111.50 | 111.50 | 25.00 | 83.63 | Replace | 1 | 83.63 | Replace | ✓ / ✓ NEC | 83.63 |
| One Time Key In | Main | | | SEAL, RR BUMPER, RH | 1 | 85.20 | 85.20 | 25.00 | 63.90 | Replace | 0 | 0.00 | Not Givr | ✓ X NN | |
| One Time Key In | Main | | | SEAL, RR BUMPER, LH | 1 | 85.20 | 85.20 | 25.00 | 63.90 | Replace | 0 | 0.00 | Not Givr | ✓ X NN | |
| One Time Key In | Main | | | CLIPS PIECE, FRT & RR BUMPER | 10 | 1.50 | 15.00 | 25.00 | 11.25 | Replace | 10 | 11.25 | Replace | ✓ / / Nec | 11.25 |
| One Time Key In | Main | | | GUARD, RR BUMPER, LOWER | 1 | 558.30 | 558.30 | 25.00 | 418.72 | Replace | 1 | 418.72 | Replace | ✓ / / SCH | 418.73 |
| One Time Key In | Main | | | FILLER, RR BUMPER, LH | 1 | 119.90 | 119.90 | 25.00 | 89.93 | Replace | 0 | 0.00 | Not Givr | ✓ X NN | |
| Total Spare Part Cost | | | | | | | | | 4,503.62 | | | Surveyor Total | 1,369.71 | | |
| Lump Sum Discount (%) | | | | | | | | | 0.00 | | | Lump Sum Dis (%) | 0.00 | | |
| Final Spare Part Cost | | | | | | | | | 4,503.62 | | | Final Sur Total | 1,369.71 | | |

| SMRT Recommendation | | | | | | | | | | | Surveyor Approval | | | |
|---------------------|--------------|---------|-----------------|--|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------------|
| BOM Type | Costing Type | Portion | Material Number | Part Name | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In | Main | | | FILLER, RR BUMPER , RH | 1 | 119.90 | 119.90 | 25.00 | 89.93 | Replace | 0 | 0.00 | Not Give | X NN |
| One Time Key In | Main | | | COVER, GUARD RR BUMPER LOWER | 1 | 14.80 | 14.80 | 25.00 | 11.10 | Replace | 1 | 11.10 | Replace | / SCH 11.10 |
| One Time Key In | Main | | | LENS & BODY ASSY , RR BUMPER , LH | 1 | 486.80 | 486.80 | 10.00 | 438.12 | Replace | 0 | 0.00 | Not Give | X NN |
| One Time Key In | Main | | | PIXEL STICKER | 2 | 60.00 | 120.00 | 0.00 | 120.00 | Replace | 2 | 120.00 | Replace | ✓ NEC / 120 |
| One Time Key In | Main | | | SPOILER SUB-ASSY, REAR | 1 | 1,322.10 | 1,322.10 | 25.00 | 991.57 | Replace | 0 | 0.00 | Not Give | X NN |
| One Time Key In | Main | | | TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY | 1 | 891.20 | 891.20 | 25.00 | 668.40 | Replace | 1 | 0.00 | Repair | X NN |
| One Time Key In | Main | | | STICKER SMRT LOGO | 1 | 7.80 | 7.80 | 0.00 | 7.80 | Replace | 1 | 7.80 | Replace | ✓ NEC / 7.80 |
| One Time Key In | Main | | | STICKER DECAL 6555 8888 | 1 | 21.60 | 21.60 | 0.00 | 21.60 | Replace | 1 | 21.60 | Replace | ✓ NEC / 21.60 |
| One Time Key In | Main | | | EMBLEM SUB-ASSY REAR | 1 | 46.30 | 46.30 | 25.00 | 34.72 | Replace | 1 | 34.73 | Replace | ✓ NEC / 34.73 |
| One Time Key In | Main | | | LENS & BODY, REAR COMBINATION LAMP , LH | 1 | 438.10 | 438.10 | 10.00 | 394.29 | Replace | 0 | 0.00 | Not Give | X NN |
| One Time Key In | Main | | | COVER, REAR COMBINATION LAMP, LH | 1 | 54.00 | 54.00 | 25.00 | 40.50 | Replace | 0 | 0.00 | Not Give | X NN |
| One Time Key In | Main | | | NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR | 1 | 52.30 | 52.30 | 25.00 | 39.22 | Replace | 1 | 39.23 | Replace | ✓ NEC 39.23 |
| One Time Key In | Main | | | NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR | 1 | 52.30 | 52.30 | 25.00 | 39.22 | Replace | 1 | 39.23 | Replace | ✓ NEC 39.23 |
| One Time Key In | Main | | | SENSOR REVERSE | 1 | 180.00 | 180.00 | 0.00 | 180.00 | Replace | 1 | 180.00 | Replace | ✓ CRU / 180 |

Total Spare Part Cost 4,503.62

Surveyor Total 1,369.71

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0.00

Final Spare Part Cost 4,503.62

Final Sur Total 1,369.71

| SMRT Recommendation | | | | | | | | | | | Surveyor Approval | | | |
|-----------------------|--------------|---------|-----------------|-------------------------|-----|-------------------------|----------------|--------|-----------------|------------------|-------------------|--------------------------|----------------|-------------|
| BOM Type | Costing Type | Portion | Material Number | Part Name | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In | Main | | | ANTENNA, ELECTRICAL KEY | 1 | 60.30 | 60.30 | 10.00 | 54.27 | Replace | 0 | 0.00 | Check | X <i>NN</i> |
| Total Spare Part Cost | | | | | | | | | 4,503.62 | Surveyor Total | | 1,369.71 | | |
| Lump Sum Discount (%) | | | | | | | | | 0.00 | Lump Sum Dis (%) | | 0.00 | | |
| Final Spare Part Cost | | | | | | | | | 4,503.62 | Final Sur Total | | 1,369.71 | | |

Labour's Cost Detail

| S.No. | Costing Type | Job Scope | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|------------------------|-------------------------|-------------------------|---------|
| 1 | Main | TO REPAIR REAR PORTION | 507.00 | 200.00 | / |
| Total: | | | 507.00 | 200.00 | |

Spray Cost Detail

| S.No. | Costing Type | Job Scope | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|--|-------------------------|-------------------------|---------|
| 1 | Main | TO RESPRAY REAR BUMPER | 378.00 | 200.00 | / |
| 2 | Main | TO RESPRAY FILLER RR BUMPER LH | 180.00 | 0.00 | |
| 3 | Main | TO RESPRAY FILLER RR BUMPER RH | 180.00 | 0.00 | |
| 4 | Main | TO RESPRAY BUMPER BEAM | 180.00 | 0.00 | |
| 5 | Main | TO RESPRAY BUMPER GUARD RR COVER LOWER | 180.00 | 0.00 | |
| 6 | Main | TO RESPRAY REAR SPOILER | 180.00 | 0.00 | |
| 7 | Main | TO RESPRAY TAILGATE OUTSIDE GARNISH | 180.00 | 100.00 | / |
| Total: | | | 1,458.00 | 300.00 | |

Other Cost Detail

| S.No. | Costing Type | Job Scope | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|-------------------------------------|-------------------------|-------------------------|---------|
| 1 | Main | TO REPLACE SUNDRY PARTS | 100.00 | 20.00 | //nec |
| 2 | Main | TO TRANSFER REAR TAILGATE MECHANISM | 120.00 | 0.00 | |
| Total: | | | 220.00 | 20.00 | |

9/13/2019

https://vacswb.smrt.com.sg/Estimation.aspx

| S.No. | Costing Type | Job Scope | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|---|-------------------------|-------------------------|---------|
| 3 | Main | TO TEST AND REFIX REVERSE SENSOR SYSTEM | 120.00 | 20.00 | // NEC |
| 4 | Main | TO APPLY RUST-PROOFING ON AFFECTED AREA | 100.00 | 20.00 | // NEC |
| 5 | Main | TO CHECK WIRING AND SYSTEM FUNCTION | 80.00 | 20.00 | // NEC |
| 6 | Main | TO WASH AND VACUUM | 50.00 | 0.00 | |
| Total: | | | 580.00 | 80.00 | |

Summary

| | Estimator Assessment(\$) | Surveyor Assessment(\$) |
|--------------------------|---|---|
| Total Spare Part Detail | 4,503.62 | 1,369.71 |
| Total Labour Cost | 507.00 | 200.00 |
| Total Spray Painting | 1,458.00 | 300.00 |
| Other | 580.00 | 80.00 |
| Overall Total | 7,048.62 | 1,949.71 |
| Lump Sum Repair Option | | |
| Lump Sum Total | 7,050.00 | 1,949.71 |
| Surveyor Approved Amount | | 1,949.71 |
| No of Repair Days* | 5 | 3 |
| Remarks | | P/P Repair. Take before spray |
| Surveyor Name | | STEVE CHEN |
| Signature |  |  |
| Survey Date | 13/09/2019 | |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

https://vacswb.smrt.com.sg/Estimation.aspx

REPAIR PARTS REQUEST - VEHICLE PARTS

| | | | |
|----------------------|----------------|-----------------------------------|------------|
| Contractor | | Date of Collection | 1 1 |
| Accident Case Number | TRM 09/19/2026 | Date of Request | 14/09/2019 |
| Vehicle No | SAB 991 J | Number of Days to Expiry (if any) | 2 0 |
| Vehicle Model | TOYOTA PLUS | | |

| S/N | Part Number | Part Description | Quantity | Unit Price |
|-----|-------------|---------------------------|----------|------------|
| | | REAR BUMPER REINFORCEMENT | 1pc | 239.10 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Please submit photographs for damaged parts

I, (Name) Sten (LKK)

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are asked for replacement for the aforesaid vehicle:


 Signature of person making this declaration
(to be signed in front of an authorized witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

| | | |
|-----------------|--|---------------------------------------|
| Acknowledge By | ARC Executive / Supervisor / BA | |
| Approval By | Surveyor / In-house Staff | |
| Parts Ordering | SMRT Store / Contractor Supply / Form 22 / WOC | Form 22 / PO / WOC Reference / Number |
| Photo Submitted | YES / NO | Date of submission |