

ASS. REC. BY:

REF: CS/FCI 190163131 Rlv f3⁵²

Special Instruction:

Surveyor: Rasu

ASSIGNMENT (Office)

From (Person): Jason Tea che kiat of FCI Date/Time: 16.9.19 3.19pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKW 5918T Insured: SHB 42184at Workshop m/s Ban chuan motor Tel: 62641191of B1C 3 Pioneer Road NOAH #01-14/15Policy No: _____ Claim No: D19005937MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 12.9.2019
(Client's Record)CA / REV / REP. / REV 24 HRS mp 17.9.2019 H.O.D. Endorsement: _____Date/Time: 16.9.19 3.25pm Person Contacted: Perlin Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SKW 5918T-X</u>
	<u>SHB 42184 - CC3/FCI 16016595 / K9h32 ROA - 01/09/2016</u>
<u>18/9/19</u>	<u>Email preti revised to FCI</u>
<u>25/9/19</u>	<u>LS \$ 4300 confirmed by email (Ref 2139.47, 33%)</u>

ASS. REC. BY

Pran

REF:

FC1

4181

ASSIGNMENT

From:

Date:

17-9-2019

Veh No:

SKW 5918T

Yr Regn: 2015/Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 5918T

at Workshop m/s Ban choon motor

of BKK 3 Pioneer road north #01-14/15

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

SSK

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Make:

TOYOTA COROLLA AXIO 1.5X 1496

Colour:

BLACK

A/C: Insured / Std / NI / NA

Sp. Reading

45642

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NRE 1610008732

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

12/09/19

D.O.A.

17/09/19

Survey held at

BAN CHOON

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

O/S REAR

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 25 SEP 2019

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2) JSA - typist

Pop. Forward:

CWS

Lump Sum / L.P. /

HS \$4300k

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

Survey Fee:

Transportation:

: S + RS. \$

Photos:

Others:

TOTAL

145

50

50

53

298

MOTOR SURVEY ASSIGNMENT

Date	13-09-2019	Our Ref No. D19005937MFSH
Accident Date	12-09-2019	Claim Type. Third Party
Insured Vehicle	SHB4218H	Third Party Vehicle. SKW5918T
Survey Location	BLK 3 PIONEER ROAD NORTH #01-14/15	
Contact Person.	PERLIN	
Contact No.	62641191/0	Fax No. 62611324
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BAN CHOON MOTOR WORKS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JASON TEA CHEE KIAT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 18 September 2019 12:21 PM
To: 'CWS Motor Claims'; SUR
Cc: 'Jason Tea'
Subject: RE: SURVEY ASSESSMENT - D19005937MFSH/1-SKW 5918T
Attachments: SKW 5918T PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKW 5918T
Date of survey: 17/9/2019
Number of days (estimated) : 8 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 16 September 2019 3:28 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19005937MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>

Sent: Monday, 16 September, 2019 3:19 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Jason Tea <JasonTea@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19005937MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19005937MFSH

Our Ref: CS/FCI19016313/R1vf3

Date : 18/9/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO: SKW 5918T


We thank you for your instruction on 16/9/2019

Please be informed that we had conducted the inspection of the above mentioned
17/9/2019 at the premises of M/s BAN CHOON MOTOR WORKS
and have the following to report:-

Workshop Estimate Amount	: S\$6,439.47
Revised Estimate Amount	: S\$5,373.10
"Check" Items Amount	: S\$166.37
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
o/s rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/09/2019 10:29
Date Of Accident	12/09/2019 17:40
Exact Location Of Accident	BOON LAY WAY/JURONG EAST STREET 11-TRAFFIC JUNCT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW5918T
Insured/Policyholder	
Name Of Registered Owner	TAN SONG YANG @ TAN SONG KHIANG
NRIC No	S0147418I
Email Address	SONGYANG.TAN@ASIANSEALAND.COM
Mobile Phone No	(LOCAL) +65-98753084
Alternative Phone No	OFFICE-98753084
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA AXIO-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102153430
Cover Note Number	
Driver	
Name of Driver	TAN SONG YANG @ TAN SONG KHIANG
NRIC No	S0147418I
Date Of Birth	01/01/1951
Occupation	OUTDOOR
Date Of Driving Pass	24/11/1972
Driving Experience	46 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98753084
Fax Number	
Contact Number	OFFICE-98753084
Email Address	SONGYANG.TAN@ASIANSEALAND.COM

Address	BLK 331 JURONG EAST AVE 1 #07-1738
Postcode	600331
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB4218H
Vehicle Make/Model/Colour	TAXI -BLUE COLOR - HYUNDAI
Details Of Properties	FRONT RIGHT PORTION
Vehicle Category	TAXI
Name of Driver	GOH KAH HENG
NRIC/Passport Number	S7100513E
Contact Number	96133113
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12-9-19 at about 1740 hours, with traffic light being "green", I was travelling on Boon Lay Way towards BIG BOX and the taxi, vehicle (B) was "turning" from Boon Lay Way towards Jurong East St 11. The taxi collided on my vehicle right side resulting in damages to both vehicle with no passengers involved. We then exchange particulars.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 13-9-19
10:10 hrs

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:

13/9/2019
Rahel

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 12-9-19
09:47 hrs

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	4181

Vehicle Details

Vehicle No.:	SKW5918T
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	2NR8492430
Chassis No.:	NRE1610008732
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$14,474.00
Original Registration Date:	05 Nov 2015
First Registration Date:	05 Nov 2015
Transfer Count:	1
Actual ARF Paid:	\$9,474.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Nov 2025
PARF Rebate Amount:	\$7,105.00

Intended COE Rebate Details

COE Expiry Date:	04 Nov 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$57,885.00
COE Rebate Amount:	\$34,452.00
Total Rebate Amount:	\$41,557.00

The information contained herein is correct as at 18 Sep 2019

OK

55,000
41,557

13,443
//



萬 春 摩 哆 BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GST Reg. No. 351915/00A

GST Regn No. 35191500A

13/09/2019

MS First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

Attn: Motor Claims Dept.

Dear Sir/Madam

QUOTATION FOR REPAIRS OF VEHICLE NO. SKW 5918 T
MODEL: TOYOTA COROLLA AXIO 1.5X A
DATE OF ACCIDENT: 12/09/2019
YOUR INSURED VEHICLE NO. SHB 4218 H

1 pc	RH front door <i>bt</i> ✓	\$	853.01
1 pc	RH rear door <i>bt</i> ✓		804.85
1 pc	RH rear fender <i>bt</i> ✓		892.02
1 pc	Rear windscreen glass moulding <i>na</i> ✓		97.80
1 pc	Rear bumper <i>sc</i> ✓		1,087.80
1 pc	RH rear fender cowl <i>? Xsrc</i>		221.82
1 pc	RH rear wheel <i>cut</i> ✓		462.82
1 pc	RH rear door inner lock <i>cut</i> ✓		352.50
		\$	4,772.62
	Less: 25% discount		1,193.15
		\$	3,579.47
1 roll	Rear windscreen gum <i>na</i> ✓		40.00 SN

LABOUR CHARGES:

To dismantle and reassemble of rear windscreen 120.00 ✓
To knocking and straightening of all necessary damaged parts.
To changing of above part.
To putty and spray painting on accident damaged parts.

1,500.00 1000
1,200.00 800
\$ 6,439.47

Yours faithfully,

Perindayo

Rasul
18/9/19
Hy 90010068

8 days

4/3

17/09/19 @ 1455

Rey after repair


LKK Auto Consultants hereby notify the Repairer of the following:

- To survey before/after every painting
- To display damaged panel during survey
- Parts prices are subject to confirmation
- Third party survey to use a "Third Party Repair" form
- No illegal modification is allowed
- Supplementary work must be approved in writing
- Is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



萬 春 摩 哆 BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324
E-mail: banchoon@singnet.com.sg
Business Reg./GSTReg. No. 351915/00A

GST Regn No. 35191500A

13/09/2019

MS First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

Attn: Motor Claims Dept.

Dear Sir/Madam

QUOTATION FOR REPAIRS OF VEHICLE NO. SKW 5918 T
MODEL: TOYOTA COROLLA AXIO 1.5X A
DATE OF ACCIDENT: 12/09/2019
YOUR INSURED VEHICLE NO. SHB 4218 H

1 pc	RH front door <i>bt</i> ✓	\$	853.01	
1 pc	RH rear door <i>bt</i> ✓		804.85	
1 pc	RH rear fender <i>bt</i> ✓		892.02	
1 pc	Rear windscreen glass moulding <i>new</i> ✓		97.80	
1 pc	Rear bumper <i>scr</i> ✓		1,087.80	
1 pc	RH rear fender cowl		221.82	
1 pc	RH rear wheel <i>cut</i> ✓		462.82	
1 pc	RH rear door inner lock <i>cut</i> ✓		352.50	
		\$	4,772.62	<i>4550.00</i>
	Less: 25% discount		1,193.15	<i>1137.70 -</i>
		\$	3,579.47	<i>3413.13</i>
1 roll	Rear windscreen gum <i>new</i> ✓		40.00	SN

LABOUR CHARGES:

To dismantle and reassemble of rear windscreen
To knocking and straightening of all necessary damaged parts.
To changing of above part.
To putty and spray painting on accident damaged parts.

	120.00	✓
	1,500.00	<i>1000</i>
	1,200.00	<i>800</i>
\$	6,439.47	<i>5373.10</i>

Yours faithfully,

Per Lindays

Rasul

Hy 90010068

8 days

4/3

17/09/19 @ 1455

Resy after repair

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 25 September 2019 2:04 PM
To: perlin; Rasul (LKKAUTO); SUR
Subject: RE: SKW 5918T - Finalization

Dear Perlin,

WITHOUT PREJUDICE

Noted with thanks.

Kindly send Final invoice and all supporting documents directly to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: perlin <banchoon@singnet.com.sg>
Sent: Wednesday, 25 September 2019 12:55 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Re: SKW 5918T - Finalization

Dear Veron

We accept your offer for the above vehicle @ lump sum \$4,300.00 (before GST)

and 8 days for repairs.

Thanks & Regards.

Perlin

On 25/09/2019 12:52 PM, Veron Chen (LKKAUTO) wrote:

Dear Perlin,

WITHOUT PREJUDICE

Offer Lump Sum \$4300 @ 8 working days.

Please check and confirm

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: perlin <banchoon@singnet.com.sg>
Sent: Wednesday, 25 September 2019 10:18 AM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: SKW 5918T - Finalization

Dear Rasul

Attached herewith are vehicle no. SKW 5918 T revised quotation and

after spray paint photos for your finalization.

Thanks & Regards.

Perlin



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19016313/R1vf3s2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 01-10-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 4218H	Veh. Inspected	SKW 5918T
Policy No.		Coverage (\$)	0.00
Claim No.	D19005937MFSH	Excess (\$)	0.00
Assign From	JASON TEA CHEE KIAT	Assign Date	16/09/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA AXIO 1.5X A	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	NRE1610008732	Colour	BLACK
Odometer	45642	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/60 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/60 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/60 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/09/2019	Inspection Date	17/09/2019
Survey held at	BAN CHOON MOTOR WORKS 3 PIONEER ROAD NORTH #01-14/15 SINGAPORE 628457		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 5918T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RH FRONT DOOR	BENT	853.01	853.01
1	RH REAR DOOR	BENT	804.85	804.85
1	RH REAR FENDER	BENT	892.02	892.02
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	97.80	97.80
1	REAR BUMPER	SCRATCHED	1,087.80	1,087.80
1	RH REAR FENDER COWLING	SERVICEABLE	221.82	-
1	RH REAR WHEEL	CUT	462.82	462.82
1	RH REAR DOOR INNER LOCK	CUT	352.50	352.50
	LESS 25% DISCOUNT		-1,193.15	-1,137.70
			3,579.47	3,413.10
SPECIAL NETT ITEMS				
1	ROLL REAR WINDSCREEN GUM (SN)	NECESSARY	40.00	40.00
			40.00	40.00
LABOUR				
	TO DISMANTLE AND REASSEMBLE OF REAR WINDSCREEN.		120.00	120.00
	TO KNOCKING AND STRAIGHTENING OF ALL NECESSARY DAMAGED PARTS. TO CHANGING OF ABOVE PART.		1,500.00	1,000.00
	TO PUTTY AND SPRAY PAINTING ON ACCIDENT DAMAGED PARTS.		1,200.00	800.00
			2,820.00	1,920.00
GRAND TOTAL			6,439.47	5,373.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,300.00

Report Ref No. CS/FCI19016313/R1vf3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever in contract or tort is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.