

Surveyor: ADRIAN DOI: ASSIGNMENT 19/09/2019

Date / Time: 16/09/2019
Registered in Merimen: 16/09/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SHC 2163P
Name of Insured : COMFORT TRANSPORTATION PTE LTD
Insured Tel No. : _____ HP: _____
Excess Sec II :SS _____ D.O.A : 11/09/2019 12:10
Is driver the owner? (YES / NO) Nature of Accident : _____
If NO, Driver Name / Age : WONG SWI SING
Driver Tel No. : +65-96608537 (V/L: YES / NO)

Claim No. : MCT19090254
Policy No. : MCOM0015
Make / Model : HYUNDAI I40
Place of Accident : SINGAPORE CHECK POINT TWDS SINGAPORE
OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
Insured Liability : % Final ? Yes / No

box

SLK 1106Y



INSRS:
WSP: AUTO N CARS
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup):	<input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PDR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD:	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

24/9/19 - III ✓ 50%
22/9/19 - TP did not send in car repair.
25/10/19 - FILE → MK to close.

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: S\$ _____ (_____ days) Reduction: _____ % Email Call

FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email Call

Final Liability: % _____ (Agreed / Assessed) BOLA S/N No. : _____ If NO or B 28, Ass. Lia : _____

Repair Cost: S\$ _____

Loss of Rental (LOR): S\$ _____ (_____ days)

Loss of Use (LOU): S\$ _____ (\$ x _____ days)

Loss of Income (LOI): S\$ _____ (\$ x _____ days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: S\$ _____

Medical: S\$ _____

Disbursement: S\$ _____ (e.g. Tow/ Independent)

Legal Cost: S\$ _____

Total: S\$ _____ **Global Sum S\$:** _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: S\$ _____ Name 1: _____

Payee 2: (Strike if N.A.) S\$ _____ Name 2: _____

Payee 3: (Strike if N.A.) S\$ _____ Name 3: _____

COPY SENT 31/10/19

1) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee: 350.00

REP. BY

REF: TJ

ASSIGNMENT

From: _____ Date: 19/9/2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLK 1106Y

at Workshop m/s: Auto N Cars Services

of BIC 1 Kabi Buret Ave 6 #01-90

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 10am-12pm

Veh No: SLK1106Y Yr Regn: 2012 Feb

Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____

Make: Bmw 116 cc _____

Colour: Silves A/C: Insured / Std / NI / NA

Sp. Reading: 138281 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA1A12010E 948816

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / STD A/Rim or _____

Tyre Size: F: 225/45R17
R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MICY OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front		Rear	
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm	
L/Bal. <u>06</u> mm		L/Bal. <u>06</u> mm	
D.O.A. _____		D.O.I. <u>19/09/19</u>	

Survey held at: Auto N Car

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or
Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

<input type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS mp

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	TP III
	HS \$1000 Cred \$ 3583 / 2211.

Date/Time, File Pass to? : Prell. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invt (\$ _____)

: Wheel end (\$ _____)

Survey Fee: _____

Transportation: _____

S + RE. SI _____

Photo: _____

Other: _____

10/11



Co. Reg: 200922097K GST Reg.No: 200922097K
 Auto Bay @ Kaki Bukit Bk 1 Area "A" Kaki Bukit Ave 6 #01-04 (S) 417883
 • Tel: 651 6555 2909 • Fax: 651 6841 7181 • Web: www.autoncars.com.sg

Date : 13/9/2019

TO: India International Insurance Pte Ltd
 64 Cecil Street
 IOB Building
 Singapore 049711

Xilod Long Total Pages : 1

Our Customer : VINODTHAN S/O MURUGAYA

Vehicle No : **SLK1106Y**

Model : BMW 116i AT ABS

Manufacture Year : 2011

Date of Accident : 11/9/2019

Total Estimate Repair Days : 3

Attn : Motor Claim Department

Email :

Re: Repair Estimate For Third Party Claim against : SHC2163P

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear Bumper <i>Byr</i>	1	\$1,300.00	\$1,300.00	x
2	Rear bumper RH retainer <i>Men</i>	1	\$70.00	\$70.00	+
3	RH Rear Fender <i>Byr</i>	1	\$1,800.00	\$1,800.00	x.
	Sub Total			\$3,170.00	
	Less 10%			\$317.00	
	Sub Total 1			\$2,853.00	
B.	Spare Parts (S/Nett)				
1	RH rear tyre rim <i>ut</i>	1	\$1,024.80	\$1,024.80	750 (sw)
2	Rear windscreen seal	1	\$15.00	\$15.00	x
3	Rear windscreen sealant <i>Men</i>	2	\$25.00	\$50.00	+
4	Rear windscreen primer	1	\$15.00	\$15.00	x.
	Sub Total 2			\$1,104.80	
	Total Spare Parts			\$1,104.80	
C.	Labour				
1	To knock and straighten rear portion. To remove and renew necessary parts. Cut and weld damaged panel. Adjust and realign the same			\$800.00	200 600
2	To putty and spray damaged panel			\$800.00	400
3	To remove and refit rear windscreen glass			\$120.00	x
4	To check wiring and lighting			\$60.00	+
	Total Labour			\$1,780.00	
	Total Repair Cost			\$4,633.00	
	* The above quoted are exclusive of GST.				

Yours faithfully,

Ekynn
 f Auto N Cars Services Pte Ltd

*Total: 1350
 4/5 1050.*

Surveyor's Details	
Name	<i>Adrian King</i>
Contact	<i>96853733</i>
Survey Date	<i>15/09/19.</i>
Recommend Before Paint	Authorize <input checked="" type="checkbox"/> Not Authorize <input type="checkbox"/>
Signature	<i>[Signature]</i>

03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian King

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 13 September 2019 4:51 PM
To: Nurashikin Abdul Mutalip; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Sundari Nagarajan - III
Subject: RE: PRI Template

q.slam@16/09/19
penang Siti
vehicle not in

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLK1106Y and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Nurashikin Abdul Mutalip [mailto:nurashikin@autoncars.com.sg]
Sent: 13 September, 2019 2:44 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: PRI Template

Dear Mr Gabriel,

We would like to appoint LKK Auto Consultants Pte Ltd for the survey.

Thank you

Best Regards,
Siti

Auto N Cars Services Pte Ltd

m: +65 8499 3326

o: +65 6555 2909 Fax: 6841 7181

web site: www.autoncars.com.sg

office: Auto Bay@ Kaki Bukit Avenue 6

Blk 1 #01-04

Singapore 417883

On Fri, Sep 13, 2019 at 11:36 AM Nurashikin Abdul Mutalip <nurashikin@autoncars.com.sg> wrote:

Dear officer-in-charge,

ACCIDENT INVOLVING OUR CLIENT'S VEHICLE SLK1106Y AND YOUR INSURED'S VEHICLE SHC2163P ON 11/09/2019

We refer to the above matter

Our client's vehicle will be ready for survey.

Failing which we shall proceed with the repair after the expiry of 48 hours notice.

Thank you

Best Regards,

Siti

Auto N Cars Services Pte Ltd

m: +65 8499 3326

o: +65 6555 2909 Fax: 6841 7181

web site: www.autoncars.com.sg

office: Auto Bay@ Kaki Bukit Avenue 6

Blk 1 #01-04

Singapore 417883

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	16 Sep 2019 16:36	Cim Dtl Modified	Claimant's Name: -> -.	[A] HOW MEI KWAN
2	16 Sep 2019 16:36	Cim Veh Model Changed	(204808) HONDA VEZEL 1.5 (A).	[A] HOW MEI KWAN
3	16 Sep 2019 16:36	Cim Created	Reg No: SLK1106Y. Acct Date: 2019/09/11. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). Workshop: Auto N Cars Services Pte Ltd (HQ)	[A] HOW MEI KWAN
4	16 Sep 2019 16:36	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	16 Sep 2019 16:36	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/25	[A] HOW MEI KWAN
6	16 Sep 2019 16:36	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] HOW MEI KWAN
7	16 Sep 2019 16:36	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] HOW MEI KWAN
8	17 Sep 2019 18:09	Cim Dtl Modified	Claimant's Name: - -> VINODTHAN S/O MURUGAYA. Claimant's ID: -> S8937380H.	[A] HOW MEI KWAN
9	17 Sep 2019 18:09	Cim Veh Model Changed	(204808) -> (205580) BMW 116I 1.6 ABS D/AIRBAG 2WD 5DR HID DSC (A).	[A] HOW MEI KWAN
10	19 Sep 2019 15:38	Adj Adjuster Assigned	MARCUS CHUA -> ADRIAN LING	[A] HOW MEI KWAN
11	19 Sep 2019 15:38	Cim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD. Insured ID: -> 199303821R.	[A] HOW MEI KWAN
12	25 Sep 2019 15:06	Video Downloaded	Downloaded Video - Accident	[A] CHEW HSIAO TONG
13	25 Sep 2019 15:09	Adj Mandate Request	Cur.Reg:0.00:PODS Liability: 50% (BOLA 18) Remark: Merging Lane collision	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2289861	24 Sep 2019 14:00:22	Video Upload	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	SLK1106Y	Sundari Nagarajan	xx.xx

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	16 Sep 2019 16:36	Clm Dtl Modified	Claimant's Name: -> -.	[A] HOW MEI KWAN
2	16 Sep 2019 16:36	Clm Veh Model Changed	(204808) HONDA VEZEL 1.5 (A).	[A] HOW MEI KWAN
3	16 Sep 2019 16:36	Clm Created	Reg No: SLK1106Y, Acct Date: 2019/09/11, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), Workshop: Auto N Cars Services Pte Ltd (HQ)	[A] HOW MEI KWAN
4	16 Sep 2019 16:36	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	16 Sep 2019 16:36	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/25	[A] HOW MEI KWAN
6	16 Sep 2019 16:36	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
7	16 Sep 2019 16:36	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] HOW MEI KWAN
8	17 Sep 2019 18:09	Clm Dtl Modified	Claimant's Name: - -> VINODTHAN S/O MURUGAYA, Claimant's ID: -> S8937380H.	[A] HOW MEI KWAN
9	17 Sep 2019 18:09	Clm Veh Model Changed	(204808) -> (205580) BMW 116! 1.6 ABS D/AIRBAG 2WD 5DR HID D5C (A).	[A] HOW MEI KWAN
10	19 Sep 2019 15:38	Adj Adjuster Assigned	MARCUS CHUA -> ADRIAN LING	[A] HOW MEI KWAN
11	19 Sep 2019 15:38	Clm Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD, Insured ID: -> 199303821 R.	[A] HOW MEI KWAN
12	25 Sep 2019 15:06	Video Downloaded	Downloaded Video - Accident.	[A] CHEW HSIAO TONG
13	25 Sep 2019 15:09	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 50% (BOLA 18) Remark: Merging Lane collision	[A] CHEW HSIAO TONG
14	25 Sep 2019 16:05	Video Downloaded	Downloaded Video - Accident	[1] Sundari Nagarajan
15	25 Sep 2019 16:06	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/25	[1] Sundari Nagarajan
16	25 Sep 2019 16:06	Adj Mandate Set	Approved:0.00.	[1] Sundari Nagarajan

Date From



Date To



Audit Type None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2289861	24 Sep 2019 14:00:22	Video Upload	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	SLK1106Y	Sundari Nagarajan	100.000

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 1 October 2019 10:07 AM
To: Darla Balingit
Cc: Admin A
Subject: Your Ref: SLK1106Y *Our Ref: CC4/III19016322/Apa3 [ACCIDENT INVOLVING SHC 2163P(III) AND SLK 1106Y ON 11/09/2019]
Attachments: Statement of SHC2163P.pdf

Your Ref: **SLK1106Y**
Our Ref: CC4/III19016322/Apa3

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING SHC 2163P(III) AND SLK 1106Y ON 11/09/2019

We refer to the above matter.

Enclosed herewith in this email is a copy of our insured's accident report for your perusal. The accident happened when both parties were merging into the same lane.

Strictly without admission of liability whatever, but with a view towards a resolution of your client's claim in the above matter without resort to litigation, we are prepared to offer 50% towards your client's claim.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Sent Message

This mail is associated with :

***SLK1106Y (MCT19090254)**
[SHC2163P]
TP
VINODTHAN S/O MURUGAYA
Sep 11 2019 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Auto N Cars Services Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 22/10/2019 10:59 AM.
To sundari@iii.com.sg
CC III_SG; chewht@lkkauto.com; admin-a@lkkauto.com
Subject <Submit wp Report>MCT19090254

Dear Sirs/Madam,

We refer to the above matter.

We have offered 50% to third party 01/10/2019. However we were informed by third party repairer that thier client did not send in vehicle for repair.

In view of non-development from the third-party, we will proceed to temporarily close this file and submit our survey report to your good-office.

In future, if there are any new developments from the claimant, we will inform you for our further handling.

Thank you.

Hsiao Tong

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Sep 2019 Edit Reg		16 Sep 2019 00:00 Edit Adj Rpt	S\$1,050.00 Edit Estimates	S\$1,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	VINODTHAN S/O MURUGAYA , ID: S8937380H								
Vehicle Reg. No.:	SLK1106Y	Date of Loss:	11/09/2019 00:00 - :59 [91 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19090254	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC2163P	Policy No. (Claimant):	MT111852						
	Excess:								
Repairer:	Auto N Cars Services Pte Ltd (HQ) Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6555 2909								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundarl Nagarajan - 6347 6071]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 25/09/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• III_SG (25/09/2019): Alert - Adj Mandate Approved (S\$0.00) - SLK1106Y - Claim Handler: Sundarl Nagara...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK1106Y (MCT19090254)
[SHC2163P]
TP
VINODTHAN S/O MURUGAYA
Sep 11 2019 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Auto N Cars Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page v <input checked="" type="checkbox"/>	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	24/09/19 14:00	Video - Accident	Load MP4	<input type="checkbox"/>
Photos/Images			3 per page v <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/09/19 15:09	General View	Load JPG	<input checked="" type="checkbox"/>
2	25/09/19 15:09	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	25/09/19 15:09	General View	Load JPG	<input checked="" type="checkbox"/>
4	25/09/19 15:09	General View	Load JPG	<input checked="" type="checkbox"/>
5	25/09/19 15:09	General View	Load JPG	<input checked="" type="checkbox"/>
6	25/09/19 15:09	General View	Load JPG	<input checked="" type="checkbox"/>
7	25/09/19 15:09	General View	Load JPG	<input checked="" type="checkbox"/>
8	25/09/19 15:09	General View	Load JPG	<input checked="" type="checkbox"/>
9	25/09/19 15:09	General View	Load JPG	<input checked="" type="checkbox"/>
10	25/09/19 15:09	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page v <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/09/19 16:37	ACKNOWLEDGEMENT EMAIL TO III DD 16.09.19	Load PDF	<input type="checkbox"/>
2	17/09/19 18:09	TP GIA REPORT	Load PDF	<input type="checkbox"/>
3	22/10/19 10:59	TP ESTIMATE_MARKED	Load PDF	<input type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	17/09/19 08:56	Singapore Accident Statement	Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19016322/APA3Q2

Date: 12/11/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant	Insured Vehicle No :	SHC2163P
Vehicle No : SLK1106Y	Nature of Claim:	TP
Date of Loss: 11/09/2019	Claim No:	MCT19090254

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK1106Y		
Make & Model:	BMW 116I, 1.6 ABS D/AIRBAG 2WD 5DR HID DSC (A)	Engine No:	A596J119N13B16A
Reg. Date:	09/02/2012 (Man. Year: 2011)	Chassis No:	WBA1A12010E948816
Colour:	Silver	Odometer:	138281 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	3,957.80	750.00	3,207.80	81.05	
Miscellaneous Items	0.00	0.00	0.00		
Labour	1,780.00	600.00	1,180.00	66.29	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	5,737.80	1,350.00	4,387.80	76.47	
Approved Total (Overridden) (S\$)		1,050.00			
	(S\$)	5,737.80	1,050.00	4,687.80	81.70
	+ GST 7.00/7.00% (S\$)	401.65	73.50	328.15	81.70
	Nett Amount (S\$)	6,139.45	1,123.50	5,015.95	81.70
	Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	16/09/2019	
Date Inspected:	19/09/2019 Inspected At:	Auto N Cars Services Pte Ltd (HQ) Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSHAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Nov 2019)
Parts: 144	BMW 116I 1.6 ABS D/AIRBAG 2WD 5DR HID DSC (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK1106Y)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Repair	1,300.00 FL	*- FL	
2	1		*REAR BUMPER RH RETAINER	Not Necessary	70.00 FL	*- FL	
3	1		*RH REAR FENDER	Repair	1,800.00 FL	*- FL	
4	1		*RH REAR TYRE RIM	Cut	1,024.80 FS	*750.00 FS	
5	1		*REAR WINDSCREEN SEAL	Not Necessary	15.00 FS	*- FS	
6	2		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS	
7	1		*REAR WINDSCREEN PRIMER	Not Necessary	15.00 FS	*- FS	
					Sub Total (\$\$)	4,274.80	750.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	317.00	0.00
					Total Parts (\$\$)	3,957.80	750.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK AND STRAIGHTEN REAR PORTION .TO REMOVE AND RENEW NECESSARY PARTS .CUT AND WELD DAMAGED PANEL .ADJUST AND REALIGN THE SAME	New	800.00	200.00
2	TO PUTTY AND SPRAY DAMAGED PANEL	New	800.00	400.00
3	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	0.00
4	TO CHECK WIRING AND LIGHTING	New	60.00	0.00
Gross Labour Cost (S\$)			1,780.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >