

ASS. REC. BY:

REF: CS/MSG/190/6305/AGS/3ⁿ²

Special Instruction:

Survisor: Adnan

ASSIGNMENT (Office)

From (Person): Johny Tay Mei Ling of MSG Date/Time: 16.9.19 12.33 p.m.

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PC 8063K Insured: SMH 6431D

at Workshop m/s Chew Motor Tel: 67479241 / 65095545

of NO 1 Kaki Bukit Ave 3, #01-11/41

Policy No: 2919902 Claim No: 604693

Sum Insured: Excess:

Make of Veh: D.O.A. 29.8.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 16.9.19 4.30 p.m. Person Contacted: Suby's Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	PC8063K - X
	SMH 6431D - X
17/09/19 @ 12:32 pm	checked with Suby's got estimate.

ADD. REC. BY: AdrianREF: MS16

ASSIGNMENT

From: _____ Date: 17.9.2019

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PC 8063

at Workshop n/s Chew Motor

of NO 1 Kaki Bukit Ave 6 # 01-11 / 41

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 11-000-1m owner warranty

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS mp

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PC8063K (r Regn: 2019 April)

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Mini Bus

Make: Toyota Hiace cc 2754

Colour: white A/C: Insured / Std / NI / NA

Sp Reading: 35670 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GDH2232001119

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/80R15
R: 195/80R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal. <u>06</u>	mm	R/Bal. <u>06</u>	mm
L/Bal. <u>06</u>	mm	L/Bal. <u>06</u>	mm
D.O.A. _____		D.O.I. <u>17/09/19</u>	

Survey held at Chew Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP MS16.</u>
<u>11/11/19</u>	<u>Confirmed US \$ 2,600/- @ 4 days with Adrian</u> <u>(\$ 7,357.30 Red. 74%)</u>
	RECEIVED 12 NOV 2019 <u>11/11/2019</u>
<u>12/11</u>	<u>check with handler date of accident is 29/8/2019</u>

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Rep. Form 1:

Temp. 2011/12/19

☐ : Prel. Report☒ : Final ReportDays Of Repair: 4

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS: \$

Phone:

Other:

TOTAL

200

11

211

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Sep 2019		16 Sep 2019 16:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ASIA EXPRESS CAR RENTAL PTE LTD, Co. Reg. No.: 201116882D								
Main Claimant:	MARITEAM TRANSPORT SERVICES PTE LTD, Co. Reg. No.: 200402055D								
Vehicle Reg. No.:	PC8063K	Date of Loss:	29/08/2019 19:00 - :59 [4 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 604693	Policy/Cover Note No.:	29119902 (TP, Fire & Theft) Coverage: 25/03/2019 - 24/03/2020						
Vehicle Reg. No. (Insured):	SMH6431D	Policy No. (Claimant):							
Repairer:	Chew Motor Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #01-11/41, Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67479241 / 65095545								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/09/2019]								
Driver/Custodian (Insured):	SIM CHIN KHOON (), NRIC: S11663721, Tel: +6597923133 Email:								
Adj Asg. Remarks:	Assign LKK on WP. Liab: unclear. Disagree on SJE. Contact: Peijie @ 9169 0825. Owner's waiting on 17/09/19 @ 11am, to re-assign case to Frederick as per request by workshop through whatsapp from Kumar and confirmation with workshop Suki.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***PC8063K (604693)
[SMH6431D]**

TP
MARITEAM TRANSPORT SERVICES PTE LTD
Aug 29 2019 7:00PM
[ASIA EXPRESS CAR RENTAL PTE LTD]
Chew Motor Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 17/09/2019 17:36 PM.
To Jowyn_tay@sg.msg-asia.com
CC sur@lkkauto.com
Subject PC8063K (604693) [SMH6431D] TP

Dear Jowyn,

Please be informed that we have inspected the vehicle PC 8063K on 17/09/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company
Owner ID: 055D

Vehicle Details

Vehicle No.: PC8063K
Vehicle to be Exported: No
Intended Deregistration Date: 31 Aug 2019
Vehicle Make: TOYOTA
Vehicle Model: HIACE COMMUTER GL 2.8
AUTO

Primary Colour: White
Manufacturing Year: 2018
Engine No.: 1GD8354275
Chassis No.: GDH2232001119
Maximum Power Output: -
Open Market Value: \$44,460.00
Original Registration Date: 16 Apr 2019
First Registration Date: 16 Apr 2019
Transfer Count: 0
Actual ARF Paid: \$2,223.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 15 Apr 2029
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
QP Paid: \$27,589.00
COE Rebate Amount: \$26,554.00
Total Rebate Amount: \$26,554.00

The information contained herein is correct as at 31 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/08/2019 15:43
Date Of Accident	29 30/08/2019 20:10
Exact Location Of Accident	TANJONG PAGAR RD - AMARA HOTEL PICK UP POINT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC8063K
Insured/Policyholder	
Name Of Registered Owner	MARITEAM TRANSPORT SERVICES PTE LTD
Co Reg No	200402055D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-86458581
Alternative Phone No	OFFICE-86458581

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORK USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B29122534MKC
Cover Note Number	

Driver

Name of Driver	MOHAMMAD RAZIF BIN ADIL
NRIC No	S8617759E
Date Of Birth	04/07/1986
Occupation	OUTDOOR
Date Of Driving Pass	08/07/2010
Driving Experience	9 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-86458581
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 873 WOODLANDS ST 81 #01-258
Postcode	730873
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	MR ALI - AMARA HOTEL SECURITY
Phone Number	91653244
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMH6431D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
This form must be completed by the Policymaker and/or the Authorized Insurer.
2. Information provided must be as truthful and accurate as possible. Any verbal false information or withholding of material facts may affect insurance companies to rescind policy liability.
3. The cover and insurer is not the Primary Insurance Companies (PICs) admitted to business liability on the part of the insurance companies.
4. Any false reporting may be referred to the Police for investigation.
5. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and must copies of this report will be available to all applicable stakeholders/interested parties.
6. By the indorsement of this report to the insurers, you hereby consent to the processing of this report and the further use and release of the report being made and false affidavit.
7. Consent under the Personal Data Protection Act (PDPA)
 - (i) I understand, acknowledge, agree and consent that:
 - (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or generated by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurer's lawyers/law firms, the Ministry Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with the instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, witness reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the internet in case of emergency/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information to collected under (i) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policymaker's Signature
Date & Time:


Driver's Signature
(If driver is not the policymaker)
Date & Time:


Authorised Person's Signature
Name:
(Print in full):

Sketch Plan #2

SKETCH PLAN



A. PCBLATK

B. PINKETID

Ty. Pagon Rd

Amman Hotel Pickup Point

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was making my parking towards the road way with the guidance of the hotel security using a traffic marker

When vehicle B came into the pickup point, the security guard signalled driver B to stop. However, driver B still proceeded and squeezed in my right side. At that point, I halted my vehicle which shortly after, I felt the impact of my driver door area

I have a witness who saw the whole accident

Name: Mr. Ali (Amman Hotel security)

#/P: 9165-3244

DECLARATION

I/We declare the foregoing statements are true to the best of my/our knowledge.


Driver's Signature
(If involved with the accident)
Date & Time


Driver's Signature
(If involved with the accident)
Date & Time


Witness (Police or Personnel's) Signature
Date & Time



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

GST Reg No.: 201718369R

MARITEAM TRANSPORT SERVICES PTE LTD

14/09/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPMS117. GDH2232001119

Shirley.

Accident date: 30/08/2019

Estimated repair cost for vehicle no: PC8063K HIACE COMMUTER GL 2.8 A '19

CHASSIS: GDH2232001119

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Repair</i>		\$486.80 <i>+</i>
2	2	Front Bonnet Hinge <i>new</i>		\$41.80 <i>+</i>
3	1	Front Bonnet Emblem Logo <i>new</i>		\$57.00 <i>-</i>
4	1	Front Bonnet Company Sticker (Special Nett) <i>new</i>		\$250.00 <i>-120(SW)</i>
5	1	Front R/H Corner Panel <i>perked</i>	<i>154.10</i>	\$408.10 <i>-</i>
6	1	Front R/H Head Lamp <i>cut</i>		\$1,624.20 <i>-</i>
7	1	Front R/H Side Mirror Assy <i>new</i>		\$693.70 <i>+</i>
8	1	Front R/H Door <i>Repair</i>		\$1,263.40 <i>+</i>
9	2	Front R/H Door Hinge <i>new</i>	\$66.40	\$132.80 <i>+</i>
10	1	Front R/H Door Company Sticker (Special Nett) <i>new</i>		\$380.00 <i>-250(SW)</i>
11	1	Front R/H Step Panel Garnish <i>new</i>		\$114.60 <i>+</i>
12	1	Front Bumper <i>detached</i>		\$390.80 <i>-</i>
13	8	Front Bumper Clip <i>new</i>	\$6.50	\$52.00 <i>-30</i>
14	1	Front R/H Bumper Side Retainer <i>new</i>		\$110.20 <i>+</i>
15	1	Front R/H Bumper Fog Lamp Cover <i>new</i>		\$47.50 <i>+</i>
16	1	Front R/H Hub Cap <i>new</i>		\$158.10 <i>+</i>

Subtotal :- \$5,927.30

2510.10

188257

SW 370

Per Price checked
H.R.

Labour charges

To remove & refit front R/H door, gear, motor, lock, glass, rubber & trim board		\$200.00 +
To remove & refit body logo		\$280.00 + 50
To check wiring	1030	\$100.00 30
Tuff kote		\$150.00 *
Panel beating		\$1,600.00 400
Spray painting		\$1,600.00 550

Subtotal :- \$3,930.00

Total:- \$9,857.30

10141

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total : 3282.57.

c/s: 26K.

04 days.

2.6K.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19016325/AGSF3N2

Date: 12/11/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29119902
Claimant Vehicle No :	PC8063K	Insured Vehicle No :	SMH6431D
Date of Loss:	29/08/2019	Nature of Claim:	TP
		Claim No:	604693

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC8063K	Engine No:	1GD8354275
Make & Model:	TOYOTA HIACE, 2.8 D (A)	Chassis No:	GDH2232001119
Reg. Date:	16/04/2019 (Man. Year: 2018)	Odometer:	35670 km
Colour:	White		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80R15	Rear Tyre Size:	195/80R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,211.00	2,252.57	3,958.43	63.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,930.00	1,030.00	2,900.00	73.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,141.00	3,282.57	6,858.43	67.63
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	10,141.00	2,600.00	7,541.00	74.36
+ GST 7.00/7.00% (S\$)	709.87	182.00	527.87	74.36
Nett Amount (S\$)	10,850.87	2,782.00	8,068.87	74.36

INSPECTION

Date of Assignment:	16/09/2019	
Date Inspected:	17/09/2019	Inspected At:
		Chew Motor Pte Ltd (HQ)
		No 1 Kaki Bukit Ave 6, #01-11/41,
		Autobay@Kaki Bukit
		Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Nov 2019)		
Parts:	N/A	TOYOTA HIACE 2.8 D (A) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for PC8063K)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	486.80 F	*- FL
2	2		*FRONT BONNET HINGE	Not Necessary	41.80 F	*- FL
3	1		*FRONT BONNET EMBLEM LOGO	Necessary	57.00 F	*57.00 FL
4	1		*FRONT R/H CORNER PANEL	Dented	408.10 F	*408.10 FL
5	1		*FRONT R/H HEAD LAMP	Cut	1,624.20 F	*1,624.20 FL
6	1		*FRONT R/H SIDE MIRROR ASSY	Not Necessary	693.70 F	*- FL
7	1		*FRONT R/H DOOR	Repair	1,263.40 F	*- FL
8	2		*FRONT R/H DOOR HINGE	Not Necessary	132.80 F	*- FL
9	1		*FRONT R/H STEP PANEL GARNISH	Not Necessary	114.60 F	*- FL
10	1		*FRONT BUMPER	Deformed	390.80 F	*390.80 FL
11	8		*FRONT BUMPER CLIP	Necessary	52.00 F	*30.00 FL
12	1		*FRONT R/H BUMPER SIDE RETAINER	Not Necessary	110.20 F	*- FL
13	1		*FRONT R/H BUMPER FOG LAMP COVER	Not Necessary	47.50 F	*- FL
14	1		*FRONT R/H HUB CAP	Not Necessary	158.10 F	*- FL
15	1		*FRONT BONNET COMPANY STICKER	Necessary	250.00 FS	*120.00 FS
16	1		*FRONT R/H DOOR COMPANY STICKER	Necessary	380.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,211.00	2,880.10
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	627.53
Total Parts (\$\$)	6,211.00	2,252.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT FRONT R/H DOOR,GEAR,MOTOR,LOCK,GLASS,RUBBER & TRIM BOARD	New	200.00	0.00
2	TO REMOVE & REFIT BODY LOGO	New	280.00	50.00
3	TO CHECK WIRING	New	100.00	30.00
4	TUFF KOTE	New	150.00	0.00
5	PANEL BEATING	New	1,600.00	400.00
6	SPRAY PAINTING	New	1,600.00	550.00
Gross Labour Cost (S\$)			3,930.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >