

ASS. REC. BY:

REF: CS/FCI 19016329 / Uvd3

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

CWS

From (Person): Sithen

of

FCI

Date/Time: 4.29pm @ 16/9/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMN 9769D

Insured:

SHB 46719

at Workshop, m/s

Euro Success

Tel:

9828 9277.

of

1 koki Buleit Ave 6 #02-03

Policy No:

Claim No:

D190059 49MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

14/09/2019

CA / REV / REP. / REV 24 HRS

'up'

17/9/2019

H.O.D. Endorsement:

Date/Time:

4.41pm @ 16/9/19

Person Contacted:

Ah Huan

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

Johnny /

SMN 9769D-X

SHB 46719-MS/NC15006939/H/ly 3s)

D.A. 23/4/2015

18/9/19

Informed FCI pending workshop est by email

26/9/19

Email preli revised to FCI

ASS. TO: BY: **Marius**REF: **FCI**

ASSIGNMENT

From: _____ Date: **17/9/19**

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: **SMN 9769D**at Workshop m/s **Gum Success**of **11caki Bukit Ave 6 #02-03**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: **25k.**

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: **3** days Res.: Yes or NoLump Sum: **20** % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS **1up**

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SMN 9769D** Regn: **9 / 19**Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **KIA Stonic** C.C. **998**Colour: **Black** A/C: Insured / Std / NI / NASp. Reading: **975** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **KNAD6811VL6347625**Gen. Cond: **Good** / Fair / Poor / BurntSteering: **Order** / Jammed / Leaked / Burnt orBrake: **Order** / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **185/65-15**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

KUMHO

Front

Rear

R/Bal. **9** mm R/Bal. **9** mmL/Bal. **9** mm L/Bal. **9** mmD.O.A. **14/9/19** D.O.I. **17/9/19**

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/5 Lt, 0/5 Rdy.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/9/19 **27A 38581**
4/5 @ 2800 confirmed with Alin. (Red 4988-25, 649)

RECEIVED 26 SEP 2019

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2) **26/9 - typst**Days Of Repair: **3**Resurvey No. of Trip: **1**Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invt (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + P3. St

Photos

Other

TOTAL

150**50****50****66****316**

Report Format:

CWS

Lump Sum / F.B. / F

2800/2



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005949MFSH

Our ref: CS/FCI19016329/Uvd3

DATE: 26/9/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO SMN 9769D


We thank for your instruction on 16/9/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 17/9/2019 at the premises of M/s EURO SUCCESS SERV PTE LTD

Workshop Estimate Amount	: S\$7,788.25
Revised Estimate Amount	: S\$2,800.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s front portion and o/s body



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	16-09-2019	Our Ref No. D19005949MFSH
Accident Date	14-09-2019	Claim Type. Third Party
Insured Vehicle	SHB4671G	Third Party Vehicle. SMN9769D
Survey Location	1 Kaki Bukit Avenue 6 #02-03 Autobay	
Contact Person.	AH HUAT	
Contact No.	6742 6231/ 9828 9277	Fax No. 0
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	EURO SUCCESS SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	CROSSBORDERS LLC	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 26 September 2019 10:01 AM
To: 'CWS Motor Claims'
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005949MFSH/1-SMN 9769D
Attachments: SMN 9769D PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SMN 9769D
Date of survey: 17/9/2019
Number of days (estimated) : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 18 September 2019 12:36 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005949MFSH/1-SMN 9769D

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SMN 9769D on 17/9/2019

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Monday, 16 September 2019 4:50 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005949MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that repairer agreed survey on 17/09/2019.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Monday, 16 September 2019 4:29 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19005949MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 18 September 2019 12:36 PM
To: 'CWS Motor Claims'
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005949MFSH/1-SMN 9769D

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SMN 9769D on 17/9/2019

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Monday, 16 September 2019 4:50 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005949MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that repairer agreed survey on 17/09/2019.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 16 September 2019 4:29 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005949MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 115E

Vehicle Details

Vehicle No.: SMN9769D

Vehicle to be Exported: No

Intended Deregistration Date: 17 Sep 2019

Vehicle Make: KIA

Vehicle Model: STONIC 1.0 DCT

Primary Colour: Black

Manufacturing Year: 2019

Engine No.: G3LCKP112201

Chassis No.: KNAD6811VL6347625

Maximum Power Output: 88.3 kW (118 bhp)

Open Market Value: \$17,973.00

Original Registration Date: 04 Sep 2019

First Registration Date: 04 Sep 2019

Transfer Count: 0

Actual ARF Paid: \$7,973.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 03 Sep 2029

PARF Rebate Amount: \$5,979.00

Intended COE Rebate Details

COE Expiry Date: 03 Sep 2029

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$32,725.00

COE Rebate Amount: \$32,602.00

Total Rebate Amount: \$38,581.00

The information contained herein is correct as at 17 Sep 2019

OK

EURO SUCCESS SERV PTE. LTD
Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231 FAX: 67411019 H/P: 98289277 (AH HUAT)

Vehicle No: SMN9769D

Model: KIA STONIC

Not Authorized
17/9/19
1/5 = 2800
3dy.

QTY	List Items	Price \$
1	FRONT R/H DOOR o/s	820.00 R X
1	FRONT R/H MIRROR o/s	450.20 Daye/Blind
1	REAR R/H DOOR o/s	825.80 R X
1	R/H SIDE SKIRT o/s	455.30 graft
1	FRONT R/H DOOR LOWER GARNISH o/s	266.20 graft
1	REAR R/H DOOR LOWER GARNISH o/s	248.50 graft
1	front fender outer protector o/s	250.00 graft
1	FRONT fender o/s	401.00 o/s
	Rear fender outer protector o/s	295.00 graft
	TOTAL	
	LESS 10%	
	TOTAL	

QTY	Special Nett Items
1	FRONT R/H DOOR MECHANISM
1	REAR R/H DOOR MECHANISM
1	FRONT R/H SPORT RIM

11 150.00 X
11 150.00 X
20/way 800.00 350 S. N

\$1,100.00

Labour Charges

TO CHECK FRONT AND REAR DOOR ELECTRICAL
WIRING
TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST
REPAIR
TO RESPRAY UNDERCOATING
TO RESPRAY PAINTING AND ETC
PANEL BEATING, CUT, WELD REMOVE AND
REPLACING ABOVE PARTS

250.00 20
300.00 X
500.00 30
1000.00 600
1000.00 400

\$3,050.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

7788.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

P-2366-20
102
2129.58
3529.58
2823



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19016329/Uvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 27-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4671G	Veh. Inspected	SMN 9769D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005949MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	16/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	KIA STONIC (A)	c.c	998	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KNAD6811VL6347625	Colour	BLACK	
Odometer	975	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	KUMHO	9 mm	
L/H Front Tyre	185/65 R15	KUMHO	9 mm	
R/H Rear Tyre	185/65 R15	KUMHO	9 mm	
L/H Rear Tyre	185/65 R15	KUMHO	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/09/2019	Inspection Date	17/09/2019	
Survey held at	EURO SUCCESS SERVICES PTE. LTD 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 9769D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR O/S	TO REPAIR SEE LABOUR	850.50	-
1	FRONT MIRROR O/S	DAMAGED / SHORTED	450.20	450.20
1	REAR DOOR O/S	TO REPAIR SEE LABOUR	825.80	-
1	SIDE SKIRT O/S	GRAZED	455.30	455.30
1	FRONT DOOR LOWER GARNISH O/S	GRAZED	266.20	266.20
1	REAR DOOR LOWER GARNISH O/S	GRAZED	248.50	248.50
1	FRONT FENDER OUTER PROTECTOR O/S	GRAZED	250.00	250.00
1	FRONT FENDER O/S	DENTED / BENT	401.00	401.00
1	REAR FENDER OUTER PROTECTOR O/S	GRAZED	295.00	295.00
	LESS 10% DISCOUNT		-404.25	-236.62
			3,638.25	2,129.58
SPECIAL NETT ITEMS				
1	FRONT R/H DOOR MECHANISM (SN)	NOT NECESSARY	150.00	-
1	REAR R/H DOOR MECHANISM (SN)	NOT NECESSARY	150.00	-
1	FRONT R/H SPORT RIM (SN)	DENTED / WARPED	800.00	350.00
			1,100.00	350.00
LABOUR				
	TO CHECK FRONT AND REAR DOOR ELECTRICAL WIRING.		250.00	20.00
	TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR.	NOT NECESSARY	300.00	-
	TO RESPRAY UNDERCOATING.		500.00	30.00
	TO RESPRAY PAINTING AND ETC.		1,000.00	600.00
	PANEL BEATING,CUT,WELD REMOVE AND REPLACING ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR O/S AND REAR DOOR O/S.		1,000.00	400.00
			3,050.00	1,050.00
GRAND TOTAL			7,788.25	3,529.58



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,800.00
---	--	--	----------

Report Ref No. CS/FCI19016329/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.