

22/07/2002

ASS. REC. BY:

REF: CSS/MSG 19012361/T19f3d

Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person):

Jasmine Lok Kheng Pui

of

MSG

Date/Time:

17.9.19 10.05am

Estimated Cost:

Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

XE 82 C

Insured:

SG 2 5614B

at Workshop m/s

Yee Keong Motor

Tel:

97 802928

of

No 14 Danjurn Road

Policy No:

100057382

Claim No:

731297

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

6.9.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

17.9.19 10.19am

Person Contacted:

An Hwee

Vehicle IN

OUT

Date/Time	Action/Instruction (X) Estimate
	XE 82C - NA/MSG 19015891/24 D.O.A - 06/09/2019
	SG 2 5614B - NA/MSG 19015891/24 D.O.A - 06/09/2019
11/10/19	Dismantle: 3/10/2019 Submit PRS

Tan Jiah

MS16

SSS 11/12/11

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To: Insured Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

(Policy Condition)
 Remarks: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS : _____
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

VEH No: **XE 82C** Date: **Nov 12**
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **1** **15681**
 Colour: **Orange** A/C Insured / Std / NI / NA
 Sp. Reading: **394365** T/Radio: Insured / Std / NI / NA
 Eng/No: **JA LC 74521070000/2**
 C/No: **2**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: **Nil** / S/Rim / STD A/Rim or
 Tyre Size: F: **12 R275**
 R: **41 (17)**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Indforce**
 Front: _____ Rear: **8/8**
 R/Bal: **8** mm R/Bal: **8/8** mm
 L/Bal: **8** mm L/Bal: **8/8** mm
 D.O.A: _____ D.O.I: **01/10/19**
 Survey held at: **Yee Keong Bengun Rd**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: _____
NO 61A
\$4000-\$5000, 5 days

RECEIVED 11 OCT 2019

Date/Time: File Pass to? ☐ : Preli. Report
11/10/2019 ☐ : Final Report
 Date/Time: File Return to?

Days Of Repair: **5**
 Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp. (\$) ☐
☐ Interview (\$) ☐
☐ Test Report (\$) ☐
☐ Workshop (\$) ☐

Survey Fee	120
Transportation	
Other	
Total	11
	131

Report Format: **PRS.**
 Lump Sum / L.B.F.:

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Sep 2019		17 Sep 2019 10:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CONCERN TRADING PTE LTD, Co. Reg. No.: 198004884E		
Main Claimant:	BUILDMATE (S) PTE LTD, Co. Reg. No.: 197801401G		
Vehicle Reg. No.:	XE82C	Date of Loss:	06/09/2019 11:00 - :59 [82 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	1000827382 (Comprehensive) Coverage: 06/11/2018 - 05/11/2019
Vehicle Reg. No. (Insured):	SGZ5614B	Policy No. (Claimant):	
		Excess:	
Repairer:	Yee Keong Motor Engineering (HQ) No. 14 Penjuru Road, 609125 Jurong West - Tel: 97808928		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/09/2019]		
Driver/Custodian (Insured):	LAURA ANTOINETTE CHEW TEOW BOON (56 / Female) , NRIC: S1572353Z Email:		
Adj Asg. Remarks:	on WP. Liab: clear. Disagree on SJE. Contact: Ah Hwee @ 9780 8928.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.

XE82C

Make / Model

ISUZU / CYH52T

Vehicle Type :

B30 - Goods (Open) Lorry (Wooden Body)

Vehicle Attachment 1 :

With Crane

Vehicle Scheme :

Normal

Chassis No. :

JALCYH52TC7000012

Propellant :

Diesel

Engine No. :

6WG1416064

Motor No. :

-

Engine Capacity :

15681 cc

Power Rating :

-

Maximum Power Output :

-

Maximum Laden Weight :

34000 kg

Unladen Weight :

15200 kg

Year Of Manufacture :

2011

Original Registration Date :

02 Nov 2012

Lifespan Expiry Date :

01 Nov 2032

COE Category :

C - Goods Vehicle & Bus

Quota Premium :

\$57,889.00

COE Expiry Date :

01 Nov 2022

Road Tax Expiry Date :

01 Nov 2019

PARF Eligibility Expiry Date :

-

Inspection Due Date :

01 Nov 2020

Intended Transfer Date :

07 Oct 2019

CO2 Emission :

-

CEV/VES Rebate Utilised Amount :

-

CO Emission :

-

HC Emission :

-

NOx Emission :

-

PM Emission :

Fees To Be Paid For Transfer

Transfer Fees	\$25.00
Road Tax Renewal - 6 months (02 Nov 2019 to 01 May 2020)	\$0.00
Road Tax Renewal - 12 months (02 Nov 2019 to 01 Nov 2020)	\$0.00

Message

The fees above do not include any late road tax fees, which apply if road tax or lay-up has expired. You can use the digital service Enquire Road Tax Payable to check if there are any late road tax fees.

Any road tax that has been paid for the vehicle will be transferred to the next owner.

This vehicle has a road tax Over Payment of \$451.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

Print

OK →

Save as PDF

Copy as Text

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	401G
Vehicle Details	
Vehicle No.:	XE82C
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Oct 2019
Vehicle Make:	ISUZU
Vehicle Model:	CYH52T
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	6WG1416064
Chassis No.:	JALCYH52TC7000012
Maximum Power Output:	-
Open Market Value:	\$117,821.00
Original Registration Date:	02 Nov 2012
First Registration Date:	02 Nov 2012
Transfer Count:	1
Actual ARF Paid:	\$5,892.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Nov 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$57,889.00
COE Rebate Amount:	\$17,756.00
Total Rebate Amount:	\$17,756.00

The information contained herein is correct as at 07 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/09/2019 13:41
Date Of Accident	06/09/2019 11:45
Exact Location Of Accident	PAYA LEBAR RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE82C
Insured/Policyholder	
Name Of Registered Owner	BUILDMATE (S) PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65895388

Vehicle Particulars

Manufacturer	ISUZU
Model	-
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z19VC05002256
Cover Note Number	-

Driver

Name of Driver	LIM LIAN HUAT
NRIC No	S1780782Z
Date Of Birth	23/07/1966
Occupation	OUTDOOR
Date Of Driving Pass	14/10/1987
Driving Experience	31 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97602077
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 159 JLN TECK WHYE #13-141
Postcode	680159
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG PAYA LEBAR RD ON THE EXTREME LEFT LANE, SUDDENLY VEH B WHO WAS EXITING FROM THE PIE SLIP RD INTO PAYA LEBAR RD AND DASHED OUT TO MAIN ROAD, AS THE RESULT, I CANNOT STOP IN TIME AND HIT ONTO VEH B RIGHT FRONT PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGZ5614B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Common Statement

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to statement

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:










































...CLAIM SUBFOLDER...(Pending for Survey Report)


CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Sep 2019		17 Sep 2019 10:05 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CONCERN TRADING PTE LTD , Co. Reg. No.: 198004884E								
Main Claimant:	BUILDMATE (S) PTE LTD , Co. Reg. No.: 197801401G								
Vehicle Reg. No.:	XE82C	Date of Loss:	06/09/2019 11:00 - :59 [82 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 231297	Policy/Cover Note No.:	1000827382 (Comprehensive) Coverage: 06/11/2018 - 05/11/2019						
Vehicle Reg. No. (Insured):	SGZ5614B	Policy No. (Claimant):							
		Excess:							
Repairer:	Yee Keong Motor Engineering (HQ) No. 14 Penjuru Road, 609125 Jurong West - Tel: 97808928								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 18/09/2019]								
Driver/Custodian (Insured):	LAURA ANTOINETTE CHEW TEOW BOON (56 / Female) , NRIC: S1572353Z Email:								
Adj Asg. Remarks:	on WP. Liab: clear. Disagree on SJE. Contact: Ah Hwee @ 9780 8928.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XE82C (231297)
[SGZ5614B]
TP
BUILDMATE (S) PTE LTD
Sep 6 2019 11:00AM
[CONCERN TRADING PTE LTD]
Yee Keong Motor Engineering

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
2	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
3	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
4	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
5	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
6	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
7	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
8	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
9	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
10	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
11	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
12	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
13	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
14	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
15	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
16	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
17	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
18	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
19	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
20	07/10/19 10:47	General View								Load JPG	<input checked="" type="checkbox"/>			
21	07/10/19 10:47	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
22	07/10/19 10:47	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
23	07/10/19 10:47	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
24	07/10/19 10:47	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
25	07/10/19 10:47	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
26	07/10/19 10:47	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
27	07/10/19 10:47	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
28	07/10/19 10:47	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
29	07/10/19 10:47	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
30	07/10/19 10:47	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
31	07/10/19 10:47	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
32	07/10/19 10:47	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
33	07/10/19 10:47	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
34	07/10/19 10:47	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
35	07/10/19 10:47	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
36	07/10/19 10:47	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
Documentation									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)								Thumbnail	Print			
1	16/09/19 17:24	PRI								Load PDF				
2	16/09/19 17:24	OI ACCIDENT REPORT								Load PDF				
3	16/09/19 17:24	TP XE82C E-REPORT								Load PDF				
4	16/09/19 17:24	status of driving license								Load PDF				
5	16/09/19 17:34	Disagree on SJE								Load PDF				

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
6	16/09/19 17:34	Workshop Details		 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19016361/T1QF3E2

Date: 14/10/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1000827382

Claimant Vehicle No : XE82C

Insured Vehicle No : SGZ5614B

Date of Loss: 06/09/2019

Nature of Claim: TP

Claim No: 231297

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XE82C

Make & Model: ISUZU CYH52T, 15.7 D (M)

Engine No: 6WG1416064

Reg. Date: 02/11/2012 (Man. Year: 2011)

Chassis No: JALCYH52TC7000012

Colour: Orange

Odometer: 394365 km

Engine Capacity: 15681 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 12 R22.5

Rear Tyre Size: 12 R22.5 (D)

Front Left Side: Indforce 8 mm

Rear Left Side: Indforce 8/8 mm

Front Right Side: Indforce 8 mm

Rear Right Side: Indforce 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 17/09/2019

Date Inspected: 01/10/2019 Inspected At:

Yee Keong Motor Engineering (HQ)
No. 14 Penjuru Road
Singapore 609125

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Oct 2019)	
Parts:	N/A	ISUZU CYH52T 15.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE82C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >