

22/03/2002

ASS. REC. BY:

REF: CSS/CTI 19016371 / Eqf3ek Special Instruction:

Survivor: Steve ASSIGNMENT (Office)From (Person): Tan Kah Leong of CTI Date/Time: 16.9.19 16.44pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SME 4346X Insured: PC 574Eat Workshop m/s Sinurekad Garage Tel: 9815 8858 / 8570 9999of 38 woodlands Industrial Park E1, #05-13Policy No: DMB1SN1500171904X Claim No: SNM 1911204288C02

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 27.8.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 17.9.19 9.54a.m Person Contacted: Raymond Chua H.O.D. Endorsement: \_\_\_\_\_  
Vehicle: IN / OUT

Date/Time	Action/Instruction ( X ) Estimate Inspection: <u>38 woodlands Industrial Park E1, #05-16</u>
	<u>SME 4346X - NBA / CTI 190159991Y D.O.A - 27/08/2019</u>
	<u>PC 574E - NBA / CTI 19015999Y D.O.A - 27/08/2019</u>
	<u>Diamond: 19/9/2019</u>

Meriman

ASS. REC. BY:

Steve

REF: CT1

ASSIGNMENT

From: \_\_\_\_\_ Date: 17.9.2019

Estimated Cost: \_\_\_\_\_

OD  TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SME 4346X

at Workshop m/s Sincere Lead Garage

of 3B madland Industrial Park E1, #05-16

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>40"</sup>

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SME 4346X Yr Regn: 28/9/18

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Fit c.c. 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 717 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: GPS-3415539

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Modi: Nil /  R/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: '1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 27/8/19 D.O.I. 17/9/19

Survey held at Sincere Lead Automotive

Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV-79K repair range - 4k-5k repair days - 8 days
	<i>[Signature]</i> 26/9/2019

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 8

1)

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee: 150

2)

Add Fee:  : Site Insp (\$)

Transportation: \_\_\_\_\_

: Interview (\$)

\_\_\_\_ S + RS. SI

: Tech. Invs (\$)

Photos

: Wheel end (\$)

Others

Rep. Form: PRS

Lump Sum / B.B. (%)

TOTAL

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Sep 2019		16 Sep 2019 16:44 Assign				<b>New Assignment</b> Cancel Case

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	A & K COACH SERVICES, Co. Reg. No.: 53158641C								
Main Claimant:	NG YEW CHYE, ID: S7114913G								
Vehicle Reg. No.:	SME4346X	Date of Loss: 27/08/2019 07:00 - :59							
Claim Type:	TP / SNM19D204288C02	Policy/Cover Note No.: DMB1SN15001719044							
Vehicle Reg. No. (Insured):	PC574E	Policy No. (Claimant): GA402492/1							
		Excess: S\$750.00							
Repairer:	Sincerelead Garage Pte Ltd (HQ) 38 WOODLANDS INDUSTRIAL PARK E1, #05-13, 757700 Woodlands - Tel: 9815 8858 / 8510 9999								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/09/2019]								
<b>ASSOCIATED MAIL RECEIVED</b>		View All   Compose Case Mail							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		View All   Search Tasks   Create New Task   Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	913G
Vehicle Details	
Vehicle No.:	SME4346X
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Sep 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT HYBRID 1.5 AUTO
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	LEB6070183
Chassis No.:	GP53415539
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$17,333.00
Original Registration Date:	28 Sep 2018
First Registration Date:	28 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$7,333.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Sep 2028
PARF Rebate Amount:	\$5,499.00
Intended COE Rebate Details	
COE Expiry Date:	27 Sep 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,429.00
COE Rebate Amount:	\$29,276.00
<b>Total Rebate Amount:</b>	<b>\$34,775.00</b>

The information contained herein is correct as at 17 Sep 2019

OK

MYT319113174 / Yew Tee Automobile Tech Pte Ltd - Woodlands  
 ENTRY DATE & TIME: 27/08/2019 16:09  
 SUBMITTED BY: Toh Tze Chang

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/08/2019 16:09
Date Of Accident	27/08/2019 07:15
Exact Location Of Accident	X-JUNCTION OF WOODLANDS AVE 2 & WOODLANDS AVE 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME4346X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG YEW CHYE
NRIC No	S7114913G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94755411
Alternative Phone No	Office-94755411
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	FIT-1.5 HYBRID (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA402492/1
Cover Note Number	
<b>Driver</b>	
Name of Driver	NG YEW CHYE
NRIC No	S7114913G
Date Of Birth	29/04/1971
Occupation	INDOOR
Date Of Driving Pass	11/03/1996
Driving Experience	23 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94755411

Fax Number	
Contact Number	OFFICE-94755411
E-Mail Address	NOEMAIL
Address	BLK 894B WOODLANDS DRIVE 50 #11-43
Postcode	731894
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS WEST N.P.C
Police Station Address	ROAD: 1 WOODLANDS STREET 12 , POSTCODE: 738622 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER TO ATTACHMENT

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH TRAFFIC POLICE
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
 Policyholder's Signature  
 Date & Time:

\_\_\_\_\_  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

\_\_\_\_\_  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

*Refer to Police Report.*

*Hit & Run.*

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*  
 Policyholder's Signature  
 Date & Time:

*[Signature]*  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

*[Signature]*  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

Sketch Plan #3


**SINGAPORE  
POLICE FORCE**


T/20190827/2035

1 of 3

Police Station Of Origin:  
Woodlands West N.P.C.  
1 Woodlands Street 12 SINGAPORE 738622  
Tel No: 1800-363 9999

Report No. T/20190827/2035

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 27/08/2019 09:48		Vide Report No.: L/20190827/0043		Station Diary No.: 83	
<b>Informant's Particulars</b>					
Name of Informant: NG YEW CHYE			Address: APT BLK 894B WOODLANDS DRIVE 50 #11-43 SINGAPORE 731894		
ID Type / ID No.: NRIC NO / S7114913G			Contact No.: Home/Office: Mobile: 94755411		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 48	Date of Birth: 29/04/1971	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: OPERATION MANAGER			Driving Licence Information: Class: 3 Date of Expiry:		

<b>General Information of the Accident</b>					
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 27/08/2019 07:15	Type of Location: X-Junction	
Location: Along Road 1 Traveling Toward Road 2 WOODLANDS AVENUE 1 WOODLANDS AVENUE 2 X-JUNCTION OF WOODLANDS AVE 2 AND WOODLANDS AVE 1.					
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SME4346X	Car	HONDA	FIT HYBRID 1.5 AUTO	Black	Seriously Damaged	0

<b>Details of Vehicle Insurance</b>					
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date	
SME4346X	AXA INSURANCE SINGAPORE PTE LTD	GA402492	28/09/2018	27/09/2019	

**Sketch Plan #4**



**SINGAPORE  
POLICE FORCE**



T/20190827/2035

2 of 3

Report No. T/20190827/2035

Police Station Of Origin:  
Woodlands West N.P.C.  
1 Woodlands Street 12 SINGAPORE 738622  
Tel No: 1800-363 9999

CONTINUATION OF REPORT

**Brief Details.**

On 27/08/2019 at about 0710hrs, I was driving my car V1) SME4346X along Woodlands Ave 2 heading towards SLE. It was a 3 lane road but nearing the junction of Woodlands Ave 2 and Woodlands Ave 1, it expand to a 5 lane road. And I was on the right most lane turning right at the traffic junction. As the traffic light shown red light with green right arrow, I continue to turn right. After making the right turn, I felt and impact coming from my rear . I then stop my car and got down, only to discover V1 had been collided by another vehicle. But the other vehicle had drove off thus I did not get the vehicle registration plate number. Subsequently, I called for Police Assistance.

V1 sustain major damages on its rear left side of the car. I had an in-car camera in my car and had over the SD card to the Traffic Police Officer that was at scene. No one was injured. No government property damage. No pedestrian/cyclist involved.

Sketch Plan #5



**SINGAPORE  
POLICE FORCE**



T/20190827/2035

Police Station Of Origin:  
Woodlands West N.P.C.  
1 Woodlands Street 12 SINGAPORE 738622  
Tel No: 1800-363 9999

3 of 3  
Report No. T/20190827/2035

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
L /  
Sgt 3 MOHAMED FAEZ BIN MOHAMED SAHID

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
27/08/2019 09:48

Officer In Charge Of Case:  
TP / HRT /  
Sr Staff Sgt ESTHER CHONG  
Contact No.: 65476368

Classification Of Case:

Authentication Stamp  
NP103

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Sep 2019		16 Sep 2019 16:44 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>A &amp; K COACH SERVICES</b> , Co. Reg. No.: 53158641C								
Main Claimant:	<b>NG YEW CHYE</b> , ID: S7114913G								
Vehicle Reg. No.:	<b>SME4346X</b>	Date of Loss:	27/08/2019 07:00 - :59 [10 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D204288C02</b>	Policy/Cover Note No.:	DMB1SN15001719044						
Vehicle Reg. No. (Insured):	<b>PC574E</b>	Policy No. (Claimant):	GA402492/1						
		Excess:	S\$750.00						
Repairer:	<b>Sincerelead Garage Pte Ltd (HQ)</b> 38 WOODLANDS INDUSTRIAL PARK E1, #05-13, 757700 Woodlands - Tel: 9815 8858 / 8510 9999								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Tan Kah Leong</b> - 63896193]								
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... [Final Rpt due 25/09/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

### Claim Documents

**\*SME4346X (SNM19D204288C02)**  
**[PC574E]**  
**TP**  
**NG YEW CHYE**  
**Aug 27 2019 7:00AM**  
**[A & K COACH SERVICES]**  
**Sincerelead Garage Pte Ltd**

Upload Documents		Upload Photos	Compose New Letter	View <span style="border: 1px solid black; padding: 2px;">View in Browser</span> <input type="button" value="v"/>
<b>Assessment Reports</b>				1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)		Thumbnail Print
1	27/08/19 16:23	<b>Accident Statement</b>	Load HTM	<input type="checkbox"/>
2	16/09/19 12:23	<b>Addendum Sheet</b>	Load JPG	<input checked="" type="checkbox"/>
3	16/09/19 12:25	<b>Accident Statement Addm. #1</b>	Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>				3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
24	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
25	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
26	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
27	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
28	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
29	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
30	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
31	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
32	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
33	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
34	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
35	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
36	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
37	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
38	17/09/19 17:42	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)		Thumbnail	Print
39	17/09/19 17:42	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
40	17/09/19 17:42	General View		Load JPG	<input checked="" type="checkbox"/>
41	17/09/19 17:42	General View		Load JPG	<input checked="" type="checkbox"/>
42	17/09/19 17:42	General View		Load JPG	<input checked="" type="checkbox"/>
43	17/09/19 17:42	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
44	17/09/19 17:42	General View		Load JPG	<input checked="" type="checkbox"/>
45	17/09/19 17:42	General View		Load JPG	<input checked="" type="checkbox"/>
46	17/09/19 17:42	General View		Load JPG	<input checked="" type="checkbox"/>
47	17/09/19 17:42	General View		Load JPG	<input checked="" type="checkbox"/>
48	17/09/19 17:42	General View		Load JPG	<input checked="" type="checkbox"/>
49	17/09/19 17:42	General View		Load JPG	<input checked="" type="checkbox"/>
50	17/09/19 17:42	General View		Load JPG	<input checked="" type="checkbox"/>
51	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
52	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
53	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
54	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
55	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
56	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
57	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
58	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
59	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
60	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
61	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
62	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
63	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
64	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
65	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
66	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
67	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
68	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
69	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
70	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
71	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
72	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
73	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
74	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
75	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
76	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
77	25/09/19 19:07	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
78	25/09/19 19:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
79	25/09/19 19:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
80	25/09/19 19:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
81	25/09/19 19:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
82	25/09/19 19:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
83	25/09/19 19:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
84	25/09/19 19:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
85	25/09/19 19:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
86	25/09/19 19:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
87	25/09/19 19:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
88	25/09/19 19:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
89	25/09/19 19:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
90	25/09/19 19:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
91	25/09/19 19:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
92	25/09/19 19:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
93	25/09/19 19:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
94	25/09/19 19:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
95	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
96	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
97	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
98	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
99	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
100	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
101	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
102	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
103	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
104	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
105	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
106	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
107	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
108	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
109	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
110	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
111	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
112	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
113	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
114	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
115	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
116	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
117	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
118	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
119	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
120	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
121	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
122	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
123	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
124	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
125	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
126	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
127	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
128	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
129	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
130	25/09/19 19:08	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/09/19 15:26	INSD PC574E GIA REPORT		Load PDF <input type="checkbox"/>
2	16/09/19 16:46	PRS EMAIL		Load PDF <input type="checkbox"/>

### Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
1	27/08/19 16:23	Accident Statement		Load HTM <input type="checkbox"/>
2	16/09/19 12:23	Addendum Sheet		Load JPG <input checked="" type="checkbox"/>
3	16/09/19 12:25	Accident Statement Addm. #1		Load HTM <input type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
1	27/08/19 16:15	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	27/08/19 16:15	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	27/08/19 16:15	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	27/08/19 16:15	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
5	27/08/19 16:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	27/08/19 16:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	27/08/19 16:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	27/08/19 16:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	27/08/19 16:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	27/08/19 16:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
1	27/08/19 16:14	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	27/08/19 16:14	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	27/08/19 16:14	Sketch Plan #3	 Load JPG	<input checked="" type="checkbox"/>
4	27/08/19 16:14	Sketch Plan #4	 Load JPG	<input checked="" type="checkbox"/>
5	27/08/19 16:14	Sketch Plan #5	 Load JPG	<input checked="" type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119016371/EQF3E2

Date: 07/10/2019

#### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN15001719044
Claimant Vehicle No :	SME4346X	Insured Vehicle No :	PC574E
Date of Loss:	27/08/2019	Nature of Claim:	TP
		Claim No:	SNM19D204288C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME4346X	Engine No:	LEB6070183
Make & Model:	HONDA FIT, 1.5 HYBRID (A)	Chassis No:	GP53415539
Reg. Date:	28/09/2018 (Man. Year: 2018)	Odometer:	717 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	16/09/2019		
Date Inspected:	17/09/2019	Inspected At:	38 WOODLAND INDUSTRIAL PARK E1 # 05-16 Repairer : Sincerelead Garage Pte Ltd (HQ)
Estimated Period of Repair:	8.0 days		

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2019)
<b>Parts:</b> 144	HONDA FIT 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SME4346X)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >