

2300/2007

ASS. REC. BY:

REF:

CS/CT1190/6386/Ky-f3¹⁷

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Irene Tay Hui Ping of CT1 Date/Time: 16.9.19 19.03pm

Estimated Cost: Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: G12 1267X Insured: SMK 9293 L

at Workshop to/2 Kang Auto Engineering Tel: 65560103

of 160 sin ming Drive #02-16

Policy No: DM PCS 306305/19000 Claim No: SVM 19020 4350C02

Sum Insured: Excess:

Make of Veh: D.O.A. 13.9.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 17.9.19 9.46am Person Contacted: May Vehicle: IN/OUT

Date/Time Action/Instruction (✓) Estimate Inspection: 160 sin ming Drive #02-16

G12 1267X - CS/CT117026019/Krb2 D.O.A. 30/11/2017

SMK 9293 L - X

25/9 C1 Lm @ 3800k email & Confirm (Red = \$3006-78, 44%)

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 File pass to

RECEIVED: 8 SEP 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 26/9/19 Typist

Report Format :

Lump Sum / I.B.I. (\$) \$3800/-

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS \$

: Fines

: Others

TOTAL

200

Veh No:

S/G 1267

Regn:

12, 05

Type: M.Car / M.Cycle / Bus / Van / Lorry / ~~Truck~~ / Prime Mover /

Truck / Trailer or

Make:

Toy T120

c.c

2494

Colour:

White / Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

621533

T/Radio:

Insured / Std / NI / NA

Eng No:

C/No:

JTFH502P000035148

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

1P5R15X8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Toca OHTSU

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

13/9/19

D.O.I.

17/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S on body

The U/C / Chassis frame / Body Structure affected due to collision.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Sep 2019		16 Sep 2019 19:03 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	I-PACIFIC OFFICE PTE LTD		
Vehicle Reg. No.:	GZ1267X	Date of Loss:	13/09/2019 14:00 - :59
Claim Type:	TP / SNM19D204350C02	Policy/Cover Note No.:	DMPCSN30630519000
Vehicle Reg. No. (Insured):	SMK9298L	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Kang Auto Engineering Pte Ltd (HQ) BLK 14 SIN MING INDUSTRIAL ESTATE SECTOR 8, #D1-03, 575658 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/09/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Monday, 16 September 2019 7:00 PM
To: kangcar@singnet.com.sg; assignments; Admin A
Subject: FW: OUR REF: SNM19D204350-SMK9298L-THP - Pre-Repair Inspection GZ1267X
Attachments: DOC160919-16092019151230.pdf

Dear Lkk,

We refer to the above matter.

Please get your surveyor to liaise with Kang Car to conduct PRS.

Regards,

Irene Tay

Executive

Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896192 | F: (65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Monday, September 16, 2019 4:48 PM

To: Irene Tay <irene.tay@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; kangauto@singnet.com.sg

Subject: OUR REF: SNM19D204350-SMK9298L-THP - Pre-Repair Inspection GZ1267X

Dear Irene,

Please conduct PRS for GZ1267X.

Note : officer in charge – Irene Tay 63896192.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: kangauto@singnet.com.sg [mailto:kangauto@singnet.com.sg]

Sent: Monday, 16 September, 2019 3:17 PM

To: Claims Dept of China Taiping Insurance <e-claims@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: Pre-Repair Inspection GZ1267X

Claims Dept,

Re : Accident involving GZ1267X & SMK9298L on 13/9/2019

Attached with Esitmate of Repair & Relevant document from our client GZ1267X for your reference & retention.

Please assign your surveyor to survey on our client's Vehicle.
Please revert Claim Handler in -Charge

Yours Sincerely,
May Ang

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 889D

Vehicle Details

Vehicle No.: GZ1267X

Vehicle to be Exported: Yes

Intended Deregistration Date: 30 Sep 2019

Vehicle Make: TOYOTA

Vehicle Model: HIACE MANUAL

Primary Colour: White

Manufacturing Year: 2005

Engine No.: 2KD1357382

Chassis No.: JTFHS02P000035149

Maximum Power Output: -

Open Market Value: \$23,795.00

Original Registration Date: 19 Dec 2005

First Registration Date: 19 Dec 2005

Transfer Count: 0

Actual ARF Paid: \$1,190.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 18 Dec 2020

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

PQP Paid: \$22,416.00

COE Rebate Amount: \$5,447.00

Total Rebate Amount: \$5,447.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 16 Sep 2019

SINGAPORE ACCIDENT STATEMENT

BASIC INFORMATION			
Date of Accident:	13-SEP-19	Time of Accident:	1445 PM
Exact Location:	JUNCTION OF MEARCS LINK		

DETAILS OF OWN VEHICLE			
Vehicle Registration No.	GZ1267X		
Name of Registered Owner:	I-PACIFIC OFFICE PTE LTD		
NRIC / FIN / Passport no:	J00003889D		
Vehicle Make:	TOYOTA HILUX	Vehicle Model:	VAN
Type of Claim:	Own Damage / <u>Third Party</u> / Reporting Only		
Vehicle Category:	Private / <u>Commercial</u> / Motorcycle / Private Hire		
Name of Insurance Co:	CHINA TAIPIING		
Type of Policy:	<u>Comprehensive</u> / Third Party / Third Party, Fire & Theft		
Policy Number:	DMCVSN1767701801		

DRIVER			
Name of Driver:	MUHAMAD FADIL BIN ABU		<input type="checkbox"/> same as owner
NRIC / FIN / Passport no:	S00320801	Date of Birth:	13-10-1980
Occupation:	Indoor / <u>Outdoor</u>	Driving Pass Date:	01-12-2009
Contact Number:	87930925	Gender:	<u>Male</u> / Female
Address:	31K1818 Boun Lay Drive #03-614 S 64081		
Relationship with Owner:	Owner / <u>Employee</u> / Spouse / Child / Hirer / Other:		

GENERAL INFORMATION OF THE ACCIDENT			
Type of Collision:	Chain collision / Side Swipe / Front to Rear / Others:		
Weather Condition:	<u>Clear</u> / Raining / Others:		
Road Surface:	<u>Dry</u> / Wet / Others:		
Was anybody injured?	Yes / <u>No</u>	Police Report Made?	Yes / <u>No</u>
No. of passenger onboard (including driver):	1 (Driver)		

DETAILS OF OTHER VEHICLE			
	Vehicle 1	Vehicle 2	Vehicle 3
Vehicle Registration No:	SMK9298L		
Vehicle Make / Model:	VOLKSWAGEN GOLF		
Name of Driver:	XING YANWEI		
NRIC / FIN / Passport no:	S82863551		
Contact Number:			
Name of Insurance Co:	CHINA		

DETAILS OF WITNESS	
Name:	Contact Info:

DETAILS OF INJURED PERSON			
	Person 1	Person 2	Person 3
Name / In which vehicle?:			

Driver's Declaration: I declare that the information given in this report are true and accurate to the best of my collection and I bear full responsibility for any consequences arising from incomplete or inaccurate information that are submitted.


 Signature of Driver

Date and time

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13.9.19, along Junction of Shearers Link, I move on going straight when traffic is in my favour, suddenly a volkswagen SMK9298L from the right ~~try~~ try to turn Left where its not suppose to resulted hitting onto the right side of my van.

Nobody was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Vehicle Insurance Particulars Result

Vehicle No.	Incident Date/Time	Insurance Company Name
SMK9298L	13 Sep 2019 / 21:00:00	CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD



中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD

Co. Reg. No. 200205384E

ME300/C

R EN

AM0640A

Cov.Type: F

PLM 322464

MOTOR COMMERCIAL VEHICLE

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)

Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960

Road Transport Act, 1987 (Malaysia)

Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

CERTIFICATE No. **DMCVEN1767701801** Engine No. **2KD1357382**
Chassis No. **JTFHS029000035149**

1. Index Mark and Registration Number of Vehicle **GB1167X**
2. Name of Policy Holder **M/S I-PACIFIC OFFICE PTE LTD**
3. Effective date of the Commencement of insurance for the purposes of the Regulations, Ordinance or Enactment **19 December 2018**
4. Date of Expiry of Insurance **18 December 2019**

5. Persons or Classes of Persons entitled to drive*

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

- (1) Use in connection with the Policyholder's business.
 - (2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
 - (3) Use for social, domestic or pleasure purposes.
- The Policy does not cover.

- (1) Use for hire or reward or racing, pace-making, reliability trial or speed testing.
- (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By:

Authorised Officer

Authorised Signatory

REPUBLIC OF SINGAPORE DRIVING LICENCE

S80320801

MUHAMAD FADIL BIN ABUBAKAR

13 Oct 1980

01 Sep 2018

0002840771E

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S80320801

MUHAMAD FADIL BIN ABU BAKAR

محمد فاديل بن ابو بكر

Malay

Date of birth: 13-10-1980 Sex: M

Country of birth: SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

EFFECTIVE DATE

Class 2B	Motorcycles <= 200 cc	25 Jan 2008
Class 2A	Motorcycles between 201 cc and 400 cc	13 Oct 2008
Class 3	Motor cars with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver; and other motor vehicles with unladen weight <= 2500kg	04 Dec 2006

Licence No: S80320801

S80320801

S80320801

13-10-2010

ART BLK 181A BOON LAY DRIVE #03-614


SINGAPORE 61181

S80320801

21/07/2013









AUTO ENGINEERING PTE LTD

Sin Ming Auto City

160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015

Email: kangauto@singnet.com.sg



M/S CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909.
Attn : Motor Claims Dept

Date: 16/09/2019

Your Insured: SMK9298L
Our Insured : GZ1267X
OUR REF: TP19/09/1143

Notice to conduct Pre-Repair Inspection within 2 working days pursuant to paragraph 6.2 of Pre-Action Protocol for NIMA Case.

We act for i-Pacific Office Pte Ltd the owner of motor vehicle **GZ1267X** who has appointed us **Kang Auto Engineering Pte Ltd** to act on his behalf to claim against your insured's vehicle. **SMK9298L** in regards to the road traffic accident on 13/9/2019.

Please be informed that the said motor vehicle can be inspected at :

Kang Auto Engineering Pte Ltd
Sin Ming AutoCity
160 Sin Ming Drive, #02-16
Singapore 575722
Tel: 6556 0103 fax: 6556 1015
Contact : May

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding and intervening Saturday, Sunday or Public holiday, the said workshop will commence repairs thereafter without further reference to you.

YOURS FAITHFULLY,


KANG AUTO ENGINEERING PTE LTD

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

M/S i-PACIFIC OFFICE PTE LTD	POLICY NO :	THIRD PARTY CLAIMS
NORTH SPRING BIZHUB	OUR REF :	TP19/09/1143
#04-36	VEHICLE NO :	GZ1267X
7 YIHUN INDUSTRIAL STREET 1	MAKE/MODEL :	TOYOTA HIACE
SINGAPORE 768162	DATE OF ACCIDENT :	13.09.2019

1 PC	FRONT BUMPER	B11 C M	S\$	497.00	✓
1 PC	FRONT BUMPER SIDE RETAINER (RH)	D11	20.00	✓	
1 PC	FRONT BUMPER CLIPS	M	30.00	✓	
1 PC	FRONT DOOR (RH)	R	845.00	✓	
1 PC	FRONT DOOR LOCK (RH)	R	162.90	X	
1 PC	FRONT DOOR REGULATORY (RH)	D11	195.65	✓	
1 PC	FRONT DOOR MOTOR (RH)	Jm	409.35	✓	
1 PC	FRONT DOOR HINGES (RH)	R	65.00	✓	
1 PC	FRONT DOOR STEP PANEL (RH)	R	218.30	✓	
1 PC	DOOR PILLAR (RH)	R	682.50	X	
1 PC	FRONT FENDER (RH)	R	280.30	✓	
1 PC	FRONT FENDER INNER SHIELD (RH)	Jm	108.50	X	
1 PC	FRONT MUDFLAG (RH)	M	124.40	✓	
1 PC	RH SLIDING DOOR	R	958.00	✓	
1 PC	RH SLIDING DOOR RUBBER	Jm	256.80	X	
		S\$	4,853.70		
		LESS	25%	1,213.43	
		S\$	3,640.28		

1 PC	FRONT DOOR COMPANY STICKER	S\$	M	20.00	S'NETT ✓
------	----------------------------	-----	---	-------	----------

TOWING CHARGES	S\$	60.00	50%
TO CHECK WIRING		50.00	20%
TO REMOVE & REFIX NEW DOOR		60.00	✓
TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL		80.00	60%
TO PUTTY AND SPRAY PAINT CHARGES		980.00	700%
LABOUR CHARGES		800.00	720%
		S\$	5,690.28

SGD FIVE THOUSAND SIX HUNDRED NINETY AND CENTS TWENTY-EIGHT ONLY.

YOURS FAITHFULLY,

KANG AUTO ENGINEERING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To remove before/after spray painting
- To display damaged parts during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Admitted by Repairer
Signature:

Not Notarised
L1 Sy @ 3800h
Penny After 12m
6 days

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

KANG

AUTO ENGINEERING PTE LTD

Sin Ming Auto City

160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015
Email: kangauto@singnet.com.sg



M/S I-PACIFIC OFFICE PTE LTD
NORTH SPRING BIZHUB
#04-36
7 YIHUN INDUSTRIAL STREET 1
SINGAPORE 768162

POLICY NO : THIRD PARTY CLAIMS
OUR REF : TP19/09/1143
VEHICLE NO : GZ1267X
MAKE/MODEL : TOYOTA HIACE
DATE : 18-Sep-19

SUPPLEMENTARY

1 PC HEADLAMP (RH)
1 PC HEADLAMP BRACKET (RH)
1 PC AIR CLEANER BOX
1 PC FRONT BUMPER BEAM
1 PC FRONT BUMPER BRACKET(RH)
1 PC FRONT DOOR STEP GARNISH

	S\$	67	358.00	✓
		br	68.00	✓
		cm	330.00	—
	(mc)	r	205.10	X
	(mc)	r	115.50	X
		rs	145.40	✓
	S\$		1,222.00	
LESS	25%		305.50	
	S\$		916.50	

LABOUR CHARGES

S\$	~	200.00	X
S\$		1,116.50	

SGD ONE THOUSAND ONE HUNDRED SIXTEEN AND CENTS FIFTY ONLY.

YOURS FAITHFULLY,


KANG AUTO ENGINEERING PTE LTD

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19016386/KYF3N2

Date: 30/09/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30630519000	
Claimant Vehicle No :	GZ1267X	Insured Vehicle No :	SMK9298L	
Date of Loss:	13/09/2019	Nature of Claim:	TP	Claim No: SNM19D204350C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GZ1267X	Engine No:	2KD1357382
Make & Model:	TOYOTA HIACE, 3.0 D DX (A)	Chassis No:	JTFHS02P000035149
Reg. Date:	19/12/2005 (Man. Year: 2005)	Odometer:	621533 km
Colour:	White/Blue		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8
Front Left Side:	OHTSU 7 mm	Rear Left Side:	OHTSU 7 mm
Front Right Side:	OHTSU 7 mm	Rear Right Side:	OHTSU 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,576.77	3,428.30	1,148.47	25.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,230.00	1,610.00	620.00	27.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,806.77	5,038.30	1,768.47	25.98
Approved Total (Overridden) (\$\$)		3,800.00		
Nett Amount (\$\$)	6,806.77	3,800.00	3,006.77	44.17

INSPECTION

Date of Assignment:	16/09/2019	
Date Inspected:	17/09/2019	Inspected At: 160 SIN MING DRIVE #02-16 SIN MING AUTOCITY SINGAPORE 575722 REPAIRER: KANG AUTO ENGINEERING PTE LTD

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Sep 2019)
Parts:	213	TOYOTA HIACE 3.0 D DX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ1267X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent/Cracked	497.00 FL	*497.00 FL
2	1		*FRONT BUMPER SIDE RETAINER (RH)	Distorted	20.00 FL	*20.00 FL
3	1		*FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
4	1		*FRONT DOOR (RH)	Bent	845.00 FL	*845.00 FL
5	1		*FRONT DOOR LOCK (RH)	Repair	162.90 FL	*- FL
6	1		*FRONT DOOR REGULATORY (RH)	Distorted	195.65 FL	*195.65 FL
7	1		*FRONT DOOR MOTOR (RH)	Jammed	409.35 FL	*409.35 FL
8	1		*FRONT DOOR HINGES (RH)	Bent	65.00 FL	*65.00 FL
9	1		*FRONT DOOR STEP PANEL (RH)	Bent	218.30 FL	*218.30 FL
10	1		*DOOR PILLAR (RH)	Repair	682.50 FL	*- FL
11	1		*FRONT FENDER (RH)	Bent	280.30 FL	*280.30 FL
12	1		*FRONT FENDER INNER SHIELD (RH)	Serviceable	108.50 FL	*- FL
13	1		*FRONT MUDFLAG (RH)	Missing	124.40 FL	*124.40 FL
14	1		*RH SLIDING DOOR	Bent	958.00 FL	*958.00 FL
15	1		*RH SLIDING DOOR RUBBER	Serviceable	256.80 FL	*- FL
16	1		*HEADLAMP (RH)	Cut	358.00 FL	*358.00 FL
17	1		*HEADLAMP BRACKET (RH)	Distorted	68.00 FL	*68.00 FL
18	1		*AIR CLEANER BOX	Cracked	330.00 FL	*330.00 FL
19	1		*FRONT BUMPER BEAM (REPAIR)	Not Consistent With The Impact	205.10 FL	*- FL
20	1		*FRONT BUMPER BRACKET (RH) (REPAIR)	Not Consistent With The Impact	115.50 FL	*- FL
21	1		*FRONT DOOR STEP GARNISH	Dented	145.40 FL	*145.40 FL
22	1		*FRONT DOOR COMPANY STICKER	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,095.70	4,564.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,518.93	1,136.10
Total Parts (\$\$)	4,576.77	3,428.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	60.00	50.00
2	TO CHECK WIRING	New	50.00	20.00
3	TO REMOVE & REFIX NEW DOOR	New	60.00	60.00
4	TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL	New	80.00	60.00
5	TO PUTTY AND SPRAY PAINT CHARGES	New	980.00	700.00
6	LABOUR CHARGES	New	800.00	720.00
7	LABOUR CHARGES	New	200.00	0.00
Gross Labour Cost (S\$)			2,230.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >