

72003368

ASS. REC. BY:

REF: CS/ASM19016412/NTD3⁵²

Special Instruction:

Assigner: NOZ

ASSIGNMENT (Office)

From (Person): Stacy Ng

of ASM (AXA)

Date/Time: 17/09/2019 @ 9.28am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PA 2621A

Insured:

at Workshop m/s

SC Auto

Tel: 6758 2222

of

51 Senoko Road

Policy No:

Claim No: SQM020Q0

Sum Insured:

Excess: TBA

Make of Veh:

D.O.A. 12/09/2019

(Client's Record)

Investigation

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:37am @ 17/09/19 Person Contacted:

Hannimah

Vehicle ID: (LOUT)

Date/Time	Action/Instruction	Estimate	Remarks
	PA 2621A - X		Pls Request for SCDF Report, maintenance record copy of driver's DL & IC.
26/9-	Re-sent IA with MV in Smart claim		
	Submit for extensive total loss.		

Market value -> \$16,000 LTA \$8,974 NV: \$7,026

PREPARED BY: Naz

REP: ASM(CAXA)

ASSIGNMENT

From: Investigation (Fire) Date: 18/9/19

Veh No: PA 2621A Yr Regt: 7 APR 2001
Type: M.Car / M.Cycle (Bus) / Van / Lorry / Taxi / Prime Mover /

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PA 2621A

at Workshop m/s

of 3 Kwong Min Road S 628706

Insured:

Policy No:

Claims No:

Sum Insured: Excess: TBA

(Client's Record)

Make of Veh: 9am - 6pm
Lai Mui @ 9239 9142

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 16k.

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Truck / Trailer or

Make: NISSAN JP252LSNRA c.c. 6,925

Colour: MULTI-COLOURED A/C: Insured / Std / NI / NA

Sp. Reading: N/A (BURNED) T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JP252LSN00011

Gen. Cond: Good / Fair / Poor Burnt

Steering: Inorder / Jammed / Leaked Burnt or

Brake: Inorder / Jammed / Leaked Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 11R22.5

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 4 mm

L/Bal. 4 mm

D.O.A. 12/9/19

Survey held at YEON BROTHERS TRANSPORT PTE. LTD

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
WIDE BUS BURNT.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Pls Request for SCDF Report, Maintenance Road copy of driver's DL & IC.
	COE Rebate \$8,974.00
	- uneconomical to repair. Recommend total loss.
	market value check with Marcus.
RECEIVED 3 4 NOV 2019	

Date/Time, File Pass to? : Preli. Report

Ali Typist : Final Report

Date/Time, File Return to?

Report Format: OD

Lump Sum / U.S.D.:

Days Of Repair: -

Resurvey No. of Trip: -

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Insp (\$)

: Weekend (\$)

Survey Fee: 2.00

Transportation: 3 + PS. SI

Photo:

Other: SCDF \$170.00

TOTAL

Stamp: LKK (QA) 24/10/19
Signature: [Handwritten]

Fire Incident Questions

10. When & Where was the insurance/accident/fire report made?

Next day.

11. How long was this vehicle owned? Bought new or Pre-owned?

NEL.

12. Only Driver or Sharing?

Only Driver.

13. How often was the vehicle driven?

Daily.

14. Who brings the vehicle for Servicing/ Inspection?

2 weeks Servicing prior to fire.

~~outside~~ own company in house workshop.

15. Any issue/abnormalities before the incident?

NO issue.

16. Any modifications/ Sounds systems to the vehicle?

NO mod.

17. Person in-charge contact/ Fleet manager?

18. Servicing records/Inspection records/ Route details, record/ Scene photos or videos?

Company office staff took photo.

◀ Service Request Details

Claim

S9M020QO

Reference

None 

Loss Date

September 12, 2019

Report Date

Sep 17, 2019 9:26:06 AM

Request Date

September 17, 2019

Due Date

September 24, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Fire

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

PA2621A

Model
NISXXX

Service Address

...

Primary Contact/Insured

AERO SUPPLY CHARTERED BUS & TRANSPORT TRADING
NO. 3 KWONG MIN ROAD, 628706, Singapore
92333889
INSURANCE@SCAUTO.COM.SG

Claim Handler

KHOR Saw Theng
6568804754
sawtheng.khor@axa.com.sg

Additional Instructions

-Pls assign Bryan -SC Auto -Pls request for SCDF report, maintenance record for this vehicle, copy o...
(expand)

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

Date: 26/9/2019

To : AXA Insurance Pte Ltd

Survey details

Date of loss	12-Sep-19
Date of appointment	27-Sep-19
Date of survey	18-Sep-19
Location of survey	Komoco Motor

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	PA 2621A
Make and Model	HYUNDAI ELANTRA
Date of registration	7/4/2001
Excess	NIL
Market Value	\$16,000
Parf Rebate	\$8,974
Nett Loss	\$7,026

Repair details

Initial Estimate	\$0
------------------	-----

Proposed/Revised repair cost:

Parts	TOTAL LOSS
Check item	\$0
Labour	\$0
Total	TOTAL LOSS
Lump Sum(if applicable)	

Number of days of repair	0
--------------------------	---

Remarks:

PENDING SCDF REPORT
TOTAL LOSS

DHAKAL Raghav

From: Hamimah Bte Jamaluden <hamimah.j@scauto.com.sg>
Sent: Monday, September 16, 2019 5:07 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: claims@scauto.com.sg
Subject: [EXTERNAL] Accident Involving PA2621A on 12.09.2019
Attachments: SAS2669728.PDF; IMG-20190913-WA0152.jpg; IMG-20190913-WA0153.jpg; IMG-20190913-WA0154.jpg

Categories: Raghav

Dear Sir/Mdm

We refer to the above mentioned accident.

Please be informed that the vehicle was on fire and it is beyond repair.

We are submitting the claim on behalf of our mutual client.

Attached GIA report and photos your necessary. Please advise if you require any other documents.

Meanwhile, please let us have your appointed surveyor to arrange for the survey.

Thank you

Hamimah

Customer Care Advisor

D +65 6571 9958

E hamimah.j@scauto.com.sg

SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road Singapore 758133

T 6758 2222 F 6257 6931

scauto.com.sg

Singapore • Hong Kong • Myanmar



SC AUTO

Global Standards. Local Support

Disclaimer Clause:
This email may contain PRIVILEGED and CONFIDENTIAL informations which is only intended for the use of the named addressee(s). Its contents do not constitute a commitment by SC Auto Industries (S) Pte Ltd except where provided for in a written agreement. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you have received this e-mail in error, please contact the sender immediately and permanently delete the original e-mail and any printout thereof.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

Date: 23/9/2019

To : AXA Insurance Pte Ltd

Survey details

Date of loss	12-Sep-19
Date of appointment	17-Sep-19
Date of survey	18-Sep-19
Location of survey	SC Auto

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	PA 2621A
Make and Model	Nissan JP252ISNRA
Date of registration	7/4/2001
Excess	0.00
Market Value	TBA
Parf Rebate	\$8,974
Nett Loss	\$0

Repair details

Initial Estimate	\$0
------------------	-----

Proposed/Revised repair cost:

Parts	TOTAL LOSS
Check item	\$0
Labour	\$0
Total	TOTAL LOSS
Lump Sum(if applicable)	

Number of days of repair	5
--------------------------	---

Remarks:

PENDING SCDF REPORT
TOTAL LOSS

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/09/2019 11:41
Date Of Accident	12/09/2019 20:10
Exact Location Of Accident	BETWEEN JURONG EAST CENTRAL & BUKIT BATOK AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PA2621A
Insured/Policyholder	
Name Of Registered Owner	AERO SUPPLY CHARTERED BUS & TRANSPORT TRADING
Co Reg No	52807823B
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63165196

Vehicle Particulars

Manufacturer	NISSAN
Model	JP252LSNRA

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	BUS
------------------	-----

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	P1694365
Cover Note Number	

Driver

Name of Driver	KHOR GIM BEE
NRIC No	S0220549A
Date Of Birth	14/05/1954
Occupation	OUTDOOR
Date Of Driving Pass	19/08/1982
Driving Experience	37 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97403599
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 209 BUKIT BATOK ST 21 #05-172
Postcode	650209
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	FIRE, EXPLOSION OR LIGHTNING
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-6659999 - FAX NO: 66655793
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT NO. J/20190914/2032

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 16/4

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE
POLICE FORCE



J/20190914/2032



2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20190914/2032

I am lodging this report for my company follow up action.

Signature Of Officer Recording The Report: J / Sgt 2 TAN HUAY HOCK	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 14/09/2019 11 44
Officer In-Charge Of Case J / Jurong Police Divisional Investigation Branch / Sr Staff Sgt MOHAMED ARIFF BIN MOHAMED KHAIR Contact No.: 67910000	Classification Of Case
Authentication Stamp 	

Annex A

Transaction ref: 20151030114909424116

The owner and vehicle particulars for Vehicle No. PA2621A as at 30 Oct 2015 are as follows:

1. Name	: AERO SUPPLY CHARTERED BUS & TRANSPORT TRADING
2. Identification No. Type	: Business
3. Identification No.	: 52807823B
4. Place Of Passport Issue	: -
5. Vehicle No.	: PA2621A
6. Previous Vehicle No.	: -
7. Effective Date of Ownership	: 30 Oct 2015
8. Original Registration Date	: 07 Apr 2001
9. First Registration Date	: 07 Apr 2001
10. Vehicle Type	: Z20 - Private Hire (Chauffeur) Bus/Coach/Minibus
11. Vehicle Scheme	: Public Service Vehicle (Others)
12. Attachment 1	: Air-Conditioned
13. Attachment 2	: -
14. Attachment 3	: -
15. Vehicle Make	: NISSAN
16. Vehicle Model	: JP252LSNRA
17. Year of Manufacture	: 2000
18. Primary Colour	: Multi-Colour
19. Secondary Colour	: -
20. Passenger Capacity	: 43
21. Chassis/Trailer Chassis No.	: JP252LSN00011 / -
22. Propellant	: Diesel
23. Engine No./Motor No.	: FE6213575D / -
24. Engine Capacity(cc)/Power Rating(kW)	: 6925 / -
25. Maximum Power Output(kW/bhp)	: - / -
26. Unladen Weight(kg)	: 9640

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Business
Owner ID:	823B
Vehicle Details	
Vehicle No.:	PA2621A
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Sep 2019
Vehicle Make:	NISSAN
Vehicle Model:	JP252LSNRA
Primary Colour:	Multicolor
Manufacturing Year:	2000
Engine No.:	FE6213575D
Chassis No.:	JP252LSN00011
Maximum Power Output:	-
Open Market Value:	\$105,689.00
Original Registration Date:	07 Apr 2001
First Registration Date:	07 Apr 2001
Transfer Count:	3
Actual ARF Paid:	\$5,285.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	06 Apr 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$30,401.00
COE Rebate Amount:	\$8,974.00
Total Rebate Amount:	\$8,974.00

The information contained herein is correct as at 20 Sep 2019

OK

> Back to OneMotoring

Enquiry on Vehicle Recall - Vehicle Specific

* ONLY INFORMATION ON VEHICLE RECALLS SUBMITTED FROM 9 APRIL 2007 IS AVAILABLE

Vehicle Owner Particulars

Owner ID Type:	Business
Owner ID:	823B

Vehicle Details

Vehicle Registration number:	PA2621A
Make:	NISSAN
Vehicle Model:	JP252LSNRA
Engine No.:	FE6213575D
Chassis No.:	JP252LSN00011

Recall Details

No Recall Detail records

OK

YEOH BROTHERS TRANSPORT PTE LTD

No.3 Kwong Min Road Singapore 628706

Tel: 6265 9181, 6265 5209 Fax: 6266 6890, 6261 1841

Email: sales@yeohbrothers.com.sg Website: www.yeosbrother.com.sg

Reg No. 201311586H GSTN: 201311586H

Invoice To
AERO SUPPLY CHARTERED BUS & TPT TRADING No.3 Kwong Min Road Singapore 628706 Attn : Mr Alvin Yeoh

Tax Invoice

Invoice No.: YB/ VS140082

Date: 28/6/2019

Terms: Net 30

Attn:

Your Ref. No.:

Our Ref. No.:

ITEM	PARTICULARS	AMOUNT
Vehicle servicing	TO PROVIDE VEHICLE MAINTENNACE & SERVICING FOR THE MONTH OF JUNE 2019	
Vehicle servicing	VEHICLE NUM: PA 2621 A	45.00
	DATE OF SERVICING : 17/06/2019, REF NO: WS0577	20.00
	CHANGE PIPE	
	LABOUR CHARGES	
Vehicle servicing	VEHICLE NUM: PC 7264 D	35.00
Vehicle servicing	DATE OF SERVICING : 11/06/2019, REF NO: WS0576	20.00
	SIDE SIGNAL LIGHT LED YELLOW	
	LABOUR CHARGES	
Vehicle servicing	VEHICLE NUM: PA 2621 A	15.00
Vehicle servicing	DATE OF SERVICING : 06/06/2019, REF NO: WS0575	30.00
	SCREW (10MM)	
	LABOUR CHARGES	

Subtotal \$165.00

GST 7% \$11.55

Total \$176.55


Order Issued By



YEOH BROTHERS TRANSPORT PTE LTD

No.3 Kwong Min Road Singapore 628706

Tel: 6265 9181, 6265 5209 Fax: 6266 6890, 6261 1841

Email: sales@yeohbrothers.com.sg Website: www.yeosbrother.com.sg

Reg No. 201311586H GSTN: 201311586H

Tax Invoice

Invoice No.: YB/ VS140083

Date: 31/7/2019

Terms: Net 30

Invoice To
AERO SUPPLY CHARTERED BUS & TPT TRADING No.3 Kwong Min Road Singapore 628706 Attn : Mr Alvin Yeoh

Attn:

Your Ref. No.:

Our Ref. No.:

ITEM	PARTICULARS	AMOUNT
Vehicle servicing	TO PROVIDE VEHICLE MAINTENNACE & SERVICING FOR THE MONTH OF JULY 2019 VEHICLE NUM: PA 9241 DATE OF SERVICING : 06/07/2019, REF NO: WS0580	
Vehicle servicing	ENGINE OIL	70.00
Vehicle servicing	OIL FILTER	15.00
Vehicle servicing	AIR FILTER	20.00
Vehicle servicing	LABOUR CHARGES, GEAR BOX OIL, BATTERY WATER, ADJUST BRAKE & CLUTCH	40.00
		<i>NS</i>
Vehicle servicing	VEHICLE NUM: PA 9548 H DATE OF SERVICING : 09/07/2019, REF NO: WS0581	
Vehicle servicing	ENGINE OIL	80.00
Vehicle servicing	OIL FILTER	12.00
Vehicle servicing	AIR FILTER	18.00
Vehicle servicing	LABOUR CHARGES	40.00
		<i>NS</i>
Vehicle servicing	VEHICLE NUM: PA 9241 DATE OF SERVICING : 09/07/2019, REF NO: WS0582	
Vehicle servicing	STEEL PLATE CLOTH	40.00
Vehicle servicing	STEEL PLATE EAR	60.00
Vehicle servicing	LABOUR CHARGES	65.00
		<i>NS</i>
Vehicle servicing	VEHICLE NUM: PA 2353 DATE OF SERVICING : 22/07/2019, REF NO: WS0583	
Vehicle servicing	WINDING PIPE IRON	55.00
Vehicle servicing	STARTER MOTOR	125.00
Vehicle servicing	LABOUR CHARGES	45.00
		<i>NS</i>

Subtotal

GST 7%

Total

Order Issued By
Page 1



YEOH BROTHERS TRANSPORT PTE LTD

No.3 Kwong Min Road Singapore 628706

Tel: 6265 9181, 6265 5209 Fax: 6266 6890, 6261 1841

Email: sales@yeohbrothers.com.sg Website: www.yeosbrother.com.sg

Reg No. 201311586H GSTN: 201311586H

Invoice To
AERO SUPPLY CHARTERED BUS & TPT TRADING No.3 Kwong Min Road Singapore 628706 Attn : Mr Alvin Yeoh

Tax Invoice

Invoice No.: YB/ VS140083

Date: 31/7/2019

Terms: Net 30

Attn:

Your Ref. No.:

Our Ref. No.:

ITEM	PARTICULARS	AMOUNT
Vehicle servicing	VEHICLE NUM: PA 2621 DATE OF SERVICING : 25/07/2019, REF NO: WS0584 SEAL ASSY 1 SET (447040-0091) & GASKET KIT (447299-221)	350.00
Vehicle servicing	COMPRESSURE OIL 1 LITER	100.00
Vehicle servicing	TOP UP 2KGS GAS	60.00
Vehicle servicing	LABOUR CHARGES	85.00 <i>175</i>
Vehicle servicing	VEHICLE NUM: PC 7264 DATE OF SERVICING : 31/07/2019, REF NO: WS0585 ENGINE OIL	105.00
Vehicle servicing	OIL FILTER	46.00
Vehicle servicing	AIR FILTER	28.00
Vehicle servicing	LABOUR CHARGES	80.00 <i>259</i>
Vehicle servicing	VEHICLE NUM: PC 7264 DATE OF SERVICING : 30/07/2019, REF NO: WS0586 LABOUR CHARGES TO CHECK JOINT SPEEDOMETER	25.00

Subtotal \$1,564.00

GST 7% \$109.48

Total \$1,673.48

Order Issued By
Page 2

PA 2621





NO 4

A/15/18/19

11.05.20

21-

W/S 0187



O - Dent X - Scratch

		Checks	Comments
1	Engine Oil	<input type="checkbox"/>	
2	Oil Filter	<input type="checkbox"/>	
3	Diesel Filter	<input type="checkbox"/>	
4	Air Filter	<input type="checkbox"/>	
5	Gear Box Oil	<input type="checkbox"/>	
6	Steering Hydraulic Oil	<input checked="" type="checkbox"/>	3L # 36.00
7	Battery Water	<input type="checkbox"/>	
8	Cycle Pin & Bush	<input type="checkbox"/>	
9	Adjust brake and clutch	<input type="checkbox"/>	
10	Internal and External Lights	<input type="checkbox"/>	
11	Horn & Wiper	<input type="checkbox"/>	
12	AirCon System	<input type="checkbox"/>	
13	Passenger Seats	<input type="checkbox"/>	
14	Tyre tread & Pressure	<input type="checkbox"/>	
15	Belts Checking	<input type="checkbox"/>	
16	Battery Terminal Cleaning	<input type="checkbox"/>	
17	AirCon : Top Up Gas	<input type="checkbox"/>	

Comments:

Signature of Driver
H/P:

Signature of Mechanic
Name:

Workshop Use Only

Bus Date Out:

Bus Time Out:

Office Use Only

Received Date:

Processed Date:





K104

1/A

NS0590

MAINTENANCE & SERVICING CHECKLIST

Vehicle No.	Mileage	Driver	Date In	Time In
P22621A		Khor Gim Bee	22/8/19	9.16am



O - Dent X - Scratch

		Checks	Comments	
1	Engine Oil	机油	<input type="checkbox"/>	
2	Oil Filter	机油滤芯	<input type="checkbox"/>	
3	Diesel Filter	柴油网	<input type="checkbox"/>	
4	Air Filter	空气滤芯	<input type="checkbox"/>	
5	Gear Box Oil	变速箱油	<input type="checkbox"/>	
6	Steering Hydraulic Oil	方向机油	<input type="checkbox"/>	
7	Battery Water	电池水	<input type="checkbox"/>	
8	Cycle Pin & Bush	钢板销子和套	<input type="checkbox"/>	
9	Adjust brake and clutch	调刹车和离合器	<input checked="" type="checkbox"/>	
10	Internal and External Lights	灯	<input type="checkbox"/>	
11	Horn & Wiper	喇叭与雨刷	<input type="checkbox"/>	
12	Aircon System	空调	<input type="checkbox"/>	
13	Passenger Seats	椅子	<input type="checkbox"/>	
14	Tyre thread & Pressure	轮胎花纹和气压	<input type="checkbox"/>	
15	Belts Checking	皮带	<input type="checkbox"/>	
16	Battery Terminal Cleaning	电瓶连头清洗	<input type="checkbox"/>	
17	AirCon : Top Up Gas	空调制冷剂	<input type="checkbox"/>	

Comments:

Signature of Driver
H/P:

Signature of Mechanic
Name:

Workshop Use Only	
Bus Date Out:	
Bus Time Out:	

Office Use Only	
Received Date:	
Processed Date:	



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20190912/0862	LOCATION OF FIRE:		
FIRE REPORTED ON : 12 September 2019	Along Jurong East Flyover		
TIME OF CALL : 20:19:46 hrs	towards Jurong East Central / Bukit Batok Avenue 1		
STATION COVERAGE : Bukit Batok Fire Station	Singapore		
2. INCIDENT INFORMATION			
FIRE INVOLVED: A Nissan bus (PA 2621A) at the above said location.			
METHOD OF EXTINGUISHMENT: By SCDF crew using four dry powder fire extinguishers, compressed air foam backpack and two 38mm hose line jets from fire appliances.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating at the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the bus was damaged. The nearby road concrete barrier and railings sustained varying degrees of heat and smoke damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			
EE YONG EN JOEL for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.