



Your Ref : S9M020QO

Date: 05th November 2019

Our Ref : CS/ASM19016412/Ntd3s2

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Stacey Ng

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE PA 2621A
ACCIDENT ON 12/09/2019**

Instruction was received to inspect the vehicle Reg. No. PA 2621A. The inspection was conducted on 18/09/2019 at the premises of M/s SC Auto Industries (Singapore) Pte Ltd, 3 Kwong Min Road Singapore 628706.

The following vehicle information was recorded:

| | |
|----------------------|---------------------|
| Registration Number | : PA 2621A |
| Make/Model | : Nissan JP252LSNRA |
| Year of Registration | : 2001 |
| Body Colour | : Multicolor |
| Chassis Number | : JP252LSN00011 |
| Engine Capacity | : 6925 cc |
| Speedometer Reading | : Burned |

The whole bus burnt. (Details see photographs enclosed).

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as “**uneconomical Total Loss**”.

| | | |
|------------------------------------|------|-----------------|
| Market Value | S\$ | 16,000.00 |
| Less: LTA Reimbursement Value (RV) | (S\$ | 8,974.00) |
| Nett Liability | S\$ | <u>7,026.00</u> |

Vehicle Inspected By:

MUHD NAZRIL (NAZ)
Technical Investigator
LL.B. (Hons) London

K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.