

ASS. REC. RT REF 083/SMOI8017605/C19031
 Surveyor Guo Qiang ASSIGNMENT (Office)
 From (Person) Chan su Hui Agnes of SMO Date/Time: 16/09/2019
 Estimated Cost Bill to
 OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SLJ 8322Z Insured: SKH 9604B
 at Workshop n/s The Mechanic Pte. Ltd Tel: 9733 0611
 of Blk 25 Kaki Bkt Rd 4# 05-85
 Policy No: D18MTPV01002716 Claim No: CMTD1804073
 Sum Insured Excess:
 Make of Veh: DOA 18/09/18
 (Client's Record)
 CA / REV / REP / REV 24 HRS (up)
 Date/Time: 9:55am @ 27/11/18 Person Contacted: Peter Vehicle: IN OUT

Date/Time	Action/Instruction (X) Estimate
	SLJ 8332Z - 02/MIDA17018311/P DOA: 8/9/17
	SKH 9604B - X
	Dismantle: 28/9/2018
	Pls forward the Report with Market Value within 5 Days

2350 5
 \$ ~~1850~~, 5 Days. (Red & 3050, 56%)
 (Red & 3550, 66%)

** MV: \$ 80 K (est), LTA: \$ 55452; ~~11/9/2019~~ 9/9/2019
 NV: \$ 24548