

ASS. REC. BY:

REF: CS/MSG 190/444/DSF312

Special Instruction:

numan

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Mhd Asit B madi

of MSG

Date/Time: 17.9.19 16.16p.m

Estimated Cost:

Bill to:

OD ~~(TP)~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 7705D

Insured:

SKJ 9409m

at Workshop m/s

Chunni

Tel:

64836016

of BHC 10 101-05/06 AMK Autopoint

Policy No:

27521155mp

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

mp

D.O.A.

14.9.2019

CA / REV / REP. / REV 24 HRS

Date/Time:

17.9.19 4.38p.m

Person Contacted:

Lynn

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time	Action/Instruction (V) Estimate
	SHA 7705D - CS/TP 13007109/ Kuber ROA = 14/04/2018
	SKJ 9409m-x

ASSIGNMENT SHUA 7705D

COE 2025 Aug
August 2017

From: _____ Date: _____
 Estimated Cost: _____
 CD / TP / WS / TP RES / CD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop: Mrs _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: ~~SH7705D~~
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Prius C.C. 1798
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 288197 T/Radio: Insured / Std / NI / NA
 Eng/No: 2ZR3062298
 C/No: JTDKB3FU603563678
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/65 R15
 R: 11

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lim Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP: / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Devanti
 Front: _____ Rear: _____
 R/Bal. S mm R/Bal. S mm
 L/Bal. S mm L/Bal. S mm
 D.O.A. 14/09/2019 D.O.I. 18/09/2019
 Survey held at Chunni AMC
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop of
O/S Body y o/s Rcr
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
25/09/19 @ 17:17 pm	MSIG SK3 9409 AM received PA to Ashika via number
15/10/19	Invoice 2/S 8450/- with 7 days of work (4 S, 735.20 Red - 40%)

RECEIVED 16 OCT 2019

16/10/19
Typist

: Prelim. Report
 : Final Report

Days Of Repair: 7
 Resurvey No. of Trip: 2

Add Fee: Site Insp 15
 Interview 15
 Tech. Insp 15
 Road sup 15

Survey Fee:
 Transportation: 200
 P/ins: 11
211

8,450/- 4/S

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 25 Sep 2019

Preliminary Advice

Insured Vehicle No	: SKJ9409M	Accident Date	: 14/09/2019
TP Vehicle No	: SHA7705D	Assignment Date	: 17/09/2019
Make	: TOYOTA PRIUS	Est. Duration of Repair	: 7 days
Date of Inspection	: 18/09/2019		
Inspection At	: Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint Singapore 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion & o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,185.24
Revised Amount	:S\$	10,742.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,742.40

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Sep 2019		17 Sep 2019 16:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured: **LINA SENIWATI TEDJA, ID: S6871004I** [Created by insurer]

Main Claimant: **COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R**

Vehicle Reg. No.: **SHA7705D** Date of Loss: **14/09/2019 23:00 - :59**
[24 Months and 15 Days From LTA Reg Date (Man Yr)]

Claim Type: **TP** Policy/Cover Note No.: **27521115SMP (Comprehensive)**
Coverage: 28/05/2019 - 27/05/2020

Vehicle Reg. No. (Insured): **SKJ9409M** Policy No. (Claimant):
Excess:

Repairer: **Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016**

Handling Insurer: **MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]**

Adjuster: **LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/09/2019]**

Driver/Custodian (Insured): **ALVIN PHUA (22 / Male) , NRIC: S9701823E Email:**

Adj Asg. Remarks: **on WP. Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Ms Lynn or Ms Irene at 65425119 / 6542 7162.**

ASSOCIATED MAIL RECEIVED

There are no mail for this case. [View All](#) [Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
						Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHA7705D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	2ZRS062298
Chassis No.:	JTDKB3FU603563678
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$31,008.00
Original Registration Date:	30 Aug 2017
First Registration Date:	30 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$36,320.00
COE Rebate Amount:	\$26,910.00
Total Rebate Amount:	\$30,660.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 Sep 2019

OK

MCD019122532 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 16/09/2019 14:17
 SUBMITTED BY: Janet Lim Slang Gek

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/09/2019 14:17
Date Of Accident	14/09/2019 23:05
Exact Location Of Accident	ALONG DEMPSEY RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7705D
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS HYBRID 4G
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	GOH BOON KWANG PETER
NRIC No	S1396695H
Date Of Birth	07/10/1960
Occupation	OUTDOOR
Date Of Driving Pass	28/06/1977
Driving Experience	42 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92392317
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 127 ANG MO KIO AVENUE 3
#07-1883

Postcode 560127

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : -
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER] HOUGANG NPC

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT NO: T/20190915/2018 * TYPE OF ACCIDENT :- HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: -

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKJ9409M

Vehicle Make/Model/Colour BMW

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver ALVIN PHU WEI XIANG

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRONT

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

GOH BOON KWANG PETER

Approximate Age

Injuries Sustain

NECK AND BACK

Injured person in which vehicle?

SHA7705D

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:

Olivia Wendy


Reporting Centre Personnel's Signature
Name: 15 SEP 2019
NRIC/FIN No.:

DRUM CC
SEA FD
DEMPSE

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DEMPSEY RD

Statement as per Police Report

RT/201909152018

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Olivia Wendy

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

15 SEP 2019

NRIC/FIN No.:


**SINGAPORE
POLICE FORCE**


T/20190915/2018

1 of 4

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20190915/2018

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/09/2019 10:25	Vide Report No.:	Station Diary No.: 60
--	------------------	--------------------------

Informant's Particulars

Name of Informant: GOH BOON YEW JOHN		Address: APT BLK 127 ANG MO KIO AVENUE 3 #07-1883 SINGAPORE 560127	
ID Type / ID No.: NRIC NO / S1437464G		Contact No.: Home/Office: Mobile: 87227083	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 58	Date of Birth: 07/10/1960	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 2B,2A,2,3,4 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 14/09/2019 23:05	Type of Location: Straight Road
Location: Along Road 1 DEMPSEY ROAD				
Near block 11 and JUMBO Seafood Restaurant				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision:			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passengers
SHA7705D	Car				Slightly Damaged	1
SKJ9409M	Car				Slightly Damaged	3

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**



T/20190915/2018

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

2 of 4

Report No. T/20190915/2018

CONTINUATION OF REPORT

Driver			
Name	GOH BOON YEW JOHN	ID No.	S1437464G
Related Vehicle	SHA7705D (Car)	Contact No.	87227083
Hospital/Clinic	MY FAMILY CLINIC (HOUGANG CENTRAL)	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4 Date of Expiry: NIL
Date Treatment	15/09/2019	Date Discharge	15/09/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	ALVIN PHUA WEI XIANG	ID No.	S9701823E
Related Vehicle	SKJ9409M (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 14/09/2019 at about 2305hrs, I was driving my vehicle - One blue Comfort Delgro Taxi (Registration plate number: SHA7705D) along Dempsey Road. As I was driving along the said road, there was one vehicle - One Black BMW (unknown model, Registration plate number: SKJ9409M) that came out from a parking lot near to Blk 11 and collided into the right side of my vehicle.

As a result of the collision, the right region of my vehicle - right driver door and right passenger door were dented and scratched. The damage to the other vehicle was that the front region was dented. I had 1 passenger in my vehicle. However, my passenger (no particulars available) was not injured. The other vehicle had 3 passengers. The driver - Mr Alvin Phu Wei Xiang (NRIC: S9701823E) and his passengers were not injured.

Upon collision, I got out of my vehicle and exchanged particulars with Mr Alvin. We agreed to go for insurance claims to settle the matter. Subsequently, we got into our vehicles and went off. No police or ambulance attended.

I wish to state that I have a CCTV in my vehicle facing the front. I am not sure whether there is any CCTV in the other vehicle or whether there is a CCTV at the vicinity of the incident location which secures footage of the accident.

I started feeling pain on my neck and back region after the accident. I went to My Family Clinic (Hougang Central) on the 15/09/2019 and was given 3 days MC for my injuries.



**SINGAPORE
POLICE FORCE**



T/20190915/2018

3 of 4

Report No. T/20190915/2018

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

CONTINUATION OF REPORT



SINGAPORE POLICE FORCE



T/20190915/2018

4 of 4

Report No. T/20190915/2018

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 MOHAMAD ZULHIZWAN AQMA BIN MOHD ZULKEFLEE	
Signature Of Interpreter: Not applicable	
Officer In Charge Of Case: TP / AEIT / SI MOHAMAD ZULFAZDLI BIN ABDULLAH Contact No: 65476204	
Authentication Stamp NP188	
Singapore Police Force	

Signature Of Informant:
Date/Time: 15/09/2019 10:25
Classification Of Case:

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHA 7705D

DATE : 16.09.2019

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

MSLG

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR BUMPER NH			\$ 458.60 X
REAR BUMPER CLIPS NH			\$ 22.00 X
REAR FENDER, RH <i>Dented</i>			\$ 836.70 L
REAR FENDER SHEILD (RH) NH			\$ 134.20 X
PANEL SUB-ASSY, FRONT DOOR, RH <i>Dented</i>			\$ 1,264.00 L
PANEL SUB-ASSY, REAR DOOR, RH <i>Dented</i>			\$ 1,258.30 L
CENTRE ROCKER PANEL (GARNISH) Cnt			\$ 576.00 L
REAR TYRE RIM ,RH Cnt			\$ 1,555.00 L
REAR WHEEL BEARING ING & HUB ,RH <i>Dem</i>			\$ 610.20 <i>Dem</i>
REAR CROSS MEMBER <i>Distorted</i>			\$ 2,200.40 <i>Distorted</i>
REAR SHOCK ABSORBER, RH <i>Distorted</i>			\$ 118.30 <i>Distorted</i>
REAR SHOCK ABSORBER MOUNTING, RH NH			\$ 125.30 X
REAR LOWER ARM, RH <i>Distorted</i>			\$ 497.50 <i>Distorted</i>
REAR UPPER ARM, RH <i>Distorted</i>			\$ 356.80 <i>Distorted</i>
REAR KNUCKLE ARM, RH <i>Distorted</i>			\$ 810.60 <i>Distorted</i>
REAR TRAILING ARM, RH <i>Distorted</i>			\$ 314.20 <i>Distorted</i>
REAR ASSIST ARM, RH <i>Distorted</i>			\$ 342.20 <i>Distorted</i>
SUB TOTAL			\$ 11,480.30
LESS 20% <i>25%</i>			\$ 2,296.06
DISCOUNTED TOTAL			\$ 9,184.24
REAR BUMPER RUBBER MAT NH			\$ 50.00 NETT <i>444</i> X
FRONT DOOR ADVERTISEMENT LOGO, RH NH			\$ 100.00 NETT L
FRONT DOOR COMFORT LOGO ,RH NH			\$ 75.00 NETT L
REAR DOOR COMFORT & APPS STICKER, RH NH			\$ 80.00 NETT L
REAR DOOR ADVERTISEMENT LOGO ,RH NH			\$ 100.00 NETT L
REAR TYRE ,RH Cnt <i>50%</i>			\$ 108.00 216.00 NETT L
			\$ 621.00
LABOUR CHARGE			
Panel Beating			\$ 1,200.00 800/-
Spray Painting Charge			\$ 1,250.00 800/-
Wiring Charge			\$ 100.00 NH
Tuff Kote			\$ 150.00 40/-
Towing Charge			\$ 90.00 NH
Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
Remove/Refix Reverse Sensor			\$ 80.00 40 NH
Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
Rear Wheel Alignment			\$ 80.00 60/-
Re-set Rear ABS System			\$ 200.00
Re-set Frt & Rear Power Window System		\$ 200.00	\$ 400.00 } 150/-
Diagnosis & Resetting To Erase Fault Code			\$ 480.00
<p>18/09/19 @ 0915hr NA Actual 7 days 2/sum</p>			
TOTAL LABOUR			\$ 4,380.00
ESTIMATE TOTAL			\$ 14,185.24

10740.20
8055.15

513.00
463.00

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

2080.00

TJen LKK Auto

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 7705 D

Technician:

Mileage: 288197

Time Printed 18.9.19 9:45 AM

TOYOTA PRIUS

Front : Left

Actual	BEFORE	Specified Range
-0°49'		-1°20' 0°10'
6°15'		2°25' 3°55'
0°00'		-0°06' 0°06'
24°46'		11°50' 13°20'
23°57'		10°30' 13°30'

Front : Right

Actual	BEFORE	Specified Range
-0°02'		-1°20' 0°10'
6°34'		2°25' 3°55'
0°00'		-0°06' 0°06'
12°23'		11°50' 13°20'
12°21'		10°30' 13°30'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°47'		-0°45' 0°45'
-0°19'		-0°45' 0°45'
12°23'		-0°45' 0°45'
0°00'		-0°12' 0°12'

Rear : Left

Actual	BEFORE	Specified Range
1°23'		-2°00' -1°00'
0°14'		0°02' 0°17'

Rear : Right

Actual	BEFORE	Specified Range
-3°38'		-2°00' -1°00'
-2°39'		0°02' 0°17'

Camber
Toe

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
5°01'		-0°30' 0°30'
-2°25'		0°03' 0°33'
1°27'		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19016444/DSF3N2

Date: 17/10/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B27521115SMP
Claimant Vehicle No :	SHA7705D	Insured Vehicle No :	SKJ9409M
Date of Loss:	14/09/2019	Nature of Claim:	TP
		Claim No:	606025

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA7705D	Engine No:	2ZRS062298
Make & Model:	TOYOTA PRIUS, 1.5 HYBRID (A)	Chassis No:	JTDKB3FU603563678
Reg. Date:	30/08/2017 (Man. Year: 2017)	Odometer:	288197 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Davanti 5 mm	Rear Left Side:	Davanti 5 mm
Front Right Side:	Davanti 5 mm	Rear Right Side:	Davanti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %	
Parts	9,805.24	8,518.15	1,287.09	13.13	
Miscellaneous Items	0.00	0.00	0.00		
Labour	4,380.00	2,080.00	2,300.00	52.51	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	14,185.24	10,598.15	3,587.09	25.29	
Approved Total (Overridden) (S\$)		8,450.00			
	(S\$)	14,185.24	8,450.00	5,735.24	40.43
	+ GST 7.00/7.00% (S\$)	992.97	591.50	401.47	40.43
	Nett Amount (S\$)	15,178.21	9,041.50	6,136.71	40.43

INSPECTION

Date of Assignment:	17/09/2019	
Date Inspected:	18/09/2019	Inspected At:
		Chunni Motor Work Pte Ltd - Amk (HQ)
		Blk 10 #01-05/06, AMK Autopoint
		Singapore 568047
Estimated Period of Repair:	7.0 days	

Adjuster: BRYAN TANI**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Oct 2019)
Parts: 144	TOYOTA PRIUS 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHA7705D)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Not Necessary	458.60 FL	*- FL
2	10	*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	1	*REAR FENDER,RH	Dented	836.70 FL	*836.70 FL
4	1	*REAR FENDER SHIELD (RH)	Not Necessary	134.20 FL	*- FL
5	1	*PANEL SUB-ASSY,FRONT DOOR,RH	Dented	1,264.00 FL	*1,264.00 FL
6	1	*PANEL SUB-ASSY,REAR DOOR,RH	Dented	1,258.30 FL	*1,258.30 FL
7	1	*CENTRE ROCKER PANEL (GARNISH)	Cut	576.00 FL	*576.00 FL
8	1	*REAR TYRE RIM,RH	Cut	1,555.00 FL	*1,555.00 FL
9	1	*REAR WHEEL BEARING ING & HUB,RH	Damaged	610.20 FL	*610.20 FL
10	1	*REAR CROSS MEMBER	Distorted	2,200.40 FL	*2,200.40 FL
11	1	*REAR SHOCK ABSORBER,RH	Distorted	118.30 FL	*118.30 FL
12	1	*REAR SHOCK ABSORBER MOUNTING,RH	Not Necessary	125.30 FL	*- FL
13	1	*REAR LOWER ARM,RH	Distorted	497.50 FL	*497.50 FL
14	1	*REAR UPPER ARM,RH	Distorted	356.80 FL	*356.80 FL
15	1	*REAR KNUCKLE ARM,RH	Distorted	810.60 FL	*810.60 FL
16	1	*REAR TRAILING ARM,RH	Distorted	314.20 FL	*314.20 FL
17	1	*REAR ASSIST ARM,RH	Distorted	342.20 FL	*342.20 FL
18	1	*REAR BUMPER RUBBER MAT	Not Necessary	50.00 FS	*- FS
19	1	*FRONT DOOR ADVERTISEMENT LOGO,RH	Necessary	100.00 FS	*100.00 FS
20	1	*FRONT DOOR COMFORT LOGO,RH	Necessary	75.00 FS	*75.00 FS
21	1	*REAR DOOR COMFORT & APPS STICKER,RH	Necessary	80.00 FS	*80.00 FS
22	1	*REAR DOOR ADVERTISEMENT LOGO,RH	Necessary	100.00 FS	*100.00 FS
23	1	*REAR TYRE,RH (50%)	Cut	216.00 FS	*108.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,101.30	11,203.20
- List Item Discount on L Items 20.00/25.00% (S\$)	2,296.06	2,685.05
Total Parts (S\$)	9,805.24	8,518.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING CHARGE	New	1,250.00	800.00
3	WIRING CHARGE	New	100.00	0.00
4	TUFF KOTE	New	150.00	40.00
5	TOWING CHARGE	New	90.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REVERSE SENSOR	New	80.00	0.00
8	REMOVE/REFIX UNDERCARRIAGE (RR)	New	200.00	150.00
9	REAR WHEEL ALIGNMENT	New	80.00	60.00
10	DIAGNOSIS & RESETTING TO ERASE FAULT CODE }	New	480.00	150.00
11	RE-SET REAR ABS SYSTEM }	New	200.00	0.00
12	RE-SET FRT & REAR POWER WINDOW SYSTEM }	New	400.00	0.00
Gross Labour Cost (S\$)			4,380.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >