

ASS. REC. BY:

REF: CS/MSG M016445/DSF332

Special Instruction:

Surveyor Bryan

ASSIGNMENT (Office)

From (Person): Chhin Nguk Rui

of MSG

Date/Time: 17.9.19 16.14p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBE 8035Y

Insured: SLH 421J

at Workshop m/s Sg 98 motor

Tel: 64524898

of BIK 4001 Amk Industrial Park / #101-21

Policy No: 29114756

Claim No: 605446

Sum Insured:

Excess:

Make of Veh:

D.O.A. 9.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

mp1

H.O.D. Endorsement:

Date/Time: 17.9.19 4.40pm

Person Contacted: Rose

Vehicle IN / OUT


Date/Time	Action/Instruction (✓) Estimate
	FBE 8035Y - X
	SLH 421J - X

**ASSIGNMENT**

COE 2020 Sept.

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop no: \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 4 days Res. Yes or No  
 Lum Sum: 20 % 3 Val: Yes or No  
 CA / REV / REP: / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: FBE 8035Y yr Regn: 2010 Sept  
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Piaggio Gilera C.C. 278  
 Colour: Black/Grey A/C: Insured / Std / NI / NA  
 Sp. Reading: LIA. T/Radio: Insured / Std / NI / NA  
 Eng/No: M356M0004146  
 C/No: ZAPM356000003957  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modif: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 120/70 R15  
 R: 140/60 R14  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Michelin  
 Front Rear  
 R/Bal. 2 mm R/Bal. 2 mm  
 L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm  
 D.O.A. 09/09/2019 D.O.I. 18/09/2019  
 Survey held at SG98 AMK  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop of  
L/S Front y O/S Portion  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MSIG SLH 4215 1.7
	MV <del>121K</del> check with bike shop. Mr Kee and SG98. LIA 130.00
	NL <del>1.5K</del> Submit not economical report. NPA = \$ 1,570/-
	Vehicle not economical to repair. Total Loss. bike not repair. Vehicle already de-registered.

RECEIVED 11 FEB 2020

Date/Time File Path: 11/02/20  
 Typist: \_\_\_\_\_  
 Date/Time File Return: \_\_\_\_\_

: Prel. Report  
 : Final Report

Days Of Repair: 4  
 Resurvey No. of Trip: 1

Add Fee:  Site Insp (\$) \_\_\_\_\_  
 Interview (\$) \_\_\_\_\_  
 Tech. Ins (\$) \_\_\_\_\_  
 Total Exp (\$) \_\_\_\_\_

Survey Fee: 150  
 Transportation: \_\_\_\_\_  
 S + PE: \_\_\_\_\_  
 Photo: \_\_\_\_\_  
 Other: 4

Total Loss

### ...CLAIM SUBFOLDER...(New Assignment)

#### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Sep 2019		17 Sep 2019 16:14 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

#### CLAIM SUBFOLDER DETAILS

Insured:	<b>GRAB RENTALS PTE LTD</b> , Co. Reg. No.: 201617200G <span style="float: right;"><a href="#">[Created by insurer]</a></span>		
Main Claimant:	<b>MOHAMMAD ZURAINI BIN HAMSANI</b> , ID: S7830397B		
Vehicle Reg. No.:	<b>FBE8035Y</b>	Date of Loss:	09/09/2019 10:00 - :59 [107 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 605446</b>	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	<b>SLH421J</b>	Policy No. (Claimant):	
Repairer:	<b>Sg 98 Motor Pte Ltd (HQ)</b> BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Chhia Nyuk Pui</b> - 6594 2521]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Imm.Advice due 18/09/2019]</b>		
Driver/Custodian (Insured):	LOH KELVIN (), NRIC: S76001831, Tel: +6588627681 Email:		
Adj Asg. Remarks:	on WP. Liab:unclear. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Rose @ 6452 4898.		

#### ASSOCIATED MAIL RECEIVED

There are no mail for this case. [View All](#) [Compose Case Mail](#)

#### ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 23 Sep 2019

**Preliminary Advice**

Insured Vehicle No	: SLH421J	Accident Date	: 09/09/2019
TP Vehicle No	: FBE8035Y	Assignment Date	: 17/09/2019
Make	: GILERA NEXUS 300 IE	Est. Duration of Repair	: 4 days
Date of Inspection	: 18/09/2019		
Inspection At	: Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 Singapore 569622		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s front & o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,878.90
Revised Amount	:S\$	4,220.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,220.80
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis. Vehicle recommended total loss due to not economical for repair.

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	12/09/2019 16:30
Date Of Accident	09/09/2019 22:30
Exact Location Of Accident	UPPER PAYA LEBAR ROAD TOWARDS KATONG
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBE8035Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MOHAMMAD ZURAINI BIN HAMSANI
NRIC No	S7830397B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90071222
Alternative Phone No	OFFICE-90071222

#### Vehicle Particulars

Manufacturer	GILERA
Model	NEXUS 300
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

#### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5088322851-02
Cover Note Number	

#### Driver

Name of Driver	MOHAMMAD SARWANI BIN HAMSANI
NRIC No	S7521476F
Date Of Birth	16/07/1975
Occupation	OUTDOOR
Date Of Driving Pass	03/09/1996
Driving Experience	23 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90071222
Tax Number	
Contact Number	OFFICE-90071222
Mail Address	NOEMAIL

Nature Of Damage

REFER POLICE REPORT AND ATTACHED


No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	MOHAMMAD SARWANI BIN HAMSANI
Approximate Age	
Injuries Sustain	REFER POLICE REPORT AND ATTACHED
Injured person in which vehicle?	FBE8035Y
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN

KATONG



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT UPPER Paya Lebar Rd

Refer to Police Report no. T/20190911/2037

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Handwritten Signature]*

Policyholder's Signature  
Date & Time:

*[Handwritten Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Handwritten Signature]*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





**SINGAPORE  
POLICE FORCE**



T/20190911/2037

3 of 3

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20190911/2037

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: TP / YOGENDRAN S/O RAJASAKARAN
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIT / Staff Sgt SUFIYAN BIN KHAIRI Contact No.: 65476390

Signature Of Informant: 
Date/Time: 11/09/2019 10:57
Classification Of Case:  Signature:

Authentication Stamp  
NP168

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	397B
Vehicle Details	
Vehicle No.:	FBE8035Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	23 Sep 2019
Vehicle Make:	PIAGGIO
Vehicle Model:	GILERA NEXUS 300 I.E. CVT
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	M356M0004146
Chassis No.:	ZAPM3560000003957
Maximum Power Output:	-
Open Market Value:	\$5,003.00
Original Registration Date:	24 Sep 2010
First Registration Date:	24 Sep 2010
Transfer Count:	1
Actual ARF Paid:	\$751.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Sep 2020
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,301.00
COE Rebate Amount:	\$130.00
<b>Total Rebate Amount:</b>	<b>\$130.00</b>

The information contained herein is correct as at 23 Sep 2019

OK

# SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg\_motor\_enterprise@yahoo.com.sg

Date: 19th August 2019

To LKK


Attn: Mr Bryan

VEHICLE NO : FBE 8035Y  
ACCIDENT DATE: 9th Sept 2019

Gilera Nexus 300

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Handle Bar <i>1st</i>	1	350.00 ✓
2 Head Lamp Assy <i>broken</i>	1	550.00 ✓
3 Centre Panel <i>cut</i>	1	395.00 ✓
4 Front LH Cover Top <i>cut</i>	1	355.00 ✓
5 Front Side Panel (LH/RH) <i>cut</i>	2	560.00 ✓
6 Front LH Signal <i>cut</i>	1	135.00 ✓
7 Belly Pan (L/RH) <i>cut</i>	2	450.00 ✓
8 Brake Lever <i>cut</i>	1	155.00 ✓
9 Fork Tube <i>distorted</i>	2	780.00 ✓
10 Fork Under Bracket <i>to HH</i>	1	280.00 X
11 Bar End Balancer <i>NH N/S o/s 1st</i>	<i>2 set pcs</i>	258.00 ✓ 129.00
12 Rear Rh Tail Panel <i>cut</i>	1	398.00 ✓
13 Signal Lamp Guard - L/RH <i>cut</i>	2 pcs	255.00 ✓
	Sub-Total	4,921.00
	Less 10%	492.10
	Sub-Total	4,428.90

*4512.00*  
*10% 4060.80*



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Sep 2019		17 Sep 2019 16:14 <a href="#">Edit Adj Rpt</a>	<b>S\$4,490.80</b> <a href="#">Edit Estimates</a>	<b>S\$4,490.80</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>GRAB RENTALS PTE LTD</b> , Co. Reg. No.: 201617200G								
Main Claimant:	<b>MOHAMMAD ZURAINI BIN HAMSANI</b> , ID: S7830397B								
Vehicle Reg. No.:	<b>FBE8035Y</b>	Date of Loss:	09/09/2019 10:00 - :59 [107 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 605446</b>	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	<b>SLH421J</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Sg 98 Motor Pte Ltd (HQ)</b> BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Chhia Nyuk Pui</b> - 6594 2521]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>BRYAN TANI</b> ] ... [Final Rpt due 17/10/2019]								
Driver/Custodian (Insured):	LOH KELVIN (), NRIC: S7600183I, Tel: +6588627681 Email:								
Adj Asg. Remarks:	on WP, Liab:unclear, Agree on SJE, Assign: LKK Auto Consultants Pte Ltd. Contact: Rose @ 6452 4898.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*FBE8035Y (605446)**  
**[SLH421J]**  
 TP  
**MOHAMMAD ZURAINI BIN HAMSANI**  
**Sep 9 2019 10:00AM**  
**[GRAB RENTALS PTE LTD]**  
**Sg 98 Motor Pte Ltd**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			View <span style="border: 1px solid black; padding: 2px;">View in Browser ▾</span>
<b>Video</b>			1 per page ▾ <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail <input type="checkbox"/> Print <input type="checkbox"/>
1	23/12/19 11:07	<b>Video - Accident (OI)</b>	Load MP4 <input type="checkbox"/>
<b>Assessment Reports</b>			1 per page ▾ <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="checkbox"/> Print <input type="checkbox"/>
1	23/09/19 13:32	<b>Adjuster Immediate Advice</b>	Load HTM <input type="checkbox"/>
<b>Photos/Images</b>			3 per page ▾ <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="checkbox"/> Print <input type="checkbox"/>
1	29/01/20 15:05	<b>Rear View Left</b>	Load JPG <input checked="" type="checkbox"/>
2	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
3	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
4	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
5	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
6	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
7	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
8	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
9	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
10	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
11	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
12	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
13	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
14	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
15	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
16	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
17	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
18	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
19	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
20	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
21	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
22	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
23	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
24	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
25	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
26	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
27	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>
28	29/01/20 15:05	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
29	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
30	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
31	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
32	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
33	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
34	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
35	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
36	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
37	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
38	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
39	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
40	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
41	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
42	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
43	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
44	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
45	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
46	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
47	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
48	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
49	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
50	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
51	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
52	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
53	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
54	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
55	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
56	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
57	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
58	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
59	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
60	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
61	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
62	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
63	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
64	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
65	29/01/20 15:05	General View	Load JPG	<input checked="" type="checkbox"/>
66	29/01/20 15:06	General View	Load JPG	<input checked="" type="checkbox"/>
67	29/01/20 15:06	General View	Load JPG	<input checked="" type="checkbox"/>
68	29/01/20 15:06	General View	Load JPG	<input checked="" type="checkbox"/>
69	29/01/20 15:06	General View	Load JPG	<input checked="" type="checkbox"/>
70	29/01/20 15:06	General View	Load JPG	<input checked="" type="checkbox"/>
71	29/01/20 15:06	General View	Load JPG	<input checked="" type="checkbox"/>
72	29/01/20 15:06	General View	Load JPG	<input checked="" type="checkbox"/>
73	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
74	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
75	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
76	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
77	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
78	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
79	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
80	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
81	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
82	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
83	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
84	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
85	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
86	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
87	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
88	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
89	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
90	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
91	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
92	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
93	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
94	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
95	29/01/20 15:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/09/19 09:26	PRI	Load PDF	
2	17/09/19 15:04	Agree on SJE	Load PDF	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/02/20 14:37	LTA REBATE	Load PDF	
2	11/02/20 14:37	GIA RPT	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19016445/DSF3S2

Date: 11/02/2020

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29114756

Claimant Vehicle No: FBE8035Y

Insured Vehicle No: SLH421J

Date of Loss: 09/09/2019

Nature of Claim: TP Claim No: 605446

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBE8035Y

Make &amp; Model: GILERA NEXUS 300 IE, 278cc

Engine No: M356M0004146

Reg. Date: 24/09/2010 (Man. Year: 2009)

Chassis No: ZAPM356000003957

Colour: Black/Grey

Odometer: 0 km

Engine Capacity: 278 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	120/70 R15	Rear Tyre Size:	140/60 R14
Front Left Side:	Michelin 2 mm	Rear Left Side:	Michelin 2 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,718.90	4,060.80	658.10	13.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,160.00	430.00	730.00	62.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>5,878.90</b>	<b>4,490.80</b>	<b>1,388.10</b>	<b>23.61</b>

## INSPECTION

Date of Assignment: 17/09/2019

Date Inspected: 18/09/2019 Inspected At:

Sg 98 Motor Pte Ltd (HQ)  
BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21  
Singapore 569622

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

**TOTAL LOSS ASPECT**

The total amount incurred will be Market Value \$ 1,700.00 minus Total Rebate \$ 130.00 = \$ 1,570.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 11 Feb 2020)	
<b>Parts:</b>	N/A	GILERA NEXUS 300 IE 278cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBE8035Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	350.00 FL	*350.00 FL
2	1		*HEAD LAMP ASSY	Broken	550.00 FL	*550.00 FL
3	1		*CENTRE PANEL	Cut	395.00 FL	*395.00 FL
4	1		*FRONT LH COVER TOP	Cut	355.00 FL	*355.00 FL
5	2		*FRONT SIDE PANEL (LH/RH)	Cut	560.00 FL	*560.00 FL
6	1		*FRONT LH SIGNAL	Cut	135.00 FL	*135.00 FL
7	2		*BELLY PAN (L/RH)	Cut	450.00 FL	*450.00 FL
8	1		*BRAKE LEVER	Cut	155.00 FL	*155.00 FL
9	2		*FORK TUBE	Distorted	780.00 FL	*780.00 FL
10	1		*FORK UNDER BRACKET	Not Necessary	280.00 FL	*- FL
11	1		*BAR END BALANCER	N/s Not Necessary / O/s Bent	258.00 FL	*129.00 FL
12	1		*REAR RH TAIL PANEL	Cut	398.00 FL	*398.00 FL
13	2		*SIGNAL LAMP GUARD - L/RH	Cut	255.00 FL	*255.00 FL
14	1		*REAR BOX	Not Necessary	290.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,211.00</b>	<b>4,512.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	492.10	451.20
<b>Total Parts (S\$)</b>	<b>4,718.90</b>	<b>4,060.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING FEE.	New	50.00	0.00
2	REMOVE REPLACE NECESSARY PARTS ALIGN & ETC.	New	380.00	200.00
3	REMOVE & REPLACE FORK ASSY FRONT RIM, FORK OIL SEAL FORK OIL.	New	250.00	80.00
4	PUTTY & RESPRAY PAINT.	New	480.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>1,160.00</b>	<b>430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >