

ASS. REC. BY: Steve

REF: NTUC NSI/MC 19016454/ESF302

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: SMM3323B
 Policy No. 5110696355 (09/07/2019 - 08/07/2020)
 Claims No. MT/1061689-002
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMB 223J Yr Regn: 13/Dec/2014
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: MAN NL320F(A22) c.c. 10518
 Colour: Multicolour A/C: Insured / Std / NI / NA
 Sp. Reading: 733327 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WMAA22ZZ3B700197
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or Steel Rim
 Tyre Size: F: 275 / 70 R22-5
 R: 275 / 70 R22-5
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 09/09/2019 D.O.I. 17/09/2019
 Survey held at SMRT
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt Right
 The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	SMB 223J - CE / SMO 19013590 / Esf302 D.O.A. - 3/07/2019 TP
	SMM 3323B - X SMM3323B
19/9/19	Finalize Confir \$899, 2 days (cf 2,095.00 red 72%)
	RECEIVED 23 SEP 2019
	<i>[Signature]</i> 20/9/2019

Date/Time, File Pass to? 23/09/19
 : Preli. Report
 : Final Report
 1) Type: 4
 Date/Time, File Return to?
 2) _____
 Rep. Formed: _____
 Lump Sum / L.B.C. / \$800/- L/S

Days Of Repair: 2
 Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	<u>160</u>
Transportation:	_____
S + RS. SI	_____
Photos	_____
Others	_____
TOTAL	<u>160</u>

Hello, NAC_PAYA_UBI_800601

[Change Language](#)
[Change Password](#)
[Log Out](#)

My Desktop
Notice of Loss

Policy Query

Policy No. Date of Accident
 Vehicle No.(For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5110696355		TEE HOCK CHUAN	S1573583Z	GPC	drive PREMIUM	SMM3323B	SMM3323B	09/07/2019	08/07/2020

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	292D

Vehicle Details

Vehicle No.:	SMB223J
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Sep 2019
Vehicle Make:	MAN
Vehicle Model:	NL320F (A22)
Primary Colour:	Multicolor
Manufacturing Year:	2011
Engine No.:	50329353632938
Chassis No.:	WMAA22ZZ3B7001197
Maximum Power Output:	-
Open Market Value:	\$263,447.00
Original Registration Date:	13 Dec 2011
First Registration Date:	13 Dec 2011
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 17 Sep 2019

OK

TP Claims against NTUC Income: Follow-Through Survey

Date : 23/09/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1046697-002	SMRT TAXIS PTE LTD	SHB 5093T	SJR 7786G	28/05/2019	11:10	\$ 9,398.50	\$ 3,539.54
2	MT/1061689-002	SMRT BUSES LTD	SMB 223J	SMM 3323B	09/09/2019	09:50	\$ 2,895.00	\$ 800.00

Claim received from LKK Auto

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/09/2019 09:02
Date Of Accident	09/09/2019 09:50
Exact Location Of Accident	HOUGANG AVENUE 3 BEFORE BS: 71061 (BEF AIRPORT ROA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB223J
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	MAN
Model	MAN NL320F (A22)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-19093203MFBP
Cover Note Number	

Driver

Name of Driver	MOHAMED HISYAMUDDIN BIN ITHNIN
NRIC No	S8711422H
Date Of Birth	02/05/1987
Occupation	OUTDOOR
Date Of Driving Pass	24/07/2019
Driving Experience	0 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	NO ADDRESS
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WHILE IN PROCESS OF ENTERING BUS STOP 71061 ALONG HOUGANG AVE 3, SUDDENLY A PTE CAR (SMM3323B) APPEARED ON THE LEFT AND SIDE SWIPE THE LEFT FRONT PORTION OF MY BUS. THE PTE CAR THEN CONTINUED TO OVERTAKE MY BUS AND STOP A FEW METRES AHEAD. I WISH TO STATE THAT I HAD CHECK FOR TRAFFIC CLEARANCE BEFORE ENTERING THE BUS BAY. THERE WERE NO INJURIES REPORTED. THAT'S ALL

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING DOWNLOAD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMM3323B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TEE HOCK CHUAN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant Government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions, or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Signature



Policyholder's Signature _____ Date & Time: _____
 Driver's Signature _____ (if driver is not the policyholder)
 Date & Time: _____
 Reporting Centre Personnel's Signature _____
 Name: BALQISH
 NIC/IN No.: S8340325Z



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 17/09/2019

User ID : BoonChewTay

Section A - Accident Details	
Registration Number	SMB223J
Case Reference Number	BUS/09/19/1026
Registration Date	13/12/2011
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Mohamed Hisyamuddin Bin Ithnin
Type of Accident	Side Swipe
Accident Date and Time	9/9/2019 9:52 AM
Accident Reported Date and Time	10/9/2019 4:30 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB223J - LEFT FRONT PORTION SMM3323B (TP) - INSURED WITH NTUC
Prepared Date and Time	16/9/2019 6:33 PM
Chassis Number	WMAA22ZZ3B7001197
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$616.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,676.00 <i>2895</i>	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	17/09/2019 9:03 AM	
Signature		
Remarks		

Store.

17/09/2019 @ 11.45 a.m

Lum Sum

Repair Day - 2.

~~Without~~ Third Party
without Prejudice.

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/09/2019

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,060.00	530.
Total Labour	\$1,060.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00	446.
Total Spray Painting & Panel Beating	\$616.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010153	Body	F01001-CW264	COVER HEADLAMP-FRT LH, FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	X R
6009997	BODY LH	A01001-CW553	PANEL SIDE L3, FOR MAN A22 BUS	1.00	\$244.30	100.00	\$0.00	Repair	X R
Total					\$1,219.00		\$0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

[Handwritten Signature]
19/9/19

2895

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/09/2019

User ID : CatherineLee

Section A - Accident Details

Registration Number	SMB223J
Case Reference Number	BUS/09/19/1026
Registration Date	13/12/2011
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Mohamed Hisyamuddin Bin Ithnin
Type of Accident	Side Swipe
Accident Date and Time	9/9/2019 9:52 AM
Accident Reported Date and Time	10/9/2019 4:30 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24103396
Special Instruction to ARC, if any	SMB223J - LEFT FRONT PORTION SMM3323B (TP) - INSURED WITH NTUC
Prepared Date and Time	16/9/2019 6:33 PM
Chassis Number	WMAA22ZZ3B7001197
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$530.00
Total Spray Cost	\$616.00	\$446.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	(\$195.20)
TOTAL COST	\$1,676.00	\$780.80
Lump Sum Total	\$0.00	\$800.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Boon Chew Tay	STEVE.
ARC / Surveyor Sign Off Date	17/09/2019 9:03 AM	17/09/2019 3:23 PM
Signature		S
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63665592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/09/2019

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$1,060.00				\$530.00			
Total Labour		\$1,060.00				\$530.00			
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$616.00				\$446.00			
Total Spray Painting & Panel Beating		\$616.00				\$446.00			
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Lump Sum Adjustment by Surveyor		\$0.00				(\$195.20)			
Total Other Costs		\$0.00				(\$195.20)			
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010153	Body	F01001-CW264	COVER, HEADLAMP: FRT LH, FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	Repair
6009997	BODY LH	A01001-CW553	PANEL, SIDE: L3, FOR MAN A22 BUS	1.00	\$244.30	100.00	\$0.00	Repair	Repair
Total					\$1,219.00		\$0.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19016454/Esf3e2			
73 BRAS BASAH ROAD		Date: 25-09-2019	
#05-01 NTUC TRADE UNION HOUSESINGAPORE		Code: INC4	
189556			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMM 3323B	Veh. Inspected	SMB 223J
Policy No.	5110696355	Coverage (\$)	0.00
Claim No.	MT/1061689-002	Excess (\$)	0.00
Assign From		Assign Date	17/09/2019
2. Vehicle Particulars & Condition			
Make & Model	MAN NL320F (A22)	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WMAA22ZZ3B7001197	Colour	MULTI COLOUR
Odometer	733327	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	5 mm
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	5 mm
R/H Rear Tyre	275/70 R22.5	BRIDGESTONE	5 mm
L/H Rear Tyre	275/70 R22.5	BRIDGESTONE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/09/2019	Inspection Date	17/09/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 223J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER, HEADLAMP:FRT,LH,FOR MAN A22 BUS	TO REPAIR SEE LABOUR	974.70	-
1	PANEL,SIDE:L3,FOR MAN A22 BUS	TO REPAIR SEE LABOUR	244.30	-
			1,219.00	-
LABOUR				
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF COVER, HEADLAMP:FRT,LH,FOR MAN A22 BUS AND PANEL,SIDE:L3,FOR MAN A22 BUS.		1,060.00	530.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		616.00	446.00
			1,676.00	976.00
GRAND TOTAL			2,895.00	976.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				800.00

Report Ref No. NS/INC19016454/Esf3e2

CHEN TSUE YEE
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.