

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automob				
AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI19016464/Kvf3e2		

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date: 23-12-2019



2398	<b>124</b>		Code: AGI		
l.		Policy Particulars	s :- THIRD PARTY CLA	.IM	
-	Insured Veh.	SJW 7666T	Veh. Inspected	FBH 6669R	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10003390/JM	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	18/09/2019	
<u>.</u>		Vehicle Part	ciculars & Condition		
	Make & Model	HONDA GLH125	c.c	125	
	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	LALJA11U5C3208227	Colour	RED / SILVER	
	Odometer	8483	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
	_	Condi	tions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	80/100X18	BRIDGESTONE	3 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	100/90X18	BRIDGESTONE	4 mm	
	L/H Rear Tyre			mm	
	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
j.	General Information				
	Accident Date	29/06/2019	Inspection Date	18/09/2019	
	Survey held at	SOON HIN			
	BLK 1018 #01-342 YISHUN INDUSTRIAL PARK A . SINGAPORE 768760				
ia.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
b.		Estimate	e Days of Repair		
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	2 Working Da	ys	