

REC. BY:

REF:

CS3/SMD19016476/Hqf36

Special Instruction:

Surveyor: Hock Anr

ASSIGNMENT (Office)

From (Person): Ruth Chua Gek Tiang of SMD

Date/Time: 18.9.19 12.48p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLB 4296J

Insured: SLB 9970M

at Workshop m/s: N20 Automotive

Tel: 90914853

of 53 ubi ave 1 #05-44

Policy No: D19MTPV01005432

Claim No: CMTD 1904370

Sum Insured:

Excess:

Make of Veh:

D.O.A. 15.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 18.9.19 1.24p.m

Person Contacted: Mrs N20

Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SLB 4296J - NA/ INC 19016407/h4 12.0A - 15/09/2019
	SLB 9970M - NA/ INC 19016407/h4 12.0A - 15/09/2019
	Dismantle: 20/9/2019
	After repair: 21/9/2019.

ASS. REC. BY:

REF: SMD

## ASSIGNMENT

From:

Veh No:

SLB 4296J

Yr Regn:

07/04/2016

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

SLB 4296J

Make:

Toyota corolla Axio AT c.c. 1496

at Workshop m/s

Neo Automotive

Colour:

silver

A/C:

Insured / Std / NI / NA

of

53 Ubi Ave 1 # 05-44

Sp. Reading

270274

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

NRE1610011364

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

Tyre Size:

F:

185/60/R15

R:

185/60/R15

IDAC Accident Rpt:

Consistent? : Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front and Rear same And (FIREN)

GIA / PR Seen:

Consistent? : Yes or No

Front

Rear

Est. Repairs:

5

days

Res.: Yes or No

R/Bal.

5

mm

R/Bal.

5

mm

Lum Sum:

%

3 Val.: Yes or No

L/Bal.

5

mm

L/Bal.

5

mm

CA / REV / REP. / 24 HRS

D.O.A.

15/9/19

D.O.I.

18/9/19

Survey held at

Neo Automotive

Des. of Damages:

Frt

Rear

O/S

N/S

U/C

Rooftop

or

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - 50000

PV - 36525

NV - 13400

MV - 49-56

range → 4 - 4.8L

repair Days → 5 days

\* NON Extensible (PRS) case  
SLB 4296J

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

5

1)

☐ : Final Report

Resurvey No. of Trip:

2

Date/Time, File Return to?

Survey Fee:

2)

Add Fee:

☐

Site Insp (\$

Transportation:

100

☐

Interview (\$

Photos

11

☐

Tech. Invs (\$

Others

☐

Weekend (\$

TOTAL

231

Rep. Formet:

PRS

Lump Sum / U/C / CS

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Sep 2019		18 Sep 2019 12:48 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HE HAI YANG, ID: S8188421H		
Main Claimant:	NEO AUTO LEASING PTE LTD		
Vehicle Reg. No.:	SLB4296J	Date of Loss:	15/09/2019 20:00 - :59
Claim Type:	TP / CMTD1904370	Policy/Cover Note No.:	D19MTPV01005432 (Comprehensive)
Vehicle Reg. No. (Insured):	SLB9970M	Policy No. (Claimant):	
		Excess:	
Repairer:	Neo Automotive Pte Ltd (HQ) 53 UBI AVE 1, #05-44 PAYA UBI INDUSTRIAL PARK, 408934 Kaki Bukit - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/09/2019]		
Driver/Custodian (Insured):	YANG XIAOJUAN (), NRIC: S8363536C, Tel: +6598358169 Email: -		
Adj Asg. Remarks:	Please assign to Mr Marcus Chua		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Enquire Vehicle Transfer Fee

### Vehicle Details

Vehicle No.  
**SLB4296J**

Make / Model  
**TOYOTA / COROLLA AXIO 1.5X CVT ABS D/AIRBAG 2WD**

Vehicle Type :  
**Z10 - Private Hire (Chauffeur) Motor Car**

Vehicle Attachment 1 :  
**No Attachment**

Vehicle Scheme :  
**Normal**

Chassis No. :  
**NRE1610011364**

Propellant :  
**Petrol**

Engine No. :  
**2NR8526846**

Motor No. :  
-

Engine Capacity :  
**1496 cc**

Power Rating :  
-



imum Power Output :  
**107 kW (107 bhp)**

Maximum Laden Weight :

**1365 kg**

Unladen Weight :

**1090 kg**

Year Of Manufacture :

**2015**

Original Registration Date :

**07 Apr 2016**

Lifespan Expiry Date :

-

COE Category :

**A - Car up to 1600cc & 97kW (130bhp)**

Quota Premium :

**\$45,000.00**

COE Expiry Date :

**06 Apr 2026**

Road Tax Expiry Date :

**06 Oct 2019**

PARF Eligibility Expiry Date :

**06 Apr 2026**

Inspection Due Date :

**06 Apr 2021**

Intended Transfer Date :

**23 Sep 2019**

CO2 Emission :

**133.00 (g/km)**

CEV/VES Rebate Utilised Amount :

**\$5,000.00**

CO Emission :

-

HC Emission :

-

NOx Emission :



mission :

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	915N
Vehicle Details	
Vehicle No.:	SLB4296J
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X CVT ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	2NR8526846
Chassis No.:	NRE1610011364
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$14,472.00
Original Registration Date:	07 Apr 2016
First Registration Date:	07 Apr 2016
Transfer Count:	2
Actual ARF Paid:	\$9,472.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Apr 2026
PARF Rebate Amount:	\$7,104.00
Intended COE Rebate Details	
COE Expiry Date:	06 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,000.00
COE Rebate Amount:	\$29,421.00
Total Rebate Amount:	\$36,525.00

The information contained herein is correct as at 23 Sep 2019

MV - 50000

PV - 36525

NV - 13400

MV - 4950 H

OK

Balance = 6 year 7 months

Depreciation = 6900 year

$6900 \div 12 = 575$  months

$41400 + 4025 + 4736$

$= 50161$

## Get More Cash for Your Car, Post an Ad Today

Receive a higher selling price by selling your car yourself.  
Advertise it for sale at just \$58, list till sold.

toyota axio Price Range Depreciation 2016 Vehicle Type

Advanced Search

Home » Used Cars » Platinum Motoring » Toyota Corolla Axio 1.5A X

### Toyota Corolla Axio 1.5A X

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM AD

**Price** \$54,800

**Depreciation** ⑦ \$7,600 /yr  
View models with similar depre

**Reg Date** 13-May-2016  
(6yrs 7mths 18days COE left)

**Mileage** 30,000 km (8.9k /yr)

**Manufactured** ⑦ 2016

**Road Tax** ⑦ \$682 /yr

**Transmission** Auto

**Dereg Value** ⑦ \$35,076 as of today (change)

**OMV** ⑦ \$18,724

**COE** ⑦ \$43,000

**ARF** ⑦ \$8,724

**Engine Cap** 1,496 cc

**Power** 80.0 kW (107 bhp)

**Curb Weight** ⑦ 1,090 kg

**No. of Owners** ⑦ 1

**Type of Vehicle** Mid-Sized Sedan

#### Features

Reliable 1.5L DOHC VVT-i Engine, 107 BHP, Super CVT-i Auto Transmission, ABS, Airbags, Front Wheel Drive And Knockdown Rear Seats. View specs of the Toyota Corolla Axio (2015-2019)

#### Accessories

Pure Leather Seats, Sports Rims, Pioneer Touch Screen Audio System, Reverse Sensors/Camera, Retractable Side Mirrors, Solar Film And Fog Lights.

#### Description

Well Maintained By Previous Owner. 1 Owner Only, Very Low Mileage Of 30k Km Only! Low Interest Rate Just At 1.98%! Condition Very Well Maintained! 1 To 1 Exchange Without Cash Top Up! 2 Years Warranty And Servicing By Platinum Motoring In House Workshop. New Paint And Leather Seats Done Up, Hurry And Call Our Friendly Sales Adviser For More Info Before It's Sold!

#### Category

PARF Car, Premium Ad Car, Low Mileage Car

#### Status

Available

#### Resources



#### Car Valuation - Free

Find out the market value of your existing car for free. Get started




#### Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



#### Price Chart

#### Summary



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

#### Seller Information

##### Company

Platinum Motoring

» dealer's pricelist

» 21 vehs sold | 12 vehs available

##### Address

53 Ubi Avenue 1 #01-25

Search cars nearby this location

##### Location

Paya Ubi Industrial Park

##### Office No

65842502

##### Contact Person(s)

Ian Oh

96972102

Posted on: 22-Sep-2019 | Last Updated on: 24-Sep-2019

#### Upfront Payment

» more Financial info

**Transf** \$25

**Dc** Compare \$16,440 (change)

Maximum 70% Loan

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/09/2019 15:11
Date Of Accident	15/09/2019 20:55
Exact Location Of Accident	CARPARK OF BLK 133 BEDOK RESERVOIR RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB4296J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NEO AUTO LEASING PTE LTD
Co Reg No	201814915N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91449265

### Vehicle Particulars

Manufacturer	TOYOTA
Model	AXIO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5103424803
Cover Note Number	-

### Driver

Name of Driver	TENG HEONG CHEONG
NRIC No	S1398313E
Date Of Birth	13/11/1959
Occupation	OUTDOOR
Date Of Driving Pass	11/10/1978
Driving Experience	40 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90286198
Fax Number	
Contact Number	
Email Address	NOEMAIL



Address	BLK 636 BEDOK RESERVOIR RD #13-27
Postcode	410636
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : XIN YI GENDER: : FEMALE
Passenger 2	NAME: : YAP MOI KAI GENDER: : FEMALE
Passenger 3	NAME: : XIN RU GENDER: : FEMALE
Passenger 4	NAME: : XIN HUI GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	EUNOS NEIGHBOURHOOD POLICE POST
Police Station Address	<b>ROAD:</b> BLK 629 BEDOK RESERVOIR ROAD #01-1620 , <b>POSTCODE:</b> 470629 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-4439999 - <b>FAX NO:</b> 62444376
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT T/20190916/2127

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SLB9970M	<i>Nissan / X-TRAIL 2.0 CVT</i>
Vehicle Make/Model/Colour		
Details Of Properties		
Vehicle Category	PRIVATE CAR	
Name of Driver		
NRIC/Passport Number		
Contact Number		
Address		
Postcode		
Insurance Company Name		
Nature Of Damage		
No. Of Passenger (Including Driver)		

**DETAILS OF INJURED PERSON 1**

Name	TENG HEONG CHEONG
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SLB4296J
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

**DETAILS OF INJURED PERSON 2**

Name	XIN YI
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SLB4296J
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to renege on policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Accident Sketch Plan

## SKETCH PLAN

A= SLB 4296 J  
B= SLB 7770 M

133 132

BIK 133 Bedok Reservoir Rd Carpark

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report T120190916 / 2137

## DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20190916/2127

1 of 4

Police Station Of Origin:  
Eunos NPP  
629 Bedok Reservoir Road #01-1620  
SINGAPORE 470629  
Tel No: 1800-4439999

Report No. T/20190916/2127

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 16/09/2019 17:21	Vide Report No.:	Station Diary No.: 31
--	------------------	--------------------------

<b>Informant's Particulars</b>			
Name of Informant: TENG HEONG CHEONG		Address: APT BLK 636 BEDOK RESERVOIR ROAD #13-27 SINGAPORE 410636	
ID Type / ID No.: NRIC NO / S1398313E		Contact No.: Home/Office: Mobile: 90286198	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 59	Date of Birth: 13/11/1959	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: GRAB DRIVER		Driving Licence Information: Class: Date of Expiry:	

<b>General Information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 15/09/2019 20:55	Type of Location: Bend
Location: Along Road 1 BEDOK RESERVOIR ROAD				
Carpark of Blk 133 Bedok Reservoir Road				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Head On			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLB4296J	Car	TOYOTA		Silver	Seriously Damaged	4
SLB9970M	Car	NISSAN		Silver	No Damage	2

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20190916/2127

Police Station Of Origin:  
Eunos NPP  
629 Bedok Reservoir Road #01-1620  
SINGAPORE 470629  
Tel No: 1800-4439999

2 of 4

Report No. T/20190916/2127

**CONTINUATION OF REPORT**

<b>Passenger</b>			
Name	XIN RU	ID No.	S9936659A
Related Vehicle	SLB4296J (Car)	Contact No.	90919908
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Passenger</b>			
Name	XIN HUI	ID No.	S9728509H
Related Vehicle	SLB4296J (Car)	Contact No.	93212397
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	TENG HEONG CHEONG	ID No.	S1398313E
Related Vehicle	SLB4296J (Car)	Contact No.	90286198
Hospital/Clinic	ACCORD MEDICAL CLINIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	16/09/2019	Date Discharge	16/09/2019
No. of Days granted Medical Leave	03	Degree of Injury	Serious
<b>Passenger</b>			
Name	XIN YI	ID No.	S9545274D
Related Vehicle	SLB4296J (Car)	Contact No.	83281108
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE  
POLICE FORCE**



T/20190916/2127

Police Station Of Origin:  
Eunos NPP  
629 Bedok Reservoir Road #01-1620  
SINGAPORE 470629  
Tel No: 1800-4439999

3 of 4

Report No. T/20190916/2127

**CONTINUATION OF REPORT**

Passenger			
Name	YAP MOI KAI	ID No.	S2596846H
Related Vehicle	SLB4296J (Car)	Contact No.	96936863
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 15/09/2019 at 2055hrs I was driving my car SLB4296J at the vicinity of Blk 133 Bedok Reservoir Road. As I wanted to exit the carpark, a car SLB9970M came in to make a right turn. I managed to stop however, the said car hit the front of my car and the plate number of my car dropped out. I was not able to get the particulars.

I wish to state that I made a check on my back as I felt uneasy and I received 3 days of my MC. My passenger which is my daughter namely Xin Yi suffered a headache and pain on the neck. She is going to see the doctor. My wife and my other 2 children who were the passenger on my car did not sustained any injury. I wish to also state that I have an in car camera installed and the accident was recorded.

I am lodging this report for record purposes.



**SINGAPORE  
POLICE FORCE**



T/20190916/2127

4 of 4

Police Station Of Origin:  
Eunos NPP  
629 Bedok Reservoir Road #01-1620  
SINGAPORE 470629  
Tel No: 1800-4439999

Report No. T/20190916/2127

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 1 NORISHAM BIN KAMIZAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SSI 2 JUREMAH BINTE AHMAD

Contact No.: 65476219

Signature Of Informant:

Date/Time:

16/09/2019 17:21

Classification Of Case:

Authentication Stamp  
NP188



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Sep 2019		18 Sep 2019 12:48 <a href="#">Edit Adj Rpt</a>	<b>\$0.00</b> <a href="#">Edit Estimates</a>	<b>\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	HE HAI YANG, ID: S8188421H								
Main Claimant:	NEO AUTO LEASING PTE LTD								
Vehicle Reg. No.:	SLB4296J	Date of Loss:	15/09/2019 20:00 - :59 [41 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1904370	Policy/Cover Note No.:	D19MTPV01005432 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLB9970M	Policy No. (Claimant):							
		Excess:							
Repairer:	Neo Automotive Pte Ltd (HQ) 53 UBI AVE 1, #05-44 PAYA UBI INDUSTRIAL PARK, 408934 Kaki Bukit - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 27/09/2019]								
Driver/Custodian (Insured):	YANG XIAOJUAN ( ), NRIC: S8363536C, Tel: +6598358169 Email:								
Adj Asg. Remarks:	Please assign to Mr Marcus Chua								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLB4296J (CMTD1904370)  
[SLB9970M]





































TP

























































NEO AUTO LEASING PTE LTD







Sep 15 2019 8:00PM

[HE HAI YANG]

Neo Automotive Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View <span>View in Browser</span>	
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	24/09/19 13:11	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>	
2	24/09/19 13:11	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>	
3	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
24	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
25	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
26	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
27	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
28	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
29	24/09/19 13:12	General View	 Load JPG	<input checked="" type="checkbox"/>	
30	24/09/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>	
31	24/09/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>	
32	24/09/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>	
33	24/09/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>	
34	24/09/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>	
35	24/09/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>	
36	24/09/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>	
37	24/09/19 13:13	General View	Load JPG	<input checked="" type="checkbox"/>	
38	24/09/19 13:13	General View	Load JPG	<input checked="" type="checkbox"/>	
39	24/09/19 13:13	General View	Load JPG	<input checked="" type="checkbox"/>	
40	24/09/19 13:13	General View	Load JPG	<input checked="" type="checkbox"/>	
41	24/09/19 13:13	General View	Load JPG	<input checked="" type="checkbox"/>	
42	24/09/19 13:13	General View	Load JPG	<input checked="" type="checkbox"/>	
43	24/09/19 13:13	General View	Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	24/09/19 13:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
85	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
86	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
87	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
88	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
89	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
90	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
91	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
92	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
93	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
94	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
95	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
96	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
97	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
98	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
99	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
101	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
102	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
103	27/09/19 09:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	17/09/19 17:30	Letter from Centrol-Legal	 Load PDF	
2	18/09/19 12:47	PRI - LKK	 Load HTM	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19016476/HQF3E2

Date: 09/10/2019

## REFERENCE

Handling Insurer: Sompoo Insurance Singapore Pte. Ltd. Policy No: D19MTPV01005432

Claimant Vehicle No: SLB4296J Insured Vehicle No: SLB9970M

Date of Loss: 15/09/2019 Nature of Claim: TP Claim No: CMTD1904370

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLB4296J

Make & Model: TOYOTA COROLLA AXIO, 1.5 HYBRID CVT (A) Engine No: 2NR8526846

Reg. Date: 07/04/2016 (Man. Year: 2015) Chassis No: NRE1610011364

Colour: Silver Odometer: 270274 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Firenza 5 mm Rear Left Side: Firenza 5 mm

Front Right Side: Firenza 5 mm Rear Right Side: Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 18/09/2019

Date Inspected: 18/09/2019 Inspected At:

Neo Automotive Pte Ltd (HQ)  
53 UBI AVE 1, #05-44 PAYA UBI  
INDUSTRIAL PARK  
Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: LEE HOCK ANN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 Oct 2019)
<b>Parts:</b>	143	TOYOTA COROLLA AXIO 1.5 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLB4296J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**