

ASS. REC. BY:

REF: OS/INC19016481/Krd3n2

Special Instruction:

Assigner: Kenneth

ASSIGNMENT (Office)

From (Person): Annie Koh

of INC

Date/Time: 9:29am @ 18/9/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKX 9109E

Insured: SLB5957D

at Workshop n/s Massive Trading

Tel: 9108 2728

of Blk 5038 # 01-405 AMK Ind-park 2

Policy No:

Claim No: MT/1062866-001

Sum Insured:

Excess:

Make of Veh:

D.O.A. 16/09/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:26am @ 18/9/19

Person Contacted: Anthony

Vehicle: IN LOIT

Date/Time	Action/Instruction	Estimated
	SKX 9109E - X	✓
	SLB 5957D - X	
24/9	11pm @ 1600h email & confirm (Ref 2924.85, 65%)	

ASS. TEO. BY:


REF: INC

ASSIGNMENT

From:                                  Date: 18/9/2019  
Estimated Cost:                                   
OD: TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SKX 9109E  
at Workshop m/s: Massive Trading  
of BLK 6038 #01- 405 AMK Ind. park  
Insured: 2  
Policy No:                                   
Claims No:                                   
Sum Insured:                                  Excess:                                   
(Client's Record)  
Make of Veh:                                 

Veh No: SKX 9109E Yr Regn: 12 / 15  
Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or                                   
Make: Toyota A/C: 1598  
Colour: M.P. White A/C: Insured / Std / NI / NA  
Sp. Reading: 123486 T/Radio: Insured / Std / NI / NA  
Eng/No:                                   
C/No: MRO53REH104540571  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD / Rim or  
Tyre Size: F: Yoko 205/55R16

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.  
Bal. or Market Value:                                   
IDAC Accident Rpt:                                  Consistent?: Yes or No  
GIA / PR Seen:                                  Consistent?: Yes or No  
Est. Repairs: 03 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS mp  
Date:                                  Person Contacted:                                  Vehicle: IN / OUT



R:                                   
BS: BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front: R/Bal. 8 mm L/Bal. 8 mm  
Rear: R/Bal. 8 mm L/Bal. 8 mm  
D.O.A. 16/9/19 D.O.I. 18/9/19  
Survey held at                                  10:47  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Table with columns: Date / Time, Action / Instruction. Multiple rows for recording actions.

Date/Time, File Pass to?  : Prel. Report  
 : Final Report

Days Of Repair: 3  
Resurvey No. of Trip: 1

Date/Time, File Return to? 25/9 - typist  
Report Format: TP  
Lump Sum / L.S.: 1600/2

Add Fee:  : Site Insp (\$)  : Interview (\$)  : Tech. Insp (\$)  : Wheel end (\$)

Table for Survey Fee: Transportation (S + RS \$), Flore, Other, Total. Total amount: 250.

**Nivitha (LKK Auto)**

**From:** Annie Koh <annie.koh@income.com.sg>  
**Sent:** Wednesday, 18 September 2019 9:44 AM  
**To:** 'assignments@lkkauto.com'; Admin-D (LKKAuto)  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 18/09/2019

Re-send

Warmest Regards

**Annie Koh**  
Senior Admin,  
Motor Insurance  
T +65 64307899  
[www.income.com.sg](http://www.income.com.sg)



**From:** Annie Koh  
**Sent:** Wednesday, 18 September 2019 9:29 AM  
**To:** 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>  
**Cc:** Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 18/09/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	OIVEH	DOA	Additional Remarks
----	-----	-----------	---------	---------------	------------------	------------------	-------	-----	--------------------

1	Eng Huey Huey	MT/1060773-002	5LD8401K	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188	SJA5936T	31/8/19	
2	Azhari	MT/1062866-001	SKX9109E	MASSIVE TRADING & AUTO	BLK 5038 #01-405 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569541	Anthony Cheong / 91082728	SLB5957D	16/9/19	
3		PENDING ADVISE	YNG081G	SMRT AUTOMOTIVE SERVICES PTE LTD	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Mr. Tan YuWei / 98506093			
4	WO Jessie	MT/1062709-002	SHC2038T	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Ms Lynn / 65425119	SGB5888D	15/9/19	Ms Irene at 6542 7162

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

**Annie Koh**  
Senior Admin Assistant, Motor Insurance  
**T +65 6430 7899**  
[www.income.com.sg](http://www.income.com.sg)





---

**Disclaimer**

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	887J
Vehicle Details	
Vehicle No.:	SKX9109E
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	1ZRY220909
Chassis No.:	MR053REH104540571
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,804.00
Original Registration Date:	31 Dec 2015
First Registration Date:	31 Dec 2015
Transfer Count:	1
Actual ARF Paid:	\$17,804.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Dec 2025
PARF Rebate Amount:	\$13,353.00
Intended COE Rebate Details	
COE Expiry Date:	30 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,399.00
COE Rebate Amount:	\$34,698.00
<b>Total Rebate Amount:</b>	<b>\$48,051.00</b>

The information contained herein is correct as at 25 Sep 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/09/2019 13:44
Date Of Accident	16/09/2019 17:00
Exact Location Of Accident	AMK AVE 8 TWDS AVE 5
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX9109E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HUANG HUAFENG
NRIC No	S7963887J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91809431
Alternative Phone No	OTHERS-91809431
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107125132
Cover Note Number	
<b>Driver</b>	
Name of Driver	HUANG HUAFENG
NRIC No	S7963887J
Date Of Birth	06/06/1979
Occupation	OUTDOOR
Date Of Driving Pass	08/08/2011
Driving Experience	8 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91809431
Fax Number	
Contact Number	OTHERS-91809431
EEmail Address	NOEMAIL

Address BLK 688A WOODLANDS DR 75  
 #05-22  
 Postcode 731688  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 3  
 Passenger 1 NAME: : NA  
 GENDER: : MALE  
 Passenger 2 NAME: : NA  
 GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

ON 16/9/2019 @ 1700HRS, I WAS TRAVELLING ALONG ANG MO KIO AVE 8 TOWARDS AVE 5. JUST BEFORE ANG MO KIO CENTRAL 2 ENTRANCE, I STOPPED AT A TRAFFIC LIGHT DUE TO RED LIGHT. WHILE WAITING FOR THE LIGHT TO TURN GREEN, SUDDENLY I FELT AN STRONG IMPACT FROM THE REAR OF MY VEHICLE. I EXITED MY VEHICLE AND REALISED THAT VEH B ( SLB 5957 D ) HAD COLLIDED INTO MY VEHICLE REAR PORTION.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLB5957D  
 Vehicle Make/Model/Colour HONDA  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number 96277310



Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow Insurance companies to repeal policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:




Driver's Signature  
(if driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16/9/2019 @ about 1700hrs, I was travelling along Ang Mo Kio Ave 8 towards Ave 5. Just before Ang Mo Kio Central 2 entrance, I stopped at a traffic light due to red light. While waiting for the lights to turn green, suddenly I felt an strong impact from the rear of my vehicle. I exited my vehicle and realised that veh B (SLB5957D) had collided into my vehicle rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*Signature*

Policyholder's Signature  
Date & Time:

*Signature*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*Signature*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225  
H/p 91082728

Fax : 64816131

NTUC Income  
73 Bras Basah Road  
#05-00 NTUC Trade Union House  
Singapore 189556

Vehicle No : SKX 9109 E  
Make : Toyota Altis  
Year : 2016

*Not with owner  
61 Lor BT Road  
Assembly after paint  
3 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear boot lid	<i>M</i> \$683.10	X
1 pc	Rear boot lid inner lock	<i>M</i> \$359.10	X
1 pc	Rear boot lid inner lock sensor	<i>Sm</i> \$205.70	X
1 pc	Rear boot lid emblem " Logo "	<i>M</i> \$65.70	—
1 pc	Rear boot lid emblem " Corolla "	<i>M</i> \$75.10	—
1 pc	Rear boot lid emblem " Altis "	<i>M</i> \$70.20	—
1 pc	Rear boot rubber	<i>M</i> \$181.70	X
1 pc	Rear end panel	<i>M</i> \$537.10	X
1 pc	Rear end panel inner garnish	<i>Sm</i> \$263.70	X
1 pc	Rear bumper	<i>Bu</i> \$553.10	—
1 pc	Rear bumper reinforcement	<i>Bu</i> \$339.60	—
2 pcs	Rear bumper bracket	\$110.20 <i>M</i> \$220.40	X
2 pcs	Rear bumper side retainer	\$85.10 <i>Sm</i> \$170.20	X
1 set	Rear reverse sensor	<i>M</i> \$395.10	—
		<u>\$4,119.80</u>	
		Less 25 %	<u>\$1,029.95</u>
			<u>\$3,089.85</u>

S Nett

20 pcs	Bumper clip	\$2.00 <i>M</i>	\$40.00	—
--------	-------------	-----------------	---------	---

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	\$600.00	<i>400</i>
To putty & spray paint rear accident affected portion.	\$600.00	<i>440</i>
Check/reconnect wiring.	\$45.00	<i>15/</i>
To spray anti rust on accident affected portion.	<i>M</i> \$150.00	X
		<u>\$4,524.85</u>

LKK Auto Consultants hereby notify the Repairer of the following:

- To receive bills, invoices, receipts, etc.
- To display damaged car in a safe manner.
- Parts price are based on market value.
- Third party claims are on a non-liable basis.
- No liability for consequential damages.
- Scratch repair is not included in the estimate.
- Is not a part of the insurance company.

Address: ...  
Company: ...  
Date: ...

Total




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT			
NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: CS/INC19016481/Kvd3n2	
73 BRAS BASAH ROAD		Date: 27-09-2019	
#05-01 NTUC TRADE UNION HOUSESINGAPORE			
189556			
ATTN: AZHARI		Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLB 5957D	Veh. Inspected	SKX 9109E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1062866-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	18/09/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MR053REH104540571	Colour	METALLIC PEARL WHITE
Odometer	123486 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	8 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	8 mm
R/H Rear Tyre	205/55 R16	DUNLOP	8 mm
L/H Rear Tyre	205/55 R16	DUNLOP	8 mm
4. Description of Damages			
<p>THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.</p> <p>DAMAGES SEE DETAILS.</p>			
5. General Information			
Accident Date	16/09/2019	Inspect Date / Time	18/09/2019 ( 10:47 AM )
Survey held at	BLK 5038 # 01-405 AMK IND.PARK 2		
Repairer	MASSIVE TRADING & AUTO		
5a. Remarks			
<p>A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.</p> <p>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.</p>			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 9109E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOT LID	TO REPAIR SEE LABOUR	683.10	-
1	REAR BOOT LID INNER LOCK	TO REPAIR SEE LABOUR	359.10	-
1	REAR BOOT LID INNER LOCK SENSOR	SERVICEABLE	205.70	-
1	REAR BOOT LID EMBLEM "LOGO"	NECESSARY	65.70	65.70
1	REAR BOOT LID EMBLEM "COROLLA"	NECESSARY	75.10	75.10
1	REAR BOOT LID EMBLEM "ALTIS"	NECESSARY	70.20	70.20
1	REAR BOOT RUBBER	SERVICEABLE	181.70	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	537.10	-
1	REAR END PANEL INNER GARNISH	SERVICEABLE	263.70	-
1	REAR BUMPER	BUCKLED	553.10	553.10
1	REAR BUMPER REINFORCEMENT	BENT	339.60	339.60
2	REAR BUMPER BRACKET @\$110.20	TO REPAIR SEE LABOUR	220.40	-
2	REAR BUMPER SIDE RETAINER @\$85.10	SERVICEABLE	170.20	-
1	SET REAR REVERSE SENSOR	DENTED	395.10	395.10
	LESS 25% DISCOUNT		-1,029.95	-374.70
			3,089.85	1,124.10
<b><u>SPECIAL NETT ITEMS</u></b>				
20	BUMPER CLIP @\$2.00 (SN)	NECESSARY	40.00	40.00
			40.00	40.00
<b><u>LABOUR</u></b>				
	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING. INCLUSIVE OF THE REPAIR OF REAR BOOT LID, REAR BOOT LID INNER LOCK, REAR END PANEL AND REAR BUMPER BRACKET.		600.00	400.00
	TO PUTTY & SPRAY PAINT REAR ACCIDENT AFFECTED PORTION.		600.00	440.00
	CHECK/RECONNECT WIRING.		45.00	15.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION.	NOT NECESSARY	150.00	-
			1,395.00	855.00
<b>GRAND TOTAL</b>			<b>4,524.85</b>	<b>2,019.10</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,600.00</b>

Report Ref No. CS/INC19016481/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.