

22/03/2002

ASS. REC. BY:

REF: CS3/CT119016485/Gc f3

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Irene Tan Hui Ping of CT1

Date/Time: 12.9.19 14.42p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMH 1993G

Insured: SLQ 9093G

at Workshop in/s Tamp: nse Auto

Tel: 6786 2884

of BIK 9002 Tamp: nse st 93, 101-34

Policy No: DMPCSN 30045319011

Claim No: SYM 190204339C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 12.9.2019

CA / REV / REP. / REV 24 HRS

"np"

H.O.D. Endorsement:

Date/Time: 18.9.19 2.46p.m

Person Contacted:

Linda

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SMH 1993G - NA/CT1 19016252 = 4

D.O.A - 12/09/2019

SLQ 9093G - X

Dismantle: 19/9/2019

Before paint: 19/9/2019

After paint: 20/9/2019

ASS. REC. BY:

REF: 012

ASSIGNMENT

From:

Date:

18.9.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMH 1993G

at Workshop m/s

Tampinuse Auto

of

Blk 902 Tampinuse St 93 # 01-34

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 1/2

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mup'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMH 1993G

Yr Regn:

15 Jan 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Noah

C.C.

1797

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

29029

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

8WR 800338954

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

11

BS / DUN / EXNOVA / SY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

18-08-19

Survey held at

w/s

4:50pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$2000 - \$3000

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

3

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

Rep. Format:

PRS

Lump Sum / L.R. / C.

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weel end (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Sep 2019		18 Sep 2019 14:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant:		PEH CHUN XIANG							
Vehicle Reg. No.:		SMH1993G	Date of Loss:	12/09/2019 15:00 - :59					
Claim Type:		TP / SNM19D204339C02	Policy/Cover Note No.:	DMPCSN30045319011					
Vehicle Reg. No. (Insured):		SLQ9093G	Policy No. (Claimant):						
		Excess:	S\$0.00						
Repairer:		Tampines Auto Services (HQ) BLK 9002 TAMPINES ST 93, #01-34/36 INDUSTRIAL PARK A, 528836 Tampines - Tel: 67862884							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/09/2019]							
Adj Asg. Remarks:		PLEASE SURVEY AND REVERT							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Wednesday, 18 September 2019 2:24 PM
To: Kavitha; Asher Sng (LKK Auto); assignments
Cc: Charles Hoon; Jolene Kuik; Seng Tat; tas0136@hotmail.com; andrew37@singnet.com.sg
Subject: RE: OUR REF: SNM19D204339-SLQ9093R-THP - Our Ref AP/2019/001686 CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 12 SEPTEMBER 2019 AT ABOUT 15:50HRS INVOLVING MOTOR VEHICLES NO(S). SMH1993G AND SLQ9093R ALONG EXPRESSWAY AFTER FLYOVER

Dear Sir/Mdm (LKK),

We refer to the above matter.

Please get your surveyor to liaise with A P Law to conduct PRS.

Regards,

Irene Tay

Executive

Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896192 | F: (65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Kavitha [mailto:kavitha@aplp.com.sg]
Sent: Tuesday, September 17, 2019 9:46 AM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Cc: Charles Hoon <charles@aplp.com.sg>; Jolene Kuik <jolene@aplp.com.sg>; Seng Tat <sengtat@aplp.com.sg>; tas0136@hotmail.com; andrew37@singnet.com.sg
Subject: RE: OUR REF: SNM19D204339-SLQ9093R-THP - Our Ref AP/2019/001686 CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 12 SEPTEMBER 2019 AT ABOUT 15:50HRS INVOLVING MOTOR VEHICLES NO(S). SMH1993G AND SLQ9093R ALONG EXPRESSWAY AFTER FLYOVER

WITHOUT PREJUDICE

Dear Sir/ Mdm,

We refer to your email of even date.

Our clients do not agree to your list of surveyors.

We are instructed to propose the use of one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

- a) Alan Cheong
- b) TT Rajan
- c) Oh Han Cheong
- d) Andrew How
- e) Dave Ho Joo Koong
- f) Sincere Appraiser
- g) Seah Kwang Boon
- h) L H Teo
- i) Mr Willy Goh
- j) Nicky Seah
- k) Jayson Liaw

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors.

In the event you are not agreeable to our list of surveyor, please note that our client's vehicle can be inspected at:

Repairer Office

M/s. Tampines Auto Services

Contact Person: Ms Linda @ 6786 2884 / 9793 3147 / (Fax: 6786 2926)

Email: tas0136@hotmail.com

Address: Blk 9002, Tampines Street 93, #01-36, Singapore 528836.

Please note that our clients' vehicle will only be available for pre-repair survey within the next two (2) working days. Our clients shall proceed to repair their vehicle thereafter without further notice or reference to you.

All our clients' rights are reserved.

Please note our new office address as of 1st June 2019.

**151 Chin Swee Road,
#10-03/05 Manhattan House,
Singapore 169876
Tel no.: 6955 8899
Office mobile no.: 9171 4767
Fax no.: 6900 9899**

kavitha

AP Law Practice

50 Chin Swee Road #07-01 Thong Chai Building, Singapore 169874

T: 6955 8899 F: 6900 9899 E: sengtat@aplp.com.sg

Singapore UEN No.: 53380739E

This email transmission is confidential and intended only for the addressee(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.

From: Irene Tay <irene.tay@sg.entaiping.com>

Sent: Monday, 16 September 2019 6:52 PM

To: Kavitha <kavitha@aplp.com.sg>

Cc: Kavitha <kavitha@aplp.com.sg>

Subject: FW: OUR REF: SNM19D204339-SLQ9093R-THP - Our Ref AP/2019/001686 CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 12 SEPTEMBER 2019 AT ABOUT 15:50HRS INVOLVING MOTOR VEHICLES NO(S). SMH1993G AND SLQ9093R ALONG EXPRESSWAY AFTER FLYOVER

WITHOUT PREJUDICE

Dear Sirs

We refer to your letter of 16 September 2019.

Kindly note the following:-

1. We would like to conduct pre-repair survey of the vehicle at the appointed workshop.
2. We propose the following list of surveyors to be nominated as the Single Joint Expert to conduct survey of the claimant's vehicle:-

1. ADRIAN LING	6. KENNETH KONG
2. Kelvin Ang	7. SIMON HO
3. SEE CHEW SENG	8. CHUA WEIJIE
4. MOHD FADHILAH BIN OSMAN	9. MARCUS CHUA
5. XING QUO QIANG	10. HENRY NG

3. If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.
4. As per the NIMA Protocol, the survey by our appointed surveyor would include survey of your vehicle pre-repair, after it is dismantled, and post repairs. Hence, you need to provide us / our surveyors with the list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.
5. As stated above, please inform us and our surveyor after the claimant's vehicle had been repaired so that our surveyor can carry out post repair inspection before the vehicle is returned to your client. Please co-ordinate with our surveyor immediately after the repair is completed.

If you have any queries, please contact us

Yours faithfully

Irene Tay

Executive

Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896192 | F: (65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Monday, September 16, 2019 11:43 AM

To: Irene Tay <irene.tay@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; kavitha@aplp.com.sg

Subject: OUR REF: SNM19D204339-SLQ9093R-THP - Our Ref AP/2019/001686 CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 12 SEPTEMBER 2019 AT ABOUT 15:50HRS INVOLVING MOTOR VEHICLES NO(S). SMH1993G AND SLQ9093R ALONG EXPRESSWAY AFTER FLYOVER

Dear Irene,

Please conduct PRS for SMH1993G.

Note: officer in charge – Irene Tay 63896192.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Kavitha [<mailto:kavitha@aplp.com.sg>]

Sent: Friday, 13 September, 2019 5:24 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Charles Hoon <charles@aplp.com.sg>; Jolene Kuik <jolene@aplp.com.sg>; Seng Tat <sengtat@aplp.com.sg>; tas0136@hotmail.com; andrew37@singnet.com.sg

Subject: Our Ref AP/2019/001686 CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 12 SEPTEMBER 2019 AT ABOUT 15:50HRS INVOLVING MOTOR VEHICLES NO(S). SMH1993G AND SLQ9093R ALONG EXPRESSWAY AFTER FLYOVER

Attn: Motor Claims Department

Dear Sirs,

Please find attached, our letter of even date

Regards,

Kavitha

Secretary to Mr Charles Hoon

AP Law Practice

151 Chin Swee Road #10-03/05 Manhattan House, Singapore 169876

T: 6955 8899 F: 6900 9899 E: kavitha@aplp.com.sg

Singapore UEN No.: 53380739E

This email transmission is confidential and intended only for the addressee(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	288Z

Vehicle Details

Vehicle No.:	SMH1993G
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	NOAH HYBRID 7-SEATER 1.8X CVT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	2ZR2B16843
Chassis No.:	ZWR800338954
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$31,940.00
Original Registration Date:	15 Jan 2019
First Registration Date:	15 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$26,716.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jan 2029
PARF Rebate Amount:	\$20,037.00

Intended COE Rebate Details

COE Expiry Date:	14 Jan 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,200.00
COE Rebate Amount:	\$30,010.00
Total Rebate Amount:	\$50,047.00

The information contained herein is correct as at 19 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/09/2019 12:22
Date Of Accident	12/09/2019 15:50
Exact Location Of Accident	EXPRESSWAY AFTER FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH1993G
Insured/Policyholder	
Name Of Registered Owner	PEH CHUN XIANG(BAI JUNXIANG)
NRIC No	S8119288Z
Email Address	KENNETH.91991332@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91991332
Alternative Phone No	OTHERS-91991332

Vehicle Particulars

Manufacturer	TOYOTA
Model	NOAH HYBRID 7-SEATER 1.8X CVT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD19V01263/VPC/R00
Cover Note Number	

Driver

Name of Driver	PEH CHUN XIANG(BAI JUNXIANG)
NRIC No	S8119288Z
Date Of Birth	12/06/1981
Occupation	INDOOR
Date Of Driving Pass	14/12/2004
Driving Experience	14 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91991332
Fax Number	
Contact Number	OTHERS-91991332
Email Address	KENNETH.91991332@GMAIL.COM

Address	BLK 804 TAMPINES AVENUE 4 #07-41
Postcode	520804
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GRACE
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

THE INCIDENT TOOK PLACE ON THE ABOVEMENTIONED LOCATION. WHILE IN THE MIDST OF TRAVELLING, THE FRONT VEHICLE SLOW DOWN. I THEN FOLLOW SUIT. THAT IS WHEN VEHICLE B UNABLE TO REACT ON TIME AND THUS TRYING TO SWERVE ON THE LEFT. BUT STILL THE COLLISION TOOK PLACE. HIS VEHICLE FRONT RIGHT HAND SIDE COLLIDED ONTO MY VEHICLE LEFT HAND SIDE REAR. WHICH RESULTED TO SUSTAIN DAMAGED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ9093R
Vehicle Make/Model/Colour	MERCEDES BENZ / S300L
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

FRONT RIGHT HAND SIDE

1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time



Driver's Signature
(If driver is not the policyholder)
Date & Time


13 SEP 2019

IDAC KAKI BUKIT (VAC)

Reporting Centre
Name: 23 Kaki Bukit Ave 4
Singapore 415933
NRIC/Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Rekr e-File

[Large handwritten signature/initials across the section]

DECLARATION

I/We declare the foregoing particulars true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

13 SEP 2019

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

Adjuster Letter/DV not verified.
This claim is to be authorized on the insurer's behalf.
Submissions will not be allowed until the Letter of Offer/DV is VERIFIED.
Click on 'View Letter/DV' to verify the offer.

You cannot authorize this offer because
Adjuster Letter/DV not verified.
File to be authorized by your superior.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19016485/GCF3Q
Date: 27/09/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30045319011
Claimant Vehicle No: SMH1993G Insured Vehicle No: SLQ9093G
Date of Loss: 12/09/2019 Nature of Claim: TP Claim No: SNM19D204339C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMH1993G
Make & Model: TOYOTA NOAH HYBRID, 1.8 X CVT (A)
Reg. Date: 15/01/2019 (Man. Year: 2018)
Colour: White
Engine Capacity: 1797 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

Engine No: 22R2B16843
Chassis No: ZWR800338954
Odometer: 29029 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15
Front Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm
Rear Tyre Size: 195/65 R15
Rear Left Side: Goodyear 6 mm
Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 18/09/2019
Date Inspected: 18/09/2019 Inspected At: Tampines Auto Services (HQ)
Estimated Period of Repair: 4.0 days BLK 9002 TAMPINES ST 93, #01-34/36 INDUSTRIAL PARK A
Singapore 528836

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

9/27/2019

Merimen e-Claims

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2019)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH1993G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items
There are no new miscellaneous items selected.

Recommended Labour
There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >