

ASS. REC. BY:

REF: CS3/CTI190/6500/H<sub>C</sub> f317 Special Instruction:

Surveyor: Hock Ann

ASSIGNMENT (Office)

From (Person): Iron Tag Hui Ping of CTI Date/Time: 18.9.19 15.37m

Estimated Cost: Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBA 9117J Insured: Ym 7775L

at Workshop m/s my car consultant Tel: 88668832

of 53 Wai Ave 1 A01-33

Policy No: DMCRSIR 30073819111 Claim No: SNM19D204135102

Sum Insured: Excess:

Make of Veh: D.O.A. 30.08.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 18.9.19 3.44p.m. Person Contacted: Hui Gin Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	GBA 9117J - NA / FCI 19015439/24 R.O.A. - 30/08/2019
	Ym 7775 L - NA / FCI 19015439/24 R.O.A. - 30/08/2019
	After repair: 20/9/2019.

HANN

REF: CTI

ASS. REC. BY:

PRS

## ASSIGNMENT

From:

Date:

18/9/19

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBA 9117J

at Workshop m/s

My car consultant

of

53 Ubi Avenue 1 #01-33

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBA 9117J

Yr Regn

18/03/2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Double cabin vehicle

Make:

Mitsubishi L200 2.5 AT CC 2477

Colour

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

173060

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MMBJRKB 407D059778

Gen. Cond (Good / Fair / Poor / Burnt)

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil (S/Rim) / STD A/Rim or

Tyre Size:

F:

225/75/R16

R:

245/70/R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front and Rear not same brand

Front

RADIAL

Rear

VITOUR SAFARIA

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

RADIAL

L/Bal.

5

mm

D.O.A.

30/8/19

D.O.I.

18/9/19

Survey held at

My car consultant

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV - 40000

PV - 26788

NV - 13200

MV - 3946

Range → 2.7 - 3.7k

repair days → 3 day

(\* NON Estimated PRS - Case)

26/9/2019

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

190

Transportation:

3 + RS, SI

Photos

Others

TOTAL

190

Report Format:

PRS

Lump Sum / L.E. / C.

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: \*Meal and

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Sep 2019		18 Sep 2019 15:25 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:									
Main Claimant: <b>SIANG HOCK CAR ENTAL PTE LTD</b>									
Vehicle Reg. No.: <b>GBA9117J</b>									
Date of Loss: 30/08/2019 21:00 - :59									
Claim Type: <b>TP / SNM19D204135C02</b>									
Policy/Cover Note No.: <b>DMCVSN300738191111</b>									
Vehicle Reg. No. (Insured): <b>YM7775L</b>									
Policy No. (Claimant):									
Excess: <b>S\$0.00</b>									
Repairer: <b>My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park, 408934 Ubi - Tel:</b>									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]</b>									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/09/2019]</b>									
Adj Asg. Remarks: <b>PLEASE SURVEY AND REVERT</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;">View All   Compose Case Mail</span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All   Search Tasks   Create New Task   Complete</span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Sent:** Wednesday, 18 September 2019 3:15 PM  
**To:** admin@mycar.sg; Admin A  
**Cc:** Asher Sng (LKK Auto); assignments  
**Subject:** FW: re: FW: OUR REF: SNM19D204135-YM7775L-TKL - FW: OUR REF: GBA9117J  
YOURREF: YM7775L PRE-REPAIR INSPECTION FOR GBA9117J  
**Attachments:** GBA9117J\_30082019.PDF

Dear Sir/Mdm (LKK),

We refer to the above matter.

Please get your surveyor to liaise with My-Car to conduct PRS.

Regards,

**Irene Tay**

Executive  
Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 63896192 | F: (65) 62247478/62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** My Car Consultant [mailto:admin@mycar.sg]  
**Sent:** Wednesday, September 18, 2019 10:37 AM  
**To:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Cc:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Subject:** fw: re: FW: OUR REF: SNM19D204135-YM7775L-TKL - FW: OUR REF: GBA9117J YOURREF: YM7775L PRE-REPAIR INSPECTION FOR GBA9117J

### WITHOUT PREJUDICE

Dear Irene,

Do come back with your proposed surveyor for this vehicle as i have not receive any arrangements.

Best Regards,

**Huiqin**

Claims | My Car Consultant Pte Ltd

☎ [+65 88668832](tel:+6588668832)

✉ [Admin@mycar.sg](mailto:Admin@mycar.sg)

🌐 [Mycar.sg](http://Mycar.sg)

📍 53 Ubi Ave 1, Paya Ubi Industrial Park, 01-33, S408934

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

---

**From:** "My Car Consultant" <admin@mycar.sg>

**Sent:** Tuesday, September 17, 2019 10:12 AM

**To:** "Irene Tay" <irene.tay@sg.cntaiping.com>

**Subject:** re: FW: OUR REF: SNM19D204135-YM7775L-TKL - FW: OUR REF: GBA9117J YOURREF: YM7775L PRE-REPAIR INSPECTION FOR GBA9117J

**WITHOUT PREJUDICE**

Dear Irene,

We refer to your email on even date.

We disagree to your list of surveyor and propose the use of one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

Alan Cheong  
TT Rajan  
Oh Han Cheong  
Andrew How  
Dave Ho Joo Koong  
Lee Kok Weng  
Seah Kwang Boon  
Lee K.W.  
Nicky Seah  
Winson Goh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors.

Best Regards,

**Huiqin**

Claims | My Car Consultant Pte Ltd

☎ **+65 88668832**

✉ [Admin@mycar.sg](mailto:Admin@mycar.sg)

🌐 [Mycar.sg](http://Mycar.sg)

📍 53 Ubi Ave 1, Paya Ubi Industrial Park, 01-33, S408934

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

---

**From:** "Irene Tay" <irene.tay@sg.cntaiping.com>

**Sent:** Monday, September 16, 2019 6:37 PM

**To:** "admin@mycar.sg" <admin@mycar.sg>

**Cc:** "admin@mycar.sg" <admin@mycar.sg>

**Subject:** FW: OUR REF: SNM19D204135-YM7775L-TKL - FW: OUR REF: GBA9117J YOURREF: YM7775L PRE-REPAIR INSPECTION FOR GBA9117J

**WITHOUT PREJUDICE**

Dear Sirs

We refer to your letter of 16 September 2019.

Kindly note the following:-

1. We would like to conduct pre-repair survey of the vehicle at the appointed workshop.
2. We propose the following list of surveyors to be nominated as the Single Joint Expert to conduct survey of the claimant's vehicle:-

1. ADRIAN LING	6. KENNETH KONG
2. Kelvin Ang	7. SIMON HO
3. SEE CHEW SENG	8. CHUA WEIJIE
4. MOHD FADHILAH BIN OSMAN	9. MARCUS CHUA
5. XING QUO QIANG	10. HENRY NG

3. If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.
4. As per the NIMA Protocol, the survey by our appointed surveyor would include survey of your vehicle pre-repair, after it is dismantled, and post repairs. Hence, you need to provide us / our surveyors with the list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.
5. As stated above, please inform us and our surveyor after the claimant's vehicle had been repaired so that our surveyor can carry out post repair inspection before the vehicle is returned to your client. Please co-ordinate with our surveyor immediately after the repair is completed.

If you have any queries, please contact us

Yours faithfully

**Irene Tay**

Executive

Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896192 | F: (65) 62247478/62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** ??? Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Claims Dept of CTI

**Sent:** Friday, September 13, 2019 3:13 PM

**To:** Tan Kah Leong <[KahLeong.Tan@sg.cntaiping.com](mailto:KahLeong.Tan@sg.cntaiping.com)>; Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; Irene Tay <[irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)>; [admin@mycar.sg](mailto:admin@mycar.sg)

**Subject:** OUR REF: SNM19D204135-YM7775L-TKL - FW: OUR REF: GBA9117J YOUR REF: YM7775L PRE-REPAIR INSPECTION FOR GBA9117J

Dear Irene,

Please assist to conduct PRS for GBA9117J.

Note : officer in charge – Kah Leong

Regards,

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: ??? Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** My Car Consultant [<mailto:admin@mycar.sg>]

**Sent:** Friday, 13 September, 2019 1:06 PM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Subject:** OUR REF: GBA9117J YOUR REF: YM7775L PRE-REPAIR INSPECTION FOR GBA9117J

**WITHOUT PREJUDICE**

OUR REF: GBA9117J  
YOUR REF: YM7775L

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR GBA9117J  
ACCIDENT INVOLVING GBA9117J AND YM7775L

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction - Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention

Warm Regards,  
Kai Ling

**My Car Consultant Pte Ltd**  
**53 Ubi Avenue 1**  
**Paya Ubi Industrial Park**  
**#01-33 S(408934)**

**Tel: +65 9868 6000 / Fax: 6925 5219**

CONFIDENTIALITY NOTICE: This message (including any attachments) is confidential and may be privileged. It may be read, copied and used only by the intended recipient. If you have received it in error please contact the sender (by return e-mail) immediately and delete this message. Any unauthorized use or dissemination of this message in whole or in parts is strictly prohibited.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	271R
Vehicle Details	
Vehicle No.:	GBA9117J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Sep 2019
Vehicle Make:	mitsubishi
Vehicle Model:	L200 DOUBLE CABIN 2.5L TURBO 4A/T DIESEL
Primary Colour:	Red
Manufacturing Year:	2006
Engine No.:	4D56UCAK2590
Chassis No.:	MMBJRKB407D059778
Maximum Power Output:	-
Open Market Value:	\$24,580.00
Original Registration Date:	18 Mar 2008
First Registration Date:	18 Mar 2008
Transfer Count:	2
Actual ARF Paid:	\$27,038.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jul 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$34,070.00
COE Rebate Amount:	\$26,788.00
Total Rebate Amount:	\$26,788.00

The information contained herein is correct as at 20 Sep 2019

OK

Balance = 8 year 2 month

Depreciation = 4900 year

$4900 \div 12 = 408 \text{ month}$

$39200 + 816$

$= 40016$

mv - 40000

pv - 26788

ivv - 13200

mv - 394016



> Back to OneMotoring

## Enquire Transfer Fee

### Vehicle Details

Vehicle No.:	GBA9117J
Vehicle Type:	C13 - Goods Cum Passenger Twin Cabin Goods Vehicle
Vehicle Attachment 1:	With Hood
Vehicle Scheme:	Normal
Vehicle Make:	MITSUBISHI
Vehicle Model:	L200 DOUBLE CABIN 2.5L TURBO 4A/T DIESEL
Chassis No.:	MMBJRKB407D059778
Propellant:	Diesel
Engine No.:	4D56UCAK2590
Engine Capacity:	2477 cc
Maximum Power Output:	-
Maximum Laden Weight:	2920 kg
Unladen Weight:	1980 kg
Year Of Manufacture:	2006
Original Registration Date:	18 Mar 2008
Lifespan Expiry Date:	17 Mar 2028
COE Category:	C - Goods Vehicle & Bus
PQP Paid:	\$34,070.00
COE Expiry Date:	31 Jul 2027
Road Tax Expiry Date:	17 Mar 2020
Inspection Due Date:	17 Mar 2020
Intended Transfer Date:	20 Sep 2019
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

### Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Total Amount Payable:</b>			<b>25.00</b>

### Message

This vehicle has a road tax Over Payment of \$88.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

You may print this page for reference.

OK

Print

**Get More Cash for Your Car, Post an Ad Today.**

Receive a higher selling price by selling your car yourself.  
Advertise it for sale at just \$58, list till sold.

Mitsubishi L200

Price Range ▼

Depreciation ▼

Year Reg ▼

Vehicle Type ▼

Advanced  
Search

Home » Used Cars » KSL Automotive Pte Ltd » Mitsubishi L200 Single-Cab 2.5M (COE till 07/2027)

**Mitsubishi L200 Single-Cab 2.5M (COE till 07/2027)**

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD


**KSL Automotive**  
Your Trusted Partner in Automotive


<b>Price</b>	<b>\$41,777</b>	<b>Lifespan</b>	10-Jan-2028
<b>Depreciation</b> ⓘ	\$5,310 /yr	<b>Reg Date</b>	11-Jan-2008 (7yrs 10mths 11days COE left)
<b>Mileage</b>	N.A.	<b>Manufactured</b> ⓘ	2007
<b>Road Tax</b> ⓘ	N.A.	<b>Transmission</b>	Manual
<b>Dereg Value</b> ⓘ	\$26,799 as of today (change)	<b>OMV</b> ⓘ	\$18,123
<b>COE</b> ⓘ	\$34,070	<b>ARF</b> ⓘ	\$907
<b>Engine Cap</b>	2,477 cc	<b>No. of Owners</b> ⓘ	2
<b>Curb Weight</b> ⓘ	1,740 kg		
<b>Type of Vehicle</b>	Truck		

**Features**

One Of The Most Reliable Commercial Vehicle In The Market Right Now! Provide You With Quality Performance And Definite Asset To Your Business. View specs of the Mitsubishi Triton L200 (2005-2009)

**Accessories**

Full Aluminum Checkered Plate, CD Player, New Paintwork, Checkered Plate Box, New 4 Tyres.

**Description**

\$0 Drive Away! No Gimmick! All Must Go! Vehicle In Excellent Condition, No Repair Needed! High Approval Rate For Loan, Trade In Are Welcome, Doorstep Viewing Can Be Arranged. Call Now Before It's Gone To Avoid Disappointment! Able To Do All Your Heavy Duty Transportation! Call Us And View This Beautiful Beast Now!

**Category**

COE Car, Premium Ad Car

**Status**

Available

**Resources****Vehicle Evaluation**

Afraid of lemons? Request to have this car evaluated professionally. Find out more

**Car Valuation - Free**

Find out the market value of your existing car for free. Get started



Shortlist

Compare

Add note

Report Error

More Actions

**Seller Information**

<b>Company</b>	<b>KSL Automotive Pte Ltd</b> » dealer's pricelist » 37 vehs sold   82 vehs available	
<b>Address</b>	2A Kian Teck Avenue Level 3 Search cars nearby this location	
<b>Office No</b>	62660777	
<b>Contact Person(s)</b>	Zhong Yuan	92332542
	Rox Toh	98252048
	Gary	96692872

Posted on: 20-Sep-2019 | Last updated on: 20-Sep-2019

Up: Compare

» more Financial info

[https://www.sgcarmart.com/used\\_cars/info.php?ID=831819&DL=3223](https://www.sgcarmart.com/used_cars/info.php?ID=831819&DL=3223)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/09/2019 09:48
Date Of Accident	30/08/2019 21:10
Exact Location Of Accident	BEDOK SHELL PETROL STATION
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBA9117J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SIANG HOCK CAR RENTAL PTE LTD
Co Reg No	201538271R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-899999999
<b>Vehicle Particulars</b>	
Manufacturer	MITSUBISHI
Model	L200 DOUBLE CABIN 2.5L TURBO 4A/T DIESEL
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-19093240MFCV/39
Cover Note Number	

### Driver

Name of Driver	YONG HAN XIAN
Passport No/FIN	G3850427X
Date Of Birth	07/06/1995
Occupation	OUTDOOR
Date Of Driving Pass	26/05/2018
Driving Experience	1 YEAR AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97708478
Fax Number	
Contact Number	OFFICE-97708478
Email Address	NOEMAIL

Address	BLK 124B BUKIT MERAH VIEW #11-414
Postcode	152124
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM7775L (MITSUBISHI / FE83BE05RDEA)
Vehicle Make/Model/Colour	1001
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Passenger 1

NAME: :

GENDER: :

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### Accident Sketch Plan

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Hindman.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature \_\_\_\_\_

Date &amp; Time:

Driver's Signature \_\_\_\_\_

(if driver is not the policyholder)

Date &amp; Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.

# Accident Sketch Plan

I was Refilling the petrol at Shell station on ~~Bedok~~ Bedok Rd. As I have get out from the car, the car was <sup>in</sup> stationary state. When I ~~begin~~ begin to start refill, the lorry with the Reg No - YM 7775L had ~~hit~~ hit the car. The incident happened around 9:11pm on 30 August 2014.

It was inside the Shell station.  
The Staff and The lorry ~~was~~ <sup>was</sup> ~~hit~~ <sup>hit</sup> the car.  
The lorry hit my car.

(The lorry with the Reg No YM 7775L who about to turn and move forward hit my car).



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Sep 2019		18 Sep 2019 15:25 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by Insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	SIANG HOCK CAR ENTAL PTE LTD								
Vehicle Reg. No.:	GBA9117J	Date of Loss: 30/08/2019 21:00 - :59 [137 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / SNM19D204135C02	Policy/Cover Note No.: DMCVSN300738191111							
Vehicle Reg. No. (Insured):	YM7775L	Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park, 408934 Ubi - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 27/09/2019]								
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GBA9117J (SNM19D204135C02)  
[YM7775L]

TP










SIANG HOCK CAR ENTAL PTE LTD

Aug 30 2019 9:00PM

[-]

My Car Consultant Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View <span>View in Browser</span>	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/09/19 14:27	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
2	20/09/19 14:27	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
3	20/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
4	20/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
5	20/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
6	20/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
7	20/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
8	20/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
9	20/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
10	20/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
11	20/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
12	20/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
13	20/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
14	20/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
15	20/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
16	20/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
17	20/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
18	20/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
19	20/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
20	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
21	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
22	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
23	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
24	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
25	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
26	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
27	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
28	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
29	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
30	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
31	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
32	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
33	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
34	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
35	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
36	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
37	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
38	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
39	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
40	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
41	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
42	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>
43	20/09/19 14:29	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	20/09/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
45	20/09/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
46	20/09/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
47	20/09/19 14:31	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
48	20/09/19 14:31	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
49	20/09/19 14:31	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
50	20/09/19 14:31	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
51	20/09/19 14:31	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
52	20/09/19 14:31	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19016500/HCF3E2

Date: 09/10/2019

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN300738191111		
Claimant Vehicle No :	GBA9117J	Insured Vehicle No :	YM7775L		
Date of Loss:	30/08/2019	Nature of Claim:	TP	Claim No:	SNM19D204135C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBA9117J</b>		Engine No:	4D56UCAK2590
Make & Model:	MITSUBISHI L200, 2.5 D Double Cabin (A)		Chassis No:	MMBJRKB407D059778
Reg. Date:	18/03/2008 (Man. Year: 2006)		Odometer:	173060 km
Colour:	Red			
Engine Capacity:	2477 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/75 R16	Rear Tyre Size:	245/70 R16
Front Left Side:	Radial 5 mm	Rear Left Side:	VITOUR 5 mm
Front Right Side:	Radial 5 mm	Rear Right Side:	VITOUR 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	18/09/2019	
Date Inspected:	18/09/2019 Inspected At:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	3.0 days	

Adjuster: LEE HOCK ANN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,700.00 - \$3,700.00

## REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 09 Oct 2019)	
Parts:	N/A	MITSUBISHI L200 2.5 D Double Cabin (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA9117J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >