

ACCORD AUTO SERVICES PTE.LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AIG

Date : 16.09.2019
Vehicle No : SLP 4975 J
Veh Make/Model : Mazda 3
YOM : 2017
Chassis No : JM6BN22A8H0158804
Date of Accident : 16.09.2019

Not Notarized
Returning B4 pain
1/10/19 82150/h ✓ 4 dots
1/10/19 11am

No	Qty	Description	Amount \$
		List Items:-	
1	1	Front bumper <i>Bu. ✓</i>	866.80
2	1 set	Front bumper clips <i>bu ✓</i>	35.00
3	2/	Front bumper side retainer <i>olser 4 @ 29.70</i>	59.40
4	1	Front RH Grille Chrome <i>7</i>	191.70
5	1 set	Front bumper foglamp cover RH <i>bu x</i>	47.30
6	1	Front bumper foglamp RH <i>bu x</i>	147.00
7	1	Front fender RH <i>Bu ✓</i>	350.60
8	1	Front fender shield RH <i>bu x</i>	101.90
9	1	Front fender shield clips <i>bu x</i>	35.00
10	1	Front grille base <i>7</i>	135.50
11	1	Front headlamp RH <i>Bu ✓</i>	1070.50
12	1	Front headlamp top panel <i>12 x</i>	-
13	1	Front headlamp lower bracket <i>12</i>	-
14	1	Front bumper top (Radiator top) upper bumper <i>bu</i>	355.40
15	1		\$ -
16	1		\$ -
17	1		\$ -
18	1		\$ -
19	1		\$ -
20	1		\$ -
21	1		\$ -
22	1		\$ -
23	1		\$ -
24	1		\$ -
25	1		\$ -
26	1		\$ -
27	1		\$ -
28	1		\$ -
29	1		\$ -
30	1		\$ -
Total - List Item			\$ 3396.10
20 Less 10%			\$ 679.22
Total			\$ 2716.88

2352.60
20 470.52
1882.08
UB 850
2732.08 - LS \$2150

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AIG

Date : 16.09.2019
Vehicle No : SLP 4975 J
Veh Make/Model : Mazda 3
YOM : 2017
Chassis No : JM6BN22A8H0158804
Date of Accident : 16.09.2019

[illegible]

40d
400l
30l
20l
x

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: