

72AG/3042

ASS. REC. BY:

REF:

CS/CTI19016584/Kg d3er

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CTI

Date/Time:

18/1/1905.09pm

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 6606M

Insured:

GG9000X

at Workshop in/s

Lim Yew Boo Spray

Tel:

9685 2332

of

Blk 10 Sin Ming Ind. Est #01-10

Policy No:

MNCVSN30621719033

Claim No:

SNM190204375602

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/1/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.30am @ 1/1/19

Person Contacted:

Serene

Vehicle: IN/OD

Date/Time

Action/Instruction

Estimate ✓

SLK6606M - X

GG9000X = CGS A1911003047 / Kg d3er

DOA: 15/2/2011

06/11/19 @

4.58pm Serene informed that the TP already convert to OD claim.
Submit Prelim. report.

ASS. REC. BY:

REF: C121

Kenneth

ASSIGNMENT

LK 6606

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop mv's _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKL 6606 M Yr Regn: 01, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Jazz c.c. 1498

Colour: M. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 38423 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHM GK 585014 X 201075

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / Rim or

Tyre Size: F: 185/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 14/9/19

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 30/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

RECEIVED 18 NOV 2019

Date/Time, File Pass to?



Prell. Report

1) 18/11/19



Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee: _____

Transportation: _____

S + RS. \$

Fines

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

220

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 18 September 2019 5:09 PM
To: serene@autocare.com.sg
Cc: assignments
Subject: RE: OUR REF: SNM19D204375-GG9000X-CBS - SLK6606M & GG9000X ALONG CLEMENTI AVENUE 2 TO COMMONWEALTH ON 14/9/2019

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis. Please merimen.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Wednesday, September 18, 2019 4:11 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; serene@autocare.com.sg

Subject: OUR REF: SNM19D204375-GG9000X-CBS - SLK6606M & GG9000X ALONG CLEMENTI AVENUE 2 TO COMMONWEALTH ON 14/9/2019

Dear Boon Sen,

Please conduct PRS for SLK6606M.

Note : officer in charge – Boon Sen

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Serene LIM [<mailto:serene@autocare.com.sg>]
Sent: Wednesday, 18 September, 2019 12:37 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: SLK6606M & GG9000X ALONG CLEMENTI AVENUE 2 TO COMMONWEALTH ON 14/9/2019

To : Motor Claims Dept (Arrangement of Surveyor Unit)

**RE: NOTICE TO THIRD PARTY INSURERS TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKINGS DAY PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIN-INJURY MOTOR ACCIDENT CLAIMS (NIMA)
ACCIDENT INVOLVING SLK6606M & GG9000X ALONG CLEMENTI AVENUE 2 TO COMMONWEALTH ON 14/9/2019**

We are the repairer for Mr Clive Heng Boon Howe the owner of vehicle no. SLK6606M

Please be informed that the said vehicle can be inspected at the following venue:

Lim Yew Boo Spray Paint Co
Blk 10 Sin Ming Industrial Estate #01-10 Singapore 575645
Tel: 64534177 Fax: 64593724 Email: serene@autocare.com.sg

Contact Person: Serene Lim Hp : +65 96852332

Please also provide us a list of 10 surveyors as your nominated SJE (Single Joint Expert)

I/ We enclosed herewith a copy of our client **SAS Statement** for your reference. Looking forward to your kind assistance and co-operative in this matter.

Please note that if you fail to conduct the pre-repair inspection within the next 2 days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you

Regards
Serene LIM
Lim Yew Boo Spray Paint Co
Direct : +65 64545011
Mobile : +65 96852332

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

LIM YEW BOO SPRAY PAINT CO.

(For Kenneth)

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
 3 ANSON ROAD #16-00
 SPRINGLEAF TOWER SINGAPORE 079909

Estimate : OD19/044

Attention : Motor Claim Department
 Contact : 63896111 Fax No. : 62221033

*Not Authorised
 Running BY PAINT
 4 days*

Date : 26/09/2019
 Vehicle Num. : SLK 6606M
 Make/Model : HONDA JAZZ-2017
 Chassis/Eng# : JHMGK5850HX201075/L15B31190751
 Accident Date : 14/09/2019
 Claim No. :
 Reference : LYB/SLK6606M/GE/od/sl
 Policy No. : 2019-V0099930-VDP-R002

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	NETT ITEMS :		
2.	1	FRONT BUMPER		
3.	2	FRONT BUMPER RETAINER		
4.	1	FRONT BUMPER CLIPS		
5.	1	FRONT HEADLAMP ASSY/LH		
6.	1	FRONT HEADLAMP LOWER BRACKET/LH		
7.	1	FRONT FENDER/RH		
8.	1 SET	FRONT FENDER INNER SHIELD/LH		
9.	1	FRONT FENDER INNER SHIELD CLIPS		
10.	1	FRONT FENDER ¼ GLASS/LH		
11.	1	FRONT GRILLE		
12.	1	FRONT GRILLE EMBLEM		
		FRONT GRILLE CLIPS		

CM	594.70	—
CM	14.70	—
5.00	10.00	—
1,036.70	—	—
38.00	—	—
425.00	—	—
81.50	—	—
12.00	—	—
281.60	—	—
294.70	—	—
54.70	—	—
3.50	—	—

Nett Total S\$:

2,847.10

1.	1	SPECIAL NETT ITEMS :		
		¼ GLASS SEALANT		

60.00 ?

Special Nett Total S\$:

60.00

LABOUR :

TO FOCUS HEADLAMP

30.00 } 20%

TO CHECK WIRING FUNCTIONS

60.00 }

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Damaged parts must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer:
 Signature:
 Date:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
 3 ANSON ROAD #16-00
 SPRINGLEAF TOWER SINGAPORE 079909

Attention : Motor Claim Department
 Contact : 63896111 Fax No. : 62221033

Estimate : OD19/044

Date : 26/09/2019
 Vehicle Num. : SLK 6606M
 Make/Model : HONDA JAZZ-2017
 Chassis/Eng# : JHMGK5850HX201075/L15B31190751
 Accident Date : 14/09/2019
 Claim No. :
 Reference : LYB/SLK6606M/GE/od/si
 Policy No. : 2019-V0099930-VDP-R002

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO REPAIR & SPRAY RIM	nn	120.00 X
		TO COMPUTERISE WHEEL ALIGNMENT	nn	120.00 X
		LABOUR TO REPLACE & REPLACE THE ¼ GLASS IN ORDER TO FACILATE REPLACEMENT OF LEFT FRT FENDER		120.00 7
		TO REPAIR, PANEL BEAT, RE-ALIGN ON FRT BONNET, LEFT AFFECTED DOOR & LABOUR TO REPLACE THE ABOVE PARTS	400l	800.00
		TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS	30l	120.00
		TO PUTTY, PRIMER & SPRAY PAINT ON LEFT FRT FENDER, DOOR, TOUCH UP ON FRT BONNET USING 2K PAINT	400l	800.00
		Labour Total S\$:		2,170.00

E. & O.E.

Total S\$: 5,077.10

=====



for LIM YEW BOO SPRAY PAINT CO.

MSNH19122789 / S & H Motor Pte Ltd - Sin Ming
 ENTRY DATE & TIME: 16/09/2019 16:51
 SUBMITTED BY: Wong Kee Nyuk

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/09/2019 16:51
Date Of Accident	14/09/2019 13:30
Exact Location Of Accident	CLEMENTI AVE 2 TO COMMONWEALTH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK6606M
Insured/Policyholder	
Name Of Registered Owner	CLIVE HENG BOON HOWE
NRIC No	S0527870H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96852332
Alternative Phone No	OFFICE-96852332

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2019-V0099930-VDP-R002
Cover Note Number	

Driver

Name of Driver	LOW SIEW TECK
NRIC No	S1046758F
Date Of Birth	18/02/1942
Occupation	INDOOR
Date Of Driving Pass	21/02/1984
Driving Experience	35 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96852332
Fax Number	
Contact Number	OFFICE-96852332
Email Address	NOEMAIL

Address -
 Postcode -
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured -
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : WIFE
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

refer attached report.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GG9000K
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on Saturday 14/09/19 travelling on Avenue 2 turning towards Corner South West.
 After I have already made my turn is indicated in the traffic light at about 1.30pm.
 Suddenly from behind my car the pick-up Toyota 666000K ran forward my car and hit it.
 on the left side near the front door thus damaging it.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Nov 2019		18 Nov 2019 10:21 Edit Adj Rpt	S\$3,377.50 Edit Estimates	S\$3,377.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	-, Co. Reg. No.: 0	
Main Claimant:	CLIVE HENG BOON HOWE, ID: S0527870H	
Vehicle Reg. No.:	SLK6606M	Date of Loss: 14/09/2019 13:00 - :59 [31 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D204375C02	Policy/Cover Note No.: DMCVSN30621719033
Vehicle Reg. No. (Insured):	GG9000X	Policy No. (Claimant): 2019-V0099930-VDP-R002
		Excess: S\$0.00
Repairer:	Lim Yew Boo Spray Paint Co (HQ) NO. 176 SIN MING DRIVE #03-05, SIN MING IND EST, 575645 Sin Ming - Tel: 64534177	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]	
Claimant's Insurer:	Great Eastern General Insurance Limited (HQ) - Tel: +65 248 2888	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 27/11/2019]	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SLK6606M (SNM19D204375C02)
[GG9000X]

TP

CLIVE HENG BOON HOWE

Sep 14 2019 1:00PM

[-]

Lim Yew Boo Spray Paint Co

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	16/09/19 17:04	Accident Statement		Load HTM	
2	25/09/19 16:46	Addendum Sheet		Load TIF	
3	25/09/19 16:49	Accident Statement Addm. #1		Load HTM	

Photos/Images

3 per page

No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	16/09/19 16:58	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	16/09/19 16:58	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	16/09/19 16:58	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	16/09/19 16:58	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	16/09/19 16:58	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	16/09/19 16:58	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	16/09/19 16:58	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>


No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/11/19 12:04	General View		Load JPG	<input checked="" type="checkbox"/>
2	18/11/19 12:04	General View		Load JPG	<input checked="" type="checkbox"/>
3	18/11/19 12:04	General View		Load JPG	<input checked="" type="checkbox"/>
4	18/11/19 12:04	General View		Load JPG	<input checked="" type="checkbox"/>
5	18/11/19 12:04	General View		Load JPG	<input checked="" type="checkbox"/>
6	18/11/19 12:04	General View		Load JPG	<input checked="" type="checkbox"/>
7	18/11/19 12:04	General View		Load JPG	<input checked="" type="checkbox"/>
8	18/11/19 12:04	General View		Load JPG	<input checked="" type="checkbox"/>
9	18/11/19 12:04	General View		Load JPG	<input checked="" type="checkbox"/>
10	18/11/19 12:04	General View		Load JPG	<input checked="" type="checkbox"/>
11	18/11/19 12:04	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
12	18/11/19 12:04	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
13	18/11/19 12:04	General View		Load JPG	<input checked="" type="checkbox"/>
14	18/11/19 12:04	General View		Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page

No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	16/09/19 16:59	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	16/09/19 16:59	Sketch Plan #2 [Linked Accident Report Documents]		Load TIF	
3	16/09/19 16:59	Identification Card [Linked Accident Report Documents]		Load TIF	

Linked Accident Report Documents

					View	View in Browser	
Assessment Reports					1 per page		<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)			Thumbnail	Print	
1	16/09/19 17:04	Accident Statement			 Load HTM		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
2	25/09/19 16:46	Addendum Sheet	Load TIF	<input type="checkbox"/>
3	25/09/19 16:49	Accident Statement Addm. #1	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	16/09/19 16:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	16/09/19 16:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	16/09/19 16:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	16/09/19 16:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	16/09/19 16:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	16/09/19 16:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	16/09/19 16:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	16/09/19 16:59	Sketch Plan	Load TIF	<input type="checkbox"/>
2	16/09/19 16:59	Sketch Plan #2	Load TIF	<input type="checkbox"/>
3	16/09/19 16:59	Identification Card	Load TIF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19016584/KQD3E2

Date: 29/11/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30621719033

Claimant
Vehicle No : SLK6606MInsured
Vehicle No : GG9000X

Date of Loss: 14/09/2019

Nature of Claim: TP

Claim
No: SNM19D204375C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK6606M

Make & Model: HONDA JAZZ, 1.5 (A)

Engine No: L15B31190751

Reg. Date: 23/01/2017 (Man. Year: 2016)

Chassis No: JHMGK5850HX201075

Colour: Metallic Blue

Odometer: 38423 km

Engine Capacity: 1498 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R16

Rear Tyre Size: 185/55 R16

Front Left Side: Yokohama 7 mm

Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm

Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,907.10	2,527.50	379.60	13.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,170.00	850.00	1,320.00	60.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,077.10	3,377.50	1,699.60	33.48

INSPECTION

Date of Assignment: 18/11/2019

Date Inspected: 30/09/2019 Inspected At:

Lim Yew Boo Spray Paint Co (HQ)
NO. 176 SIN MING DRIVE #03-05,
SIN MING IND EST
Singapore 575645

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S\$499.60 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Nov 2019)
Parts:	144	HONDA JAZZ 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK6606M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	594.70 F	*594.70 F
2	1		*FRONT BUMPER RETAINER	Cracked	14.70 F	*14.70 F
3	2		*FRONT BUMPER CLIPS	Necessary	10.00 F	*10.00 F
4	1		*FRONT HEADLAMP ASSY/LH	Cut	1,036.70 F	*1,036.70 F
5	1		*FRONT HEADLAMP LOWER BRACKET/LH	*Check	38.00 F	*- F
6	1		*FRONT FENDER/RH	Bent	425.00 F	*425.00 F
7	1		*FRONT FENDER INNER SHIELD/LH	Distorted	81.50 F	*81.50 F
8	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	12.00 F	*12.00 F
9	1		*FRONT FENDER 1/4 GLASS LH	*Check	281.60 F	*- F
10	1		*FRONT GRILLE	Mtg Cracked	294.70 F	*294.70 F
11	1		*FRONT GRILLE EMBLEM	Necessary	54.70 F	*54.70 F
12	1		*FRONT GRILLE CLIPS	Necessary	3.50 F	*3.50 F
13	1		*1/4 GLASS SEALANT	*Check	60.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					2,907.10	2,527.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO FOCUS HEADLAMP.}	New	30.00	20.00
2	TO CHECK WIRING FUNCTIONS.}	New	60.00	0.00
3	TO REPAIR & SPRAY RIM.	New	120.00	0.00
4	TO COMPUTERISE WHEEL ALIGNMENT.	New	120.00	0.00
5	TO REPAIR, PANEL BEAT, RE-ALIGN ON FRT BONNET, LEFT AFFECTED DOOR & LABOUR TO REPLACE THE ABOVE PARTS.	New	800.00	400.00
6	TO APPLY RUST-PROOFING ON REPAIRED/REPLACED PANELS.	New	120.00	30.00
7	TO PUTTY, PRIMER & SPRAY PAINT ON LEFT FRT FENDER, DOOR, TOUCH UP ON FRT BONNET USING 2K PAINT.	New	800.00	400.00
8	LABOUR TO REPLACE & REPLACE THE 1/4 GLASS IN ORDER TO FACILATE REPLACEMENT OF LEFT FRT FENDER (*Check)	New	120.00	0.00
Gross Labour Cost (S\$)			2,170.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >