ASS. REC. BY	PC19016586/Gfd30 pecial Enteroction: OF
Saverial - (100000)	SIGNMENT (Office) PC Dute/Time: 18/01/1905526
OD OF WS/TP RES/OD RES/EVA/INV	Bill to:
To Inspect Vehicle No:	1) 8830Y Insured: SJP 3467P
Policy No:	Claim No: 19/19/19/VP09/012392
Sum Insured:	Excess:
Make of Veh;(Client's Record)	D.O.A. 17/9/2019
CA / REV / REP. / REV 24 HRS Date/Time: 10.4 CM D 19 19 Person Co	ontacted: Sew Hoor Vehicle IN OUT
Date/Time Action/Instruction Shand	
SD 8430X -×	
8) p 3-167 p- cs/Lp	19016539/Gyf3 DUA: 19/012019
12 00	
	8 8

把節

Sinveyor al. REF: De	•		
Autredon Contraction	ASSIGNMENT	(-2028
From: Date:	Veh No: \$118830 Y	Yr Regn: 6 Ag	200
From: Date:	Type: M.Car / M.Cycle / Bus / Van / Lorn		
DD TR/ WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or Type		
	Make: Honda Interv	19 2.0 c.c	1998
To Inspect Vehicle No:	Colour white	A/C: Insured / St	
at Workshop m/s Lye Designs	Sp.Reading —	T/Radio: Insured / S	td / NI / NA
f	Eng/No:		
nsured:	C/No: DC 52306	302.	
Policy No.	Gen. Cond: Good / Fair / Poor / Burnt		
Claims No.	Steering: Inorder / Jammed / Leaked / E	Burnt or	
Sum Insured: Excess:	Brake: Infider / Jammed / Leaked / E		
(Client's Record)	Modi: Nil / S/Rim / STD A/Rim or		
Make of Veh:		45 R17	
	lyre size. F. (DCS)	42 1.1	
(Policy Condition) Remark: The year had commenced its N/S	O/S BS / DUN/ EXNOVA / GY / FS / LIZA / I	MIC / OUTSII / PIP / S	SUMI/
Remark: The veh had commenced its N/S repair at the time of inspection.	TOYO / YOKO or	MIC / OH I SO / FIX / S	JOHII /
repair at the time of inspection.	9 —	Page	
Bal. or Market Value:	Front R/Bal. 6- mm	Rear R/Bal.	mr
IDAC Accident Rport: Consistent? : Yes or No	- P - · · · · · · · · · · · · · · · · ·	L/Bal.	
GIA / PR Seen: Consistent? : Yes or No	L/Bal mm	D.O.I. 19-0	9 10
Est. Repairs: days Res.: Yes or No	D.O.A. Survey held at	1/20	1-1
Lum Sum: 20 % _ 3 Val.: Yes or No			4pm
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rea / 1 O/S /	N/S / U/C / ROOM	b or a
Date: Person Contacted:	The U/C / Chassis frame / Body	Structure affected di	ue to collisio
Date / Time Action / Instruction		Ottactare unocide a	
Cot : 30094			
1/10	11/ 6. 1		
1017 Finalize \$670	go with Silw Ho	oon	
(fed: 8651-20; 56%)		*	
	RECEIVED		
	RECEIVED 2 / SEP 2019		
Date/Time, File Pass to? : Preli. Report	Days Of Repair:		
1)28 9 What Final Report	Resurvey No. of Trip:	Survey Fee:	390
Date/Time, File Return to?		Transportation:	
2)A	dd Fee: Site Insp (\$)S + RS,SI	
70	: Interview (\$) Photos	
Report Format :	: Tech. Invs (\$	Others	
Lump Sum / I.B.I: (\$ 6700 -)	: Weekend (\$)	
		TOTAL	209

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC			
Owner ID:	105J			
Vehicle No.:	SJJ8830Y			
Vehicle to be Exported:	No			
Intended Deregistration Date:	19 Sep 2019			
Vehicle Make:	HONDA			
Vehicle Model:	INTEGRA TYPE-R 2.0 M			
Primary Colour:	White			
Manufacturing Year:	2006			
Engine No.:	K20A3673550			
Chassis No.:	DC52306302			
Maximum Power Output:	162.0 kW (217 bhp)			
Open Market Value:	\$21,038.00			
Original Registration Date:	19 Sep 2006			
First Registration Date:	26 Sep 2008			
Transfer Count:	4			
Actual ARF Paid:	\$21,038.00			
PARF Eligibility:	Forfeited			
PARF Eligibility Expiry Date:				
PARF Rebate Amount:	\$0.00			
COE Expiry Date:	25 Sep 2028			
COE Category:	E - Open Category			
COE Period(Years):	10			
PQP Paid:	\$33,377.00			
COE Rebate Amount:	\$30,094.00			
Total Rebate Amount:	\$30,094.00			

The information contained herein is correct as at 19 Sep 2019

ОК

SGCARMART.COM THE ONLY PLACE FOR SMART CAR BUYERS

Integra Used Vehicle List (8 vehicles)

Availability Mileage Company Car Model Price Depreciation Reg Date Eng Cap 18-Jul-2006 1,998 cc NC Auto Available Honda Integra Type R 2.0M \$77,000 \$11,350 /yr (COE till 06/2026)

Well Taken Care And Maintain By Owner. Nicely Done Up The Most Powerful And Best Handling Of The Integra Type R. Don't Miss Out This Beauty, Call Now For Viewing And Test Drive, Trade In And Loan Avai...

Lincoln - 98346868 | Nick - 97484664

Available 175,700 km Honda Integra 2.0M (COE till \$68,800 \$10,520 /yr 04-Apr-2006 1,998 cc 04/2026)

Well Maintained Car To Continue Driving For The Balance Of COE Term.

Office No. - -

Eric - 98586056

12-Jul-2006 1.998 cc Monster Motors Pte Ltd Available Honda Integra 2.0M GSR \$51,800 \$7,730 /vr (COE till 05/2026)

Well Maintain By Owner. Loan And Trade In Available. Viewings Strictly By Appointment Only.

Office No. - -

Edwin - 94999696 | Calvin - 90673002

Speed7 Available Honda Integra 2.0A (COE till \$23,500 \$11,880 /yr 11-Sep-2006 1,998 cc 09/2021)

Wedsport Tc105 17" Rims, Bc Racing Coilovers. Hardrace Rear Camber Kit. Summit Front/rear Strut. Ultra Racing Room Bar. Greddy 6 Pot BBK. 330mm Ventilated Slotted Rotors. Custom Steel Braided Hoses.Mu...

Zen Ang - 98451005 | Pamela Goh - 98411005

Available Honda Integra 2.0M (COE till \$20,388 \$10,930 /yr 03-Aug-2006 1,998 cc 07/2021)

A Rare Gem And Reluctant Sale. Great For Short Term Drive And Able To Handover Immediately. Not To Worry About Buying An Old Car As The Car Needs To Be Send To Workshop Due To Breakdown, I Have Done M ...

Office No. - -

Brandy - 96162802

\$11,200 /yr 24-Mar-2006 1,998 cc 103,669 km Imperium Car Motor Pte Available Honda Integra 2.0A (COE till \$16,900

Very Well Maintained, Fully Stock, Road Tax Paid Till 23 Mar 2020, 100% No Repair Needed, Original Paintwork, Trade In Welcome, Kindly Contact Our Sales Advisor For Viewing.

Office No. - 65572663

Melvin Teo - 87870008 | Eugene Lim - 92725924

Available Honda Integra 2.0A (COE till \$14,888 \$10,610 /yr 13-Feb-2006 1,998 cc 02/2021)

Our Dream Car Since Young. If You Have Dreamt About It, Don't Hesitate, It Can Be Yours Right Now. Reluctant Sale By Direct Owner. Revive The Teenage Spirit In You!

Office No. - -

Chong Chwen Jiun - 87888687

Available Honda Integra 2.0A (COE till \$13,288 \$9,050 /yr 09-Mar-2006 1,998 cc 117,000 km 03/2021)

Agent Serviced Since Day 1. Last Service Done Recently With New Parts Replaced. Stock Condition Throughout Which Means Worry Free Drive. Great Shape For Its Age Apart From Some Dings On Paintwork Whic...

Office No. - -

Ed - 96395335

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

Denise Tay (LKKAuto)

From: ONG LI LI < llong@lonpac.com>

Sent: Tuesday, 15 October 2019 11:07 AM

To: Denise Tay (LKKAuto)

Cc: MT_Claim_SG

Subject: RE: PRE-REPAIR SURVEY --- YOUR REF: SJP 3467 P --- ACCIDENT INVOLVING SJJ

8830 Y AND SJP 3467 P ON 17 SEPTEMBER 2019 ALONG TOH GUAN ROAD AT

ABOUT 1855 HOURS Our Ref: TBA

Dear Denise

Our Claim ref: 19/19/19/VP05/022392

Regards, Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd 300 Beach Road #17-04/07 The Concourse

Singapore 199555

Tel: (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]

Sent: Tuesday, 15 October 2019 10:30 AM

To: ONG LI LI Cc: MT Claim SG

Subject: RE: PRE-REPAIR SURVEY --- YOUR REF: SJP 3467 P --- ACCIDENT INVOLVING SJJ 8830 Y AND SJP 3467 P ON

17 SEPTEMBER 2019 ALONG TOH GUAN ROAD AT ABOUT 1855 HOURS Our Ref: TBA

Dear Lili,

Can provide your ref no.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)

Sent: Monday, 14 October 2019 9:04 AM To: 'ONG LI LI' < llong@lonpac.com>

Cc: mt_claim@lonpac.com

Subject: RE: PRE-REPAIR SURVEY --- YOUR REF: SJP 3467 P --- ACCIDENT INVOLVING SJJ 8830 Y AND SJP 3467 P ON

17 SEPTEMBER 2019 ALONG TOH GUAN ROAD AT ABOUT 1855 HOURS Our Ref: TBA

Dear Lili,

Can provide your ref no.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Wednesday, 18 September 2019 5:52 PM

To: Elaine Toh < Elainetoh@visionlawllc.com >; MT_Claim_SG < mt_claim@lonpac.com >; assignments@lkkauto.com;

admin-d@lkkauto.com

Subject: RE: PRE-REPAIR SURVEY --- YOUR REF: SJP 3467 P --- ACCIDENT INVOLVING SJJ 8830 Y AND SJP 3467 P ON

17 SEPTEMBER 2019 ALONG TOH GUAN ROAD AT ABOUT 1855 HOURS Our Ref: TBA

Without Prejudice

Dear Elaine


We shall appoint LKK Auto Consultants Pte Ltd to conduct the survey. We note that you have breached the NIMA protocol by not providing a list of at least 10 surveyors.

Dear Nivitha

FYA

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555

Tel: (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Elaine Toh [mailto:Elainetoh@visionlawllc.com]
Sent: Wednesday, 18 September 2019 5:19 PM

To: ONG LI LI; MT Claim SG

Subject: RE: PRE-REPAIR SURVEY --- YOUR REF: SJP 3467 P --- ACCIDENT INVOLVING SJJ 8830 Y AND SJP 3467 P ON

17 SEPTEMBER 2019 ALONG TOH GUAN ROAD AT ABOUT 1855 HOURS Our Ref: TBA

Importance: High

Our Ref: SJJ 8830 Y (et) WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to your email of even date informing that you wish to conduct a pre-repair survey and to your List of Surveyors.

TAKE NOTICE that we are instructed to object to all your surveyors stated in your said List for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose <u>FormTeam Consultancy Pte Ltd</u> as Single Joint Expert for your consideration:

Please be informed that the said vehicle can be inspected at:

Venue:

Lye Designs

10 Ang Mo Kio Industrial Park 2A

#04-04 AMK Autopoint Singapore 568047

Contact:

Siew Hoon @ 64833353 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

FOR SURVEYOR

Please initial here after completion of pre-repair inspection.

Thank you.

Appointed surveyor (Name & Signature)

Date & Time of Inspection :

Regards,

Elaine Toh (Secretary)

Vision Law LLC

Tel: 65342811 (Ext. 122)

Fax: 65356802

SJJ 8830 Y - By fax: 64842457 only

This email has been checked for viruses by AVG antivirus software. www.avg.com

Nivitha (LKK Auto)

From:

ONG LI LI < llong@lonpac.com>

Sent:

Wednesday, 18 September 2019 5:52 PM

To: Subject: Elaine Toh; MT_Claim_SG; assignments@lkkauto.com; admin-d@lkkauto.com RE: PRE-REPAIR SURVEY --- YOUR REF: SJP 3467 P --- ACCIDENT INVOLVING SJJ

8830 Y AND SJP 3467 P ON 17 SEPTEMBER 2019 ALONG TOH GUAN ROAD AT

ABOUT 1855 HOURS Our Ref: TBA

Attachments:

20190918172625.pdf

Without Prejudice

Dear Elaine

We shall appoint LKK Auto Consultants Pte Ltd to conduct the survey. We note that you have breached the NIMA protocol by not providing a list of at least 10 surveyors.


Dear Nivitha

FYA

Regards, Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd 300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel: (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Elaine Toh [mailto:Elainetoh@visionlawllc.com]

Sent: Wednesday, 18 September 2019 5:19 PM

To: ONG LI LI; MT_Claim_SG

Subject: RE: PRE-REPAIR SURVEY --- YOUR REF: SJP 3467 P --- ACCIDENT INVOLVING SJJ 8830 Y AND SJP 3467 P ON

17 SEPTEMBER 2019 ALONG TOH GUAN ROAD AT ABOUT 1855 HOURS Our Ref: TBA

Importance: High

Our Ref: SJJ 8830 Y (et) WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to your email of even date informing that you wish to conduct a pre-repair survey and to your List of Surveyors.

TAKE NOTICE that we are instructed to object to all your surveyors stated in your said List for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose <u>FormTeam Consultancy Pte Ltd</u> as Single Joint Expert for your consideration:

Please be informed that the said vehicle can be inspected at:

Venue:

Lye Designs

10 Ang Mo Kio Industrial Park 2A

#04-04 AMK Autopoint Singapore 568047

Contact:

Siew Hoon @ 64833353 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

FOR SURVEYOR

Please initial here after completion of pre-repair inspection.

Thank you.

Appointed surveyor (Name & Signature)

Date & Time of Inspection :

Regards,

Elaine Toh (Secretary)

Vision Law LLC

Tel: 65342811 (Ext. 122)

Fax: 65356802

cc:

SJJ 8830 Y - By fax: 64842457 only



ESTIMATE

Date:

19 Sep 2019

To:

Owner:

Lim Thian Kwui

Vehicle Reg. No.: Make/Model:

SJJ8830Y Honda Integra DC52306302

Chasis No. Year Mfg

2006

Shops report.
After report photos.
Guo arouf

Lift Ame Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- * Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	ESTIMATE COST OF REPAIR TO "HONDA INTEGRA"		
ITEM	" REG. NO. SJJ8830Y"	LINIT DDICE	AMOUNT
ITEM	DESCRIPTION	UNIT PRICE	AMOUN
	List Items Rear Boot Cover(Boot Lid)		
	Real Boot Cover(Boot Eld)		
	Rear Boot Cover Trim		
	Rear Boot Spoiler X (1971 - Rear Boot Lock(Upper) / 1971 -		
- 0.00	Rear Boot Lock(Lower)		
	Rear Boot Brake Light 7		
the state of the s	Rear Boot Hinge X		
	Rear Boot Stopper X Rear Boot Weatherstrip		
5,741.51	, and Door Wooding of		
1pc	Rear Boot Emblem "Integra"		
1pc	Rear Boot Emblem Logo (Red colour) 'H'		
ipc	Rear Boot Emblem Typer R		
	Rear End Panel / Buc.		
2 pcs	Rear End Panel Cover(small piece)- LHR, RHR 💢		
1pc	Rear End Panel Top Garnish / Pl		
? pcs	Rear End Panel Top Garnish Clips		
1pc	Rear Spare Tyre Compartment / 149.		
	Rear Bumper / P15		
	Rear Bumper Clips / AC		
2 pcs	Rear Bumper Side Retainer / 25		
	Rear Bumper Lower Center Protector X		
	Rear Bumper Lip X		
	Rear Bumper Sponge X		
1pc	Rear Bumper Reinforcement / GT.		
	Rear Bumper Reinforcement Bracket		
	Rear Bumper Bracket X 31		
	Rear Bumper Number Plate Bracket		
	Taillamp: LHR and RHR AA.		
	Taillamp Brackets: LHR and RHR / 81		
	Taillamp Clips		
	Rear Exhaust		
	Rear Exhaust Mounting		
	1.0 %		
- 17	Rear Fender Inner Trim: RHR, LHR ' 79 CP/		
2 pcs	Rear Fender Side Air Duct : RHR, LHR		
	,		0.
	Less 20%		0.
	Total List Items		0.
	2		
	Special Nett Items		(A)
	Reverse Sensor X		280
1set	Rear No Plate		80.
	Total Special Nett Items		360

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies 4. The issue and acceptance
- Any false reporting may be referred to the Police for investigation.
- ient Centru established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

ACCIL	U = IV	_ # # (~ () (11-42

Date Of Report 18/09/2019 14:38

Date Of Accident 17/09/2019 18:55

Exact Location Of Accident ALONG TOH GUAN ROAD

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

SJJ8830Y Vehicle Registration Number

Insured/Policyholder

Name Of Registered Owner LIM THIAN KWUI

NRIC No S1444105J NOEMAIL Email Address

Mobile Phone No. (LOCAL) +65-83043698 Alternative Phone No OTHERS-83043698

Vehicle Particulars

Manufacturer HONDA

Model INTEGRA TYPE-R 2.0 M

Exact Purpose for which vehicle was being used at PRIVATE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

COMPREHENSIVE Type Of Coverage

Fleet Policy NO

5104326315 Policy Number

Cover Note Number

Driver

Name of Driver CHIA ZI MENG

NRIC No. S9271831Z Date Of Birth 09/03/1992 Occupation INDOOR Date Of Driving Pass 18/02/2011

Driving Experience 8 YEARS AND 6 MONTHS

MALE Gender

Mobile Number (LOCAL) +65-98573239

Fax Number Contact Number

ZIMENG_CHIA@HOTMAIL.COM EMail Address

Address BLK 660 HOUGANG AVENUE 8 #03-479

Postcode

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OTHER - UNCLE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

CLEAR Weather Conditions Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

NO.

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Passenger 1

NAME

ANNA LIM PUI WIN

FEMALE GENDER

Details of Police Action

Was the accident reported to the police?

YES

If Yes Please state which Police Station

Police Station Name

TOA PAYOH NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING.

POSTCODE: 319194 . COUNTRY: SINGAPORE TEL NO: 1800-2519999 - FAX NO: 63548749

Police Station Contact

NO

Was notice of intended Prosecution given?

If Yes against whom?

Circumstances of Accident

REFER TO ATTACHED POLICE REPORT NO. T/20190918/2004. WILL REPAIR AND CLAIM AT LYE DESIGN.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

Remarks/ Reasons:

PASS TO WORKSHOP

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Make/Model/Colour

SJP3467P

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

TEW KIAN HOE

NRIC/Passport Number

S7502317J

Contact Number

86188144

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

CHIA ZI MENG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJJ8830Y

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

NO

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

ANNALIM

Approximate Age

Injunes Sustain

Injured person in which vehicle?

SJJ8830Y

Were seat belts wom?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided most be as <u>truthful</u> and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 5. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ["GIA"] may/are permitted to collect, use, disclose and/or process my personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims:
 - (III) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/faw firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(iii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature

(if driver is not the galicyholder)

Date & Time: | 2

Reporting Centre Personnel's Signature

Hame:

NRIC/FIN No

SKETCH PLAN			
IMM 1			278 x 30 A
= 10	H GUAN ROAD)	J F 3 4 67 P
	OAD EAST ES OF THE ACCIDENT		
Refer to po	he report		
	the period and when	and claim.	
DECLARATION			
	Skulars are true in every respect	(me)	
Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time: 9 7	Reporting Centre Personnel's Signature Name: NBIC/FIN NO.	





Police Station Of Origin Toa Payoh N.P.C 93 Toa Payoh Central #01-02 Toa Payoh Community Building SINGAPORE 319194 Tel No: 1800-2519999 1 of 4 Report No T/20190918/2004

Date/Time Report Made: 18/09/2019 00:28			Vide Report No.	Station Diary No. 8	
nforma	nt's Partic	ulars		10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
	Informant:		Address: APT BLK 660 HOUGANG AV 530660	ENUE 8 #03-479 SINGAPORE	
ID Type / ID No.: NRIC NO / S9271831Z		312	Contact No. Home/Office: Mobile: 98573239		
Nationality: SINGAPORE CITIZEN		EN	Email:		
Sex: Age: Date of Birth: Male 27 09/03/1992		and the second s	Type of Informant: Driver		
Race: Chinese			Language;	Institution / School Name	
Occupation: SUPERVISOR			Driving Licence Information: Class: 3	Date of Expiry	

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 17/09/2019 18:55	Type of Location After Zebra crossing
Location: Along Road t TOH GUAN f		Road Surface		Road Speed Limit
Cléar				
Clear Traffic Flow: One Way		Traffic Control		Traffic Volume

Vehicle No.	Тура	Make	Manel	Colore	Condition	No of Passenger
SJJ8830Y	Car	HONDA	INTEGRA TYPE-R 2.0 M	White	Seriously Damaged	1
SJP3467P	Car	HONDA	STREAM 1.8X A	Silver	Seriously Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





Report No. T/20190918/2004

Police Station Of Origin:

Toa Payoh N.P.C 93 Toa Payoh Central #01-02 Toa Payoh Community Building SINGAPORE 319194 CONTINUATION OF REPORT

Tel No: 1800-2519999

Passenger -						
Name	LIM PUI WIN ANNA			ID No		S9301054Z
Related Vehicle	SJJ8830Y (Car)			Conta	ct No	91073382
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL			Class Drivin Licen Expin	g	Class NIL Date of Expiry NIL
Date Treatment	17/09/2019 Date D			Discharge 17/09/2019		
	ted Medical Leave	05	Degree of	Injury	Sligh	1
Driver .					-	
Namé	CHIA ZI MENG			ID No.		S9271831Z
Related Vehicle	SJJ8830Y (Car)			Contact No.		98573239
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL			Class Drivin Licen Expin	9	Class: 3 Date of Expiry: NIL
Date Treatment	17/09/2019		Date Discharge 17/09		/2019	
No. of Days gran	ted Medical Leave	05		ree of Injury Sligh		
Driver II						are a
Name	TEW KIAN HOE			ID No.		S7502317J
Related Vehicle	SJP3467P (Car)			Contact No.		86188144
Hospital/Clinic	NIL			Class Drivin Licent Expiry	g ce &	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Disch		NIL	
No of Days grant	ed Medical Leave	NIL	Degree of		NIL	

On 17/09/2019 at about 6.56pm, I was driving along Toh Guan Road together with my girlfriend. I gradually stopped my vehicle (SJJ8830Y) as we approached the zebra crossing before turning left into Toh Guan Road East. Out of a sudden, I felt a strong impact from the rear after we passed the zebra crossing. I realized that another vehicle (SJP3467P) had collided into our vehicle. I went out to make a check, and saw that the back portion of my vehicle was badly damaged. I could not drive the vehicle off, as such, we had to activate a tow truck. No ambulance or police called as no one was injured.

A few hours after the accident, my girlfriend and I felt some discomfort on our back, as such we went to Mount Alvernia Hospital to get ourselves checked. We were given 5 days of medical leave each





Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

Report No. T/20190918/2004





4 of 4 Report No. T/20190918/2004

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194 CONTINUATION OF REPORT
Tel No: 1800-2519999

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report, if you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature of Officer Recording The Report: E / Signature Officer Recording The Recording	Signature of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 18/09/2019 00:28
Officer in Charge Of Case TP / AEIT / Sr Staff Sut ONG YONG HOCK Contage Solice Form Authentication Stamp NPISS	Classification Of Case:

Printedice of 200810052138214-10079

The owner and vehicle particulars for Vohicle So. STORAGY as at 0.5 Get 2018 are as follows

- 2 Identification No. Type
- 3 Hamitecanies No.
- 4 Comment Regions
- 5 Vetrole No
- 6 Previous Vehicle No
- 7 Fifective Date of Ownership
- 8. Original Registration Date
- 9. Trust Registration Date
- 1D. Michie Be Tarme
- 11 Voltagle Sollevan
- 12 Attachment
- 13 Allachment
- 14 Alexanders 12
- L5: Vetricle Make
- 16 Vehicle Mosiel
- 17. Very of Manufacture
- IN Printing Colour
- 10 Section Colour
- 20. Pussenher Cons. its
- 11. Chassis/Tenifer Chassis No.
- 222 Propellant
- 23. Inuino Nucretor No.
- 24. Engine Caracity to Power Ramork W.
- 15. Maximum Power Output & Wilshi
- 26. Umbelen Weighnung

DINE CHIASI KWILL

Singueson SRIC

S144-108

SJIBBRANY

US OFFICE S

19 Sep 2006

18 Sept 20038

PART Prevenger Motor Car

Scores at

No. 2 Programment

THE PARTY

IN BUCKULA TYPE ROUND

TOTAL .

D/1616

100 S 12/16 31/15 /

Edinary.

A 70 A 30 T 3 5 T 1 2

15000

1862 0 / 2075

UB

(Panel Beating , Repair, Servicing & General Claim)

10, AMK Autopoint, #04-04 Ang Mo Kio, Ind. Park 2A, Singapore 568047

TEL: 6483 3353 FAX: 6484 2457 Email: Idential@wingnet.com.ag

Reg No. 52806993D

ESTIMATE

Date

19 Sep 2019

To

Owner

Lim Thian Kwui

Vehicle Reg. No. SJJ8830Y

Make/Model

Honda Integra Type R(Spec C)

Chasis No.

DC52306302

Year Mfg

2006

Date of Accident 17 September 2019

ITEM	DESCRIPTION	UNIT PRICE	AMOUNT
	List Items Cala	m1 2	
1pc	Rear Boot Cover(Boot Lid)	975.9	1,100.0
1pc	Rear Boot Cover Trim X (NN)		(275.0
1pc	Rear Boot Spoiler 🐰		775.0
1pc	Rear Boot Lock(Upper) / / B7		318.0
1pc	Rear Boot Lock(Lower)		50.0
1pc	Rear Boot Brake Light X		313.0
	Rear Boot Hinge X 7	88.00	176.0
	Page Page Stanger V	8.50	17.0
1pc	Rear Boot Weatherstrip / Twi	12	165.0
		-10	48.0
1pc	Rear Boot Emblem "Integra" Rear Boot Emblem Logo (Red colour) 'H'	31.9	90.0
1pc	Rear Boot Emblem "Typer R"		85.0
	Rear End Panel / but		575.0
1pc	Rear End Panel Top Garnish		82.0
	Rear End Panel Top Garnish Clips	1100.5,00	30.0
	Rear Spare Tyre Compartment / buc	0019	1365
1pc	Rear Bumper / 013	4551	1,620.0
10 nos	Pear Rumper Clins / KC	30 5.00	50.0
2 pcs	Rear Bumper Side Retainer & R.S.	32.00	64.0
2 pcs	Rear Bumper Lower Center Protector		-
	Rear Bumper Lip		-
1pc	Rear Bumper Sponge a 7	7	
1pc	Rear Bumper Reinforcement / D (.		425.0
2 pcs	Rear Bumper Reinforcement Bracket / BT	40.00	80.0
1pc	Rear Bumper Bracket X 54 MV 2 L		42.0
2 pcs	Taillamp: LHR and RHR / Fig. Cuts 792	495.00	990.0
2 pcs	Taillamp Brackets: LHR and RHR / 67.	143.00	286.0
8 pcs	Taillamp Clips / / C.	5.00	40.0
		42.00	84.0
2 pcs	Rear Fender: RHR, LHR X MCFW8 LL XNN	1,082.00	2,164.0
2 pcs	Rear Fender Inner Trim: RHR, LHR \ 111 LR 352		980.0
2 pcs	Rear Fender Side Air Duct: RHR, LHR	120.00	240.0
-,	Rear Exhaust Mounting Rear Fender: RHR, LHR Rear Fender Inner Trim: RHR, LHR Rear Fender Side Air Duct: RHR, LHR		11,164.0
	63 19.3 Less 200	%	(2,232.8
	Total List Item	is	8,931.2

Lye Designs

Date

19 Sep 2019

To

Owner

Lim Thian Kwui

Vehicle Reg. No. SJJ8830Y

Make/Model

Honda Integra Type R(Spec C)

Chasis No.

DC52306302

Year Mfg

2006

Date of Accident 17 September 2019

ITEM	DESCRIPTION	UNIT PRICE	AMOUNT
	Balance C/F		8,931.20
1set 1 set	Special Nett Items Reverse Sensor Rear Exhaust Rear No Plate Total Special Nett Items	850 40	280.00 2,500.00 80.00 2,860.00
	Labour Charges Tow fee: accident site to workshop To remove, refix windscreen To remove, refix interior upholstery to facilitate repair works To remove, refix rear reverse sensor To refocus, re-wire & check wiring; check computer To putty and re-spray paint of the affected areas To remove and replace the above damaged, knock out dents on affected poladjust and realign the same Total Labour Charges	rtion,	100.00 200.00 30.00 30.00 100.00 1,600.00 1,500.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8405.44 1644320

20%: 6700 9 Days.



10, AMK Autopoint, #04-04 Ang Mo Kio, Ind. Park 2A, Singapore 568047 TEL: 6483 3353 FAX: 6484 2457 Email: Idemail@singnet.com.sg Reg No: 52806993D

ESTIMATE(SUPPLEMENTARY)

Date

24 Sep 2019

To

Owner

Lim Thian Kwui

Vehicle Reg. No. SJJ8830Y

Make/Model

Honda Integra Type R(Spec C)

Chasis No.

DC52306302

Year Mfg

2006

Date of Accident 17 September 2019

ITEM	DESCRIPTION	UNIT PRICE	AMOUNT
	<u>List Items</u>		
1p	Rear Bumper Reinforcement(Aluminium)		700.00
	c Rear Number Plate Bracket		55.00
	c LHR Fender Type R Sticker		125.00
	c RHR Fender Type R Sticker		125.00
. 1	o Taraca dinasi i i jara di ana		1,005.00
	Less 20%		(201.00
	Total List Items	- A	1,206.00

6m° Q. . 25/9/19.

Denise Tay (LKKAuto)

From:

Siew Hoon <siewhoon@lyedesigns.com.sg>

Sent:

Friday, 20 September 2019 3:26 PM

To:

Guo Qiang (LKKAuto)

Cc:

Admin-D (LKKAuto); assignments

Subject:

RE: SJJ8830Y ESTIMATE BILL

Attachments:

SJJ8830Y_Estimate Cost_Amend.pdf

Hi Guo Qiang

Pls use this copy instead of the first 1.

- This is a Honda Integra Type R Spec C
- The Rear Exhaust is Fujitsubo brand which had passed inspection as I have showed you the certification. The pipe is kink. Will take it down and get you to come and assess again next Mon, Tue.

Thank you.

Warm Regards
Siew Hoon
Lye Designs
10 Ang Mo Kio Industrial Park 2A
#04-04 AMK Autopoint
Singapore 568047

T: 6483 3353 F: 6484 2457

E : siewhoon@lyedesigns.com.sg W : www.lyedesigns.com.sg

From: Siew Hoon [mailto:siewhoon@lyedesigns.com.sg]

Sent: Friday, 20 September 2019 3:11 PM

To: 'guoqiang@lkkauto.com'

Cc: 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'

Subject: SJJ8830Y ESTIMATE BILL

Importance: High

Hi Guo Qiang,

Pls find the Estimate Bill for marking and finalisation.

Kindly note that the RHR Fender Inner Trim is broken and has to be replaced.

Thank you.

Warm Regards Siew Hoon

TOWING SERVICES (Specialized in 4WD / Body Kit / F1CARS)

CASH BILL

Blk 263, Bishan Street 22, #04-265, Singapore 570263 H/P: 96751296

	DATE: 18/09/19
M/S:	Tel:
Place from: Coh Guan Kol Kost-along	Pager:
Place from: Toh Guan Rol Eost-along	H/Phone:
Breakdown vehicle no: SJJ38307 Wrecker veh	nicle no: 4M 5505M
Vehicle model: HT Friderica Remarks: Recy dealers	Time: 8:05pm
Remarks: Recy dealdown	\$ 100/
24 Hours - 365 Days, Accident / Emergence	y Towing Services
ssued by: Rece	iver's signature:

Note: Conditions on the use of our towing trucks, truck cranes, etc. Towing of vehicles is at customer's risks. We will not be responsible for any consequences which may arise due to breakage or other unforeseen circumstances.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHS S	12 may 2 1 2 10	Affiliated to Federation Internation	nale Des Experts En Automob	ile .
LON	IPAC INSURANCE	BHD	Ref : CS/LPC19016586/	/Gtd3e2
	BEACH ROAD 04/07 THE CONC	OURSESINGAPORE 199555	Date: 15-10-2019 Code: LPC2	
1.		Policy Particulars	:- THIRD PARTY CLAIM	
	Insured Veh.	SJP 3467P	Veh. Inspected	SJJ 8830Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	19/19/19/VP05/022392	Excess (\$)	0.00
	Assign From	ONG LI LI	Assign Date	18/09/2019
2.	100000	Vehicle Partie	culars & Condition	
	Make & Model	HONDA INTEGRA TYPE-R 2.0 M	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2006
	Chassis No.	DC52306302	Colour	WHITE
	Odometer	8	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.	THE RESERVE	Conditi	ons of Tyres	
		Size	Make	Balance
	R/H Front Tyre	245/45 R17	DUNLOP	6 mm
	L/H Front Tyre	245/45 R17	DUNLOP	6 mm
	R/H Rear Tyre	245/45 R17	DUNLOP	6 mm
	L/H Rear Tyre	245/45 R17	DUNLOP	6 mm
4.		Description	on of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE RE	AR PORTION.	
5.			I Information	
	Accident Date	17/09/2019	Inspection Date	19/09/2019
	Survey held at	LYE DESIGNS		
		10, AMK AUTOPOINT, 04-04 ANG MO KIO IND PARK 2A, SINGAPORE 568047		
5a.		R	emarks	
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W		
5b.	SERVICE SERVICE	Estimate	Days of Repair	Lieby Park Control
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 8830Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT COVER (BOOT LID)	BUCKLED	1,100.00	993.30
1	REAR BOOT COVER TRIM	NOT NECESSARY	275.00	-
1	REAR BOOT SPOILER	NOT NECESSARY	775.00	-
1	REAR BOOT LOCK (UPPER)	BENT	318.00	318.00
1	REAR BOOT LOCK (LOWER)	BENT	50.00	50.00
1	REAR BOOT BRAKE LIGHT	NOT NECESSARY	313.00	-
2	REAR BOOT HINGE @\$88.00	NOT NECESSARY	176.00	-
2	REAR BOOT STOPPER @\$8.50	NOT NECESSARY	17.00	-
1	REAR BOOT WEATHERSTRIP	TWISTED	165.00	121.00
1	REAR BOOT EMBLEM "INTEGRA"	NECESSARY	48.00	48.00
1	REAR BOOT EMBLEM LOGO (REAR COLOUR) 'H'	NECESSARY	90.00	31.90
	REAR BOOT EMBLEM "TYPER R"	NECESSARY	85.00	85.00
1	REAR END PANEL	BUCKLED	575.00	575.00
1	REAR END PANEL TOP GARNISH	DEFORMED	82.00	82.00
6	REAR END PANEL TOP GARNISH CLIPS @\$5.00	NECESSARY	30.00	30.00
1	REAR SPARE TYRE COMPARTMENT	BUCKLED	1,365.00	1,100.60
1	REAR BUMPER	DISTORTED	1,620.00	953.70
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	30.00
2	REAR BUMPER SIDE RETAINER @\$32.00	DISTORTED	64.00	64.00
1	REAR BUMPER REINFORCEMENT	BENT	425.00	425.00
2	REAR BUMPER REINFORCEMENT BRACKET @\$40.00	BENT	80.00	80.00
1	REAR BUMPER BRACKET	NOT NECESSARY	42.00	-
2	TAILLAMP: LHR AND RHR @\$495.00	сит	990.00	792.00
2	TAILLAMP BRACKETS : LHR AND RHR @\$143.00	BENT	286.00	63.80
8	TAILLAMP CLIPS @\$5.00	NECESSARY	40.00	40.00
1	REAR EXHAUST MOUNTING	BENT	84.00	84.00
2	REAR FENDER: RHR, LHR @\$1082.00	TO REPAIR SEE LABOUR	2,164.00	-
2	REAR FENDER INNER TRIM : RHR, LHR @\$490.00	N/S NOT NECESSARY / O/S DEFORMED	980.00	352.00
2	REAR FENDER SIDE AIR DUCT : RHR, LHR @\$120.00	NOT NECESSARY	240.00	-
	LESS 20% DISCOUNT		-2,505.80	-1,263.86
			10,023.20	5,055.44

Report Ref No. CS/LPC19016586/Gtd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	SET REAR EXHAUST (SN)	DENTED	2,500.00	850.00
1	SET REAR NO PLATE (SN)	SCRATCHED	80.00	40.00
			2,860.00	890.00
	LABOUR			
	TOW FEE : ACCIDENT SITE TO WORKSHOP.		100.00	50.00
	TO REMOVE, REFIX WINDSCREEN.		200.00	100.00
	TO REMOVE, REFIX INTERIOR UPHOLSTERY TO FACILITATE REPAIR WORKS.		30.00	30.00
	TO REMOVE, REFIX REAR REVERSE SENSOR.	NOT NECESSARY	30.00	-
	TO REFOCUS, RE-WIRE & CHECK WIRING; CHECK COMPUTER.		100.00	30.00
	TO PUTTY AND RE-SPRAY PAINT OF THE AFFECTED AREAS.		1,600.00	1,250.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED, KNOCK OUT DENTS ON AFFECTED PORTION, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR FENDER: RHR, LHR.		1,500.00	1,000.00
			3,560.00	2,460.00
	GRAND TOTAL		16,443.20	8,405.44

RECOMMENDED COST OF LUMP SUM REPAIRS	6,700.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/LPC19016586/Gtd3e2

XING GUO QIANG

ADRIAN LING WAI PING

M.MATAI, AMSAE-A

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Automotive Assessor

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.