

ASS. REC. BY:

REF:

CS3/PWD19016593/Pcd30b

Special Instruction:

Surveyor: Ram

ASSIGNMENT (Office)

From (Person):

Vanessa Chan

of

PWD

Date/Time:

19/9/19 @ 11:42am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 400C

Insured:

SLK 6356J

at Workshop m/s

SKM Garage

Tel:

6636 0738

of

10 Kakei Bukit Pond 2# 03-31

Policy No:

PNPY2018-00000678-01

Claim No:

1201900027623

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/9/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time

230pm @ 19/9/19

Person Contacted:

Ms. Yolce Peng

Vehicle IN/OUT

Date/Time	Action/Instruction
	Take photo (X)
	SKW 400C-X
	SLK 6356J-X
	Dismantle: 20/9/2019.
	After repair: 26/9/2019

ASS. REC. BY:

REF: FWD

PRS

ASSIGNMENT

From:

Date: 19/9/2019

Veh No:

SKW 400C

Yr Regn: OCT / 2015

Estimated Cost:

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SKW 400C

Make:

Honda Vezel

C.C 1496

at Workshop m/s

SKM Garage & Trading

Colour:

Silver

A/G: Insured / Std / NI / NA

of 10 kaka Bukit Road 2 #03-31

Sp. Reading

87817

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

-

Policy No.

C/No:

RV1-1102326

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or


(Policy Condition)

Tyre Size:

F: 215/60 R16

R: 215/60 R16

Remark: The veh had commenced its repair at the time of inspection.

BS ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

4

mm

R/Bal.

4

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

4

mm

L/Bal.

4

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A. 15/09/2019

D.O.I.

19/09/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

SKM Garage

CA / REV / REP. / 24 HRS ^(up)Des. of Damages: Frt / ☒ Rear / ☒ O/S / D/S / U/C / Rooftop or

Q/S / Rear d/s

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range: \$1000 - \$3000

Repair days: 4 days

MV: \$55000

PV: \$40250

NV: \$14000

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 4

1)

☐

Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$)

Survey Fee:

Transportation:

S + RS, \$1

Photos

Others

Report Formist:

PRS

Lump Sum / L.B. is

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Week end (\$)

TOTAL

180

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd
Main	16 Sep 2019 Edit Reg		19 Sep 2019 00:00 Edit Adj Rpt			
						Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Rajamanickam S/O Samiappan, ID: S1460294A		
Main Claimant:	LI YANGYANG, ID: S9179110B		
Vehicle Reg. No.:	SKW400C	Date of Loss:	15/09/2019 14:00 - :59
Claim Type:	TP / 1201900027623	Policy/Cover Note No.:	PNPV2018-00000678-01 (Comprehensive) Coverage: 23/01/2019 - 22/01/2020
Vehicle Reg. No. (Insured):	SLK6356J	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Skm Garage & Trading Llp - Kaki Bukit (HQ) 10 Kaki Bukit Road 2, #03-31 First East Centre, 417868 Kaki Bukit - Tel:		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 30/09/2019]		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: venessa.chan@fwd.com
Sent: Thursday, 19 September 2019 11:42 AM
To: admin-d@lkkauto.com; admin-a@lkkauto.com
Cc: motorclaims.sg@fwd.com; eileen.bay@fwd.com
Subject: PRE-REPAIR SURVEY- ACCIDENT INVOLVING SKW400C & SLK6356J ON 15TH SEPTEMBER 2019 [RSS/1909-7462 (SKM)(PD)] OUR CLAIM REF: 1201900027623
Attachments: PRI - RS SOLOMON LLC.pdf

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen & I will upload the documents accordingly.


Thank you.

Best Regards,

Venessa Chan
Administrative Assistant, Claims



FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
E venessa.chan@fwd.com
W www.fwd.com.sg



From: Venessa Chan - SGUser
Sent: Thursday, September 19, 2019 11:41 AM
To: 'Lua Siew Hui'
Cc: Wendy Jiang; Natalie Ng; Motor Claims SG - SG Common; Eileen Bay - SGUser
Subject: PRE-REPAIR SURVEY- ACCIDENT INVOLVING SKW400C & SLK6356J ON 15TH SEPTEMBER 2019 [RSS/1909-7462 (SKM)(PD)] OUR CLAIM REF: 1201900027623

WITHOUT PREJUDICE

Dear Siew Hui,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s **LKK Auto Consultant Pte Ltd**, to conduct the pre-repair survey (PRS) on your client's vehicle, SKW400C. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.*

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Lua Siew Hui [mailto:lua_siewhui@rssolomon.com]

Sent: Thursday, September 19, 2019 11:19 AM

To: Venessa Chan - SGUser

Cc: Wendy Jiang; Natalie Ng; Motor Claims SG - SG Common; Eileen Bay - SGUser

Subject: Re: PRE-REPAIR SURVEY- ACCIDENT INVOLVING SKW400C & SLK6356J ON 15TH SEPTEMBER 2019

[RSS/1909-7462 (SKM)(PD)] OUR CLAIM REF: 1201900027623

Dear Venessa,

We refer to your email of even date.

We write to inform that our client will be appointing her own Surveyors.

In this regard, please contact Ms. Yoke Peng of SKM Garage & Trading LLP at tel no. 6636 0738 for a pre-repair survey of our client's vehicle located at 10 Kaki Bukit Road 2 #03-31 First East Centre Singapore 417868.

Thank you and best regards

Lua Siew Hui | Legal Executive

Advocates & Solicitors

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e lua_siewhui@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information. If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system. Thank you.

On Thu, Sep 19, 2019 at 11:05 AM <venessa.chan@fwd.com> wrote:

WITHOUT PREJUDICE

Dear Siew Hui,

We refer to your email dated on 18.09.2019 of the PRI Notice of your client's vehicle SKW400C.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT APPRAISAL PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

***Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.**

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Lua Siew Hui [mailto:lua_siewhui@rssolomon.com]

Sent: Wednesday, September 18, 2019 9:12 AM

To: Motor Claims SG - SG Common

Cc: Wendy Jiang; Natalie Ng

Subject: PRE-REPAIR SURVEY- ACCIDENT INVOLVING SKW400C & SLK6356J ON 15TH SEPTEMBER 2019 [RSS/1909-7462 (SKM)(PD)]

Dear Sirs,

We act for the owner ('our Client') of vehicle no. SKW400C.

Our Client's vehicle was involved in the aforesaid accident with your insured's vehicle no. SLK6356J at the material time. As a result, our Client's vehicle was damaged and before our Client proceeds to repair her vehicle, please let us know within 2 working days upon receipt of this notice whether you intend to conduct a pre-repair survey of our Client's vehicle within the stipulated timeline, our Client will proceed to repair her vehicle without further reference to you.

Please see below, the following documents for your necessary action:-

1. Our letter of even date; and
2. GIA Report lodged by our client's driver.

Let us hear from you soonest.

Lua Siew Hui | Legal Executive

R. S. Solomon LLC | 正氣律師事務所

Advocates & Solicitors

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e lua_siewhui@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information. If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system. Thank you.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 110B

Vehicle Details

Vehicle No.: SKW400C
Vehicle to be Exported: No
Intended Deregistration Date: 20 Sep 2019
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X CVT
Primary Colour: Silver
Manufacturing Year: 2015
Engine No.: L15B4022325
Chassis No.: RU11102326
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$18,399.00
Original Registration Date: 14 Oct 2015
First Registration Date: 14 Oct 2015
Transfer Count: 1
Actual ARF Paid: $\$8,399.00 \times 50\% = \4199.50

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 13 Oct 2025
PARF Rebate Amount: \$6,299.00

Intended COE Rebate Details

COE Expiry Date: 13 Oct 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$56,001.00
COE Rebate Amount: \$33,951.00
Total Rebate Amount: \$40,250.00

The information contained herein is correct as at 20 Sep 2019

Remaining: 6 years 29 days (72.9)

OK

Depri: \$8500/yearly \$708.33/monthly

$72.9 \times \$708.33 = \$51,637.25$

$\$51,637.25 + \$4,199.50 = \$55,836.75$

Audi A3 Sedan/Sportsback Owners - Check In

Nissan QashQai 2014 Part 2

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Cheapest 1 Year 7 Months Left Sporty White Peugeot R...



1 Transfer! Tip Top Condition,
Low Mileage Done. 100%
Accident-Free. Don't Miss.
StarAd



Browse by Category ▼

« Back (1 2 3) Next »

Sort by Depreciation ▼ 20 results/page ▼

44 vehicles

Honda Vezel

Advanced Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection Honda Vezel Any Any 2015 Any Any Any Available



Honda Vezel 1.5A X \$54,951 \$8,420 /yr 21-Sep-2015 1,496 cc 47,000 km SUV Available

Car Is Almost New Condition, Low Depreciation, High Loan, Bank Loan, In House Loan Are All Available Now! Trade In Are Welcome Too!
Call Us Now For A Viewing!

Posted: 11-Sep-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X \$56,800 \$8,480 /yr 04-Nov-2015 1,496 cc 77,000 km SUV Available

New Paintwork. Regularly Serviced. Cheapest In Market. Price Negotiable, Trade In Welcome. Strictly Via Appointment.

Posted: 08-Sep-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X \$57,800 \$8,550 /yr 20-Nov-2015 1,496 cc 46,258 km SUV Available

Well Maintained Unit! Selling Cheap! Practical And Fuel Efficient SUV! Spacious And Easy To Maintain! Trade In Available! Call Our Friendly
Salesman For An Viewing By Appointment Today! Don't Miss!

Mayfair Motoring

Posted: 16-Sep-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X \$56,800 \$8,560 /yr 22-Oct-2015 1,496 cc 48,000 km SUV Available

1 Owner! In House Loan Available. Free 1 Year Engine And Gearbox Warranty! New Arrival In Showroom. Luna Silver With Black Leather,
Excellent Condition, Super Great Fuel Efficient, Trade In Available, Call Now For Viewing!

Posted: 18-Sep-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Kakimoto Racing Exhaust System @ \$1150

Kakimoto Racing Exhaust With Cert For Honda Freed DAA-GB7 Model One Set Selling @ \$1150. Please Contact Lun @ 92406288.

More info about this product



Honda Vezel 1.5A X \$56,800 \$8,790 /yr 10-Sep-2015 1,496 cc 63,021 km SUV Available

Well Maintained Unit! Selling Cheap! Practical And Fuel Efficient SUV! Spacious And Easy To Maintain! Trade In Available! Call Our Friendly
Salesman For An Viewing By Appointment Today! Don't Miss!

Mayfair Motoring

Posted: 10-Sep-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X \$59,800 \$8,810 /yr 22-Dec-2015 1,496 cc 76,000 km SUV Available

NON PHV Owner! Well Maintained With No Paintwork Done. Totally In Showroom Condition. Flexible Loan Package Available With Low
Interest Rate. Call Me Now For Viewing Now.

Ka-Hup Vehicles Trading

Posted: 17-Sep-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Honda Vezel 1.5A X \$59,800 \$8,840 /yr 14-Dec-2015 1,496 cc 45,288 km SUV Available

B by STA

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/09/2019 20:20
Date Of Accident	15/09/2019 14:30
Exact Location Of Accident	LOADING BAY OF 950 HOUGANG ST 91
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW400C
Insured/Policyholder	
Name Of Registered Owner	LI YANGYANG
NRIC No	S9179110B
Email Address	YVONNE.LIYANGYANG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96677465
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5111181675
Cover Note Number	

Driver

Name of Driver	EUGENE YEO HAO MING
NRIC No	S9121339G
Date Of Birth	17/06/1991
Occupation	OUTDOOR
Date Of Driving Pass	23/04/2012
Driving Experience	7 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96677465
Fax Number	
Contact Number	
Email Address	YVONNE.LIYANGYANG@GMAIL.COM

Address	985B BUANGKOK CRESCENT #10-20
Postcode	532985
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	ADVISED TO SUBMIT TO MOTORVIDEO@INCOME.COM.SG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK4356J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	RAJAMANICKAM S/O SAMIAPPAN
NRIC/Passport Number	S1460294A
Contact Number	81802048
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations/laws or court orders.


Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time: 12/1/2017

Reporting Centre Personnel's Signature
Name: Jee Jih
NRIC/FIN No.: 6722491E

Sketch Plan #2

SKETCH PLAN



VEH A = SKW400C

VEH B = 34K6356T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 15/4/2019 around 1430hrs, I parked my vehicle at the above
 sketched location to wait for my mother.
 I was standing outside my car.
 I saw vehicle B collide onto my left when he was attempting
 to reverse out.
 I also found damage on my right rear rim as the impact caused
 my rim to be scratched by the right backside.
 No one was injured in the my accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time 15/4/2019

Driver's Signature

(If driver is not the policyholder)

Date & Time 15/4/2019

Reporting Centre Personnel's Signature

Name J E Tan

NRIC/FIN No 8021405

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Sep 2019 Edit Reg		19 Sep 2019 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]			
Insured:	Rajamanickam S/O Samiappan, ID: S1460294A				
Main Claimant:	LI YANGYANG, ID: S9179110B				
Vehicle Reg. No.:	SKW400C	Date of Loss:	15/09/2019 14:00 - :59 [47 Months and 1 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP / 1201900027623	Policy/Cover Note No.:	PNPV2018-00000678-01 (Comprehensive) Coverage: 23/01/2019 - 22/01/2020		
Vehicle Reg. No. (Insured):	SLK6356J	Policy No. (Claimant):			
		Excess:	S\$500.00		
Repairer:	Skm Garage & Trading Lip - Kaki Bukit (HQ) 10 Kaki Bukit Road 2, #03-31 First East Centre, 417868 Kaki Bukit - Tel:				
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 30/09/2019]				











ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SKW400C (1201900027623)
[SLK6356J]
TP
LI YANGYANG
Sep 15 2019 2:00PM
[Rajamanickam S/O Samiappan]
Skm Garage & Trading Llp - Kaki Bukit

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
2	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
3	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
4	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
5	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
6	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
7	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
8	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
9	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
10	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
11	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
12	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
13	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
14	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
15	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
16	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
17	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
18	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
19	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
20	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
21	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
22	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
23	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
24	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
25	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
26	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
27	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
28	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
29	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
30	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
31	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
32	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
33	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
34	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
35	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
36	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
37	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
38	25/09/19 10:55	General View								Load JPG	<input checked="" type="checkbox"/>	
39	25/09/19 10:56	General View								Load JPG	<input checked="" type="checkbox"/>	
40	25/09/19 10:56	General View								Load JPG	<input checked="" type="checkbox"/>	
41	25/09/19 10:56	General View								Load JPG	<input checked="" type="checkbox"/>	
42	25/09/19 10:56	General View								Load JPG	<input checked="" type="checkbox"/>	
43	25/09/19 10:56	General View								Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	25/09/19 10:56	General View	 Load JPG	<input checked="" type="checkbox"/>
45	25/09/19 10:56	General View	 Load JPG	<input checked="" type="checkbox"/>
46	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	25/09/19 10:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	26/09/19 16:06	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
72	26/09/19 16:06	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
73	26/09/19 16:06	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
74	26/09/19 16:06	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
75	26/09/19 16:06	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
76	26/09/19 16:06	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
77	26/09/19 16:06	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
78	26/09/19 16:06	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
79	26/09/19 16:06	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	19/09/19 17:19	SLK6356J OI GIA.	 Load PDF	
2	19/09/19 17:21	PRI - R.S SOLOMON LLC	 Load PDF	
3	19/09/19 17:22	SKW400C TP GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD19016593/FCD3E2

Date: 07/10/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00000678-01

Claimant
Vehicle No : SKW400C **Insured Vehicle No :** SLK6356J

Date of Loss: 15/09/2019 Nature of Claim: TP Claim No: 1201900027623

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW400C**

Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4022325

Reg. Date: 14/10/2015 (Man. Year: 2015) Chassis No: RU11102326

Colour: Silver Odometer: 87817 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/09/2019

Date Inspected: 19/09/2019 Inspected At: Skm Garage & Trading Llp - Kaki Bukit (HQ)
 10 Kaki Bukit Road 2, #03-31 First East Centre
 Singapore 417868

Estimated Period of Repair: 4.0 days

Adjuster: PARASURAM SHANMUGAM**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW400C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >