

Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/02/2018 12:00
Date Of Accident	30/01/2018 11:45
Exact Location Of Accident	CHANGI VILLAGE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBE2572C
Insured/Policyholder	
Name Of Registered Owner	SAAD BIN AHMAD
NRIC No	S1397886G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94850662
Alternative Phone No	Office-94850662

Vehicle Particulars

Manufacturer	SYM
Model	SYM GTS200
Exact Purpose for which vehicle was being used at time of accident	Personal use
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	SAAD BIN AHMAD
NRIC No	S1397886G
Date Of Birth	23/08/1959
Occupation	INDOOR
Date Of Driving Pass	02/04/1984
Driving Experience	33 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94850662

Fax Number	OFFICE-94850662
Contact Number	NOEMAIL
EMail Address	182 PASIR RIS ST 11
Address	#07-32
Postcode	510182
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PASIR RIS NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 1 PASIR RIS DRIVE 4 , POSTCODE: 519457 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5852999 - FAX NO: 65855261
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

See attached

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF INJURED PERSON 1

Name	SAAD BIN AHMAD
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBE2572C
Were seat belts worn?	NO
Was this injured conveyed to hospital by	YES

ambulance?

Address

BLK 182 #07-32
PASIR RIS STREET 11

Postcode

510182

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

SAD 27/02/18
11:58am
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
Suria Begum (1098)
Senior Admin Officer
Customer Centre

Sketch Plan



Describe Circumstances of the Accident

See attached police report

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time

11:58 am
27/02/18.

Driver's Signature (if driver is not the policyholder) / Date
& Time

 Suria Begum (1098)
Senior Admin Officer
Customer Centre

Witnessed by Reporting Centre
Personnel

Enquire Vehicle & Owner Information (Vehicle No. FBE2572C As At 30 Jan 2018 / 11:30:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: 2018.1107.PD.U2

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S1397886G

Owner Name: SA'AD BIN AHMAD

Registered Address Type: HDB / HUDC

Registered Block/House
No.: 182

Registered Street Name: PASIR RIS STREET 11

Registered Unit No.: #07 - 32

Registered Building Name: -

Registered Postal Code: 510182

Current Vehicle Details

Vehicle No.: FBE2572C

Make Description/Model: SYM / GTS200

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

THANK YOU



Lim Choon How has successfully logged out.

Your last login date and time was 05 Mar 2018, 15:17:24.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>S/No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(S\$)</u>	<u>Log Date/Time</u>
1	Vehicle	SLM9349A	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	05 Mar 2018 / 15:18:04

THANK YOU



Lim Choon How has successfully logged out.

Your last login date and time was 05 Mar 2018, 15:10:08.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>S/No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(S\$)</u>	<u>Log Date/Time</u>
1	Vehicle	FBE2572C	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	05 Mar 2018 / 15:10:47

10/1/2018

Invoice



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

RECORDS MANAGEMENT CENTRE

SEARCH RESULTS

Our Ref No: GR-18-150968
Date of Request: 01/10/2018

Your Ref No: 2018.1107.PD.U2

PRINCEPS LAW CORPORATION
150 SOUTH BRIDGE ROAD
#02-09 FOOK HAI BUILDING
Singapore 058727

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 30/01/2018
Place of Accident: CHANGI VILLAGE ROAD
Client Vehicle No: SKN2109D

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
FBE2572C	Changi Village road	30/01/2018 11:45

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.



This is a computer generated document and requires no signature.

10/1/2018

Invoice



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-150968
Date of Request: 01/10/2018

Your Ref No: 2018.1107.PD.U2

PRINCEPS LAW CORPORATION
150 SOUTH BRIDGE ROAD
#02-09 FOOK HAI BUILDING
Singapore 058727

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 30/01/2018
Place of Accident: CHANGI VILLAGE ROAD
Client Vehicle No: SKN2109D

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ [] Cash ☐ [] Cheque

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-148820
Date of Request: 26/09/2018

Your Ref No: 2018.1107.PD.U2

PRINCEPS LAW CORPORATION
150 SOUTH BRIDGE ROAD
#02-09 FOOK HAI BUILDING
Singapore 058727

Dear Sir/Madam,

Date of Accident: 30/01/2018
File No: SKN2109D
Place of Accident: CHANGI VILLAGE ROAD
Involving Vehicle No: SLM9349A

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SLM9349A	CHANGI VILLAGE ROAD	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

9/26/2018

Invoice



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-148816

Date of Request: 26/09/2018

Your Ref No: 2018.1107.PD.U2

PRINCEPS LAW CORPORATION
150 SOUTH BRIDGE ROAD
#02-09 FOOK HAI BUILDING
Singapore 058727

Dear Sir/Madam,

Yr Search Criteria:

Date of Accident: 30/01/2018
Place of Accident: CHANGI VILLAGE ROAD
Client Vehicle No: SKN2109D

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-18-148816

Date of Request: 26/09/2018

Your Ref No: 2018.1107.PD.U2

PRINCEPS LAW CORPORATION
150 SOUTH BRIDGE ROAD
#02-09 FOOK HAI BUILDING
Singapore 058727

Dear Sir/Madam,

Your Search Criteria:

of Accident: 30/01/2018
Place of Accident: CHANGI VILLAGE ROAD
Client Vehicle No: SKN2109D

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
SLM9349A	ALONG ROAD 1 CHANGI VILLAGE ROAD	30/01/2018 11:30

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



SINGAPORE
POLICE FORCE

PAYMENT

TAX INVOICE

Invoice No: SPF2019043001000378
Date/Time: 30/04/2019 16:02:15

Application Paid Via: Master
GST Reference No: MG-8400000-5

Transaction Ref No: TP000121868

Service Type	Service Fee	eService Reference No	Unit Price (S\$)	GST (S\$)	Qty	Amount (S\$)
1 Police Document	Search Fee	0050000002045627	14.00	0.00	1	14.00
Total (S\$)						14.00

This is a computer-generated invoice. No signature is required.

Please print a copy of the invoice for your reference.

A FORCE FOR THE NATION

wirecard

EASYPAY

Your transaction is successful

Merchant Name : SINGAPORE POLICE FORCE
Reference No : SPFEACR2019043000612
Amount : SGD 14.00
Card Type : DBS MasterCard
Approval Code : R07744
Transaction date/time : 30 April 2019 16:03:43

Please print this page as a reference for your transaction.

To continue, please click 'OK'.

Or you will be automatically redirected to the next page within 20 seconds

Copyright © 2018 Wirecard Singapore Pte Ltd. All rights reserved.

claimed
 petty cash
30/4/2019
4.28 pm
R

U2 SPRAY PAINTING PTE LTD

No.25 Kaki Bukit Road 4, #06-43 Synergy @ KB Singapore 417800

Tel : 6385 0687

Name : Ang Tiong Yew
Address : Blk 168A Queensway
#08-236
Singapore 140168

Date : 10-Aug-18

Final repair bill for vehicle no. SKN 2109 D

To supply and replace parts, labour charges for
repairing, knocking, welding and to respray painting
(Lump Sum Repair)

\$ 5,300.00

Dollar : Five Thousand Three Hundred Only

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883

Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Invoice No 03-18003/AY

Date 10 Aug 2018

Billing Name & Address
Ang Tiong Yew
Blk 168A Queensway
#08-236
Singapore 140168

Vehicle No : SKN 2109 D

Model : Toyota Avanza

Item	Descriptions	Amount S\$
1	Date of inspection : <u>1 Mar 2018</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>108</u> copies	
3	Transportation Charges	
4	2nd Inspection and Final Inspection	
	Total	<u>\$ 648.00</u>
	SDLS : SIX HUNDRED AND FORTY-EIGHT ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 03-18003/AY / 2018

Date of Report : 10 Aug 2018

Ang Tiong Yew
Blk 168A Queensway
#08-236
Singapore 140168

THIRD PARTY SURVEY

ACCIDENT HAPPENED ON 30 Jan 2018

As per your instruction dated 1 Mar 2018 with regard to the above matter. We have carried out a physical inspection on the said vehicle SKN 2109 D. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SKN 2109 D
Model : Toyota Avanza
Year / Capacity : 2014/1497
Chassis No : MHKM1CB4TBK008377
Engine No : 3SZDDT9130
Mileage : 125983
Colour : Black

2. TYRES CONDITION

			<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	:	205/55 R16	Lassa	7.00	mm	Sport
REAR	O/S	:	205/55 R16	Lassa	7.00	mm	Sport
FRONT	N/S	:	205/55 R16	Lassa	7.00	mm	Sport
REAR	N/S	:	205/55 R16	Lassa	7.00	mm	Sport

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

Workshop Address : U2 Spray Painting Pte Ltd
No.25 Kaki Bukit Road 4
#06-43 Synergy@KB
Singapore 417800

5. Estimated normal period of repair : ~~8~~⁶ working days to complete.
6. Enclosed number of photograph : 108 copies.
7. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
8. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SKN 2109 D
Report No: TP/ 03-18003/AY / 2018

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Rear tailgate	Damage	\$ 1460.85	\$ 1460.85 ✓ BT
1	Rear tailgate lock	Damage	\$ 112.65	\$ 112.65 ✓ JM
1	Rear tailgate rubber	Necessary	\$ 211.60	\$ 211.60 ✓ acc
1	Rear tailgate logo	Necessary	\$ 58.50	\$ 58.50 ✓ acc
1	Rear tailgate 'AVANZA' emblem	Necessary	\$ 52.20	\$ 52.20 ✓ acc
1	Rear tailgate outer handle	Damage	\$ 165.40	\$ 165.40 X SVC
1	Rear tailgate inner board	Damage	\$ 485.60	\$ 485.60 ✓ acc
1	Rear tailgate '1.5' emblem	Necessary	\$ 55.00	\$ 55.00 ✓ acc
1	Rear tailgate 'S' emblem	Necessary	\$ 48.50	\$ 48.50 ✓ acc
1/2	Rear taillamps	O/S Damage	\$ 881.00	\$ 440.50 ✓ acc
1	Rear end panel outer	Damage	\$ 590.50	\$ 590.50 X R
1	Rear end panel inner garnish	Damage	\$ 142.20	\$ 142.20 ✓ acc
1	Rear end panel inner	Damage	\$ 511.50	\$ 511.50 X R
1	Rear bumper	Damage	\$ 660.90	\$ 660.90 ✓ BT
1/2	Rear bumper side retainers RH only	Necessary	\$ 85.70	\$ 42.85 85.70 ✓ acc
2	Rear bumper reflectors	Intact	\$ 70.40	\$ SVC
1	Rear spare tyre carriage	Damage	\$ 315.00	\$ 315.00 R S
1	Rear spare tyre carriage lock nut	Repair	\$ 42.00	\$ R S
Discount 25.0%			\$ 5949.50	\$ 5396.60
			\$ 1487.38	\$ 1349.15
			\$ 4462.12	\$ 4047.45
<u>Special Nett Items</u>				
1	Rear windscreen inner seal	Necessary	\$ 65.00	\$ 65.00 30 ✓
1	Rear windscreen sealant	Necessary	\$ 60.00	\$ 50.00 40 ✓
1	Rear reverse sensor (1 set)	Damage	\$ 280.00	\$ 280.00 200 ✓
			\$ 405.00	\$ 395.00 ↓ short

Spare Parts Total \$ 4867.12 \$ 4442.45

Vehicle No: SKN 2109 D
Report No: TP/ 03-18003/AY / 2018

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 4867.12	\$ 4442.45
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 50.00	\$ 40.00 20
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 150.00	\$ 80.00 30
3	To remove and refit rear bumper sensor.	\$ 150.00	\$ 80.00 20
4	To remove and refit rear windscreen glass.	\$ 200.00	\$ 120.00 100
5	To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings.	\$ 100.00	Not Required X
6	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools. 3 day	\$ 1100.00	\$ 880.00 600
7	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available. 3 pcs	\$ 1100.00	\$ 880.00 600
8	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ 90.00 30
Total		<u>\$ 7867.12</u>	<u>\$ 6612.45</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 5300.00

SDLS: FIVE THOUSAND THREE HUNDRED ONLY


Qualified Appraiser

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Feb 2018		05 Feb 2018 14:54 Edit Adj Rpt	S\$3,600.00 Edit Estimates	S\$3,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SA'AD BIN AHMAD , ID: S1397886G								
Main Claimant:	ANG TIONG YEW , ID: S7433316H								
Vehicle Reg. No.:	SKN2109D	Date of Loss:	30/01/2018 11:00 - :59 [48 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-000200	Policy/Cover Note No.:	MSD/VMFT/17-357766 (TP, Fire & Theft) Coverage: 08/02/2017 - 07/02/2018						
Vehicle Reg. No. (Insured):	FBE2572C	Policy No. (Claimant):							
		Excess:							
Repairer:	U2 Spary Painting Pte Ltd (HQ) 25 KAKI BUKIT ROAD 4, #06-43 SYNERGY@KB, 417800 Kaki Bukit - Tel: 86186474								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 19/09/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (17/09/2019): Report Send Back Alerts - SKN2109D (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKN2109D (MSC/V/18-000200)**
[FBE2572C]

TP

ANG TIONG YEW

Jan 30 2018 11:00AM

[SA'AD BIN AHMAD]

U2 Spary Painting Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/02/18 13:13	Accident Statement From: SC - Reg. No: FBE2572C, Claimant: SAAD BIN AHMAD	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
2	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
3	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
4	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
5	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
6	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
7	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
8	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
9	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
10	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
11	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
12	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
13	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
14	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
15	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
16	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
17	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
18	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
19	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
20	03/04/18 16:08	General View	Load JPG	<input checked="" type="checkbox"/>
21	03/04/18 16:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
22	03/04/18 16:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
23	03/04/18 16:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
24	03/04/18 16:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
25	03/04/18 16:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
26	03/04/18 16:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
27	03/04/18 16:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
28	03/04/18 16:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
29	03/04/18 16:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
30	03/04/18 16:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
31	03/04/18 16:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
32	03/04/18 16:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
33	03/04/18 16:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
34	03/04/18 16:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
35	03/04/18 16:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
36	03/04/18 16:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Claim Documents

***SKN2109D (MSC/V/18-000200)**
[FBE2572C]

TP

ANG TIONG YEW

Jan 30 2018 11:00AM

[SA'AD BIN AHMAD]


U2 Spary Painting Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼





































Assessment Reports

1 per page ▼ ☒

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/02/18 13:13	Accident Statement From: SC - Reg. No: FBE2572C, Claimant: SAAD BIN AHMAD	 Load HTM	<input checked="" type="checkbox"/>

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	03/04/18 16:08	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	03/04/18 16:08	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	03/04/18 16:08	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	03/04/18 16:08	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	03/04/18 16:08	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	03/04/18 16:08	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	03/04/18 16:08	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27	03/04/18 16:08	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28	03/04/18 16:08	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
29	03/04/18 16:08	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
30	03/04/18 16:08	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
31	03/04/18 16:08	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
32	03/04/18 16:08	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
33	03/04/18 16:08	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
34	03/04/18 16:08	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
35	03/04/18 16:08	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
36	03/04/18 16:08	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page ▼	Thumbnail	Print
37	03/04/18 16:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
38	03/04/18 16:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
39	03/04/18 16:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
40	03/04/18 16:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
41	03/04/18 16:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
42	03/04/18 16:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
43	03/04/18 16:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>

Documentation

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page ▼	Thumbnail	Print
1	05/02/18 14:54	TP GIA REPORT		Load PDF	
2	17/09/19 10:09	LOD		Load PDF	
3	17/09/19 10:09	Survey Report		Load PDF	
4	17/09/19 19:26	Instruction to LKK to prepare paper survey report		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/09/19 09:25	PRS INVOICE		Load PDF	

Documents Checklist**DOCUMENTS CHECKLIST**

There are no document checklists configured.

Reset

Save

Print

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18002302/HVD3S2-1
Date: 30/09/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMFT/17-357766
Claimant Vehicle No : SKN2109D **Insured Vehicle No :** FBE2572C
Date of Loss: 30/01/2018 **Nature of Claim:** TP **Claim No:** MSC/V/18-000200

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKN2109D
Make & Model: TOYOTA AVANZA, 1.5 (A) **Engine No:** 3SZDDT9130
Reg. Date: 01/01/2014 (Man. Year: 2014) **Chassis No:** MHKM1CB4TBK008377
Colour: Black **Odometer:** 0 km
Engine Capacity: 1497 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:** Yes

CONDITION OF TYRES

Front Tyre Size: 205/55R16 **Rear Tyre Size:** 205/55R16
Front Left Side: Driveway 4 mm **Rear Left Side:** Driveway 4 mm
Front Right Side: Driveway 4 mm **Rear Right Side:** Driveway 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,867.12	3,098.51	1,768.61	36.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	1,400.00	1,600.00	53.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,867.12	4,498.51	3,368.61	42.82
Approved Total (Overridden) (\$\$)		3,600.00		
Nett Amount (\$\$)	7,867.12	3,600.00	4,267.12	54.24

INSPECTION

Date of Assignment: 05/02/2018
Date Inspected: 06/03/2018 **Inspected At:** U2 Spary Painting Pte Ltd (HQ)
 25 KAKI BUKIT ROAD 4, #06-43 SYNERGY@KB
 Singapore 417800
Estimated Period of Repair: 6.0 days **Repairer:** Mova Automotive Pte Ltd

Adjuster: LEE HOCK ANN

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Sep 2019)	
Parts:	N/A	TOYOTA AVANZA 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKN2109D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,460.85 FL	*1,460.85 FL
2	1		*REAR TAILGATE LOCK	Jammed	112.65 FL	*112.65 FL
3	1		*REAR TAILGATE RUBBER	Necessary	211.60 FL	*211.60 FL
4	1		*REAR TAILGATE LOGO	Necessary	58.50 FL	*58.50 FL
5	1		*REAR TAILGATE AVANZA EMBLEM	Necessary	52.20 FL	*52.20 FL
6	1		*REAR TAILGATE OUTER HANDLE	Serviceable	165.40 FL	*- FL
7	1		*REAR TAILGATE INNER BOARD	Crushed	485.60 FL	*485.60 FL
8	1		*REAR TAILGATE 1.5 EMBLEM	Necessary	55.00 FL	*55.00 FL
9	1		*REAR TAILGATE S EMBLEM	Necessary	48.50 FL	*48.50 FL
10	1		*REAR TAILLAMPS	O/s Cracked	881.00 FL	*440.50 FL
11	1		*REAR END PANEL OUTER	Repair	590.50 FL	*- FL
12	1		*REAR END PANEL INNER GARNISH	Crushed	142.20 FL	*142.20 FL
13	1		*REAR END PANEL INNER	Repair	511.50 FL	*- FL
14	1		*REAR BUMPER	Bent	660.90 FL	*660.90 FL
15	1		*REAR BUMPER SIDE RETAINERS	O/s Necessary	85.70 FL	*42.85 FL
16	1		*REAR BUMPER REFLECTORS	Serviceable	70.40 FL	*- FL
17	1		*REAR SPARE TYRE CARRIAGE	Repair	315.00 FL	*- FL
18	1		*REAR SPARE TYRE CARRIAGE LOCK NUT	Repair	42.00 FL	*- FL
19	1		*REAR WINDSCREEN INNER SEAL	Necessary	65.00 FS	*30.00 FS
20	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
21	1		*SET REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,354.50	4,041.35
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,487.38	942.84
Total Parts (\$\$)	4,867.12	3,098.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.	New	50.00	20.00
2	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS.	New	150.00	30.00
3	TO REMOVE AND REFIT REAR BUMPER SENSOR.	New	150.00	20.00
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	New	200.00	100.00
5	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTINGS.	New	100.00	0.00
6	TO REMOVE AND REPLACED THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.	New	1,100.00	600.00
7	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.	New	1,100.00	600.00
8	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.	New	150.00	30.00
Gross Labour Cost (S\$)			3,000.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >