

22/03/2002

ASS. REC. BY:

REF: CS3/MSG190166111 TIC f306

Special Instruction:

Surveyor: Taugkh

ASSIGNMENT (Office)

From (Person): Jasmine Lok Kheng Kwai of MSG

Date/Time: 19.9.19 16.45pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PA 58 P

Insured: XD 1774M

at Workshop m/s S S Transport Management

Tel: 92323269

of 15 Pioneer Sector 2

Policy No: B28718557MPF

Claim No: 589051

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 28.3.2019

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 20.9.19 9.15am

Person Contacted: Mr Wong

Vehicle: IN OUT

Date/Time

Action/Instruction (✓) Estimate

PA 58 P - CS / TP / 10004385 / Rch

D.O.A. - 10/02/2010

XD 1774M - NJA / MSG 100210311 / 1

D.O.A. - 24/09/2010

24/9/19

@ 1125am Mr Wong: said no est, use independant

7/55/REC BY

Taufhi

REP

MSG

ASSIGNMENT

CoE 2028 Dec.

From: Date: 23.9.2019

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PA 58P

at Workshop m/s: STS Transport Management

of 15 Pioneer Setor 2

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh: 2.00p.m - 3.00p.m Amr Wady

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

PA 58P

Yr Regn: 2008 / Dec.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Isuzu LT134P

c.c 7700.

Colour:

Yellow.

A/C: Insured / Std / NI / NA

Sp. Reading:

533439

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JA LLT134P870000 96

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

11K27.5

R:

~ ~ (17)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

8

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

D.O.I.

23/9/19 P 215p

Survey held at

STS Transport

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

96000 - 97000, 7 days

RECEIVED 08 OCT 2019

Date/Time, File Pass Int

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return Int

2)

Days Of Repair: 7

Resurvey No. of Trip: -

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Work end (\$)

Survey Fee:

120

Transportation:

S + RS, SI

Photos:

Notes:

11

TOTAL

131

Report Form: PRS.

Long Sum A/B/C/D

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Apr 2019		19 Sep 2019 16:15 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CWT INTEGRATED PTE. LTD., Co. Reg. No.: NA		
Main Claimant:	STS TRANSPORT MANAGEMENT PTE LTD, Co. Reg. No.: 200107540Z		
Vehicle Reg. No.:	PA58P	Date of Loss:	28/03/2019 09:00 - :59 [123 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 589051	Policy/Cover Note No.:	B28718557MKF (Third Party Only) Coverage: 01/04/2018 - 31/03/2019
Vehicle Reg. No. (Insured):	XD1774M	Policy No. (Claimant):	
		Excess:	
Repairer:	Sts Transport Management Pte Ltd (HQ) 15 PIONEER SECTOR 2, 628376 Pioneer - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/09/2019]		
Driver/Custodian (Insured):	XING CHAOHUA (), NRIC: G5121779P, Tel: +6596719836 Email:		
Adj Asg. Remarks:	on WP. Liab:clear. Disagree on SJE. Contact: Mr Wong / Mei Jun @ 9232 3269 / 6898 2668.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	540Z
Vehicle Details	
Vehicle No.:	PA58P
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2019
Vehicle Make:	ISUZU
Vehicle Model:	LT134P
Primary Colour:	Multicolor
Manufacturing Year:	2008
Engine No.:	6HK1468395
Chassis No.:	JALLT134P87000096
Maximum Power Output:	-
Open Market Value:	\$88,646.00
Original Registration Date:	12 Dec 2008
First Registration Date:	12 Dec 2008
Transfer Count:	0
Actual ARF Paid:	\$4,433.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Dec 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$28,187.00
COE Rebate Amount:	\$25,968.00
Total Rebate Amount:	\$25,968.00

The information contained herein is correct as at 24 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/03/2019 11:46
Date Of Accident	28/03/2019 09:40
Exact Location Of Accident	NEAR STS TRANSPORT MANAGEMENT 15 PIONEER SECTOR 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PA58P
Insured/Policyholder	
Name Of Registered Owner	STS TRANSPORT MANAGEMENT PTE LTD
Co Reg No	200107540Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68982668

Vehicle Particulars

Manufacturer	ISUZU
Model	LT134P
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTSCBU000182
Cover Note Number	

Driver

Name of Driver	SHANMUGAM SURESH
NRIC No	G7137455L
Date Of Birth	06/05/1974
Occupation	OUTDOOR
Date Of Driving Pass	05/12/2002
Driving Experience	16 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90364058
Fax Number	
Contact Number	
Email Address	INFO@STSTRANSPORT.COM.SG

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I (PA0058P) was driving slowly along Pioneer sector 2, as the traffic was congested at that point of time, following behind a lorry who was moving slowly at that point of time too, when suddenly a truck, turning left to Pioneer sector 2, coming from Pioneer sector 1, hit me. The rear left side of the truck make contact with the rear right side of my bus. No injuries involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD1774M
Vehicle Make/Model/Colour	NISSAN/GKB45CLBHNH/WHITE
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	XING CHAOHUA
NRIC/Passport Number	G5121779P
Contact Number	96719835
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

IMPORTANT NOTICE

1. Please read carefully the details of the accident to assist in the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as accurate and complete as possible. Any information representation or withholding of material facts may affect insurance coverage and/or future policy liability.
4. The terms and conditions of this form, by insurance companies, is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded to the Insurers of the GIA Service Management Centre established by the General Insurance Association of Singapore (GIA) for processing and that copies of the report will be made available application by interested parties.
7. Before signing this report, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.
8. Consent under the Personal Data Protection Act (PDPA)
 - (i) I, the policyholder, agree and consent that the Insurers, the Insurers and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data and/or information set out in this report and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurers who have insured vehicles involved in the accident (all Insurers) and to be shared with any other Insurers involved in the accident and to parties referred to as the Insurers, Insurers, Insurers and the General Insurance Association of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my obligations or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages) and/or;
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (ii) I, the policyholder, agree and consent that the Insurers, the Insurers and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (iii) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHAMMAD SULHANDI BIN
MOHD AFFANDI

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I (PA0058P) was driving slowly along Pioneer sector 2, as the traffic was congested at that point of time, following behind a lorry who was moving slowly at that point of time too, when suddenly a truck, turning left to Pioneer sector 2, coming from Pioneer sector 1, hit me. The rear left side of the truck make contact with the rear right side of my bus. No injuries involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMMAD SULHANDI BIN MOH AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

28 March 2019 at 10:56 AM

Date/Time:

28 March 2019 at 10:56 AM

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Apr 2019		19 Sep 2019 16:15 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CWT INTEGRATED PTE. LTD., Co. Reg. No.: NA								
Main Claimant:	STS TRANSPORT MANAGEMENT PTE LTD, Co. Reg. No.: 200107540Z								
Vehicle Reg. No.:	PA58P	Date of Loss:	28/03/2019 09:00 - :59 [123 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 589051	Policy/Cover Note No.:	B28718557MKF (Third Party Only) Coverage: 01/04/2018 - 31/03/2019						
Vehicle Reg. No. (Insured):	XD1774M	Policy No. (Claimant):							
		Excess:							
Repairer:	Sts Transport Management Pte Ltd (HQ) 15 PIONEER SECTOR 2, 628376 Pioneer - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 20/09/2019]								
Driver/Custodian (Insured):	XING CHAOHUA (), NRIC: G5121779P, Tel: +6596719836 Email:								
Adj Asg. Remarks:	on WP. Liab:clear. Disagree on SJE. Contact: Mr Wong / Mei Jun @ 9232 3269 / 6898 2668.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PA58P (589051)
[XD1774M]
TP
STS TRANSPORT MANAGEMENT PTE LTD
Mar 28 2019 9:00AM
[CWT INTEGRATED PTE. LTD.]
Sts Transport Management Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports						1 per page 1 <input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	17/06/19 15:07	Accident Statement From: SC - Reg. No: XD1774M, Claimant: CWT INTEGRATED PTE. LTD.		Load HTM			
Photos/Images						3 per page 3 <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	07/10/19 11:37	General View		Load JPG	<input checked="" type="checkbox"/>		
2	07/10/19 11:37	General View		Load JPG	<input checked="" type="checkbox"/>		
3	07/10/19 11:37	General View		Load JPG	<input checked="" type="checkbox"/>		
4	07/10/19 11:37	General View		Load JPG	<input checked="" type="checkbox"/>		
5	07/10/19 11:37	General View		Load JPG	<input checked="" type="checkbox"/>		
6	07/10/19 11:37	General View		Load JPG	<input checked="" type="checkbox"/>		
7	07/10/19 11:37	General View		Load JPG	<input checked="" type="checkbox"/>		
8	07/10/19 11:37	General View		Load JPG	<input checked="" type="checkbox"/>		
9	07/10/19 11:37	General View		Load JPG	<input checked="" type="checkbox"/>		
10	07/10/19 11:37	General View		Load JPG	<input checked="" type="checkbox"/>		
11	07/10/19 11:37	General View		Load JPG	<input checked="" type="checkbox"/>		
12	07/10/19 11:37	General View		Load JPG	<input checked="" type="checkbox"/>		
13	07/10/19 11:37	General View		Load JPG	<input checked="" type="checkbox"/>		
14	07/10/19 11:37	General View		Load JPG	<input checked="" type="checkbox"/>		
15	07/10/19 11:37	General View		Load JPG	<input checked="" type="checkbox"/>		
16	07/10/19 11:37	General View		Load JPG	<input checked="" type="checkbox"/>		
Documentation						1 per page 1 <input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	19/09/19 10:11	email to workshop - STS, change of workshop		Load PDF			
2	19/09/19 13:19	PRI from Cheonghoh Law		Load PDF			
3	19/09/19 13:19	Disagree on SJE		Load PDF			
4	19/09/19 13:19	Workshop Details		Load PDF			
5	19/09/19 13:19	PRI for PA58P		Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19016611/T1CF3E2

Date: 08/10/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B28718557MKF
Claimant
Vehicle No : PA58P **Insured Vehicle No :** XD1774M
Date of Loss: 28/03/2019 **Nature of Claim:** TP **Claim No:** 589051

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PA58P**
 Make & Model: ISUZU LT134P, 7.8 D (M) Engine No: 6HK1468395
 Reg. Date: 12/12/2008 (Man. Year: 2008) Chassis No: JALLT134P87000096
 Colour: Yellow Odometer: 533439 km
 Engine Capacity: 7790 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 11 R22.5 Rear Tyre Size: 11 R22.5 (D)
 Front Left Side: West Lake 8 mm Rear Left Side: West Lake 8/8 mm
 Front Right Side: West Lake 8 mm Rear Right Side: West Lake 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/09/2019
 Date Inspected: 23/09/2019 Inspected At: Sts Transport Management Pte Ltd (HQ)
 15 PIONEER SECTOR 2
 Singapore 628376
 Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 08 Oct 2019)
Parts:	N/A	ISUZU LT134P 7.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for PA58P)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >