Surveyor From (Person	June Tan Get		IGNMENT (Office)		20	9.19 9.50 11
Estimate Co		of _	Bill to:		Date/Time: 00-	9.19 4.750.19
/	STTP RESTOR	RESTEVATIONS Stw 7008 G	/MV/CS	Insured:	SLz 7	45×D
of 36 To	h Gwa Ro	utocare and Easy	# 01-3L	Tel:	877 9 3631	6 (200060
Policy No: 2	6046 4B63 41	ń×	Claim No:	6061	34	
Sum Insured:			Excess:			
Make of Veh (Client's Record		"ry"	,		D.O.A. 4. 9.	19
Date/Time 2			stacted Now	V	H.O.D. Endersens	
Date/Time	Action/instruction	on ( 🗸 ) (	Stinute			
	Stan ford	G -×				
-	SLZ 745	20.×				
23 9 19	Saud pr	eli revised	vice merimen			
27/9/19	13 \$ 27	Su consum	ad by email (R	ed in a	29.22 789	ð

					23/91	
tota/Time, File Pass Id?	: Preli, Report	Day	s Of Repair:	4		
	: Final Report	Res	urvey No. of Tr	ip: 2	Survey Fee:	
ioto/Tene, File Robert In?					Transportation	200
		Add Fee:	Site Insp	5	)5+R55k	TI
		Ē	: Interview 0	\$	) Photos	
ep Forms:	2	ř	: Tech. Invs (	\$	) 199esc	
ump Sum P.E.T.			-Westend 6			
		Line	and the same of th		1978/4	211

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

MSIG Insurance (Singapore) Pte. Ltd. To:

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Irene Tan Gek Ing

Date:

23 Sep 2019

### **Preliminary Advice**

Insured Vehicle No : SLZ7452D

TP Vehicle No

: SKW7008G

Accident Date

: 17/09/2019

Make

: NISSAN QASHQAI

Assignment Date

: 20/09/2019

Date of inspection

: 20/09/2019

Est. Duration of Repair

: 4.00

Inspection At

: AMA AUTOCARE PTE LTD (HQ)

36 TOH GUAN ROAD EAST, #01-36

SINGAPORE 608580

#### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,789.20
Revised Amount	:S\$	4,544.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,544.80

Lump Sum Repair

#### **Total Loss Consideration**

New for Old Value	:5\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:5\$
Margin for Repair	:S\$

#### Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

# ...CLAIM SUBFOLDER...(New Assignment)

ts Show All ted by insurer] 7@gmail.com	
ted by insurer] 7@gmail.com	
7@gmail.com	
2019 18:00 - :59	
9/2019 18:00 - :59 donths and <b>5</b> Days From LTA Date (Man Yr)]	
803QMX (Comprehensive) age: 29/11/2018 - /2020	
er er Welt	
East - Tel:	
ed by Irene Tan Gek Ing	
ie 21/09/2019]	
l: davidhuan7@gmail.com	
ear. Agree on SJE. Assign:	
Compose Case Mail	

#### Nivitha (LKK Auto)

From:

Crystal Lee <crystal\_lee@sg.msig-asia.com>

Sent:

Thursday, 19 September 2019 4:26 PM

To:

Admin-D (LKKAuto); assignments

Cc:

Ong Zi Hui

Subject:

Survey Request - Manual Assigned

Attachments:

img-919141918.pdf

# PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKW7008G & SLZ7452D (MSIG) ON 19/09/2019

#### Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards, Crystal Lee Admin Officer, Claims Services (In-House Survey) D: +65 6594 2535 | F: +65 6643 1349 | crystal\_lee@sg.msig-asia.com



# MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg







A Member of MS&AD INSURANCE GROUP

From: Helene Phua

Sent: Thursday, 19 September, 2019 3:19 PM

To: Crystal Lee <crystal\_lee@sg.msig-asia.com>; Ong Zi Hui <zihui\_ong@sg.msig-asia.com>

Subject: FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKW7008G & SLZ7452D

(MSIG) ON 19/09/2019

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene\_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg 🚺 🎯 🛅 🖸







A Member of MS&AD INSURANCE GROUP

From: Helene Phua

Sent: Thursday, 19 September, 2019 3:19 PM To: AMA Automotive <ama.claim@gmail.com> Cc: Irene Tan <irene tan@sg.msig-asia.com>

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKW7008G & SLZ7452D (MSIG)

ON 19/09/2019

Hi,

Thank you for your selection.

We will proceed to assign LKK Auto Consultants Pte Ltd via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

#### Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene\_phua@sg.msig-asia.com



# MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg







A Member of MSRAD INSURANCE GROUP

From: AMA Automotive [mailto:ama.claim@gmail.com]

Sent: Thursday, 19 September, 2019 3:05 PM

To: Helene Phua <helene phua@sg.msig-asia.com>

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKW7008G & SLZ7452D (MSIG)

ON 19/09/2019

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Hi

Inai	nk you for your email.
We	choose LKK Auto Consultants Pte Ltd
Tha	nk You and Best Regards
Alv	in Wee
	A Automotive Pte Ltd
	oh Guan Road East (Enterprise Hub) #01-36
	<u>apore 608580</u> +65 8778 3636
	+65 6200 0600
www	v.amaauto.sg
are her	DENTIAL NOTE: The information contained in this email is intended only for the use of the individual or entity named above and may contain ation that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you reby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, immediately notify the sender and delete the mail.
111101	rivacy Policy Notice: AMA Automotive Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is itted/required by laws, our third party service providers and agents (acting on our behalf).
On T	hu, Sep 19, 2019 at 2:35 PM Helene Phua < helene phua@sg.msig-asia.com > wrote:
Hi,	
Wer	refer to your email dated 19/09/2019.
Pleas	se choose one surveyor from the list that you wish for us to appoint to and at the
- 1 - 34	se choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:
11	LVV Auto Consultante Description
1)	LKK Auto Consultants Pte Ltd
2)	Formteam Consultancy Pte Ltd

- 3) Automobile Inspection Services Pte Ltd
- STA Inspection Pte Ltd
- Appraisal VP Pte Ltd
- AutoProbe Consultants
- MSIG In-House Surveyors

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

<ol> <li>Kalvin Ang</li> </ol>	6) Chow Bo Xiong	
2) Kenneth Kong	7) E C Looi	
3) Marcus Chua	8) Daniel Chan	
4) Ng You Han	9) Victor Png	
5) Gary Soon	10) Samuel Phun	

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

### (a) \*Fast lane settlement is not applicable for cases that liability is in dispute\*

(b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: <a href="mailto:motorsurvey@sg.msig-asia.com">motorsurvey@sg.msig-asia.com</a>

<sup>\*</sup>This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor\*

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene\_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

A Member of MSSAD INSURANCE GROUP

From: AMA Automotive [mailto:ama.claim@gmail.com]

Sent: Thursday, 19 September 2019 2:12 PM

To: Motor Survey <motorsurvey@sg.msig-asia.com>; Claims <claims@sg.msig-asia.com>

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKW7008G & SLZ7452D ON

19/09/2019

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sirs/Madam

Please find the attached PRS Letter and GIA report for your perusal. Kindly let us have the Pre-Repair Surveyor Lists and advise me about the liability of this accident case.

Take note that the Repair Estimate will be ready upon the Pre-Repair Survey.

Workshop

AMA Autocare Pte Ltd

Address	â	36 TOH GUAN ROAD EAST #01-36 ENTERPRISE HUB SINGAPORE 608580	
Contact Person	1	Alvin Wee HP: 8778 3636 / 9017 3393 / Office: 6200 0600	
Thank You and Best Regard	s		
Alvin Wee			
AMA Automotive Pte Ltd		#01.26	
36 Toh Guan Road East (Ente Singapore 608580	erprise Hub)	#01-30	
Hp: +65 8778 3636			
Tel:+65 6200 0600			
www.amaauto.sg			

CONFIDENTIAL NOTE: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail.

Data Privacy Policy Notice: AMA Automotive Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy.

This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf).

#### CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



### AMA AUTOCARE PTE LTD

36 Toh Guan Road East #01-36 Enterprise Hub Singapore 608580

Email :AMA.CLAIM@GMAIL.COM

(201735370W)

Our Ref: SKW7008G Your Ref: To be advised

19/09/2019

MSIG INSURANCE (SINGAPORE) PTE LTD 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

BY EMAIL ONLY

Dear Sir,

RE: PROPERTY DAMAGE CLAIM

CLAIMANT NGO SIANG KIN BENJAMIN
ACCIDENT INVOLVING SKW7008G & SLZ7452D ALONG THE ADELPHI BASEMENT 4 CARPARK
ON 17/09/2019 AT ABOUT 1830HRS
PRE-REPAIR SURVEY NOTICE

- 1 We are instructed by NGO SIANG KIN BENJAMIN, the owner of motor vehicle no SKW7008G which was involved in the aforesaid accident.
- As a result of the accident, Our Client's vehicle has been damaged. Before We proceed to repair the damaged vehicle, Please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle, M/s AMA Autocare Pte Ltd at 36 Toh Guan road East #01-36 Singapore (608580) and kindly arrange with Mr. Alvin at 8778 3636.
- 3 If We do not receive any reply from you within the stipulated timeline. We shall proceed to repair the vehicle without further reference to you.



Alvin Wee (65) 8778 3636 AMA AUTOCARE PTE LTD

Enterprise Hub 36 Toh Guan Road East #01-36 S(608580)

### Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Friday, 27 September 2019 12:35 PM

To:

AMA Automotive; SUR

Subject:

RE: SKW 7008G-DOA:17/9/2019

Dear Alvin,

#### WITHOUT PREJUDICE

Noted with thanks.

# Kindly send Final invoice and all supporting documents directly to MSIG

Best Regards,

Veron Chen | Case Handler

#### LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: AMA Automotive <ama.claim@gmail.com>

Sent: Friday, 27 September 2019 11:20 AM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: Re: SKW 7008G-DOA:17/9/2019

Dear Veron

Thank you for your email.

Lump Sum \$2750 @ 4 working days confirmed.

LOD sent to who?

#### Thank You and Best Regards



#### Alvin Wee

AMA Automotive Pte Ltd

36 Toh Guan Road East (Enterprise Hub) #01-36

Singapore 608580 Hp: +65 8778 3636

Best Regards,

www.amaauto.sg
×
CONFIDENTIAL NOTE: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, yo are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail.
Data Privacy Policy Notice: AMA Automotive Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf).
On Fri, Sep 27, 2019 at 10:58 AM Veron Chen (LKKAuto) < veronchen@lkkauto.com > wrote:
Dear Sir,
WITHOUT PREJUDICE
Offer Lump Sum \$2750 @ 4 working days.
Offer Lump Sum \$2750 @ 4 working days.
PARTS-\$3133.60 (less 30%)=\$2193.52
SN-\$40
LABOUR-\$1260
TOTAL-\$3493.52 (less 20%)=\$2794.82
Please check and confirm
riease check and continu

# Veron Chen | Case Handler

# LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Bik 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

	ACCIDENT STATEMENT
Date Of Report	18/09/2019 11:10
Date Of Accident	17/09/2019 18:30
Exact Location Of Accident	AT THE ADELPHI BASEMENT 4 CARPARK
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SKW7008G
Insured/Policyholder	
Name Of Registered Owner	NGO SIANG KIN BENJAMIN
NRIC No	S8402963G
Email Address	BEN_NGO03@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96540308
Alternative Phone No	OFFICE-96540308
Vehicle Particulars	
Manufacturer	NISSAN
Model	QASHQAI-1.2 DIG-T CVT ABS 2WD 5DR (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	

Name of Insurance Company DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number MT/00340175/02

Cover Note Number

#### Driver

Name of Driver NGO SIANG KIN BENJAMIN

NRIC No S8402963G Date Of Birth 10/02/1984 Occupation INDOOR Date Of Driving Pass 08/01/2005

Driving Experience 14 YEARS AND 8 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96540308

Fax Number

Contact Number OFFICE-96540308

EMail Address BEN\_NGO03@HOTMAIL.COM

30 SEGAR ROAD Address

#06-05

677721 Postcode

Was driver an employee of the Insured's Company NO

OWNER If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

SIDE SWIPE Type Of Accident

CLEAR Weather Conditions

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) 2

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

YES Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

**Details of Police Action** 

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

Please refer to the attached Sketch Plan for the accident details.

Attachment(s)

Are accident photos available for attachment?

YES

NO

NO

1

NO

NO

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLZ7452D

TOYOTA WHITE Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

DAVID Name of Driver

NRIC/Passport Number

Contact Number 96717789

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

Passenger 1

NAME:

GENDER: :

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of .
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (Iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Bignature

Date & Time: 18/09/2019


- 1- --

Oriver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

#### Sketch Plan Pg. 2



#### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

KUDENT	OCLOPE	d in	THE ANELPY	II BANGHEN	n 4 c	ナクサイヤン	5(179)	FO
							A CHRPAR	
CARPARI	K 107	AND	Course				IG THE	
Passeno	FO FO	T/40						

DECLARATION

Collect Woulders

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 18/09/19

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



AMA Autocare Pte Ltd Enterprise Hub 36 Toh Guan Road East #01-36

T: 87783636

Page No. 1

SKW7008G Nissan Qashqai 1.2A Vehicle No.

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	ADJUSTMENT
	PARTS (LIST ITEMS)			100
1	Bonnet		1067.0	
2	Bonnet hinge@\$107.00			0×100
1	Front bumper		630 930.0	
1	Front lower bumper			5 vv
1	Front bumper retainer LH		108.0	
1	Front bumper undercover		383.0	D × VW .
1	Fog lamp LH			DECE
1	Fog lamp chrome cover LH		96.50 316.0	
1	Fog lamp bracket LH			Nun
1	Headlamp LH		886.0	000
1	Headlamp panel		568.0	NNN
1	Front fender LH		677 10980.0	011-
1	Front fender inner shield LH		120 220.0	ole
1	Front fender wheel arch LH		276.0	ole-
1	Front sport rim LH		680.0	0 × )
1	Front shock absorber LH		692.0	0 × ( ×
1	Front wheel bearing LH		378.0	2 × 10
1	Front stabilizer link LH		248.0	0× ( 0
1	Front knuckle arm LH		492.0	ok \
1	Front lower control arm LH		482.0	312 1
			10174.0	0.0
		less	20% 2034.8	0 20% 0.0
			8139.2	
	SPECIAL NETT ITEMS			
1	Front bumper clips		60.0	3000
1	Headlamp clips		70.0	xnn
1	Front fender inner shield clips		40.0	0/000
1	Front bumpe undercover clips		40.0	X n .
		TOTAL PARTS	8349.2	0.0



AMA Autocare Pte Ltd Enterprise Hub 36 Toh Guan Road East #01-36

E: ama.claim@gmail.com

T: 87783636

#### Page No. 2

Vahiela Na SYNTHONGS Nisson Oschool 1 24

s/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; replace damaged parts and components	2000.00	500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1600.00	600
3	To clear fault code with diagnostic computer and reset to specifications	250.00	100
4	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	200.00	20
5	To remove and refix/replace rear trims, garnish and fittings so as to facilitate repairs at rear compartment	180.00 ×	WW.
6	To provide anti-rust treatment on affected areas	210.00	30
	Labour Total :	4440.00	
	TOTAL (PARTS & LABOUR):	12789.20	

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illigal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signifure:

Tayfur 9749749 20/1/12 4pm

#### LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19016620/T1VF3N2

Date:

02/10/2019

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

80464803QMX

Claimant Vehicle No:

SKW7008G

Insured Vehicle No:

SLZ7452D

Date of Loss:

17/09/2019

Nature of Claim:

TP

Claim No: 606138

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKW7008G

Make & Model:

NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR Engine No:

HRA2190888A

Reg. Date:

12/11/2015 (Man. Year: 2015)

Chassis No: Odometer:

SJNFEAJ11U1489289

Colour:

Grey 1197 cc

36024 km

**Engine Capacity:** Market Value/New Car

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

78.50

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size: Front Left Side:

215/60 R17 Continental 6 mm Rear Tyre Size:

12,789.20

215/60 R17

Rear Left Side: Rear Right Side: Continental 6 mm Continental 6 mm

Front Right Side: Continental 6 mm The above values represent the remaining tyre treads depth

Parts Miscellaneous Item		Repairer's 8,349.20 0.00	Adjuster's 2,233.52 0.00	6,115.68 0.00	Diff % 73.25
Labour Paintwork Labour		4,440.00 0.00	1,260.00	3,180.00 0.00	71.62
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	12,789.20	3,493.52	9,295.68	72.68
	Approved Total (Overridden) (S\$)		2,750.00		

INSPECTION

Date of Assignment:

20/09/2019

Date Inspected:

20/09/2019 Inspected At:

Nett Amount (S\$)

Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36

10,039.20

Singapore 608580

2,750.00

Estimated Period of Repair:

4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

Referen	ce		
Part Source	MRM-SG	Version: 1.0 (Last Synchronised: 01 Oct 2019)	
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitte	d, no print-code for SKW7008G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running pag- numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info	tems/values	not in reference catalogue are prefixed with an asterisk *.	

D			1-1	D-4	
Kec	omr	nen	IOEG	Parts	•

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,067.00 FL	*-FL
2	2		*BONNET HINGE	Not Necessary	214.00 FL	*-FL
3	1		*FRONT BUMPER	Deformed	930.00 FL	*630.00 FL
4	1		*FRONT LOWER BUMPER	Not Necessary	730.00 FL	*-FL
5	1		*FRONT BUMPER RETAINER LH	Deformed	108.00 FL	*108.00 FL
6	1		*FRONT BUMPER UNDERCOVER	Not Necessary	383.00 FL	*-FL
7	1		*FOG LAMP LH	Cracked	340.00 FL	*340.00 FL
8	1		*FOG LAMP CHROME COVER LH	Cut	316.00 FL	*96.50 FL
9	1		*FOG LAMP BRACKET LH	Not Necessary	184.00 FL	*-FL
10	1		*HEADLAMP LH	Cracked	886.00 FL	*886.00 FL
11	1		*HEADLAMP PANEL	Not Necessary	568.00 FL	*-FL
12	1		*FRONT FENDER LH	Bent	980.00 FL	*677.10 FL
13	1		*FRONT FENDER INNER SHIELD LH	Deformed	220.00 FL	*120.00 FL
14	1		*FRONT FENDER WHEEL ARCH LH	Deformed	276.00 FL	*276.00 FL
15	1		*FRONT SPORT RIM LH	Not Necessary	680.00 FL	*-FL
16	1		*FRONT SHOCK ABSORBER LH	Not Necessary	692.00 FL	*-FL
17	1		*FRONT WHEEL BEARING LH	Not Necessary	378.00 FL	*-FL
18	1		*FRONT STABILIZER LINK LH	Not Necessary	248.00 FL	*-FL
19	1		*FRONT KNUCKLE ARM LH	Not Necessary	492.00 FL	*-FL
20	1		*FRONT LOWER CONTROL ARM LH	Not Necessary	482.00 FL	*-FL
21	1		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
22	1		*HEADLAMP CLIPS	Not Necessary	70.00 FS	*-FS
23	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	40.00 FS	*10.00 FS
24	1		*FRONT BUMPER UNDERCOVER CLIPS	Not Necessary	40.00 FS	*-FS
F=Fn	inchise	part. S=SpcN	lett. L=ListItemDisc.	-		
				Sub Total (S\$)	10,384.00	3,173.60
			- List Item Discount on L Item		2,034.80	940.08
				Total Parts (S\$)	8,349.20	2,233.52

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS	New	2,000.00	500.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED	New	1,600.00	600.00
3	TO CLEAR FAULT CODE WITH DIAGNOSTIC COMPUTER AND RESET TO SPECIFICATIONS	New	250.00	100.00
4	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	200.00	30.00
5	TO REMOVE AND REFIX/REPLACE REAR TRIMS,GARNISH AND FITTINGS SO AS TO FACILITATE REPAIRS AT REAR COMPARTMENT	New	180.00	0.00
6	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	210.00	30.00
	Gross Labou	Gross Labour Cost (S\$)		1,260.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >