(c3) msg 19016630/usf3n2 (08/11/13) REF: SLX5-7738 YrRegn: 3 118 Veh No: Date: From: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Estimated Cost: OD / THY WS / TP RES / OD RES / EVA SLX5-773B Make: To Inspect Vehicle No: Insured / Std / NI / NA Colour at Workshop m/s T/Radio: Insured / Std / NI / NA Sp.Reading of 5KM 8970 L Eng/No: Insured: MNTBBAB 172003/656 C/No: Policy No. Gen. Cond Goo Claims No. Steering: Korder / Jammed / Leaked / Burnt or Excess: Sum Insured: Interder / Jammed / Leaked / Burnt or (Client's Record) Modi: Nik / SARIm / STD A/Rim or Make of Veh: Tyre Size: (Policy Condition) 9 B8 / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / N/S OIS Remark: The veh had commenced its repair at the time of inspection TOYO / YOKO or Rear Front Bal. or Market Value: R/Bal. R/Bal. Consistent?: Yes or No IDAC Accident Rport: L/Bal. L/Bal. Consistent?: Yes or No GYA / PR Seen: 9 D.O.A. Res.: Yes or No Est. Repairs: 3 Val.: Yes or No Survey held at Lum Sum: Des. of Damages : Frt | Rear | O/S | N/S | U/C | Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collision Person Contacted: 5BR938B Action / Instruction Date / Time Days Of Repair: Preli. Report Survey Fee: Resurvey No. of Trip: Final Report 150 Transportation: Date/Time, File Return to? Add Fee: Site Insp (\$ S + RS.__SI Interview (\$ Photos Tech. Invs (\$). Others Report Format: 2,200/- 4/5) ump Sum / I.B.I: (\$ Weekend (\$ 161 TOTAL

DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD ,DOA: 19/09/2019 ,SLX 5773B (TP VEHICLE), SLM 8970L (OI VEHICLE)

Shirley Hiew (LKK Auto)

Mon 23/9/2019 2:02 PM

To: motorsurvey@sg.msig-asia.com <motorsurvey@sg.msig-asia.com>

Cc: KKLau <kklau@lkkauto.com>; Accounts (LKKAuto) <account@lkkauto.com>; SUR <sur@lkkauto.com>

🛮 1 attachments (686 KB)

TP GIA REPORT.pdf;

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SLX 5773B at M/s: FASTECH AUTO PTE LTD,1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 20/09/2019.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources


Audi A3 Sedan/Sportsback Owners - Check In


Nissan QashQai 2014

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD! Volkswagen Passat Variant 2.0A TSi R-Line.



Immaculate Family Express. The Ultimate Dad's Car? GTI Performance, Huge Space Direct Owner StarAd







Nissan Sylphy 1.6A Premium

\$72,777

\$7,450 /yr

21-May-2018

1.598 cc

1.598 cc

10,428 km

Sedan Available

Cheapest In Town. Car In New Condition, Still Have New Car Smell. 5 Years Unlimited Mileage Warranty From Agent, Low Mileage Done....

Posted: 01-Sep-2019 Tags: 2018 Nissan Sylphy, 2018 nissan sylphy, Nissan Sylphy,



Nissan Sylphy 1.6A

\$74,800

\$7,170 /yr

29-Dec-2018

Sedan

Available

100% Loan Available With Our Flexible In-House Loan Options! Warranty By Tan Chong Motors Till Dec 2021. Premium Pearl White With...

Jack Cars Enterprise Pte Ltd

Posted: 23-Aug-2019 Tags: 2018 Nissan Sylphy, 2018 nissan sylphy, Nissan Sylphy, nissan sylphy, Nissan, Sylphy, sylphy, Used Nissan



Infratint Solar Film Package

Infratint solar film package available from \$288. Car owners can block up to 99.6% of UV rays, and 99% of IR rays.

More info about this product



Nissan Sylphy 1.6A

\$75,000

\$7,610 /yr

28-Jun-2018

1.598 cc

27,000 km

Available Sedan

Loan Interest At 2,28%, Extremely Well Maintained And Fully Agent Maintained. Comes With First 3 Years Agent Warranty. This Beast D...

Tags: 2018 Nissan Sylphy, 2018 nissan sylphy, Nissan Sylphy, nissan sylphy, Nissan, Sylphy, sylphy, Used Posted: 17-Jul-2019

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Reg Date

Veh Type

For old advertisements, view Expired ads

20 v results/page

Compare

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

https://www.sgcarmart.com/used_cars/listing.php?MOD=Nissan+Sylphy&PRC=0&DEP=0&RGD=201... 20-Sep-19

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	297B
Vehicle Details	
Vehicle No.:	SLX5773B
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Sep 2019
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.6 CVT
Primary Colour:	Brown
Manufacturing Year:	2018
Engine No.:	HR16923012C
Chassis No.:	MNTBBAB17Z0031656
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$16,572.00
Original Registration Date:	29 Mar 2018
First Registration Date:	29 Mar 2018
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$16,572.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Mar 2028
PARF Rebate Amount:	\$12,429.00
Intended COE Rebate Details	
COE Expiry Date:	28 Mar 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,830.00
COE Rebate Amount:	\$33,089.00
Total Rebate Amount:	\$45,518.00

The information contained herein is correct as at 20 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.		
	ACCIDENT STATEMENT	
Date Of Report	20/09/2019 11:17	
Date Of Accident	19/09/2019 14:45	
Exact Location Of Accident	AT 1 ELLIOT RD CARPARK	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLX5773B	
Insured/Policyholder		
Name Of Registered Owner	HO KOK LEUNG	
NRIC No	S1176297B	
Email Address	NOEMAIL	
Mobile Phone No	(LOCAL) +65-90686061	

OFFICE-90686061

Alternative Phone No
Vehicle Particulars

Manufacturer Model	NISSAN
Model	SYLPHY

Exact Purpose for v	which vehicle	was I	being	used	at
time of accident					

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 1800032793-01

Cover Note Number

Driver

Name of Driver HO SHAU YUE, LESTER (HE XIUYU)

 NRIC No
 S9136026H

 Date Of Birth
 01/10/1991

 Occupation
 OUTDOOR

 Date Of Driving Pass
 16/01/2012

Driving Experience 7 YEARS AND 8 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-90686061

Fax Number

Contact Number

EMail Address NOEMAIL

Address

BLK 114 BEDOK RESERVOIR RD #04-150

Postcode

470114

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

CHILDREN

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

3

Passenger 1

NAME:

: VALERIE NG

GENDER:

: FEMALE

Passenger 2

NAME:

: AUDREY LEE

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

WITH DRIVER

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLM8970L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the filinerary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of -
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the socident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (IV) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information to collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Oriver's Signature (If driver is not the policyholder) Data & Time: Reporting Centre Personnel's Signature Name: NRIC/Fits No.:

CANACINALIPENTAL VI

Accident Sketch Plan

SKETCH PLAN



A - SLX 5773B B - SLM 8970L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

N.	the	5-	tate		donte	and	time	. 1	wis	dr	iving	14	welie
9	at	1	EII	ot	Road	conf	urk.	s s	top	my	veh.	Je	to
et	the	pa	seny	ers	to	be a	lighted.	Su	ddent	ve	hile	. 6	revers
nd	[n:	t	in	m	from	nt RI	4 Side						
												_	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

tool

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Not Adorad 20/9/19 4/5#2200/

FASTECH AUTO PTE LTD BLK1 KAKI BUKIT AVE 6 #01-46,48,50 AUTOBAY SINGAPORE 417883

QTY	PARTICULAR
1 PCS	FRONT BUMPER 47650
1 PCS	FRONT BUMPER SPONGE 206.30
1 PCS	FRONT BUMPER REINFORCEMENT 455-120
1 PCS	FRONT BUMPER SIDE RETAINER O/S
1 SET	FRONT BUMPER CLIPS 30-00
1 PCS	FRONT BUMPER FOG LAMP O/S 321-65
1 PCS	FRONT BUMPER FOG LAMP COVER O/S
1 PCS	WIPER WASHER TANK
1 PCS	FOR SUPPORT PANEL
1 PCS	HEADLAMP OLS 744, 10

\$768.30 \$211.50 \$488.20 \$95.50 X \$50.00 \$388.20 \$211.60 \$677.80 X \$1,099.20 \$4,245.60

LABOUR CHARGES
TO CHECK WIRING
TO SPRAY RUSH PROOFING
TO REFILL AIR CON GAS
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

TOTAL \$

LKK Auto Consultants hence notify the Papares of the following:

- pelors after spray painting
- in a solar gamagau partis) during resurvey
- « Parts prices, are subject to confirmation.
- . Thin any lavey is on a "Without Projectice" basis
- + No. 19 Institution(s) is allowed
- Suppressentiate nam(s) must be resurveyed and is suppressent in first approval from Insurance Company

Acknowledged by Requirer

Signa Life:

i in

2349.40

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/MSG19016630/USF3N2

Date:

04/10/2019

REFERENCE

Handling

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

29114756

Insurer: Claimant

SLX5773B

Insured Vehicle No:

SLM8970L

Vehicle No: Date of Loss:

19/09/2019

Nature of Claim:

TP

Claim No: 606357

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLX5773B

Make & Model:

NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A)

Engine No:

HR16923012C

27291 km

Reg. Date:

29/03/2018 (Man. Year: 2018)

Chassis No: Odometer:

MNTBBAB17Z0031656

Colour:

Brown

Engine Capacity:

1598 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Yes Engine Modification:

Front Tyre Size: Front Left Side:

195/60R16

Rear Tyre Size: Rear Left Side:

No

195/60R16 Bridgestone 6 mm

Front Right Side:

Bridgestone 6 mm Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,245.60	2,114.46	2,131.14	50.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	650.00	950.00	59.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,845.60	2,764.46	3,081.14	52.71
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	5,845.60	2,200.00	3,645.60	62.36
+ GST 7.00/7.00% (S\$)	409.19	154.00	255.19	62.36
Nett Amount (S\$)	6.254.79	2.354.00	3,900.79	62.36

INSPECTION

Date of Assignment:

02/10/2019

Date Inspected:

20/09/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #01-46/48/50

Autobay

Singapore 417883

Estimated Period of Repair:

3.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.