

22/03/2002

ASS. REC. BY:

Surveyor: RaSuL

REF:

CS/ASM19016555/RI+d300

Special Instruction:

ASSIGNMENT (Office)

FROM (Person):

Stacey Ng

of

ASM (AXA)

Date/Time:

11:34am @ 20/9/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMF 5760X

Insured:

at Workshop in/s

Komoco Motor

Tel:

907 00151

of

253 Alexandra Road

Policy No:

Claim No:

39M02050

Sum Insured:

Excess:

NIL

Make of Veh:

(Client's Record)

D.O.A.

17/9/19CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:57pm @ 20/9/19

Person Contacted:

GedyVehicle IN/OUT

Date/Time	Action/Instruction
	<u>Johnnie</u>
	<u>SMF-5760X-X</u>
<u>23/9</u>	<u>Upload VMA Smart claim 1A.</u>
	<u>Supplementary approve</u>
	<u>Part by Part \$3,268.16 (Red: 4350.88, 57%)</u>

ASS. REC BY:

REF:

ARM(CAXA)

340T

ASSIGNMENT

From:

Date: 2019/2019

Veh No:

SMF 5760X

Yr Regn: 2018 / NOV

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SMF 5760X

Make:

HYUNDAI ELANTRA 1.6 GLS AT 1591

at Workshop m/s

KOMOCO Motor

Colour:

BLUE

A/C: Insured / Std / NI / NA

of

253 Alexandra Road

Sp. Reading

10263

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

KM HD 84 / CM JU 739928

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

NIL

(Client's Record)

Steering: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Eddy 90700151

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F: 195/65R15

R:

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NEXEN

Bal. or Market Value:

66k

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

6 mm

R/Bal.

6 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6 mm

L/Bal.

6 mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

12/09/19

D.O.I.

20/09/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

KOMOCO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Frt

The U/C / Chassis frame / Body Structure affected due to collision.

☒ CA

REV

REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Attach DV & Final Bill

RECEIVED 31 OCT 2019

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 4

1) 30/10 typist

☒

Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

200

Transportation:

S + RS, SI

Photos

Others

TOTAL

200

Report Format:

OD

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Lump Sum / L.O.C:

3268.16



Service Request Details

Claim

S9M020SQ

Reference

None 

Loss Date

September 17, 2019

Report Date

Sep 17, 2019 2:14:22 PM

Request Date

September 20, 2019

Due Date

September 27, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SMF5760X

Model

ELANTRA AD 1.6 GLS AT

Service Address

, , ,

Primary Contact/Insured

KHOO KEH HOCK

BLK 111 JURONG EAST STREET 13, #12-336, 600111, Singapore

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

OD XS: NIL

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

VISHNU BATHAM Shekhar

From: Eddie Ang Khea Chwee <eddieang@hyundaimotors.com.sg>
Sent: Thursday, September 19, 2019 6:33 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: Heng Swee Hee; Chris Ang; Muhammad Asyraf Noor Azman
Subject: [EXTERNAL] SMF5760X - HYUNDAI ELANTRA
Attachments: Scan_20190919_182210.pdf

Categories: Shekhar

Good Evening to all,

Kindly take note that the above attached for your attention and arrange for survey at our workshop. Car is in Komoco.

Thank you so much for your time

Regards,
Eddie Ang
Komoco Motors Pte Ltd
Mobile: +65 90700151

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	340I
Vehicle Details	
Vehicle No.:	SMF5760X
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Sep 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT (AMS)
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	G4FGJU249880
Chassis No.:	KMHD841CMJU739928
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$10,937.00
Original Registration Date:	17 Nov 2018
First Registration Date:	17 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$10,937.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Nov 2028
PARF Rebate Amount:	\$8,202.00
Intended COE Rebate Details	
COE Expiry Date:	16 Nov 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$28,199.00
COE Rebate Amount:	\$25,800.00
Total Rebate Amount:	\$34,002.00

The information contained herein is correct as at 23 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/09/2019 15:49
Date Of Accident	17/09/2019 08:30
Exact Location Of Accident	BLK 113 JURONG EAST ST 13 OPEN CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF5760X
Insured/Policyholder	
Name Of Registered Owner	KHOO KEH HOCK
NRIC No	S0125340I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98337238
Alternative Phone No	OFFICE-98337238

Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P2217104
Cover Note Number	

Driver

Name of Driver	KHOO KEH HOCK
NRIC No	S0125340I
Date Of Birth	31/03/1950
Occupation	INDOOR
Date Of Driving Pass	15/09/1971
Driving Experience	48 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98337238
Fax Number	
Contact Number	OFFICE-98337238
EMail Address	NOEMAIL

Address	BLK 111 JURONG EAST ST 13 #12-336 SINGAPORE
Postcode	600111
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTCAH SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS9815P
Vehicle Make/Model/Colour	HYUNDAI AVANTE WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report **correctly** the details of the accident to speed up the claims process.
- 2 This Form must be **completed by the Policyholder and/or the Authorised Driver**.
- 3 Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 **Any false reporting may be referred to the Police for investigation.**
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature
Date & Time


17/9/19

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/Fin No

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above time, when I was about to drive off from the car park. I check there was no car traffic was clear. I slowly inch out. Suddenly car nos SL9815P appear from nowhere & driving fast & hit the front right side of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

o/2
17/9/19

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No:



KOMODO MOTORS PTE. LTD.

253 Alexandra Road #01-01 Singapore 120302
TEL: (65) 6473 3588 FAX: (65) 6472 7333 WWW.KOMODOTRADING.COM.SG
RCR NO: 1996092633

(GST REGISTRATION NO: MR-8500364-4)

Date : 19/09/2019

AXA INSURANCE PTE LTD

Attn: Claim Dept.

LKK Auto Care Pte. Ltd.
the Repairer of the vehicle
• To resurvey before after repair
• To display damaged parts in a bag for survey
• Parts prices are subject to final approval
• Third party survey is on a "without prejudice" basis
• No illegal modification (s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: **Estimate**

Date:

Vehicle number : **SMF5760X**
Make and model : **ELANTRA 1.6 4DR AUTO**
Registration Date : **17/11/2018**
Chassis number : **KMHD841CMJU739928**
Engine number : **G4FGJU249880**

Job No. : **2019034129**
Owner name : **KHOO KEH HOCK**
Date of Acc. : **17/09/2019**
Policy number : **P2217104**
Claim Type : **OD -Excess TBC**

Handwritten signature and date 23/9/19

Front Items :

				Estimate
1	CARRIER ASSY-FRONT END MODULE <i>? x su</i>	64101-F2000	\$	949.30 X
2	REINF ASSY-HEAD LAMP SUPT,RH <i>? cr</i>	64128-F2000	\$	24.00 ✓
3	BEAM COMPLETE-FR BUMPER <i>? x su</i>	64900-F2000	\$	695.80 X
4	PANEL ASSY-HOOD <i>repair</i>	66400-F2000	\$	1,910.30 X
5	GARNISH ASSY-RAD GRILLE,UPR <i>cut</i>	86356-F2000	\$	74.10 ✓
6	STRIP ASSY-FR BUMPER UPR <i>? x su</i>	86357-F2000	\$	29.40 X
7	GRILLE ASSY-RADIATOR <i>sea</i>	86350-F2000	\$	460.20 ✓
8	COVER ASSY-FR BUMPER <i>de</i>	86510-F2000	\$	474.40 ✓
9	BRACKET-FRT BUMPER MOUNTING,RH <i>? cr</i>	86554-F2000	\$	18.80 ✓
10	CAP ASSY-FR BPR <i>sea</i>	86588-F2000	\$	10.20 ✓
11	LIP ASSY-FRONT BUMPER <i>? x su</i>	86591-F2000	\$	30.20 X
12	COVER-FR BUMPER BLANKING,RH <i>cr</i>	86564-F2000	\$	28.30 ✓
13	DUCT ASSY-AIR CURTAIN,RH <i>? x su</i>	86568-F2000	\$	29.40 X
14	GUARD ASSY-FRONT WHEEL,RH <i>cut</i>	86812-F2001	\$	85.70
15	LATCH ASSY-HOOD <i>x su</i>	81130-F2910	\$	129.90 X
16	LAMP ASSY-HEAD,RH <i>cr</i>	92102-F2030	\$	1,198.80 ✓
17	SUNDRIES <i>x su</i>		\$	100.00 X
			\$	6,248.80

Handwritten: Rasul Hp 90010068

Handwritten: 4-5 days P/P

Handwritten: 20/09/19 @ 1600

Handwritten: EXCESS: NIL

Handwritten: Authorised

Handwritten: Resurvey before part

Less 20% Discount \$ 1,249.76
Total \$ 4,999.04

Body & Paint Repairs:

		Estimate
1	TO CARRY OUT BODY REPAIR	\$ 1,280.00 <i>640</i>
2	TO COMPLETE PUTTY AND SPRAY AFFECTED AREAS	\$ 1,120.00 <i>560</i>
		\$ 2,400.00

Labour Repair:

		Estimate
1	TO SUPPLY & INSTALL FRONT NUMBER PLATE (S.NETT)	\$ 40.00 <i>cut</i>
2	TO REFOCUS FRT HEADLAMP (S.NETT)	\$ 40.00 ✓
3	TO TOP UP A/C GAS (S.NETT)	\$ 140.00 <i>? x su</i>
		\$ 220.00

\$ 7,619.04
Less Excess
Total \$ 7,619.04
Add GST 7% \$ 533.33
Grand Total \$ **8,152.37**

Handwritten: 7707.60

Please let us know if there is any discrepancy or error in the Finalized Bill in the next Three (3) working days.
Kindly contact Mr. Asyraf at 90700157 if there is any error. If we do not hear from your good office we

12. 88-0271 JUNE 01 1988 100 PAGES \$12.00
 13. 88-0272 JUNE 01 1988 100 PAGES \$12.00
 14. 88-0273 JUNE 01 1988 100 PAGES \$12.00

Hp:90700151

**KOMOCO MOTORS PTE. LTD.**

KOMOCO SERVICE CENTRE
253 Alexandra Road
#01-01 Singapore 159936
T (65) 6473 5588 F (65) 6472 1633
www.hyundaimotors.com.sg

KEMBANGAN SERVICE BRANCH
460 Changi Road
Singapore 419883
T (65) 6440 1131 F (65) 6440 0365

GST Ref No MR-8500364-4

Page No : 1

Date : 23/10/2019

To : AXA INSURANCE PTE LTD**8 SHENTON WAY,
#24-01 AXA TOWER,****SINGAPORE 068811****Tel : 6338 7288 Fax : 6338 2522****Email: customer.service@axa.com.sg****Attn :****Tax Invoice**

Invoice No : CGI-ASC-2019016854

Invoice Date : 23/10/2019

Repair Date : 17/09/2019

Our Ref : WSR-ALX-2019034129

Mileage : 10262

Term : 30 Days

Mode : Cash

Service Advisor : ANG KHEA CHWEE EDDIE

Your Ref : SMF5760X

Item	Description	Quantity	UOM	Discount (%)	Unit Price SGD	GST	Amount SGD
1	TO CARRY OUT ACCIDENT BODY REPAIRS			0.00		STD	640.00
2	TO SPRAY PAINT ON DAMAGED PORTIONS			0.00		STD	560.00
3	TO SUPPLY & RENEW FRONT NUMBER PLATE WITH FRAME			0.00		STD	40.00
4	REFOCUS BOTH FRONT HEADLAMP ASSY			0.00		STD	40.00
5	BRACKET-FRT BUMPER MOUNTING,RH	1	UNIT	20.00	18.80	STD	18.80
6	REINF ASSY-HEAD LAMP SUPT,RH	1	UNIT	20.00	24.00	STD	24.00
7	GARNISH ASSY-RAD GRILLE,UPR	1	UNIT	20.00	74.10	STD	74.10
8	GRILLE ASSY-RADIATOR	1	UNIT	20.00	460.20	STD	460.20
9	COVER ASSY-FR BUMPER	1	UNIT	20.00	474.40	STD	474.40
10	CAP ASSY-FR BPR	1	UNIT	20.00	10.20	STD	10.20
11	COVER-FR BUMPER BLANKING,RH	1	UNIT	20.00	28.30	STD	28.30
12	GUARD ASSY-FRONT WHEEL,RH	1	UNIT	20.00	85.70	STD	85.70
13	LAMP ASSY-HEAD,RH	1	UNIT	20.00	1,198.80	STD	1,198.80
14	ABSORBER-FRONT BUMPER ENERGY	1	UNIT	20.00	110.70	STD	110.70
Sub Total							3,765.20
Discount Amount							(497.04)
Total							3,268.16
Goods and Services Tax							228.77
7% GST(Tax on SGD 3,268.16@1.000000 = SGD 228.77)							
Rounding Adjustment							0.00
Total Amount With GST							3,496.93

RIGHT HERE, RIGHT CARE

**KOMOCO MOTORS PTE. LTD.**

KOMOCO SERVICE CENTRE
253 Alexandra Road
#01-01 Singapore 159936
T (65) 6473 5588 F (65) 6472 1633
www.hyundaimotors.com.sg

KEMBANGAN SERVICE BRANCH
460 Changi Road
Singapore 419883
T (65) 6440 1131 F (65) 6440 0365

GST Ref No : MR-8500364-4

Page No : 2

Tax Invoice

Invoice No : CGI-ASC-2019016854

Invoice Date : 23/10/2019

Item	Description	Quantity	UOM	Unit Price	GST	Amount
				SGD		SGD

Remark : AXA OWN DAMAGE CLAIM EXCESS NIL D V SIGN
INCIDENT DATE:17/09/2019
POLICY NOS:P2217104

Amount :SGD THREE THOUSAND, FOUR HUNDRED NINETY-SIX DOLLARS AND NINETY-THREE CENTS ONLY

Confidential



E. & O. E.

Komoco Motors Pte Ltd

Created By : AW001 23/10/2019 6:06:01 PM

Printed By : AW001 23/10/2019 6:08:24 PM

RIGHT HERE, RIGHT CARE



KOMOCO MOTORS PTE. LTD.

253 Alexandra Road #01-01 Singapore 159936
TEL (65) 6473 5588 FAX (65) 6472 1633 www.komoco.com.sg
RCB NO. 199609783R

REPAIR DISCHARGE AND SATISFACTION NOTE

Claim No. : _____

Policy No. : P2217104

Excess : N/A

I/We hereby acknowledge having received my/our vehicle bearing registration number SMF5700X from the repairer M/s Komoco Motors Pte Ltd that has repaired to my/our satisfaction and I/We agree that the cost of settlement for such repair invoiced to **AXA Insurance Singapore Pte Ltd** is in full and final discharge of my/our claim in respect of damages caused to the said vehicle as a result of accident/incident that occurred on

17.09.2019

In addition, I/We have no further claim on the above repairs in respect thereof.

Witnessed by repairer

Komoco Motors Pte Ltd

Date : 24.09.2019



Signature of Claimant/Company Stamp

Name : Choo Keh Hock

NRIC No. : S01253401

Date : 24.09.2019

REPAIR DISCHARGE AND SATISFACTION NOTE

Claim No. : _____

Policy No. : P2217104

Excess : N/A

I/We hereby acknowledge having received my/our vehicle bearing registration number SMF5700X from the repairer M/s Komoco Motors Pte Ltd that has repaired to my/our satisfaction and I/We agree that the cost of settlement for such repair invoiced to **AXA Insurance Singapore Pte Ltd** is in full and final discharge of my/our claim in respect of damages caused to the said vehicle as a result of accident/incident that occurred on

17.09.2019

In addition, I/We have no further claim on the above repairs in respect thereof.

Witnessed by repairer

Komoco Motors Pte Ltd

Date : 24.09.2019



Signature of Claimant/Company Stamp

Name : Choo Keh Hock

NRIC No. : S01253401

Date : 24.09.2019



KOMODO MOTORS PTE. LTD.
253 Alexandra Road #01-01 Singapore 119932
TEL: (65) 6472 3588 FAX: (65) 6472 1633 www.komodo.com.sg
RCA NO: 1866092833

(GST REGISTRATION NO: MR-8500364-4)

Date : 19/09/2019

AXA INSURANCE PTE LTD

Attn: Claim Dept.

Finalise

Vehicle number : **SMF5760X**
Make and model : **ELANTRA 1.6 4DR AUTO**
Registration Date : **17/11/2018**
Chassis number : **KMHD841CMJU739928**
Engine number : **G4FGJU249880**

Job No. : **2019034129**
Owner name : **KHOO KEH HOCK**
Date of Acc. : **17/09/2019**
Policy number : **P2217104**
Claim Type : **OD -Excess NIL**

Front Items :

				<i>Estimate</i>	<i>Revised</i>
1	CARRIER ASSY-FRONT END MODULE	64101-F2000	\$	949.30	Refit
2	REINF ASSY-HEAD LAMP SUPT,RH	64128-F2000	\$	24.00	\$ 24.00
3	BEAM COMPLETE-FR BUMPER	64900-F2000	\$	695.80	Refit
4	PANEL ASSY-HOOD	66400-F2000	\$	1,910.30	Refit
5	GARNISH ASSY-RAD GRILLE,UPR	86356-F2000	\$	74.10	\$ 74.10
6	STRIP ASSY-FR BUMPER UPR	86357-F2000	\$	29.40	Refit
7	GRILLE ASSY-RADIATOR	86350-F2000	\$	460.20	\$ 460.20
8	COVER ASSY-FR BUMPER	86510-F2000	\$	474.40	\$ 474.40
9	BRACKET-FRT BUMPER MOUNTING,RH	86554-F2000	\$	18.80	\$ 18.80
10	CAP ASSY-FR BPR	86588-F2000	\$	10.20	\$ 10.20
11	LIP ASSY-FRONT BUMPER	86591-F2000	\$	30.20	Refit
12	COVER-FR BUMPER BLANKING,RH	86564-F2000	\$	28.30	\$ 28.30
13	DUCT ASSY-AIR CURTAIN,RH	86568-F2000	\$	29.40	Refit
14	GUARD ASSY-FRONT WHEEL,RH	86812-F2001	\$	85.70	\$ 85.70
15	LATCH ASSY-HOOD	81130-F2910	\$	129.90	Refit
16	LAMP ASSY-HEAD,RH	92102-F2030	\$	1,198.80	\$ 1,198.80

Supplementary Front Items :

				<i>Estimate</i>	<i>Revised</i>
17	ABSORBER-FRONT BUMPER ENERGY	86520-F2000	\$	110.70	\$ 110.70
18	SUNDRIES		\$	100.00	None
			\$	6,359.50	\$ 2,485.20
	Less 20% Discount		\$	1,271.90	\$ 497.04
	Total		\$	5,087.60	\$ 1,988.16

Body & Paint Repairs:

				<i>Estimate</i>	<i>Revised</i>
1	TO CARRY OUT BODY REPAIR		\$	1,280.00	\$ 640.00
2	TO COMPLETE PUTTY AND SPRAY AFFECTED AREAS		\$	1,120.00	\$ 560.00
			\$	2,400.00	\$ 1,200.00

Labour Repair:

				<i>Estimate</i>	<i>Revised</i>
1	TO SUPPLY & INSTALL FRONT NUMBER PLATE (S.NETT)		\$	40.00	\$ 40.00
2	TO REFOCUS FRT HEADLAMP (S.NETT)		\$	40.00	\$ 40.00
3	TO TOP UP A/C GAS (S.NETT)		\$	140.00	None
			\$	220.00	\$ 80.00
			\$	7,707.60	\$ 3,268.16
	Less Excess				
	Total		\$	7,707.60	\$ 3,268.16
	Add GST 7%		\$	539.53	\$ 228.77
	Grand Total		\$	8,247.13	\$ 3,496.93

Please let us know if there is any discrepancy or error in the Finalized Bill in the next Three (3) working days.
Kindly contact Mr. Asyraf at 90700157 if there is any error. If we do not hear from your good office we



KOMOTO MOTORS PTE. LTD.

253 Alexandra Road #01-01 Singapore 119938
TEL: (65) 6473 3588 FAX: (65) 6472 1633 www.komoto.com.sg
RCS NO: 1966092R33

(GST REGISTRATION NO: MR-8500364-4)

Date : 19/09/2019

AXA INSURANCE PTE LTD

Attn: Claim Dept.

Supplementary

Vehicle number : **SMF5760X**
Make and model : ELANTRA 1.6 4DR AUTO
Registration Date : 17/11/2018
Chassis number : KMHD841CMJU739928
Engine number : G4FGJU249880

Job No. : 2019034129
Owner name : KHOO KEH HOCK
Date of Acc. : 17/09/2019
Policy number : P2217104
Claim Type : OD -Excess TBC

Supplementary Front Items :

		<i>Estimate</i>	
1	ABSORBER-FRONT BUMPER ENERGY <i>cm</i> / 86520-F2000	\$	110.70
		\$	110.70
	Less 20% Discount	\$	22.14
	Total	\$	88.56