

ASS. REC. BY:

REF:

03/PWD/9016673/Gcd3<sup>st</sup>

Special Instruction:

Senior:

GWO (GWO)

ASSIGNMENT (Office)

From (Person):

meimen

Vanessa Chan

of

FWD

Date/Time:

20/9/19 @ 1:37pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FC 6348H

Insured:

SMD7400H

at Workshop m/s

Ah Thua Motor

Tel:

9012 1588

of

Blk 1016, Yishun Ind. Park A # 01-228

Policy No:

PNP2018-00013085

Claim No:

1201900026258

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02/09/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:40pm @ 20/9/19

Person Contacted:

Payee

Vehicle

IN OUT

Date/Time

Action/Instruction

Johnny X

FC 6348H - X

SMD7400H - X

Dismantle: 25/9/2019

ASS. REC. BY:

Re.

REF: FWD

PRS

## ASSIGNMENT

From

Date:

20/9/2019

Veh No:

FC6348X

Yr Regn:

Apr / 84

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

FC 6348X

Make:

Yamaha RX-K C.C. 135

at Workshop m/s

Ah Hwei Motor

Colour

Black

A/C:

Insured / Std / NI / NA

of BK1016 - Yishun Ind. Park A # 01-

Sp. Reading

16552

T/Radio: Insured / Std / NI / NA

Insured:

228

Eng/No:

Policy No.

C/No:

13X - 0124

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or


Make of Veh:

Rayco @ 90121588

Modi: ☒ Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

4 mm

R/Bal.

4 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

4 mm

L/Bal.

4 mm

Est. Repairs:

4

days

Res.: Yes or No

D.O.A.

D.O.I.

20-09-19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

w/s

4:40pm

CA / REV / REP. / 24 HRS (up)

Des. of Damages: ☒ Frt / ☒ Rear / ☒ O/S / ☒ N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$3000 - \$4000

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

4

1)

☐

: Final Report

Resurvey No. of Trip:

1

Date/Time, File Return to?

Survey Fee:

2)

Add Fee:

☐

: Site Insp (\$)

Transportation:

Report Formed:

PRS

☐

: Interview (\$)

Photos

Lump Sum / T.E.J. (\$)

☐

: Tech. Inve (\$)

Other

☐

: West end (\$)

TOTAL

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Sep 2019 <a href="#">Edit Reg</a>		20 Sep 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Jasper Nai Zhi Hao, ID: S8512246J		
Main Claimant:	NUR RASYIDIN BIN ABIDIN, ID: S8115203I		
Vehicle Reg. No.:	FC6348H	Date of Loss:	02/09/2019 00:00 - :59
Claim Type:	TP / 1201900026258	Policy/Cover Note No.:	PNPV2018-00013085 (Comprehensive) Coverage: 03/10/2018 - 02/10/2019
Vehicle Reg. No. (Insured):	SMD7400H	Policy No. (Claimant):	
		Excess:	
Repairer:	Ah Hwa (HQ) BLOCK 1016 YISHUN INDUSTRIAL PARK A#01-228, 768758 Yishun - Tel:		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 01/10/2019]		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

**From:** venessa.chan@fwd.com  
**Sent:** Friday, 20 September 2019 1:37 PM  
**To:** admin-d@lkkauto.com; admin-a@lkkauto.com  
**Cc:** motorclaims.sg@fwd.com; clara.li@fwd.com  
**Subject:** ACCIDENT INVOLVING SMD7400H & FC6348X ON 02.09.2019 (Our Ref: 1201900026258 // Your ref: LWP/NRA/4338A/19/sm)  
**Attachments:** (FC6348X) PRI - LAWRENCE LEE & CO.pdf

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen & I will upload the documents accordingly.

Thank you

Best Regards,

Venessa Chan  
Administrative Assistant, Claims




**FWD Singapore Pte. Ltd.**

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E [venessa.chan@fwd.com](mailto:venessa.chan@fwd.com)

W [www.fwd.com.sg](http://www.fwd.com.sg)



**From:** Venessa Chan - SGUser  
**Sent:** Friday, September 20, 2019 1:35 PM  
**To:** 'sukmei@lawrencelee.com.sg'  
**Cc:** Motor Claims SG - SG Common; Lionel Tan Tian Pei - SGUser  
**Subject:** ACCIDENT INVOLVING SMD7400H & FC6348X ON 02.09.2019 (Our Ref: 1201900026258 // Your ref: LWP/NRA/4338A/19/sm)

WITHOUT PREJUDICE

Dear Suk Mei,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s **LKK Auto Consultant Pte Ltd**, to conduct the pre-repair survey (PRS) on your client's vehicle, FC6348X. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

*\*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com).*

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E [venessa.chan@fwd.com](mailto:venessa.chan@fwd.com)

W [www.fwd.com.sg](http://www.fwd.com.sg)



**From:** [sukmei@lawrencelee.com.sg](mailto:sukmei@lawrencelee.com.sg) [mailto:[sukmei@lawrencelee.com.sg](mailto:sukmei@lawrencelee.com.sg)]

**Sent:** Friday, September 20, 2019 10:46 AM

**To:** Venessa Chan - SGUser

**Cc:** Motor Claims SG - SG Common; Lionel Tan Tian Pei - SGUser

**Subject:** RE: ACCIDENT INVOLVING SMD7400H & FC6348X ON 02.09.2019 (Our Ref: 1201900026258 // Your ref: LWP/NRA/4338A/19/sm)

WITHOUT PREJUDICE

Dear Venessa,

We refer to your email dated 19.09.19.

Please be informed that our client objects to the motor surveyors proposed by you.

Our client proposes to use one of the 10 motor surveyors below to conduct the joint pre-repair survey as the single joint expert:

Jayson Liaw	Michael Ee
Chuah Poh Siong Gary	Teo Liak Hoo
Dave Chang	Danny Ho
Francis Ng	Fong Kok Heng

Michael Yap

Dennis Yap

Kindly revert within two (2) working days by fax 6533 3689 or email to [sukmei@lawrencelee.com.sg](mailto:sukmei@lawrencelee.com.sg).

Regards,

Suk Mei ([sukmei@lawrencelee.com.sg](mailto:sukmei@lawrencelee.com.sg))  
Secretary to Lee Wee Peng Lawrence  
Lawrence Lee & Co (UEN: 53159236K)  
133 New Bridge Road #13-05 Chinatown Point Singapore 059413  
tel. 6533 3680 fax. 6533 3689 email. [info@lawrencelee.com.sg](mailto:info@lawrencelee.com.sg)

This email is confidential and may be subject to legal privilege. If you are not the intended recipient, please delete this email and its contents/attachments immediately.

**From:** [venessa.chan@fwd.com](mailto:venessa.chan@fwd.com) <[venessa.chan@fwd.com](mailto:venessa.chan@fwd.com)>

**Sent:** Thursday, 19 September 2019 12:36 PM

**To:** [sukmei@lawrencelee.com.sg](mailto:sukmei@lawrencelee.com.sg)

**Cc:** [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com); [lionel.tan@fwd.com](mailto:lionel.tan@fwd.com)

**Subject:** ACCIDENT INVOLVING SMD7400H & FC6348X ON 02.09.2019 (Our Ref: 1201900026258 // Your ref: LWP/NRA/4338A/19/sm)

WITHOUT PREJUDICE

Dear Suk Mei,

We refer to your email dated on 18.09.2019 of the PRI Notice of your client's vehicle FC6348X.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT APPRAISAL PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

\*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

\*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com).

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




**FWD Singapore Pte. Ltd.**

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E [venessa.chan@fwd.com](mailto:venessa.chan@fwd.com)

W [www.fwd.com.sg](http://www.fwd.com.sg)



**From:** [sukmei@lawrencelee.com.sg](mailto:sukmei@lawrencelee.com.sg) [mailto:[sukmei@lawrencelee.com.sg](mailto:sukmei@lawrencelee.com.sg)]

**Sent:** Wednesday, September 18, 2019 4:10 PM

**To:** Motor Claims SG - SG Common

**Subject:** Notice of Accident (Your ref: Please advise // Our ref: LWP/NRA/4338A/19/sm)

Dear Sirs,

We refer to the above matter.

We enclose herewith our Notice of Accident for your attention.

Regards,

Suk Mei ([sukmei@lawrencelee.com.sg](mailto:sukmei@lawrencelee.com.sg))

Secretary to Lee Wee Peng Lawrence

Lawrence Lee & Co (UEN: 53159236K)

133 New Bridge Road #13-05 Chinatown Point Singapore 059413

tel. 6533 3680 fax. 6533 3689 email. [info@lawrencelee.com.sg](mailto:info@lawrencelee.com.sg)

This email is confidential and may be subject to legal privilege. If you are not the intended recipient, please delete this email and its contents/attachments immediately.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.



# LAWRENCE LEE & CO

Advocates & Solicitors

李伟平律师楼

UEN: 53159236K

133 New Bridge Road #13-05  
Chinatown Point Singapore 059413  
tel: 6533 3680 fax: 6533 3689

Your ref: please advise  
Our ref: LWP/NRA/4338A/19/sm

18 September 2019

FWD Singapore Pte. Ltd.

EMAIL

Dear Sirs

**NOTICE OF ACCIDENT PURSUANT TO THE NIMA PROTOCOL  
ACCIDENT ALONG WELLINGTON CIRCLE TWDS CANBERRA RD ON 02.09.19  
INVOLVING FC6348X & SMD7400H**

We are instructed by Mr Nur Rasyidin Bin Abidin to notify you of the abovementioned road traffic accident involving our client's vehicle registration number FC6348X and vehicle registration number SMD7400H owned by your insured and driven by him or his servant/agent at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

We do hereby notify you that our client's damaged vehicle may be inspected at the workshop at Ah Hwa Motor Servicing at Blk 1016 Yishun Industrial Park A #01-228 Singapore 768758 (contact person: Ah Hwa/Reyco, mobile phone: 9652 8606/9012 1588).

*Kindly revert within two (2) working days by fax 6533 3689 or email to [sukmei@lawrencelee.com.sg](mailto:sukmei@lawrencelee.com.sg).*

Yours faithfully



LEE WEE PENG LAWRENCE

Cc client

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/09/2019 15:44
Date Of Accident	02/09/2019 16:45
Exact Location Of Accident	ALONG WELLINGTON CIRCLE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FC6348X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NUR RASYIDIN BIN ABIDIN
NRIC No	S8115203I
Email Address	RAS.RASTA14@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91063398
Alternative Phone No	OFFICE-91063398

### Vehicle Particulars

Manufacturer	YAMAHA
Model	RXK-135CC (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5046206834-08
Cover Note Number	

### Driver

Name of Driver	NUR RASYIDIN BIN ABIDIN
NRIC No	S8115203I
Date Of Birth	14/05/1981
Occupation	INDOOR
Date Of Driving Pass	21/03/2011
Driving Experience	8 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91063398
Fax Number	
Contact Number	OFFICE-91063398
Email Address	RAS.RASTA14@GMAIL.COM

Address	APT BLK 429B YISHUN AVENUE 11 #02-360 SINGAPORE
Postcode	762429
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ROSZIANA BINTE AHMAD SANI GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 32 YISHUN ST 81 , POSTCODE: 768456 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8522999 - FAX NO: 68522239
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMD7400H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name	NUR RASYIDIN BIN ABIDIN
Approximate Age	38
Injuries Sustain	REFER POLICE REPORT
Injured person in which vehicle?	FC6348X
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	APT BLK 429B YISHUN AVENUE 11 #02-360 SINGAPORE
Postcode	762429

#### DETAILS OF INJURED PERSON 2

Name	ROSZIANA BINTE AHMAD SANI (PILLION)
Approximate Age	
Injuries Sustain	REFER POLICE REPORT
Injured person in which vehicle?	FC6348X
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	APT BLK 429B YISHUN AVENUE 11 #02-360 SINGAPORE
Postcode	762429

## Sketch Plan

### SKETCH PLAN


#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN

A hand-drawn sketch plan on grid paper showing the layout of the Wellington Primary School site. The school building is represented by a large rectangle at the bottom, with the text 'WELLINGTON PRIMARY SCHOOL' written below it. A road, labeled 'WELLINGTON ROAD' at the top, runs horizontally across the middle of the plan. A 'WELLINGTON CIRCLE' is indicated by a curved line on the right side of the road. Two proposed bus stops are marked: 'A' is a circle on the road near the circle, and 'B' is a rectangle on the road near the school. Arrows indicate traffic flow: a rightward arrow on the road above the circle, a leftward arrow on the road below the circle, and a downward arrow on the road near the school. A north arrow is located in the top right corner, pointing towards the top right. The text 'A: FC 6348X' and 'B: SMD 7400H' are written in the top right corner.

A: FC 6348X  
B: SMD 7400H

WELLINGTON ROAD

WELLINGTON CIRCLE

WELLINGTON PRIMARY SCHOOL

B:  $\text{SMO} \rightarrow \text{H}_2\text{O}$

WELLINGTON CIRCLE

WELLINGTON PRIMARY SCHOOL

Refer to police report.

I/We declare the foregoing particulars are true in every respect.

Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### Common Statement



**SINGAPORE  
POLICE FORCE**



T/20190905/2168

1 of 4

Police Station Of Origin:  
Yishun South N.P.C  
32 Yishun Street 81 SINGAPORE 768456  
Tel No: 1800-8522999

Report No. T/20190905/2168

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 05/09/2019 22:57		Vide Report No.: L/20190902/0089		Station Diary No.: 85	
<b>Informant's Particulars</b>					
Name of Informant: NUR RASYIDIN BIN ABIDIN			Address: APT BLK 429B YISHUN AVENUE 11 #02-360 SINGAPORE 762429		
ID Type / ID No.: NRIC NO / S81152031			Contact No.: Home/Office: Mobile: 91063398		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 38	Date of Birth: 14/05/1981	Type of Informant: Rider		
Race: Malay			Language:		Institution / School Name:
Occupation: Manufacturing engineering technician (general)			Driving Licence Information: Class: Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 02/09/2019 16:45	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 WELLINGTON CIRCLE CANBERRA ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FC6348X	Motorcycle	YAMAHA	RX-K	Black	Seriously Damaged	1
SMD7400H	Car					0

<b>Details of Vehicle Insurance</b>				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FC6348X	NTUC Income Insurance Co-Operative Limited	5046206834-08	01/06/2019	31/05/2020

**Common Statement**





**SINGAPORE  
POLICE FORCE**



T/20190905/2168

Police Station Of Origin:  
Yishun South N.P.C  
32 Yishun Street 81 SINGAPORE 768456  
Tel No: 1800-8522999

2 of 4

Report No. T/20190905/2168

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Rider</b>			
Name	NUR RASYIDIN BIN ABIDIN	ID No.	S8115203I
Related Vehicle	FC6348X (Motorcycle)	Contact No.	91063398
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	02/09/2019	Date Discharge	03/09/2019
No. of Days granted Medical Leave	05	Degree of Injury	Serious
<b>Pillion</b>			
Name	ROSZIANA BINTE AHMAD SANI	ID No.	S8839938B
Related Vehicle	FC6348X (Motorcycle)	Contact No.	91053244
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	02/09/2019	Date Discharge	02/09/2019
No. of Days granted Medical Leave	04	Degree of Injury	Slight

**Brief Details.**

On 02/09/2019 at around 4.45pm, I was riding along Wellington Circle towards Canberra Road. It was a 1-lane road. My wife was riding with me as my pillion. Ahead of us was a dark navy car (Registration Plate: SMD7400H) and it was driving quite slow. As there were no oncoming vehicles, I decided to overtake the car as there was still some space between the car and the middle white line. As I was passing by the car, suddenly the car turned right abruptly, without signalling, to enter the carpark on the right, and had hit my motorcycle at the left side rear and my wife's leg, which caused me to lose balance and I skidded to the opposite side of the road.

I was still conscious but there were some passer-bys who came to assist and advised me not to move. My wife was able to get up and sit by the side of the road. However, she sustained abrasions on both knees and cuts on her legs. The extent of my injuries include bruises on my left hand and abrasions and cuts on my right leg.

Ambulance had attended to me and subsequently my wife and I was conveyed to Khoo Teck Puat Hospital. A passer-by had also called for the Police and Police had attended to my case, vide L/20190902/0089, under IO Isa.

**Common Statement**





**SINGAPORE  
POLICE FORCE**



T/20190905/2168

Police Station Of Origin:  
Yishun South N.P.C  
32 Yishun Street 81 SINGAPORE 768456  
Tel No: 1800-8522999

3 of 4

Report No. T/20190905/2168

CONTINUATION OF REPORT

**Common Statement**



**SINGAPORE  
POLICE FORCE**



T/20190905/2168

4 of 4

Police Station Of Origin:  
Yishun South N.P.C  
32 Yishun Street 81 SINGAPORE 768456  
Tel No: 1800-8522999

Report No. T/20190905/2168

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
L /  
Sgt 2 MUHAMMAD ALIF AFIF BIN MOHD  
AMRAN

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
05/09/2019 22:57

Officer In Charge Of Case:  
TP / GIT /  
Sr Staff Sgt CHONG GUAN FATT  
Contact No.: 65476083



Classification Of Case:

SN 085

Authentication Stamp  
NP168

Signature:

Singapore Police Force

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	203I
<b>Vehicle Details</b>	
Vehicle No.:	FC6348X
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Sep 2019
Vehicle Make:	YAMAHA
Vehicle Model:	RX-K
Primary Colour:	Black
Manufacturing Year:	1984
Engine No.:	13X012498
Chassis No.:	13X012498
Maximum Power Output:	-
Open Market Value:	\$0.00
Original Registration Date:	16 Apr 1984
First Registration Date:	16 Apr 1984
Transfer Count:	8
Actual ARF Paid:	\$0.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	30 Nov 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,930.00
COE Rebate Amount:	\$613.00
<b>Total Rebate Amount:</b>	<b>\$613.00</b>
<b>Message</b>	
Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.	
This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.	
This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.	
For more information, please visit <a href="http://www.nea.gov.sg/mtc incentive">http://www.nea.gov.sg/mtc incentive</a> or contact NEA at 1800-2255-632.	

The information contained herein is correct as at 26 Sep 2019

OK

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Sep 2019 <a href="#">Edit Reg</a>		20 Sep 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS			[Created by adjuster]
Insured:	Jasper Nai Zhi Hao, ID: S8512246J		
Main Claimant:	NUR RASYIDIN BIN ABIDIN, ID: S8115203I		
Vehicle Reg. No.:	FC6348H	Date of Loss:	02/09/2019 00:00 - :59 [424 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201900026258	Policy/Cover Note No.:	PNPV2018-00013085 (Comprehensive) Coverage: 03/10/2018 - 02/10/2019
Vehicle Reg. No. (Insured):	SMD7400H	Policy No. (Claimant):	
		Excess:	
Repairer:	Ah Hwa (HQ) BLOCK 1016 YISHUN INDUSTRIAL PARK A#01-228, 768758 Yishun - Tel:		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 01/10/2019]		

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

3

## Claim Documents

**\*FC6348H (1201900026258)**  
**[SMD7400H]**

TP

**NUR RASYIDIN BIN ABIDIN**









































**Sep 2 2019 12:00AM**
















































**[Jasper Nai Zhi Hao]**

**Ah Hwa**









































[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser ▼](#)

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
2	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
3	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
4	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
5	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
6	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
7	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
8	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
9	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
10	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
11	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
12	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
13	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
14	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
15	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
16	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
17	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
18	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
19	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
20	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
21	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
22	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
23	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
24	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
25	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
26	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
27	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
28	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
29	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
30	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
31	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
32	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
33	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
34	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
35	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
36	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
37	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
38	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>
40	23/09/19 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	23/09/19 10:23	General View		<input checked="" type="checkbox"/>
42	23/09/19 10:23	General View		<input checked="" type="checkbox"/>
43	23/09/19 10:23	General View		<input checked="" type="checkbox"/>
44	23/09/19 10:23	General View		<input checked="" type="checkbox"/>
45	23/09/19 10:23	General View		<input checked="" type="checkbox"/>
46	23/09/19 10:23	General View		<input checked="" type="checkbox"/>
47	23/09/19 10:23	General View		<input checked="" type="checkbox"/>
48	23/09/19 10:23	General View		<input checked="" type="checkbox"/>
49	23/09/19 10:23	General View		<input checked="" type="checkbox"/>
50	23/09/19 10:23	General View		<input checked="" type="checkbox"/>
51	23/09/19 10:23	General View		<input checked="" type="checkbox"/>
52	23/09/19 10:23	General View		<input checked="" type="checkbox"/>
53	23/09/19 10:23	Odometer Reading		<input checked="" type="checkbox"/>
54	23/09/19 10:23	Chassis Number		<input checked="" type="checkbox"/>
55	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
56	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
57	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
58	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
59	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
60	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
61	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
62	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
63	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
64	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
65	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
66	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
67	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
68	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
69	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
70	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
71	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
72	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
73	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
74	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
75	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
76	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
77	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
78	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
79	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
80	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
81	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
82	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
83	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
84	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
85	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
86	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
87	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
88	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
89	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
90	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
91	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
92	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
93	26/09/19 18:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
94	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	26/09/19 18:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	20/09/19 17:37	PRI - LAWRENCE LEE & CO	 Load PDF	
2	20/09/19 17:49	SMD7400H OI GIA	 Load PDF	
3	20/09/19 17:49	FC6348X TP GIA	 Load PDF	
4	20/09/19 17:49	EMAIL LKK TO ARRANGE SURVEY	 Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.





## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD19016673/GCD3S2

Date: 09/10/2019

## REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00013085  
 Claimant Vehicle No: FC6348H Insured Vehicle No: SMD7400H  
 Date of Loss: 02/09/2019 Nature of Claim: TP Claim No: 1201900026258

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FC6348H  
 Make & Model: YAMAHA RXK, 135cc (M) Engine No: 13X012498  
 Reg. Date: 16/04/1984 (Man. Year: 1984) Chassis No: 13X012498  
 Colour: Black Odometer: 16552 km  
 Engine Capacity: 135 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 80/90-18 Rear Tyre Size: 90/90-18  
 Front Left Side: IRC 4 mm Rear Left Side: IRC 4 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 20/09/2019  
 Date Inspected: 20/09/2019 Inspected At: Ah Hwa Motor (HQ)  
 BLOCK 1016 YISHUN INDUSTRIAL PARK A#01-228  
 Singapore 768758  
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 09 Oct 2019)	
<b>Parts:</b>	N/A	YAMAHA RXK 135cc (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FC6348H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >