Tampin

ASS. REC. BY:

REF: ASM (AXA)

ASSIGNMENT

COE 2029 April.

From: Date: 24.9.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJY8555M

at Workshop m/s Avantage Vag

of 48 Toh Guan Road East #05-123

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: 3.30 p.m Owner Waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $72K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (rmp')

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJY8555M Yr Regn: 2010 Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Audi Q5 c.c 1984

Colour White A/C: Insured / Std / NI / NA

Sp.Reading 120768 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAUZZZ8RUAA047980

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 265/35R20

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	24/9/19 @ 3.40pm

Survey held at VAG

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: S + RS S

Photos

Others

TOTAL

Report Format:

Lump Sum / LB / LC