

Assigner:

Ram

ASSIGNMENT (Office)

Assignee:

Mumen

From (Person):

Hor Yinnul

of

AIG

Date/Time: 20/9/19 @ 1:36pm

Estimated Cost:

Bill to:

GD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJC 1123M

Insured:

SJG 6494M

at Workshop in/s

Tel:

82632225

of

Fix mate
& Keki Bukit Ave 4 # 04-06 Premier

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 19/09/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:50pm 20/9/19

Person Contacted:

Ah chei

Vehicle

☒ IN / ☐ OUT

Date/Time

Action/Instruction

Schnitz ✓

SJC 1123M - X

SJG 6494M - NA. / AIG 18010261 / h4

DOA: 7/6/2018

26/09/19

Checked with AH Chei, no proceed direct settlement.

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJ 1123m

at Workshop n/s: fixmate

of 8 Kaki Bukit Ave 4 #04-06

Insured: Premier

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

AH Chai @ 82632225

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJC 1123m

Yr Regn: FEB / 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Serena 2.0GS-Hybrid s.c 1997

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 81863

T/Radio: Insured / Std / NI / NA

Eng/No: -

C/No: HFC26-272176

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 4 mm

R/Bal. 5 mm

L/Bal. 4 mm

L/Bal. 5 mm

D.O.A. 19/09/2019

D.O.A. 20/9/2019

Survey held at

Fixmate

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear / N/S rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L/S: \$4700 Confirm with AH Chai on 25/09/2019
6 repair days

(\$ 9,904.42 Red - 68%)

RECEIVED 27 SEP 2019

MV: \$84000

PV: \$57100

NV: \$26000

Date/Time, File Pass to?

26/9/19

1) Typ. 34

Date/Time, File Return to?

2)



Prel. Report



Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$) 4,700/- L/S

Survey Fee:

Transportation

3 + RS, 34

Photos

Others

TOTAL

1.1

TOTAL

26/9/2019

PRE-REPAIR INSPECTION REQUEST – SJC1123M vs SJG6494M (OI) on D.O.A.: 19/09/2019

From: Hor, Yinrul
To: 'Assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni
Sent: 9/20/2019 1:36:22 PM
Attachments: 20092019111720.pdf; 20092019111720.pdf

Hi,

Please refer to the enclosed request from **RIAZ LLC**.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign **Adrian Ling** as *Single Joint Expert as requested*.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208
Yinrul.Hor@aig.com | www.aig.sg

From: Hui Ling [mailto:riaz@justice.com.sg]
Sent: Friday, September 20, 2019 12:09 PM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni
Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJG6494M AND SJC1123M ON 19/09/2019

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE

Dear sirs,

We would like to appoint Mr Adrian Ling from LKK AUTO CONSULTANTS as our mutual surveyor-SJE

Thanks & Best Regards,

Hui Ling

RIAZ LLC
Advocates and Solicitors
133 NEW BRIDGE ROAD
09-09 CHINATOWN POINT
SINGAPORE 059413
TEL : 6534-0110 FAX : 6534-0220

Disclaimer: This message is privileged and confidential and is intended solely for the named recipient. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is strictly prohibited. If this e-mail has reached you in error, please delete the e-mail immediately and inform us of the error by sending an e-mail to riaz@justice.com.sg, though internet communications cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost or infected with viruses, we have scanned this message to minimise the possibility of corruption.

From: Hor, Yinrul <Yinrul.Hor@aig.com>
Sent: Friday, September 20, 2019 11:53 AM
To: riaz@justice.com.sg
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJG6494M AND SJC1123M ON 19/09/2019

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-09-27 11:53 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinrul.Hor@aig.com
To: riaz@justice.com.sg
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithosingh@aig.com, Theerthan.Parthiban@aig.com, Divyashni.Subramaniam@aig.com
Subject: aigenocrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJG6494M AND SJC1123M ON 19/09/2019
Date: Fri, 20 Sep 2019 03:52:32 +0000
Without Prejudice

Your Reference : SJC 1123M (V) FIXMATE
Our Reference : SJG6494M

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208
Yinrul.Hor@aig.com | www.aig.sg

From: Hul Ling [mailto:riaz@justice.com.sg]
Sent: Friday, September 20, 2019 11:18 AM
To: Hor, Yinrul; Abu Kassim, Noor Mariesa; 'Md Ishak, Mohd Imran'; 'Md Ishak, Mohd Imran'
Cc: Tan, Lily (AIG); Azlan, Syazairdina; Kaur, Baljit; Fong, Andy-SY; 'Md Ishak, Mohd Imran'
Subject: [EXTERNAL] RE: ACCIDENT INVOLVING MOTOR VEHICLES NO: SJC 1123M AND SJG 6494M ON 19.09.2019

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE

Dear sirs,

We refer to the above captioned matter.

Please find the enclosed notice of accident for your immediate action

Thanks & Best Regards,

Hailing

RIAZ LLC
133 NEW BRIDGE ROAD
09-09 CHINATOWN POINT
SINGAPORE 059413
TEL : 6534-0110
FAX : 6534-0220

Disclaimer: This message is privileged and confidential and is intended solely for the named recipient. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is strictly prohibited. If this e-mail has reached you in error, please delete the e-mail immediately and inform us of the error by sending an e-mail to riaz@justice.com.sg. though internet communications cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost or infected with viruses, we have scanned this message to minimise the possibility of corruption.



RIAZ
L.L.C
ADVOCATES AND SOLICITORS
COMMISSIONER FOR OATHS

ACRA NUMBER : 200911678H

GST REGISTRATION NUMBER : 200911678H

20/09/2019

Our Ref: SJC 1123M (V) FIXMATE

Your Ref: SJG 6494M

RIAZ QAYYUM (LLB HONS) NUS
(DIRECTOR)

ABDUL HALIM BIN ROSALAN (LLB HONS) UTAS
(ASSOCIATE)

MUHD RIDHWAN ABDUL RAHIM (LLB HONS) LEEDS
(ASSOCIATE)

TO: **AIG Asia Pacific Insurance Pte. Ltd.**
78 Shenton Way
Tower 2 #07-16
Singapore 079120
Attention: Motor claims Department

BY EMAIL ONLY

NOTICE OF ACCIDENT

Dear Sir

We are instructed by our client to notify you of a road traffic accident on 19 September 2019 at about 0430 hours along 311 Geylang Road involving our client's vehicle registration number SJC 1123M and vehicle registration number SJG 6494M driven by you or your authorized driver at the material time. A copy of Singapore accident statement / traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop : **FIXMATE PTE LTD**
Address : **8 KAKI BUKIT AVENUE 4**
#04-06 Premier @KB
SINGAPORE 415875

Telephone no. : **8263 2225 Ah Chai**

Please let us hear from you by the stipulated time.

Yours faithfully

Riaz

encs

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor
(Name & signature)

Date & time of inspection

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/09/2019 11:41
Date Of Accident	19/09/2019 16:30
Exact Location Of Accident	311 GEYLANG ROAD (STRAIGHT ROAD)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJC1123M
Insured/Policyholder	
Name Of Registered Owner	CHAN HWEE PING
NRIC No	S7244709C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96436972
Alternative Phone No	OFFICE-96436972

Vehicle Particulars

Manufacturer	NISSAN
Model	SERENA 2.0G S-HYBRID A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B29114420UBI
Cover Note Number	

Driver

Name of Driver	CHAN HWEE PING
NRIC No	S7244709C
Date Of Birth	23/11/1972
Occupation	INDOOR
Date Of Driving Pass	25/07/1996
Driving Experience	23 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-96436972
Fax Number	
Contact Number	OFFICE-96436972
EMail Address	NOEMAIL

Address	APT BLK 40 SIMS DRIVE #07-221
Postcode	380040
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJG6494
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The style and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and then copies of this report will for a fee be made available upon application to interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA):
 I, undersigned, do hereby agree and consent that:
 - (a) My Insurer, my solicitor and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form, and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Regulatory Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries to me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me) which could involve disclosure of certain personal data about me to bring about delivery of the same as well as to the extent: cover of my vehicle(s), third packages), and/or;
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims collectively for "Purposes".
 - (b) all Insurers, who have insured vehicle(s) involved in this accident and the Insurers' lawyers, law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above "Purposes"; and
 - (c) my Personal Information may/also be disclosed by any of the Insurers and/or GIA to other third parties, be providers or agents (including the Insurers' law firms), which may be situated outside Singapore, for one or more of the above "Purposes".
 - (d) my Personal Information will also be collected and used to combat claims fraud for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud;
 - (ii) regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (iii) for complying with requirements under any regulations, enactment or court orders.

Policyholder's Signature

Date & Time 20 Sep 2019
9.35am

Driver's Signature


If driver is not the policyholder:
Date & Time

Reporting Centre Personnel's Signature

Name VENICE
NR 01111111

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19 Sep 2019 1631hrs, I was driving along 311 Gylenny road, suddenly vehicle B hit left rear of my car.

DECLARATION

I do declare the foregoing particulars are true in every respect.

Accident Holder's Signature

Date & Time: 20 Sep 2019
0930

Driver's Signature

If driver is not the accident holder
Date & Time:

Reporting Officer/Personnel's Signature

Name: verice
VPC No.:

> Back to OneMotoring

Inquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	709C
Vehicle Details	
Vehicle No.:	SJC1123M
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2019
Vehicle Make:	NISSAN
Vehicle Model:	SERENA 2.0G S-HYBRID A
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	MR20707506B
Chassis No.:	HFC26272176
Maximum Power Output:	109.8 kW (147 bhp)
Open Market Value:	\$26,870.00
Original Registration Date:	02 Feb 2016
First Registration Date:	02 Feb 2016
Transfer Count:	0
Actual ARF Paid:	\$29,618.00 $\times 50\% = \$14,809$
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Feb 2026
PARF Rebate Amount:	\$22,213.00
Intended COE Rebate Details	
COE Expiry Date:	01 Feb 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,920.00
COE Rebate Amount:	\$34,887.00
Total Rebate Amount:	\$57,100.00

The information contained herein is correct as at 25 Sep 2019

Remaining: 6 years 4 months 13 days (76.4)
Depn: \$11,000/yearly \$916.66/monthly

OK

$$76.4 \times \$916.66 = \$70,032.82$$

$$\$70,032.82 + \$14,809 = \$84,841.82$$



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loan. Trade In Are
Welcome. 100% Deposit Refund
For Unapproved Loan.
Classic Credit [Start Ad](#)

PRIME MOTOR & LEASING

(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.

Browse by Category

Sort by Date Posted 20 results/page

Advanced Search

1 vehicles

nissan serena

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	nissan serena		Any	Any	2016	Any	Any	Any	Available
		Nissan Serena S-Hybrid 2.0A G	\$95,000	\$11,790 /yr	30-Jun-2016	1,997 cc	47,000 km	MPV	Available
		Fuel Type: Petrol-Electric Full Service Records At Tan Chong Motors. Sheltered Parking At Office And Home. Food Trays. Cruise Control. Front And Reverse Camera. Auto Lock Doors. Accident Free. High COE. Made In Japan. Power Sliding Doors. No Dealers, Agents Or Consignment. Downgrading To...							
		Tags: 2016 Nissan Serena, 2016 nissan serena, Nissan Serena, nissan serena, Nissan, Serena, serena, Used							
		Posted: 18-Sep-2019							

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
								20 results/page

For old advertisements, view [Expired ads](#)

Home | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used nissan serena, nissan serena Singapore, used nissan serena Singapore, used vehicles Singapore or even buy used nissan serena Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner site for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

If prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)

FIXMATE PTE LTD

10,KAKI BUKIT AVE 4,#04-06 PREMIER,S(415875)

Email Address: tfyong1966@gmail.com

COMPANY / GST REG. NO. : 201901818H

Contact: CHAI 82632225

Vehicle Number : SJC1123M
Vehicle Model : NISSAN SERENA
Accident Date : 19.09.2019

Date : 20.09.2019
Chassis : HFC262742176
TP Ins. : AIG insurance

ESTIMATE

1	1 pc	Tailgate		2,210.70	X (R)
2	1 pc	Tailgate INNERTRIM		352.10	xnn
3	1 set	Tailgate Windscreen Moulding		283.00	xnn
4	2 pc	Tailgate striker	24.00	48.00	xnn
5	2 pcs	Tailgate Stopper	28.00	56.00	xnn
6	2 pcs	Tailgate damper	183.50	\$296 367.00	BT
7	1 pc	Tailgate Inner Lock		\$389 538.00	SC
8	1 pc	Tailgate Lock Catch		42.60	xnn
9	1 pc	Tailgate Weatherstrip		\$159 211.30	CU
10	2 pcs	Tailgate Hinges	85.00	170.00	xnn
11	1 pc	Tailgate logo		92.30	nee
12	1 pc	Tailgate "highway" emblem		\$66 85.20	nee
13	1 pc	Tailgate "pure drive" emblem		\$66 86.30	nee
14	1 pc	Tailgate outer chrome molding		328.50	xnn
15	1 pc	Tailgate outer open actuator		147.90	xnn
16	1 pc	Rear Bumper		697.60	crq
17	2 pcs	Rear Bumper Side Retainers	65.70	131.40	nee
18	1 pc	Rear Bumper Reflector Lh		\$56 117.00	scr
19	1 pc	Rear Bumper Beam		\$36 158.70	BT
20	1 pc	Taillamps Assy Lh		\$520 652.90	crq
21	1 pc	Taillamps Sealer		40.00	nee
22	1 pc	End Panel		\$391 689.70	oo
23	1 pc	End Panel Top Trim		289.50	xnn
24	1 pc	Rear Fender LH		911.90	scr
25	1 pc	Rear Fender Inner Trim LH		586.20	xnn

C/F 9,293.80

Parts Discount

Less 10% 8,364.42

Page 1 of 2

Total : \$3952.20

est 10% : \$3556.98

Special Nett

1	1 set	Reverse Camera		380.00	xnn
2	1 set	Reverse Sensor	\$200	250.00	sc
3	1 set	Rear Windscreen Sealant		80.00	xnn
4	1 set	Rear Number Plate with Cover		50.00	xnn
5	1 set	Rear bumper clips		30.00	nee
6	1 set	End panel top trim clips		30.00	xnn
7	1 set	Rear fender inner trim clips		30.00	nee
8	1 set	Tailamps Clips		30.00	nee
9	1 set	Audio Display unit		850.00	xnn
10	1 set	Body Panel Joint Sealant		150.00	nee

sub total: 1,880.00

\$440

Labour charge

Panel Beating		1,800.00	\$800
Spray painting		1,600.00	\$800
Check Wiring on rear tailamps		120.00	\$80
Anti rust		150.00	\$80
Remove and install rear winscreen.		180.00	xnn
Remove and transfer tailgate parts.		120.00	\$50
Remove and install interior uphostery		120.00	xnn
Remove and install reverse sensor		120.00	\$50
Remove and install reverse camera.		150.00	xnn

sub total \$ 4,360.00

Total : 14,604.42

Page 2 of 2

Labour : \$1860

List Item : \$3556.98

nett item : \$440

Labour : \$1860

Total : \$5856.98

20% L/S : \$4700.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram(LKK)

88622772

Repair days : 6days

45

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Sep 2019 Edit Reg		20 Sep 2019 00:00 Edit Adj Rpt	S\$4,700.00 Edit Estimates	S\$4,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	DLS AUTO, Co. Reg. No.: 53359130M		
Main Claimant:	CHAN HWEE PING		
Vehicle Reg. No.:	SJC1123M	Date of Loss:	19/09/2019 16:00 - :59 [43 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0943684752SG	Policy/Cover Note No.:	0999994217 (Third Party Only)
Vehicle Reg. No. (Insured):	SJG6494M	Policy No. (Claimant):	
		Excess:	
Repairer:	Fixmate Auto Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #02-16 Premier @ KB, 415875 Kaki Bukit - Tel: 82632225		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 01/10/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (23/09/2019): TP GIA REPORT

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)








































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





















































Claim Documents













***SJC1123M (0943684752SG)**
[SJG6494M]

TP

CHAN HWEE PING
Sep 19 2019 4:00PM
[DLS AUTO]
Fixmate Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser ▼		
Photos/Images															3 per page ▼			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
2	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
3	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
4	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
5	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
6	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
7	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
8	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
9	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
10	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
11	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
12	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
13	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
14	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
15	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
16	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
17	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
18	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
19	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
20	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
21	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
22	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
23	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
24	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
25	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
26	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
27	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
28	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
29	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
30	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
31	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
32	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
33	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
34	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
35	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
36	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
37	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
38	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
39	25/09/19 09:08	General View													 Load JPG			<input checked="" type="checkbox"/>		
40	25/09/19 09:09	Photographs of Damaged Parts													Load JPG			<input checked="" type="checkbox"/>		

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	25/09/19 09:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
94	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	25/09/19 09:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	27/09/19 17:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
99	27/09/19 17:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
100	27/09/19 17:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
101	27/09/19 17:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
102	27/09/19 17:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
103	27/09/19 17:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/09/19 10:21	SJC 1123M GIA.pdf	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte, Ltd. (SG)	Thumbnail	Print
1	23/09/19 09:52	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG19016675/FSD3S2
Date: 08/10/2019REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994217
Claimant Vehicle No :	SJC1123M	Insured Vehicle No :	SJG6494M
Date of Loss:	19/09/2019	Nature of Claim:	TP
		Claim No:	0943684752SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJC1123M		
Make & Model:	NISSAN SERENA, 2.0 G S-HYBRID D/AIRBAGS 5DR 2WD (A)	Engine No:	MR20707506B
Reg. Date:	02/02/2016 (Man. Year: 2015)	Chassis No:	HFC26272176
Colour:	Silver	Odometer:	81863 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Goodyear 4 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 4 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,244.42	3,996.98	6,247.44	60.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,360.00	1,860.00	2,500.00	57.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,604.42	5,856.98	8,747.44	59.90
Approved Total (Overridden) (S\$)		4,700.00		
Nett Amount (S\$)	14,604.42	4,700.00	9,904.42	67.82

INSPECTION

Date of Assignment:	20/09/2019	
Date Inspected:	20/09/2019	Inspected At: Fixmate Auto Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #02-16 Premier @ KB Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: PARASURAM SHANMUGAM**Manager:** Hiew May Fung*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	2,210.70 FL	*- FL
2	1		*TAILGATE INNER TRIM	Not Necessary	352.10 FL	*- FL
3	1		*SET TAILGATE WINDSCREEN MOULDING	Not Necessary	283.00 FL	*- FL
4	2		*TAILGATE STRIKER	Not Necessary	48.00 FL	*- FL
5	2		*TAILGATE STOPPER	Not Necessary	56.00 FL	*- FL
6	2		*TAILGATE DAMPER	Bent	367.00 FL	*296.00 FL
7	1		*TAILGATE INNER LOCK	Short Circuit	538.00 FL	*389.00 FL
8	1		*TAILGATE LOCK CATCH	Not Necessary	42.60 FL	*- FL
9	1		*TAILGATE WEATHERSTRIP	Cut	211.30 FL	*159.00 FL
10	2		*TAILGATE HINGES	Not Necessary	170.00 FL	*- FL
11	1		*TAILGATE LOGO	Necessary	92.30 FL	*92.30 FL
12	1		*TAILGATE HIGHWAY EMBLEM	Necessary	85.20 FL	*66.00 FL
13	1		*TAILGATE PURE DRIVE EMBLEM	Necessary	86.30 FL	*66.00 FL
14	1		*TAILGATE OUTER CHROME MOULDING	Not Necessary	328.50 FL	*- FL
15	1		*TAILGATE OUTER OPEN ACTUATOR	Not Necessary	147.90 FL	*- FL
16	1		*REAR BUMPER	Cracked	697.60 FL	*697.60 FL
17	2		*REAR BUMPER SIDE RETAINERS	Necessary	131.40 FL	*131.40 FL
18	1		*REAR BUMPER REFLECTOR LH	Scratched	117.00 FL	*56.00 FL
19	1		*REAR BUMPER BEAM	Broken	158.70 FL	*136.00 FL
20	1		*TAILLAMPS ASSY LH	Cracked	652.90 FL	*520.00 FL
21	1		*TAILLAMPS SEALER	Necessary	40.00 FL	*40.00 FL
22	1		*END PANEL	Dented	689.70 FL	*391.00 FL
23	1		*END PANEL TOP TRIM	Not Necessary	289.50 FL	*- FL
24	1		*REAR FENDER LH	Buckled	911.90 FL	*911.90 FL
25	1		*REAR FENDER INNER TRIM LH	Not Necessary	586.20 FL	*- FL
26	1		*SET REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
27	1		*SET REVERSE SENSOR	Short Circuit	250.00 FS	*200.00 FS
28	1		*SET REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
29	1		*SET REAR NUMBER PLATE WITH COVER	Not Necessary	50.00 FS	*- FS
30	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
31	1		*SET END PANEL TOP TRIM CLIPS	Not Necessary	30.00 FS	*- FS
32	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	30.00 FS	*30.00 FS
33	1		*SET TAILLAMPS CLIPS	Necessary	30.00 FS	*30.00 FS
34	1		*SET AUDIO DISPLAY UNIT	Not Necessary	850.00 FS	*- FS
35	1		*SET BODY PANEL JOINT SEALANT	Necessary	150.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,173.80	4,392.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	929.38	395.22
Total Parts (\$\$)	10,244.42	3,996.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING.	New	1,800.00	800.00
2	SPRAY PAINTING.	New	1,600.00	800.00
3	CHECK WIRING ON REAR TAILLAMPS.	New	120.00	80.00
4	ANTI RUST.	New	150.00	80.00
5	REMOVE AND INSTALL REAR WINDSCREEN.	New	180.00	0.00
6	REMOVE AND TRANSFER TAILGATE PARTS.	New	120.00	50.00
7	REMOVE AND INSTALL INTERIOR UPHOLSTERY.	New	120.00	0.00
8	REMOVE AND INSTALL REVERSE SENSOR.	New	120.00	50.00
9	REMOVE AND INSTALL REVERSE CAMERA.	New	150.00	0.00
Gross Labour Cost (S\$)			4,360.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >