

ASS. REC. BY:

REF: CS/MSG 19016712/KYF3N2

Special Instruction:

SUNAJOR: Kenneth

ASSIGNMENT (Office)

From (Person): Jolwyn Tay Mui Ling of MSIG

Date/Time: 20.9.19 11.30p.m.

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKT 918414

Insured: SLT 26450

at Workshop m/s Wei Lee Motor

Tel: 64569830

of Block 9 Sh Ming Industrial Estate #01-32

Policy No: A29114756 MKF

Claim No: 606235

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19.9.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 23.9.19 11.04a.m.

Person Contacted: Karan Sah

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLT 918414-x

SLT 26450 - CC4/ AIG 18014210/ K463 P.O.A - U/08/ 219

29/9/19 Sent Preli via Merimen

31/10 6/1 Sy @ 1200 email &amp; confirmed Karan (Red \$1546-30, 56%)

photo o.k.

ASS. REC. BY:

REF: MJG/

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Wes Lee

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 1.1B1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKT 9184H Yr Regn: 06, 15Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or \_\_\_\_\_

Make: Toy AIAN c.c. 1598Colour: Br. Brown A/C: Insured / Std / NI / NASp. Reading: 70109 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MRO 53RE1104535060Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16

R: \_\_\_\_\_

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 8 mmR/Bal. 6 mmL/Bal. 8 mmD.O.A. 18/9/19D.O.I. 23/9/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File post to

RECEIVED 07 NOV 2019

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 6/11/19 Typist

Days Of Repair: 2Resurvey No. of Trip: 1

Survey Fee:

Transportation: 150  
S - RS - St 11

Fuel cost

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / B.I. (\$

\$1200/-

|     |
|-----|
| 150 |
| 11  |
|     |
|     |
| 161 |

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 24 Sep 2019

**Preliminary Advice**

|                    |                                                                                             |                         |              |
|--------------------|---------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SLT2645D                                                                                  | Accident Date           | : 18/09/2019 |
| TP Vehicle No      | : SKT9184H                                                                                  | Assignment Date         | : 20/09/2019 |
| Make               | : TOYOTA COROLLA ALTIS                                                                      | Est. Duration of Repair | : 2.00       |
| Date of Inspection | : 23/09/2019                                                                                |                         |              |
| Inspection At      | : WEI LEE MOTOR WORKS (HQ)<br>BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32<br>SINGAPORE 575644 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages FRONT O/S portion and parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 2,746.30 |
| Revised Amount              | :S\$ | 1,530.15 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 1,530.15 |

Lump Sum Repair :S\$

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING |             |               |                                |         |               |            |                                                      |
|--------------------------|-------------|---------------|--------------------------------|---------|---------------|------------|------------------------------------------------------|
| Case                     | Notified    | Est Submitted | Adj Assigned                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                                               |
| Main                     | 19 Sep 2019 |               | 20 Sep 2019<br>16:12<br>Assign |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

  

| Main                                                                                                                   | Reference                                                                                                                           | Claim Details          | Documents                                                                    | Show All |         |             |              |            |       |
|------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>                                 |                                                                                                                                     |                        |                                                                              |          |         |             |              |            |       |
| Insured:                                                                                                               | GRAB RENTALS PTE.LTD., Co. Reg. No.: 201617200G                                                                                     |                        |                                                                              |          |         |             |              |            |       |
| Main Claimant:                                                                                                         | KH LEASING PTE. LTD., Co. Reg. No.: 201611813C                                                                                      |                        |                                                                              |          |         |             |              |            |       |
| Vehicle Reg. No.:                                                                                                      | SKT9184H                                                                                                                            | Date of Loss:          | 18/09/2019 08:00 - :59<br>[50 Months and 23 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:                                                                                                            | TP / 606235                                                                                                                         | Policy/Cover Note No.: | A29114756MKF (Comprehensive)<br>Coverage: 01/02/2019 - 31/01/2020            |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):                                                                                            | SLT2645D                                                                                                                            | Policy No. (Claimant): |                                                                              |          |         |             |              |            |       |
|                                                                                                                        |                                                                                                                                     | Excess:                | S\$2,000.00                                                                  |          |         |             |              |            |       |
| Repairer:                                                                                                              | Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32, 575644 Sin Ming - Tel:                                          |                        |                                                                              |          |         |             |              |            |       |
| Handling Insurer:                                                                                                      | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]                      |                        |                                                                              |          |         |             |              |            |       |
| Adjuster:                                                                                                              | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/09/2019]                                                  |                        |                                                                              |          |         |             |              |            |       |
| Driver/Custodian (Insured):                                                                                            | CHUA KIM HOCK CECIL (44 / Male) , NRIC: S75012783, Tel: +6587385378 Email:                                                          |                        |                                                                              |          |         |             |              |            |       |
| Adj Asg. Remarks:                                                                                                      | on WP. OI:Grab. Liab: clear. Agree on SJE. Assign: Kenneth Kong from LKK Auto Consultants Pte Ltd. Contact: Karen Seah @ 6456 9830. |                        |                                                                              |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;">View All    Compose Case Mail</span>                       |                                                                                                                                     |                        |                                                                              |          |         |             |              |            |       |
| There are no mail for this case.                                                                                       |                                                                                                                                     |                        |                                                                              |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All    Search Tasks    Create New Task    Complete</span> |                                                                                                                                     |                        |                                                                              |          |         |             |              |            |       |
| Due Date                                                                                                               | Priority                                                                                                                            | Type                   | Task Group                                                                   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                            |                                                                                                                                     |                        |                                                                              |          |         |             |              |            |       |

# 威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,  
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com  
Business Regn No: 269436/00J

20, Sep 2019

MSIG Insurance (Singapore) PL  
4 Shenton Way  
#21-01 SGX Centre 2  
S 068807

Attn: Motor claim dept=3<sup>rd</sup> party claim  
Claiming against your insured vehicle no: SLT2645D  
Accident involving vehicle No: SKT9184H/SLT2645D  
DOA: 18/09/2019 Bayfront Avenue

Re: Estimate cost of repair for vehicle no: SKT9184H  
To supply—

| Description     | Qty  | Amount      |
|-----------------|------|-------------|
| Front bumper    | 1 Bu | 458.00 ✓    |
| Bumper retainer | 1    | Dis 82.30 — |
| Bumper clip     |      | M 38.00 —   |
| Headlamp        | 1    | Gr 789.00 ✓ |
| Foglamp         | 1    | PL 248.20 x |
| Foglamp cover   | 1 Gr | 112.90 x    |
| Parts           |      | 1,728.40    |
| Parts less 25%  |      | 432.10      |
|                 |      | 1,296.30    |
|                 |      |             |
|                 |      |             |

To remove damaged parts and attachments.  
Repair/reshape dented areas.  
Replace/align all parts into position.  
To spray paint.

750.00 20d  
700.00 22ol  
-----  
2,746.30

LKK Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Approved by Repairer:

Signature:

Date:

Not with order  
Repair by paint  
2 days  
11 Sep @ 1200h

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19016712/KYF3N2

Date: 07/11/2019

## REFERENCE

|                       |                                      |                      |              |
|-----------------------|--------------------------------------|----------------------|--------------|
| Handling Insurer:     | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:           | A29114756MKF |
| Claimant Vehicle No : | SKT9184H                             | Insured Vehicle No : | SLT2645D     |
| Date of Loss:         | 18/09/2019                           | Nature of Claim:     | TP           |
|                       |                                      | Claim No:            | 606235       |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | SKT9184H                          | Engine No:  | 1ZRX518420        |
| Make & Model:               | TOYOTA COROLLA ALTIS, 1.6 CVT (A) | Chassis No: | MR053REH104535060 |
| Reg. Date:                  | 26/06/2015 (Man. Year: 2015)      | Odometer:   | 70109 km          |
| Colour:                     | Metallic Brown                    |             |                   |
| Engine Capacity:            | 1598 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (\$\$):         | Market Value/New Car Price        |             |                   |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 205/55R16   | Rear Tyre Size:  | 205/55R16   |
| Front Left Side:  | Dunlop 8 mm | Rear Left Side:  | Dunlop 6 mm |
| Front Right Side: | Dunlop 8 mm | Rear Right Side: | Dunlop 6 mm |

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

|                                           | Repairer's      | Adjuster's      | Difference      | Diff %       |
|-------------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                                     | 1,296.30        | 1,110.15        | 186.15          | 14.36        |
| Miscellaneous Items                       | 0.00            | 0.00            | 0.00            |              |
| Labour                                    | 1,450.00        | 420.00          | 1,030.00        | 71.03        |
| Paintwork Labour                          | 0.00            | 0.00            | 0.00            |              |
| Towing                                    | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (\$\$)</b>      | <b>2,746.30</b> | <b>1,530.15</b> | <b>1,216.15</b> | <b>44.28</b> |
| <b>Approved Total (Overridden) (\$\$)</b> |                 | <b>1,200.00</b> |                 |              |
| <b>(\$\$)</b>                             | 2,746.30        | 1,200.00        | 1,546.30        | 56.30        |
| <b>+ GST 7.00/7.00% (\$\$)</b>            | 192.24          | 84.00           | 108.24          | 56.30        |
| <b>Nett Amount (\$\$)</b>                 | <b>2,938.54</b> | <b>1,284.00</b> | <b>1,654.54</b> | <b>56.30</b> |

## INSPECTION

Date of Assignment: 20/09/2019

Date Inspected: 23/09/2019 Inspected At:

Wei Lee Motor Works (HQ)  
BLOCK 9 SIN MING INDUSTRIAL  
ESTATE #01-32  
Singapore 575644

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                    |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 07 Nov 2019)                      |
| <b>Parts:</b>        | 143                                                                                                                                                                          | TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                  |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SKT9184H)                                                                                                                                    |                                                                    |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                    |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                    |

### Recommended Parts

| No. | Qty | Part No. | Particulars      | Condition   | Repairer's | Amount     |
|-----|-----|----------|------------------|-------------|------------|------------|
| 1   | 1   |          | *FRONT BUMPER    | Buckled     | 458.00 FL  | *458.00 FL |
| 2   | 1   |          | *BUMPER RETAINER | Distorted   | 82.30 FL   | *82.30 FL  |
| 3   | 1   |          | *BUMPER CLIP     | Necessary   | 38.00 FL   | *38.00 FL  |
| 4   | 1   |          | *HEADLAMP        | Cut         | 789.00 FL  | *789.00 FL |
| 5   | 1   |          | *FOGLAMP         | Serviceable | 248.20 FL  | *- FL      |
| 6   | 1   |          | *FOGLAMP COVER   | Cut         | 112.90 FL  | *112.90 FL |

F=Franchise part. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>1,728.40</b> | <b>1,480.20</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 432.10          | 370.05          |
| <b>Total Parts (\$\$)</b>                                  | <b>1,296.30</b> | <b>1,110.15</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                       | Particulars                                                                                               | Lab.Type | Repairer's | Amount |
|--------------------------|-----------------------------------------------------------------------------------------------------------|----------|------------|--------|
| <u>Labour Items</u>      |                                                                                                           |          |            |        |
| 1                        | TO REMOVE DAMAGED PARTS AND ATTACHMENTS.REPAIR/RESHAPE DENTED AREAS.REPLACE/ALIGN ALL PARTS INTO POSITION | New      | 750.00     | 200.00 |
| 2                        | TO SPRAY PAINT                                                                                            | New      | 700.00     | 220.00 |
| Gross Labour Cost (\$\$) |                                                                                                           |          | 1,450.00   | 420.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >