

12/20/2019

ASS. REC. BY:

REF:

CS/AIG19016717/Eq302

Special Instruction:

Surveyor: Seva

ASSIGNMENT (Office)

Minimum

From (Person): Chin Lee Ying

of AIG

Date/Time: 23/9/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SHH1932U

Insured: SMA5072A

at Workshop m/s LCR

Tel: 97422188 Mr Sim

of 60 Jalan Lam Huat #04-35

Policy No: 999994314

Claim No: 027039716356

Sum Insured:

Excess:

Make of Veh:

D.O.A. 18/9/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 23/9

Person Contacted: Mr Sim

Vehicle: INV OUT

Date/Time	Action/Instruction
	Estimate (✓)
	SHH1932U - X
	SMA5072A - COT/AIG18021386/Kia342 DOA: 26/11/2018

Surveyor

Steve

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLH 19324

Yr Regn: 26/10/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle

c.c 1496

Colour Red

A/C: Insured / Std / NI / NA

Sp. Reading 196151

T/Radio: Insured / Std / NI / NA

Eng/No:

CiNo: GP 7104 2222

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal. 6

mm

R/Bal. 6

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. 18/9/19

D.O.I. 23/9/19

Survey held at

Lim City

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/11/19

MV - 63K

Finalize confirm \$5750, 7 days (Red p 6867.68, 54%)

RECEIVED 07 NOV 2019

Date/Time, File Pass to?



: Prel. Report

1) 07/11/19



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format :

MEK-TP

Lump Sum / I.B.I. (\$

5750

250

11

261

PRE-REPAIR INSPECTION REQUEST – SLH1932U vs SMA5072A (OI) on D.O.A.: 18/09/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divy
Sent: 9/23/2019 9:23:55 AM

Hi,

Please refer to the enclosed request from **Lion City Rentals**.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor Yin Rul (Viviane)

AIG

FNOL Adjuster I

Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208

Yinrul.Hor@aig.com | www.aig.sg

From: Siak Tong Sim [mailto:siaktong@lioncityrentals.com.sg]

Sent: Saturday, September 21, 2019 9:14 AM

To: Hor, Yinrul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni

Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMA5072A AND SLH1932U ON 18/09/2019

This message is from an external sender; be cautious with links and attachments.

Dear sir

We would like to engage LKK for this survey

Regards

S.T.Sim (65-97422188)

Manager

Accident Reporting Center

60 Jalan Lam Huat

#04-35/36 Carros Centre

Singapore 737869



On Fri, Sep 20, 2019 at 3:34 PM Hor, Yinrul <Yinrul.Hor@aig.com> wrote:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมัน ให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-09-27 15:34 +08 to read your message. After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinrul.Hor@aig.com

To: siaktong@lioncityrentals.com.sg

Cc: Andy-SY.Fong@aig.com ,Lee-Ying.Chin@aig.com ,NoorMariesa.AbuKassim@aig.com ,Syazairdina.Azlan@aig.com ,yokeshi.chan@aig.com ,ShengYang.Lim@aig.com ,Aashweenjeetkaur.Mithoosingh@aig.com ,Theerthan.Parthiban@aig.com ,Divyashni.Subramaniam@aig.com

Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMA5072A AND SLH1932U ON 18/09/2019

Date: Fri, 20 Sep 2019 07:33:48 +0000

Without Prejudice

Your Reference : SLH1932U
Our Reference : SMA5072A

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)

AIG

FNOL Adjuster I

Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208

Yinrul.Hor@aig.com | www.aig.sg

From: Siak Tong Sim [mailto:siaktong@lioncityrentals.com.sg]

Sent: Friday, September 20, 2019 3:05 PM

To: AIG SGP, Claims-Survey

Cc: Lion City Rentals ARC

Subject: [EXTERNAL] Re: 3rd party survey for SLH1932U

This message is from an external sender; be cautious with links and attachments.

Dear sir

Please arrange 3rd party survey for the following car

Our insured: SLH1932U

Your Insured: SMA5072A

Date of accident:18/09/2019

Regards

S.T.Sim (65-97422188)

Manager

Accident Reporting Center

60 Jalan Lam Huat

#04-35/36 Carros Centre


Singapore 737869

Steve Chen (LKK Auto)

From: Siak Tong Sim <siaktong@lioncityrentals.com.sg>
Sent: Thursday, November 07, 2019 7:52 AM
To: Steve Chen (LKK Auto)
Subject: Re: Final Bill: SLH1932U

Steve
Ok confirmed lump sum \$5,750.00/7 days

Regards
S.T.Sim (65-97422188)
Manager
Accident Reporting Center
60 Jalan Lam Huat
#04-35/36 Carros Centre
Singapore 737869



On Wed, Nov 6, 2019 at 5:31 PM Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Mr Sim,

Kindly refer our finalize.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	621K
Vehicle Details	
Vehicle No.:	SLH1932U
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Sep 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5 HYBRID AT ABS D/AIRBAG 2W
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	LEB4261870
Chassis No.:	GP71042222
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$20,787.00
Original Registration Date:	26 Oct 2016
First Registration Date:	26 Oct 2016
Transfer Count:	2
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Oct 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	25 Oct 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,156.00
COE Rebate Amount:	\$34,845.00
Total Rebate Amount:	\$38,595.00

The information contained herein is correct as at 23 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/09/2019 16:34
Date Of Accident	18/09/2019 20:10
Exact Location Of Accident	ALONG CANTONMENT ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH1932U
Insured/Policyholder	
Name Of Registered Owner	LION CITY RENTALS PTE LTD
Co Reg No	201504621K
Email Address	RENTALS@LIONCITYRENTALS.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-31381884

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE HYBRID-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	19-MK000199-R00
Cover Note Number	

Driver

Name of Driver	NG YEW YAN
NRIC No	S8126188A
Date Of Birth	27/08/1981
Occupation	OUTDOOR
Date Of Driving Pass	08/04/2005
Driving Experience	14 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90480000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 57 TEBAN GARDENS ROAD #19-489
Postcode	600057
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG WEST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2689999 - FAX NO: 62672438
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMA5072A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

YM8748J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SJU6114L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

PORTANT NOTICE

Platz reports correctly the details of the accident to speed up the claims process.

This Form must be completed by the Policyholder and/or the Authorized Driver.

Policyholder's Signature _____
Date & Time: _____

[illegible]

Sketch Plan #2

CH PLAN



A = Tm 8748 J

B = SMA 5072 A

C = SLH 1932 LI

D = SSu 6114 L

SCRIBE CIRCUMSTANCES OF THE ACCIDENT

Ref Police Report

DECLARATION

I/We declare the foregoing to be true and correct.


Policyholder's Signature




Driver's Signature


Reporting Officer's Signature

$$\begin{array}{r} 6438.60 \\ - 20\% \\ \hline 5150.88 \end{array}$$

SPECIAL NETT

1	Reverse sensor	X	N/A	1 SET	\$260.00	
2	Windscreen sealant	/	NPC	1 SET	\$120.00	40
3	Body Sealant	/	NPC	1 SET	\$300.00	30
4	Bumper clips	/	NPC	1 SET	\$120.00	60
5	End panel to garnish clips	/	NPC	1 SET	\$80.00	15
Special Nett Total S\$:					\$880.00	145

LABOUR CHARGES

1	TO REMOVE R/L FENDER, REAR TAILGATE, REAR BUMPER, END PANEL OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS AND ALSO STARIGHTEN SPARE TYR PANEL INCLUDE CUTTING/WELDING OF DAMAGED PARTS		\$1,500.00	900
2	TO RESPRAY R/L FENDER, REAR TAILGATE, REAR BUMPER, END PANEL AND SPARE TYRE PANEL(INNER/OUTER)		\$1,200.00	800
3	TO REMOVE & INSTALL REAR WINDSCREEN		\$160.00	120
4	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS.		\$80.00	30
5	TO TRANSFER TAILGATE MECHANISM		\$100.00	50
6	To deactivate and activate hybrid battery as a safety precaution	(photo)	\$300.00	X ? X
7	To conduct a standard of opearting procedures post repairs diagnostic scan test as a requirements for hybrid cars upon completion of collision repairs	(photo)	\$300.00	X ? X

LABOUR TOTAL S\$: \$3,640.00
TOTAL S\$: \$12,617.68
7% GST \$883.24
GRAND TOTAL S\$: \$13,500.92

1900

[Signature]
24/9/19

Steve (LKK) w/L Mr L 13/9/19, 3:00pm
7 days

L/S
Ry AL SM

P- 5150-88
AI- 145
L- 1900
7195-88
L/S- 5756-70
= 5750

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Sep 2019 Edit Reg		23 Sep 2019 00:00 Edit Adj Rpt	S\$5,750.00 Edit Estimates	S\$5,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	GOLDBELL CAR RENTAL PTE LTD, Co. Reg. No.: 200710651D		
Main Claimant:	LION CITY RENTALS PTE LTD, Co. Reg. No.: 201504621K		
Vehicle Reg. No.:	SLH1932U	Date of Loss:	18/09/2019 20:00 - :59 [34 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0270397163SG	Policy/Cover Note No.:	0999994314 (Comprehensive)
Vehicle Reg. No. (Insured):	SMA5072A	Policy No. (Claimant):	
		Excess:	
Repairer:	Lion City Rentals Pte Ltd (HQ) 60 Jalan Lam Huat, #04-01 Carros Centre, 737869 Kranji - Tel: 92988888 / 97884060		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (LCR) - Tel: ... [Handled by Ler, Bernard-JQ] BernardJlQian.Ler@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 03/10/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH1932U (0270397163SG)
[SMA5072A]
TP
LION CITY RENTALS PTE LTD
Sep 18 2019 8:00PM
[GOLDBELL CAR RENTAL PTE LTD]
Lion City Rentals Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
2	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
3	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
4	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
5	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
6	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
7	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
8	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
9	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
10	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
11	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
12	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
13	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
14	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
15	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
16	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
17	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
18	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
19	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
20	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
21	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
22	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
23	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
24	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
25	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
26	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
27	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
28	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
29	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
30	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
31	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
32	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
33	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
34	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
35	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
36	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
37	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
38	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
39	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
40	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
41	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
42	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	
43	07/11/19 08:56	General View														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
44	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
45	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
46	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
47	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
48	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
49	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
50	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
51	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
52	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
53	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
54	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
55	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
56	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
57	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
58	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
59	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
60	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
61	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
62	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
63	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
64	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
65	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
66	07/11/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>
67	07/11/19 08:56	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
68	07/11/19 08:56	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
69	07/11/19 08:56	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
70	07/11/19 08:56	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
71	07/11/19 08:56	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
72	07/11/19 08:56	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/09/19 11:32	TP GIA REPORT		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	26/09/19 10:21	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19016717/EQF3E2

Date: 22/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994314
Claimant
Vehicle No : SLH1932U **Insured Vehicle No :** SMA5072A
Date of Loss: 18/09/2019 **Nature of Claim:** TP **Claim No:** 0270397163SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH1932U
Make & Model: HONDA SHUTTLE, 1.5 (A) **Engine No:** LEB4261870
Reg. Date: 26/10/2016 (Man. Year: 2016) **Chassis No:** GP71042222
Colour: Red **Odometer:** 196151 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:** Yes

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 **Rear Tyre Size:** 185/60 R15
Front Left Side: Pirelli 6 mm **Rear Left Side:** Pirelli 6 mm
Front Right Side: Pirelli 6 mm **Rear Right Side:** Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,977.68	5,295.88	3,681.80	41.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,640.00	1,900.00	1,740.00	47.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,617.68	7,195.88	5,421.80	42.97
Approved Total (Overridden) (S\$)		5,750.00		
(S\$)	12,617.68	5,750.00	6,867.68	54.43
+ GST 7.00/7.00% (S\$)	883.24	402.50	480.74	54.43
Nett Amount (S\$)	13,500.92	6,152.50	7,348.42	54.43

INSPECTION

Date of Assignment: 23/09/2019
Date Inspected: 23/09/2019 Inspected At: 60 JALAN LAM HUAT #04-35/36
 Repairer : Lion City Rentals Pte Ltd (HQ)
Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,850.00 FL	*1,250.00 FL
2	1		*REAR TAILGATE LOCK	Bent	550.00 FL	*180.00 FL
3	1		*REAR TAILGATE LOCK CATCH	Not Necessary	158.00 FL	*- FL
4	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*195.00 FL
5	1		*REAR TAILGATE WEATHERSTRIP	Crushed	255.00 FL	*197.00 FL
6	1		*REAR TAILGATE HOLDER COVER	Crushed	80.00 FL	*55.00 FL
7	1		*REAR TAILGATE HONDA EMBLEM	Necessary	81.30 FL	*81.30 FL
8	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	88.40 FL	*88.40 FL
9	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	88.40 FL	*88.40 FL
10	1		*REAR END PANEL TOP GARNISH	Crushed	300.00 FL	*155.50 FL
11	1		*REAR END PANEL	Dented	1,200.00 FL	*560.80 FL
12	1		*REAR BUMPER	Dented	1,350.00 FL	*1,150.60 FL
13	1		*REAR BUMPER LH SIDE RETAINER	Broken	128.00 FL	*128.00 FL
14	1		*REAR BUMPER LH REFLECTOR GARNISH COVER	Cut	178.00 FL	*178.00 FL
15	1		*REAR BUMPER LH REFLECTOR	Not Necessary	250.00 FL	*- FL
16	1		*REAR BUMPER SPONGE	Not Necessary	150.00 FL	*- FL
17	1		*FRONT BUMPER	Broken	1,650.00 FL	*1,050.00 FL
18	1		*SET REVERSE SENSOR	Not Necessary	260.00 FS	*- FS
19	1		*SET WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
20	1		*SET BODY SEALANT	Necessary	300.00 FS	*30.00 FS
21	1		*SET BUMPER CLIPS	Necessary	120.00 FS	*60.00 FS
22	1		*SET END PANEL TO GARNISH CLIPS	Necessary	80.00 FS	*15.00 FS
23	1		*R/L TAILLAMP	N/S Cut	850.00 FL	*690.60 FL
24	1		*R/L TAILLAMP REFLECTOR	N/S Cut	720.00 FL	*390.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,002.10	6,583.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,024.42	1,287.72
Total Parts (\$\$)	8,977.68	5,295.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE R/L FENDER, REAR TAILGATE, REAR BUMPER, END PANEL OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS AND ALSO STRAIGHTEN SPARE TYRE PANEL INCLUDE CUTTING / WELDING OF DAMAGED PARTS	New	1,500.00	900.00
2	TO RESPRAY R/L FENDER, REAR TAILGATE, REAR BUMPER, END PANEL AND SPARE TYRE PANEL (INNER / OUTER)	New	1,200.00	800.00
3	TO REMOVE & INSTALL REAR WINDSCREEN	New	160.00	120.00
4	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS	New	80.00	30.00
5	TO TRANSFER TAILGATE MECHANISM	New	100.00	50.00
6	TO DEACTIVATE AND ACTIVATE HYBRID BATTERY AS A SAFETY PRECAUTION	New	300.00	0.00
7	TO CONDUCT A STANDARD OF OPEARTING PROCEDURES POST REPAIRS DIAGNOSTIC SCAN TEST AS A REQUIREMENTS FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS	New	300.00	0.00
Gross Labour Cost (\$\$)			3,640.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >