

reference

ASS. REC. BY:

Surveyor: Kenneth

REF:

CS/AIG/19016719/Kwf3 02

Special Instructions:

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of AIG

Date/Time: 23/9/2019

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SKW 3658-G

Insured: STR 9474T

at Workshop m/s 8 Three Automotive

Tel: 9662 0282

of BIK 8 Sin Ming Ind Est #01-64

Policy No:

Claim No: 4760280456SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14/9/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

Ishtayid



SKW 3658-G-X

STR 9474T - CS / MSG 1401608 / T/brn2 DCA: 11/9/2017

26/9 11 Lm 8 24506 email & confirm (Red 60x6 80, 71%)

ASS. REC. BY:

REF: 146/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

Res.: Yes or No

Lum Sum:

20

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKW36586

Yr Regn:

10, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

c.c.

1498

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading:

89154

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM8BM42A8G0320447

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: Nexen

R: B.S

205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

5

mm

L/Bal.

8

mm

L/Bal.

5

mm

D.O.A.

14/8/19

D.O.I.

23/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

RECEIVED 3 SEP 2019

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2) x69 - typist

Report Format:

merimen

Lump Sum / I.B.I: (\$

2450/-

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ = RS. \$1

250

), Fuel

11

), Others

TOTAL

261

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Sep 2019 Edit Reg		24 Sep 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	BKW RENT- A - CAR PTE LTD		
Main Claimant:	NATIONAL CAR RENTALS (PRIVATE)LIMITED, Co. Reg. No.: 196100157E		
Vehicle Reg. No.:	SKW3658G	Date of Loss:	14/09/2019 12:00 - :59
Claim Type:	TP / 4760280456SG	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SJR9474T	Policy No. (Claimant):	
		Excess:	
Repairer:	S Three Automative Recovery (HQ) Blk 8 Sin Ming Industrial Estate, #01-64/66, 575643 Sin Ming - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 03/10/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION REQUEST – SKK7377D vs SJR9474T (OI) on D.O.A.: 14/09/2019

From: Chin, Lee-Ying
To: Hor, Yinnul, 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni, Ng, Hai-K
Sent: 18/23/2019 11:40:11 AM
Attachments:  Pre-Repair Survey - AIG Asia Pacific Insurance Pte Ltd.pdf

Hi LKK,

Please note TP vehicle number should be SKW3658G, kindly contact repairer to arrange for survey at the soonest.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Hor, Yinnul
Sent: Friday, September 20, 2019 11:24 AM
To: 'assignments@lkkauto.com'; Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni
Subject: aigencrypt PRE-REPAIR INSPECTION REQUEST – SKK7377D vs SJR9474T (OI) on D.O.A.: 14/09/2019

Hi,

Please refer to the enclosed request from **LIBERTY LAW PRACTICE LLP**.
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.*

Thanks & Regards,

Hor Yin Rui (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001208556 | Ext: 1002208
Yinnul.Hor@aig.com | www.aig.sg

From: Serene Chul Yoke Har [<mailto:serene@libertylaw.com.sg>]
Sent: Friday, September 20, 2019 10:21 AM
To: Hor, Yinnul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni
Subject: [EXTERNAL] PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJR9474T AND SKK7377D ON 14/09/2019

This message is from an external sender; be cautious with links and attachments.

Your ref: SJR 9474T
Our ref: CS/1116/19/S3

Dear Viviane,

We refer to your email dated 19 September 2019.

Kindly arrange for **Kenneth Kong** from **LKK Auto Consultants Pte Ltd**, to carry out the pre-repair survey of our client's vehicle SKW 3658G as a 'single joint expert'.

Please be informed that the said vehicle can be surveyed / inspected at:

Venue : **S Three Automotive Recovery Pte Ltd**
Blk 8 Sin Ming Industrial Estate
#01-64/66
Singapore 575643
Contact / Tel : **Ms. Joey / 9662 0282**

Kindly acknowledge receipt hereof.

Kind Regards,

Serene
DID: 3152 0980

LIBERTY LAW PRACTICE LLP

- 10 Hoe Chiang Road, #13-03A Keppel Towers, Singapore 089315

* Tel : (65) 6223 6767 | Fax : (65) 6223 7262

web: www.libertylaw.com.sg

Privileged and/or confidential information may be contained in this email or its attachments. If you are not the intended recipient, you must not disclose, copy or distribute the contents therein or take any action in reliance of such contents. Communication of any information in this email or its attachments to an unauthorized person is prohibited

Please consider the environment before printing this e-mail

On Thu, Sep 19, 2019 at 4:24 PM Hor, Yinrul <Yinrul.Hor@aig.com> wrote:



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสลับ เพื่ออ่าน
มันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려
면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,
membuka attachment.

[Click here](#) by 2019-09-26 16:24 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the
addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Protonmail Encryption, Copyright © 2006-2017 Protonmail, Inc. All rights
reserved.



Virus-free. www.avast.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	157E
Vehicle Details	
Vehicle No.:	SKW3658G
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP6EAT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	P520321917
Chassis No.:	JM6BM42A8G0320447
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$17,996.00
Original Registration Date:	27 Oct 2015
First Registration Date:	27 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$12,996.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Oct 2025
PARF Rebate Amount:	\$9,747.00
Intended COE Rebate Details	
COE Expiry Date:	26 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,399.00
COE Rebate Amount:	\$33,730.00
Total Rebate Amount:	\$43,477.00

The information contained herein is correct as at 24 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/09/2019 11:16
Date Of Accident	14/09/2019 12:10
Exact Location Of Accident	27 WOKING ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW3658G
Insured/Policyholder	
Name Of Registered Owner	NATIONAL CAR RENTALS (PRIVATE) LIMITED
Co Reg No	196100157E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90297210

Vehicle Particulars

Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5057621347-06
Cover Note Number	

Driver

Name of Driver	BROMLEY JILLIAN RITA
Passport No/FIN	G5588295P
Date Of Birth	19/10/1946
Occupation	INDOOR
Date Of Driving Pass	09/12/2002
Driving Experience	16 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90297210
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 27 WOKING ROAD
#02-03
Postcode 138705
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name QUEENSTOWN N.P.C
Police Station Address ROAD: 3 QUEENSWAY #01-03 , POSTCODE: 149073 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-4719999 - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER ATTACHED POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

Details of Witness 1

Name JANET ANNE PLEW
Phone Number
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJR9474T
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE HIRE
Name of Driver LOH JOO SIANG
NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Abstract of Police Report T/2017/2413, 2002

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature _____
Date & Time: _____

(5) All NC School Plan-Form_VB

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____



**SINGAPORE
POLICE FORCE**



T/20190915/2002

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

1 of 4

Report No: T/20190915/2002

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/09/2019 00:26		Vide Report No.:		Station Diary No.: 1	
Informant's Particulars					
Name of Informant: BROMLEY JILLIAN RITA			Address: APT BLK 27 WOKING ROAD #02-03 PEGU SINGAPORE 138705		
ID Type / ID No.: FIN NO / G5588295P			Contact No.: Home/Office: Mobile: 90297210		
Nationality: AUSTRALIAN			Email:		
Sex: Female	Age: 72	Date of Birth: 19/10/1946	Type of Informant: Vehicle Owner		
Race: Caucasian			Language: English		Institution / School Name:
Occupation: Company director			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 14/09/2019 12:10	Type of Location: Straight Road
Location: Along Road 1 WOKING ROAD At 27 Woking Road				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJR9474T	Car					1
SKW3658G	Car	MAZDA	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT	Silver	Seriously Damaged	0



**SINGAPORE
POLICE FORCE**



T/20190915/2002

2 of 4

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

Report No. T/20190915/2002

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	Loh Joo Siang	ID No.	NIL
Related Vehicle	SJR9474T (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Vehicle Owner			
Name	BROMLEY JILLIAN RITA	ID No.	G5588295P
Related Vehicle	SKW3658G (Car)	Contact No.	90297210
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 14/09/2019, at about 1210hrs, my sister namely: Janet Anne Plew and her husband, were sitting at the balcony of my house when her husband saw one of my acquaintance namely: Abigail, HP: 91790268 waiting for a Gojek car. Suddenly, my sister heard a loud impact sound which sounded like a car hitting another car. My sister saw the driver of the Gojek car came out and looked at the damage and went back into his car and drove away and my sister's husband and her saw the car moving forward from my car and the driver waved at my sister. My sister then tried to chase after the car, however she could not catch up.

I would like to state that Abigail is a acquaintance and she was the one who booked the Gojek car. She was in the vehicle when the accident happened and the driver told her that nobody will know or nobody saw the accident and he just drove off.

I then contacted Abigail through my neighbor who passed me her number and enquired more details from her and Abigail provided me with the driver's name: Loh Joo Siang, driving vehicle: SJR9474T. After that I contacted Gojek and I spoke to a customer service representative namely: Aisa, who provided me with a report number: 644249.

I wish to state that my vehicle is a rented car which I rented from Avis Car Rental and I have been renting it for the past 2 weeks. The damage to the car are deep dents and deep scratches to the right rear bumper. I do not know the cost to repair the damages. I have an in-vehicle camera, however it only turns



**SINGAPORE
POLICE FORCE**



T/20190915/2002

3 of 4

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

Report No. T/20190915/2002

CONTINUATION OF REPORT

on when the engine is on.



**SINGAPORE
POLICE FORCE**



T/20190915/2002

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

4 of 4

Report No. T/20190915/2002

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Sgt 3 YIP XUANYU

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

15/09/2019 00:26

Officer In Charge Of Case:

TP / HRT /

SI KALESWARI PALANI

Contact No: 65476902

Classification Of Case:

Authentication Stamp

NP168

SIGNATURE

TO :
ATTN : **MOTOR CLAIM DEPT.** T/P VEH. NO. : **SJR9474T**

ESTIMATE REPORT 1st QUOTATION
OWNER'S PARTICULAR

JOB NO : _____

NAME : **NATIONAL CAR RENTALS PTE LTD**
ADDRESS :

CONTACT :

LICENSE NO. : **SKW3658G** TRANS.
MAKE / MODEL : **MAZDA 3**
OWNER'S INSURER : **NTUC INCOME**
JOB-CODE : **TP** S/A : **MICHELLE**

CHASSIS NO :
ENGINE NO :

ACCIDENT DATE : **14-Sep-19**

CLAIM DETAIL

MATERIALS

		QTY	QUO-PRICE	DISC. %	DISC- PRICE	SUR	
1	REAR BUMPER	1.00	\$ 1,074.80	10.00	\$ 967.32	Y	✓
2	REAR BUMPER RETAINER LH	1.00	\$ 46.00	10.00	\$ 41.40	Y	✗
3	REAR BUMPER RETAINER RH	1.00	\$ 46.00	10.00	\$ 41.40	Y	✗
4	REAR BUMPER TOP RETAINER LH	1.00	\$ 54.00	10.00	\$ 48.60	Y	✗
5	REAR BUMPER TOP RETAINER RH	1.00	\$ 54.00	10.00	\$ 48.60	Y	✗
6	TAILLAMP RH	1.00	\$ 669.00	10.00	\$ 602.10	Y	✓
7	TAILLAMP INNER PANEL RH	1.00	\$ 377.80	10.00	\$ 340.02	Y	✗
8	REAR FENDER RH	1.00	\$ 1,175.00	10.00	\$ 1,057.50	Y	✗
9	REAR FENDER INNER SHIELD RH	1.00	\$ 145.90	10.00	\$ 131.31	Y	✗
10	REAR SHOCK ABSORBER RH	1.00	\$ 330.00	10.00	\$ 297.00	Y	✗
11	REAR KNUCKLE ARM RH	1.00	\$ 620.60	10.00	\$ 558.54	Y	✗
12	REAR WHEEL HUB W/BEARING RH	1.00	\$ 349.00	10.00	\$ 314.10	Y	✓
13	REAR LOWER ARM RH	1.00	\$ 285.00	10.00	\$ 256.50	Y	✗
14	REAR UPPER ARM RH	1.00	\$ 224.90	10.00	\$ 202.41	Y	✗
15	REAR WHEEL COVER RH	1.00	\$ 280.00	10.00	\$ 252.00	Y	✗

TOTAL (PARTS) :

5732.00

4906.80

SPECIAL NETT ITEM

1	REAR BUMPER CLIPS	1.00	50.00	0.00	50.00	Y	✓
2	REAR FENDER INNER SHIELD CLIPS	1.00	50.00	0.00	50.00	Y	✗
3	REAR RIM RH	1.00	450.00	0.00	450.00	Y	✓
4	REAR TYRE RH	1.00	380.00	0.00	380.00	Y	✗

TOTAL (PARTS) :

930.00

930.00

Not Withheld
6/1 Sep 82450h
Running After Paint
4 days
208

1/500

As per Consultants hence notify the Repairer of the following:
 • To recover before tax and duty
 • To display damaged parts in a timely manner
 • Parts prices are subject to change
 • Third party survey is subject to 'Insured' limits
 • No illegal modifications
 • Supplementary items are subject to 'Insured' limits
 • Is subject to that act of the Police and the Insurance Company

Acknowledged by: _____
Signature: _____
Date: _____

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	1.00	1000.00	0.00	1000.00	Y	4001
2	SPRAY PAINTING ON ACCIDENT AREAS	1.00	1000.00	0.00	1000.00	Y	4004
3	CHECK AND REPAIR WIRING SYSTEM	1.00	120.00	0.00	120.00	Y	201
4	RESPRAY TUFF KOTE ON ACCIDENT AREAS	1.00	120.00	0.00	120.00	Y	X
5	R&R REAR SUSPENSION COMPONENT RH	1.00	280.00	0.00	280.00	Y	502
6	COMPUTERISED WHEEL ALIGNMENT AND BALANCING TYRE	1.00	120.00	0.00	120.00	Y	601

TOTAL (LABOUR) :

2640.00 2640.00

TOTAL PARTS & LABOUR

9302.00 8476.80

EXCESS : : S\$

8728.80

NO. OF DAY : 04 days

RE-SURVEY : ~~BEFORE~~ / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : S\$

DATE OF SURVEY : 23/9/19

SURVEY BY : Kennerh

CONTACT NO : 96910663

FAX NO : 62564315

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19016719/KVF3N2

Date: 01/10/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SKW3658G	Insured Vehicle No :	SJR9474T
Date of Loss:	14/09/2019	Nature of Claim:	TP
		Claim No:	4760280456SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW3658G	Engine No:	P520321917
Make & Model:	MAZDA 3, 1.5 (A)	Chassis No:	JM6BM42A8G0320447
Reg. Date:	27/10/2015 (Man. Year: 2015)	Odometer:	89154 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Nexen 8 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,088.80	2,174.24	3,914.56	64.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	930.00	1,710.00	64.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,728.80	3,104.24	5,624.56	64.44
Approved Total (Overridden) (\$\$)		2,450.00		
(\$\$)	8,728.80	2,450.00	6,278.80	71.93
+ GST 7.00/7.00% (\$\$)	611.02	171.50	439.52	71.93
Nett Amount (\$\$)	9,339.82	2,621.50	6,718.32	71.93

INSPECTION

Date of Assignment:	23/09/2019	
Date Inspected:	23/09/2019 Inspected At:	S Three Automative Recovery (HQ) Blk 8 Sin Ming Industrial Estate, #01-64/68 Singapore 575643
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Cut	1,074.80 FL	*1,074.80 FL
2	1		*REAR BUMPER RETAINER LH	Serviceable	46.00 FL	*- FL
3	1		*REAR BUMPER RETAINER RH	Serviceable	46.00 FL	*- FL
4	1		*REAR BUMPER TOP RETAINER LH	Serviceable	54.00 FL	*- FL
5	1		*REAR BUMPER TOP RETAINER RH	Serviceable	54.00 FL	*- FL
6	1		*TAILLAMP RH	Cut	669.00 FL	*669.00 FL
7	1		*TAILLAMP INNER PANEL RH	Repair	377.80 FL	*- FL
8	1		*REAR FENDER RH	Repair	1,175.00 FL	*- FL
9	1		*REAR FENDER INNER SHIELD RH	Serviceable	145.90 FL	*- FL
10	1		*REAR SHOCK ABSORBER RH	Serviceable	330.00 FL	*- FL
11	1		*REAR KNUCKLE ARM RH	Serviceable	620.60 FL	*- FL
12	1		*REAR WHEEL HUB W/BEARING RH	Jammed	349.00 FL	*349.00 FL
13	1		*REAR LOWER ARM RH	Serviceable	285.00 FL	*- FL
14	1		*REAR UPPER ARM RH	Serviceable	224.90 FL	*- FL
15	1		*REAR WHEEL COVER RH	Serviceable	280.00 FL	*- FL
16	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
17	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
18	1		*REAR RIM RH	Scratched	450.00 FS	*450.00 FS
19	1		*REAR TYRE RH	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,662.00	2,592.80
- List Item Discount on L Items 10.00/20.00% (\$\$)	573.20	418.56
Total Parts (\$\$)	6,088.80	2,174.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	New	1,000.00	400.00
2	SPRAY PAINTING ON ACCIDENT AREAS	New	1,000.00	400.00
3	CHECK AND REPAIR WIRING SYSTEM	New	120.00	20.00
4	RESPRAY TUFF KOTE ON ACCIDENT AREAS	New	120.00	0.00
5	R&R REAR SUSPENSION COMPONENT RH	New	280.00	50.00
6	COMPUTERISED WHEEL ALIGNMENT AND BALANCING TYRE	New	120.00	60.00
Gross Labour Cost (S\$)			2,640.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >