

22052002

ASS. REC. BY:

REF:

C83/F0019016722/G6B3

Special Instruction

Surveyor:

QA

ASSIGNMENT (Office)

From (Person):

Vanessa Chan

of

F00

Date/Time:

20/9/2019.

Estimated Cost:

Bill to:

OD-TP WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SKM 6795B

Insured:

SLW 8648 R

at Workshop m/s The Mechanic

Tel:

9119.3959 Bao Bao

of 25 Kaki Bukit Rd 4 #05-85 Synergy

Policy No: PNC/2019-00000194

Claim No:

1201900028351

Sum Insured:

Excess:

D.O.A.

19/9/2019

Make of Veh:

(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time: 23/9

Person Contacted:

Bao Bao

Vehicle IN OUT

Date/Time	Action/Instruction
	Estimate (x) Inspection - 8 Kaki Bukit Ave 4 #02-47
	SKM 6795B - X
	SLW 8648 R - X.
	Dismantle: 24/9/2019
	After repair: 25/9/2019

Surveyor:

Gul.
PRS

REF:

FWD

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

The Mechanic

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt.: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKM6795B

Yr Regn:

03, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 320i

c.c

1998

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

65551

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA3B16000NS51606

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 275/30 ZR19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

23-09-19

Survey held at

w/s

4:40pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$2000 - \$3000

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) \$ + RS. \$ SI

) Photos

) Others

TOTAL

Report Format:

PRS

Lump Sum / I.B.I: (\$

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Sep 2019 Edit Reg		24 Sep 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	TING FOOK SENG, ID: S8178306C		
Main Claimant:	ALVIN LIM HONG GHUAN (ALVIN LIN FENGYUAN), ID: S78077668		
Vehicle Reg. No.:	SKM6795B	Date of Loss:	19/09/2019 00:00 - :59
Claim Type:	TP / 1201900028351	Policy/Cover Note No.:	PNCV2019-00000194 (Comprehensive) Coverage: 06/03/2019 - 05/03/2020
Vehicle Reg. No. (Insured):	SLW8648R	Policy No. (Claimant):	
		Excess:	
Repairer:	The Mechanic (Private Limited) (HQ) 25 Kaki Bukit Road, # 05-85 Synergy@KB, 417800 Kaki Bukit - Tel: 67023123		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/10/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Nivitha (LKK Auto)

From: venessa.chan@fwd.com
Sent: Friday, 20 September 2019 3:41 PM
To: admin-d@lkkauto.com; admin-a@lkkauto.com
Cc: motorclaims.sg@fwd.com; lionel.tan@fwd.com
Subject: PRE-REPAIR SURVEY- ACCIDENT INVOLVING SKM6795B & SLW8648R ON 19TH SEPTEMBER 2019 [RSS/1909-7467 (MECH)(PD)]
Attachments: SKM6795B PRI - R.S SOLOMON LLC .pdf

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen & I will upload the documents accordingly.

Thank you

Best Regards,


Venessa Chan

Administrative Assistant, Claims



After 2pm

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
E venessa.chan@fwd.com
W www.fwd.com.sg



From: Venessa Chan - SGUser
Sent: Friday, September 20, 2019 3:38 PM
To: 'Lua Siew Hui'
Cc: Natalie Ng; Wendy Jiang; Motor Claims SG - SG Common; Lionel Tan Tian Pei - SGUser
Subject: PRE-REPAIR SURVEY- ACCIDENT INVOLVING SKM6795B & SLW8648R ON 19TH SEPTEMBER 2019 [RSS/1909-7467 (MECH)(PD)]

WITHOUT PREJUDICE

Dear Siew Hui,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s **LKK Auto Consultant Pte Ltd**, to conduct the pre-repair survey (PRS) on your client's vehicle, SKM6795B. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.***

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Lua Siew Hui [mailto:lua_siewhui@rssolomon.com]

Sent: Friday, September 20, 2019 2:38 PM

To: Venessa Chan - SGUser

Cc: Natalie Ng; Wendy Jiang; Motor Claims SG - SG Common; Lionel Tan Tian Pei - SGUser

Subject: Re: PRE-REPAIR SURVEY- ACCIDENT INVOLVING SKM6795B & SLW8648R ON 19TH SEPTEMBER 2019 [RSS/1909-7467 (MECH)(PD)]

Dear Venessa,

We thank you for your email of even date.

We write to inform that our client will be appointing his own surveyors.

In this respect, please arrange your surveyors to contact Ms. Bao Bao of The Mechanic at mobile no. 9119 3959 for a pre-repair survey of our client's vehicle located at 25 Kaki Bukit Road 4 #05-85 SYNERGY @ KB, Singapore 417800.

Thank you and best regards

Advocates & Solicitors

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e lua_siewhui@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information. If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system. Thank you.

On Fri, Sep 20, 2019 at 2:29 PM <venessa.chan@fwd.com> wrote:

WITHOUT PREJUDICE

Dear Siew Hui,

We refer to your email dated on 19.09.2019 of the PRI Notice of your client's vehicle SKM6795B.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT APPRAISAL PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

***Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.**

Thank you.

Best Regards,

Venessa Chan


Administrative Assistant, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Lua Siew Hui [mailto:lua_siewhui@rssolomon.com]

Sent: Friday, September 20, 2019 9:19 AM

To: Motor Claims SG - SG Common

Cc: Natalie Ng; Wendy Jiang

Subject: PRE-REPAIR SURVEY- ACCIDENT INVOLVING SKM6795B & SLW8648R ON 19TH SEPTEMBER 2019
[RSS/1909-7467 (MECH)(PD)]

Dear Sirs,

We act for the owner ('our Client') of vehicle no. SKM6795B.

Our Client's vehicle was involved in the aforesaid accident with your insured's vehicle no. SLW8648R at the material time. As a result, our Client's vehicle was damaged and before our Client proceeds to repair his vehicle, please let us know within 2 working days upon receipt of this notice whether you intend to conduct a pre-repair survey of our Client's vehicle within the stipulated timeline, our Client will proceed to repair his vehicle without further reference to you.

Please see below, the following documents for your necessary action:-

1. Our letter of even date; and
2. GIA Report lodged by our client.

Let us hear from you soonest.

Lua Siew Hui | Legal Executive

R. S. Solomon LLC | 正氣律師事務所

Advocates & Solicitors

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e lua_siewhui@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information. If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system. Thank you.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Our Ref. : RSS/1909-7467 (MCH)(PD)
Your Ref. :

W : Lua Siew Hui / Wendy Jiang
E : lua_siewhui@rssolomon.com/wendy_jiang@rssolomon.com

20 September 2019



R. S. SOLOMON LLC
ADVOCATES & SOLICITORS

FWD Singapore Pte Ltd
No. 6 Temasek Boulevard
#18-01 Suntec Tower Four
Singapore 038986
Attn: Motor Claim Dept

By Email: [motorclaims.sg@fwd.com]
& Hand

Dear Sirs,

PRE-REPAIR SURVEY

ACCIDENT INVOLVING SKM6795B & SLW8648R ON 19TH SEPTEMBER 2019 AT ABOUT 0845 HRS

We act for the owner ("our Client") of vehicle no. SKM6795B.

2. We hereby notify you of a road traffic accident on **19th September 2019** at about **0845 hours** along Middle Road involving Client's vehicle and vehicle registration no. SLW8648R driven by your insured. A copy of our Client's Singapore Accident Statement is enclosed.
3. As a result of the accident, our Client's vehicle has been damaged. Before our Client proceeds to repair the damaged vehicle, please let us know within 2 working days upon receipt of this notice whether you would intend to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our Client shall proceed to repair his vehicle without further reference to you.

Yours faithfully,



R. S. SOLOMON LLC
ADVOCATES & SOLICITORS

ENCL

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	19/09/2019 12:44
Date Of Accident	19/09/2019 08:45
Exact Location Of Accident	MIDDLE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKM6795B
Insured/Policyholder	
Name Of Registered Owner	ALVIN LIM HONG GHUAN (ALVIN LIN FENGYUAN)
NRIC No	S7807766B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98313505
Alternative Phone No	OTHERS-98313505
Vehicle Particulars	
Manufacturer	BMW
Model	320I
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5108240450 (DRIVO CLASSIC)
Cover Note Number	
Driver	
Name of Driver	ALVIN LIM HONG GHUAN (ALVIN LIN FENGYUAN)
NRIC No	S7807766B
Date Of Birth	23/03/1978
Occupation	INDOOR
Date Of Driving Pass	14/07/2000
Driving Experience	19 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98313505
Fax Number	
Contact Number	OTHERS-98313505
EMail Address	NOEMAIL

Address	BLK 10C BENDEMEER ROAD #03-131
Postcode	333010
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	UNABLE TO UPLOAD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLW8648R
Vehicle Make/Model/Colour	HONDA VEZEL
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TING FOOK SENG
NRIC/Passport Number	S8178306C
Contact Number	96671919
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A- SKM 6795B

B- SLW 8648R

DOA - 19/9/19

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along middle road on 19 sep 2019 between 8.40 - 8.50 am, a car in front of me brake and slow down. I brake and slow down as well. As I slow down, car B hit my car from behind.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	766B
Vehicle Details	
Vehicle No.:	SKM6795B
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Sep 2019
Vehicle Make:	B.M.W.
Vehicle Model:	320I SEDAN AT D/AB 4DR ABS HID
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	A2780662N20B20B
Chassis No.:	WBA3B16000NS51606
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$35,862.00
Original Registration Date:	27 Mar 2014
First Registration Date:	27 Mar 2014
Transfer Count:	2
Actual ARF Paid:	\$32,207.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Mar 2024
PARF Rebate Amount:	\$22,544.00
Intended COE Rebate Details	
COE Expiry Date:	26 Mar 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$82,000.00
COE Rebate Amount:	\$36,319.00
Total Rebate Amount:	\$58,863.00

The information contained herein is correct as at 26 Sep 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Sep 2019 Edit Reg		20 Sep 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	TING FOOK SENG, ID: S8178306C		
Main Claimant:	ALVIN LIM HONG GHUAN (ALVIN LIN FENGYUAN), ID: S7807766B		
Vehicle Reg. No.:	SKM6795B	Date of Loss:	19/09/2019 00:00 - :59 [65 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201900028351	Policy/Cover Note No.:	PNCV2019-00000194 (Comprehensive) Coverage: 06/03/2019 - 05/03/2020
Vehicle Reg. No. (Insured):	SLW8648R	Policy No. (Claimant):	
		Excess:	
Repairer:	The Mechanic (Private Limited) (HQ) 25 Kaki Bukit Road, # 05-85 Synergy@KB, 417800 Kaki Bukit - Tel: 67023123		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/10/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKM6795B (1201900028351)**
[SLW8648R]

TP

ALVIN LIM HONG GHUAN (ALVIN LIN FENGYUAN)

Sep 19 2019 12:00AM

[TING FOOK SENG]





















The Mechanic (Private Limited)

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	Thumbnail	Print
1	25/09/19 11:04	General View	1	Load JPG	✓
2	25/09/19 11:04	General View	1	Load JPG	✓
3	25/09/19 11:04	General View	1	Load JPG	✓
4	25/09/19 11:04	General View	1	Load JPG	✓
5	25/09/19 11:04	General View	1	Load JPG	✓
6	25/09/19 11:04	General View	1	Load JPG	✓
7	25/09/19 11:04	General View	1	Load JPG	✓
8	25/09/19 11:04	General View	1	Load JPG	✓
9	25/09/19 11:04	General View	1	Load JPG	✓
10	25/09/19 11:04	General View	1	Load JPG	✓
11	25/09/19 11:04	General View	1	Load JPG	✓
12	25/09/19 11:04	General View	1	Load JPG	✓
13	25/09/19 11:04	General View	1	Load JPG	✓
14	25/09/19 11:04	General View	1	Load JPG	✓
15	25/09/19 11:04	General View	1	Load JPG	✓
16	25/09/19 11:04	General View	1	Load JPG	✓
17	25/09/19 11:04	General View	1	Load JPG	✓
18	25/09/19 11:04	General View	1	Load JPG	✓
19	25/09/19 11:04	General View	1	Load JPG	✓
20	25/09/19 11:04	General View	1	Load JPG	✓
21	25/09/19 11:04	General View	1	Load JPG	✓
22	25/09/19 11:04	General View	1	Load JPG	✓
23	25/09/19 11:04	General View	1	Load JPG	✓
24	25/09/19 11:04	General View	1	Load JPG	✓
25	25/09/19 11:05	Odometer Reading	1	Load JPG	✓
26	25/09/19 11:05	Chassis Number	1	Load JPG	✓
27	25/09/19 11:05	Dismantled Parts	1	Load JPG	✓
28	25/09/19 11:05	Dismantled Parts	1	Load JPG	✓
29	25/09/19 11:05	Dismantled Parts	1	Load JPG	✓
30	25/09/19 11:05	Dismantled Parts	1	Load JPG	✓
31	25/09/19 11:05	Dismantled Parts	1	Load JPG	✓
32	25/09/19 11:05	Dismantled Parts	1	Load JPG	✓
33	25/09/19 11:05	Dismantled Parts	1	Load JPG	✓
34	25/09/19 11:05	Dismantled Parts	1	Load JPG	✓
35	25/09/19 11:05	Dismantled Parts	1	Load JPG	✓
36	25/09/19 11:05	Dismantled Parts	1	Load JPG	✓
37	25/09/19 11:05	Dismantled Parts	1	Load JPG	✓
38	25/09/19 11:05	Dismantled Parts	1	Load JPG	✓
39	25/09/19 11:05	Dismantled Parts	1	Load JPG	✓
40	25/09/19 11:05	Dismantled Parts	1	Load JPG	✓

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	25/09/19 11:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	25/09/19 11:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	25/09/19 11:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	25/09/19 11:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	26/09/19 10:08	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
46	26/09/19 10:08	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
47	26/09/19 10:08	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
48	26/09/19 10:08	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
49	26/09/19 10:08	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
50	26/09/19 10:08	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
51	26/09/19 10:08	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
52	26/09/19 10:08	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
53	26/09/19 10:08	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
54	26/09/19 10:08	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
55	26/09/19 10:08	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
56	26/09/19 10:08	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
57	26/09/19 10:08	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	24/09/19 12:35	SLW8648R OI GIA	 Load PDF	
2	24/09/19 12:36	SKM6795B TP GIA	 Load PDF	
3	24/09/19 12:39	EMAIL LKK TO ARRANGE SURVEY.	 Load PDF	
4	24/09/19 12:42	SKM6795B PRI - R S SOLOMON LLC	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD19016722/GCF3S2
Date: 08/10/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNCV2019-00000194
Claimant Vehicle No: SKM6795B Insured Vehicle No: SLW8648R
Date of Loss: 19/09/2019 Nature of Claim: TP Claim No: 1201900028351

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKM6795B
Make & Model: BMW 320I, 2.0 (A) Engine No: A2780662N20B20B
Reg. Date: 27/03/2014 (Man. Year: 2013) Chassis No: WBA3B16000NS51606
Colour: Black Odometer: 65551 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/30 ZR19 Rear Tyre Size: 275/30 ZR19
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm
The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/09/2019
Date Inspected: 23/09/2019 Inspected At: 8 KAKI BUKIT AVE 4 #02-47
Estimated Period of Repair: 4.0 days Repairer: The Mechanic (Private Limited)

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 08 Oct 2019)

Parts: N/A BMW 320I 2.0 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKM6795B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >