

22/03/2002

SS. REC. BY:

REF: CS/PCI 19016724/64 f327

Special Instruction:

Survivor: GR

ASSIGNMENT (Office)

From (Person): Minna Chia San San of FCI Date/Time: 23.9.16 11.35a.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: FBK 241P Insured: SHA 0609Uat Workshop m/s Tong Ark motor Tel: 6337 9912of 89 short Street # 01-02Policy No: \_\_\_\_\_ Claim No: D19005996 MP54

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 14.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 23.9.19 1.33p.m Person Contacted: Madam Soo Vehicle IN/OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	<u>#05-07. Inspection.</u>
	<u>FBK 241P -x</u>
	<u>SHA 0609U -x</u>
<u>25/9 -</u>	<u>Revised via press advise</u>

Surveyor: ad.

REF: Fci

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Tong Aik

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt.: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: FBK 241 P Yr Regn: 06 Feb 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Piaggio Vespa c.c. 278

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 48330 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 24 PM 452 0000 86172

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70-12

R: 130/70-12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Rear

Front

Rear

R/Bal. 4 mm

R/Bal. 4 mm

L/Bal. 4 mm

L/Bal. 4 mm

D.O.A. \_\_\_\_\_

D.O.I. 24-09-19

Survey held at w/s

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Finalized \$1459.2 with Soh.

(Red: 952; 39%)

RECEIVED 10 OCT 2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 18/10 Typist

☒

: Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Photos \_\_\_\_\_

Others \_\_\_\_\_

Report Format : TP

Lump Sum / I.B.I: (\$ 1459.20)

TOTAL

110
90
50
52
262

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	17-09-2019	<b>Our Ref No.</b> D19005996MFSH
<b>Accident Date</b>	14-09-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA0609U	<b>Third Party Vehicle.</b> FBK241P
<b>Survey Location</b>	89 SHORT STREET #01-02/03 GOLDEN WALL CENTRE	
<b>Contact Person.</b>	NA	
<b>Contact No.</b>	6337 9912/ 0	<b>Fax No.</b> 6337 9246
<b>Survey Type</b>	WITHOUT PREJUDICE:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	TONG AIK MOTOR SUPPLY CO	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	MERINA CHIA SAN SAN	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Denise Tay (LKKAUTO)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Wednesday, 25 September 2019 11:35 AM  
**To:** Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments; SUR  
**Cc:** 'Merina Chia'  
**Subject:** RE: SURVEY ASSESSMENT - D19005996MFSH/1  
**Attachments:** PRELI ADVISED OF FBK 241P.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **FBK 241P**  
Number of days (estimated) : 4 days

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Sent:** Monday, 23 September 2019 1:34 PM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** 'Merina Chia' <[MerinaChia@msfirstcapital.com.sg](mailto:MerinaChia@msfirstcapital.com.sg)>  
**Subject:** RE: SURVEY ASSESSMENT - D19005996MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

**Summer Lee** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>  
**Sent:** Monday, 23 September, 2019 11:35 AM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Merina Chia <[MerinaChia@msfirstcapital.com.sg](mailto:MerinaChia@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19005996MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



**SINGAPORE  
POLICE FORCE**



E/20190915/7001

1 of 3

**POLICE REPORT (NP299)**

Report No. E/20190915/7001

Police Station Of Origin  
Tanglin Division HQ  
21 Kampong Java Road SINGAPORE  
228892  
Tel No:1800-3910000

Date/Time Report Made 15/09/2019 09:04	Vide Report No.	Station Diary No.		
Name Of Informant LOO WAI LEONG	Address APT BLK 81 STRATHMORE AVENUE #03-128 SINGAPORE 141081			
ID Type / ID No. NRIC NO / S8526410I	Contact No. Home/Office:                      Mobile: 97948313			
Nationality SINGAPORE CITIZEN	Email Address waileong.loo@gmail.com			
Occupation Other engineering professionals nec	Sex Male	Age 34	Date of Birth 09/08/1985	Race Chinese
Institution/School Name	Language English			
Date/Time Of Incident 14/09/2019 19:00 - 14/09/2019 19:20	Location Of Incident ADAM ROAD			

**Brief details.**

I, Mr Loo Wai Leong(S8526410I) and My pillion/wife Mdm Koh Khee Hoon(S8421954A) was riding my Black Vespa GTS300 Scooter(FBK 241P) travelling along Adam Road towards Farrer Road(Just exit out from PIE).

I was riding on the fourth lane at about 50-60 km/hr before a Taxi suddenly cut in from the 3rd lane and hit us on our right side of my Scooter. The taxi driver, Mr Lee Kim Toong (S7204976D) claimed that he wanted to pick a passenger and did not see us. (Refer to the attachment for more details)There was a

Signature Of Officer Recording The Report:  Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 15/09/2019 09:04
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



**POLICE REPORT (NP299)**

**CONTINUATION OF REPORT**

Report No. E/20190915/7001

witness Mr Jonathon Ho(HP 96431126) who was driving behind the Taxi (SHA609U) who witness the whole accident. He has made Police Report(D/20190914/7021) at Buona Vista NPP.

We were sent to Tan Tock Seng Hospital & my wife was diagnosed with a right foot fracture, abrasion to the jaw & the right limbs. I have abrasion along my foot, knee and hip area.

My wife is on cast and on 2 weeks MC while I am on 3 day MC.

Subjects Involved			
Suspect			
Person Name	Lee Kim Toong		
ID Type	NRIC NO	ID No	S7204976D
Gender	Male	Age	45-50
Race	Chinese	Language	Chinese
Occupation	Taxi driver	Mobile No	87824976
Complexion	Light tan	Build	Medium
Height About	175cm	Attire Last Worn	White Long Sleeve with dark coloured pants
Hair Colour	Blonde	Relation To Informant	Suspect
Victim			
Person Name	LOO WAI LEONG		
ID Type	NRIC NO	ID No	S8526410I
Gender	Male	Age	34
Race	Chinese	Language	English

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:

15/09/2019 09:04

Classification Of Case:

Authentication Stamp



**POLICE REPORT (NP299)**

**CONTINUATION OF REPORT**

Report No. E/20190915/7001

Occupation	Other engineering professionals nec	Address Type	
Address	APT BLK 81 STRATHMORE AVENUE #03-128 SINGAPORE 141081	Mobile No	97948313
Is Informant A Victim?	Yes		
Person Name	Koh Khee Hoon		
ID Type	NRIC NO	ID No	S8421954A
Gender	Female	Age	35
Race	Chinese	Language	English
Occupation	Teacher	Address	81 81, STRATHMORE AVENUE #03-128 SINGAPORE 141081
Home/Office No	97948313	Mobile No	93390885
Relation To Informant	Wife		
Person Name	LOO WAI LEONG (Informant)		

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant:

The identity of the person making this  
report has been authenticated by  
SingPass. No signature is required.

Date/Time:

15/09/2019 09:04

Classification Of Case:

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	410I
Vehicle No.:	FBK241P
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2019
Vehicle Make:	PIAGGIO
Vehicle Model:	VESPA GTS 300 SUPER
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	M454M1049314
Chassis No.:	ZAPM4520000086172
Maximum Power Output:	-
Open Market Value:	\$4,688.00
Original Registration Date:	06 Feb 2015
First Registration Date:	06 Feb 2015
Transfer Count:	3
Actual ARF Paid:	\$704.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	05 Feb 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$5,504.00
COE Rebate Amount:	\$2,954.00
<b>Total Rebate Amount:</b>	<b>\$2,954.00</b>

The information contained herein is correct as at 24 Sep 2019

OK



# TONG AIK MOTORS SUPPLY CO

89, Short Street, #01-02/03,  
Golden Wall Centre,  
Singapore 188216  
Workshop: -  
89, Short Street, #05-07

Tel: 63379912 / 63370201  
Fax: 63379246  
E-mail: vescom100@hotmail.com  
Web Site:-  
www.teamvespa.com.sg  
20<sup>th</sup>. September 2019

*25/9/19*

To : First Capital Insurance Ltd.  
Attention: Motor Claim Department  
Email : [motorclaims@msfirstcapital.com.sg](mailto:motorclaims@msfirstcapital.com.sg)

Re: Scooter FBK 241 P with your insured vehicle SHA 609 U dated 14/9/2019  
Quotations To Repair Scooter FBK 241 P

## To Change:-

1) 1 pc. Exhaust protection chrome plate -----	\$ 48.00	/	CA
2) 1 pc. RH front body beading -----	\$ 45.00	/	CA
3) 1 pc. RH mirror -----	\$ 45.00	/	BR
4) 1 set. Masteeer cylinder for RH mirror -----	\$ 168.00	/	BR
5) 1 pc. RH Footrest -----	\$ 95.00	/	CA
6) 1 set. Balancer at handlegrip -----	\$ 48.50	/	BT
7) 1 set. Tail lamp assy -----	\$ 155.00	/	CRA
8) 1 set. Rear RH signal -----	\$ 38.50	/	CA
	\$ 643.00		
Less 10 %	\$ 64.30		
	\$ 578.70		

Knocking rear RH top panel , RH body till floorboard -----	\$ 280.00	/	200
Jack handle alignment -----	\$ 125.00	/	X
Spray painting matt colour -----	\$1000.00	/	300 400
1 set. Front and rear number plate -----	\$ 25.00	/	MC 625

## Complete Emblems:-

Vespa name (small) x2 pcs. For front body / top box -----	\$ 33.00	/	MC
Vespa name (big) x1 pc. At side body -----	\$ 22.50	/	MC
Super Sport name at front box -----	\$ 28.50	X	NN
GTS 300 ie name at side panel -----	\$ 28.50	X	NN
S sticker at top of tail lamp -----	\$ 20.00	/	MC
Labour charges -----	\$ 180.00	/	150
Transport from TP to IDAC to workshop -----	\$ 90.00	/	30
Total:-	\$ 2411.20		255.5

**Remarks: Any unforeseen parts damaged in process of repair another supplement quotation will be advised.**

• This party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

1459.2




**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19016724/Gtf3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 22-10-2019	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 609U	Veh. Inspected	FBK 241P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005996MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA SAN SAN	Assign Date	23/09/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	PIAGGIO VESPA GTS 300 SUPER	c.c	278	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZAPM4520000086172	Colour	BLACK	
Odometer	48330	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	120/70-12	PIRELLI	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	130/70-12	MICHELIN	4 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	14/09/2019	Inspection Date	24/09/2019	
Survey held at	TONG AIK MOTORS SUPPLY CO. 89 SHORT STREET GOLDEN WALL CENTER #05-07 SINGAPORE 180011			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 241P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	EXHAUST PROTECTION CHROME PLATE	CUT	48.00	48.00
1	RH FRONT BODY BEADING	CUT	45.00	45.00
1	RH MIRROR	BROKEN	45.00	45.00
1	SET MASTEER CYLINDER FOR RH MIRROR	BROKEN	168.00	168.00
1	RH FOOTREST	CUT	95.00	95.00
1	SET BALANCER AT HANDLEGRIP	BENT	48.50	48.50
1	SET TAIL LAMP ASSY	CRACKED	155.00	155.00
1	SET REAR RH SIGNAL	CUT	38.50	38.50
	LESS 10% DISCOUNT		-64.30	-64.30
			578.70	578.70
<b>SPECIAL NETT ITEMS</b>				
1	SET FRONT AND REAR NUMBER PLATE (SN)	NECESSARY	25.00	25.00
2	VESPA NAME (SMALL) FOR FRONT BODY / TOP BOX (SN)	NECESSARY	33.00	33.00
1	VESPA NAME (BIG) AT SIDE BODY (SN)	NECESSARY	22.50	22.50
1	SUPER SPORT NAME AT FRONT BOX (SN)	NOT NECESSARY	28.50	-
1	GTS 300 IE NAME AT SIDE PANAL (SN)	NOT NECESSARY	28.50	-
1	S STICKER AT TOP OF TAIL LAMP (SN)	NECESSARY	20.00	20.00
			157.50	100.50
<b>LABOUR</b>				
	KNOCKING REAR RH TOP PANEL, RH BODY TILL FLOORBOARD.		280.00	200.00
	JACK HANDLE ALIGNMENT.	NOT NECESSARY	125.00	-
	SPRAY PAINTING MATT COLOUR.		1,000.00	400.00
	LABOUR CHARGES.		180.00	150.00
	TRANSPORT FROM TP TO IDAC TO WORKSHOP.		90.00	30.00
			1,675.00	780.00
<b>GRAND TOTAL</b>			<b>2,411.20</b>	<b>1,459.20</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,459.20</b>

Report Ref No. CS/FCI19016724/Gtf3e2



Report Ref No. CS/FCI19016724/Gtf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.